

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1152/2017/GW
Date	:	20-Nov-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tan Lian See
Address	:	389 Kew Crescent

Singapore 466284

Telephone	:	94579549
Type of Claim	:	Third party claim
Policy No.	:	5095791937
Vehicle No	:	SKB 2000 X
Model Code	:	Audi A4 2.0 TFSI qu
Model / Year	:	Jul-12
Engine No	:	CDN 277395
Chassis No	:	WAUZZZ8K4DA071898
Mileage	:	
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Nov-17
Place of Accident	:	Slip RD of Queensway onto Alexandra road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 2000 X

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damages.	S/N	280.00	✓
2	To remove and transfer rear lids convenience lock system and wire harness for tail lights.	S/N	280.00	X
3	To dismantle and renew rear bumper and rear lid. Align to position. Re-organise rear crash management components. Reinstall all parts removed.		1,500.00	500
4	To respray rear bumper and rear lid		1,700.00	1100
5	To carry out diagnostic check	S/N	192.00	✓
TOTAL LABOUR CHARGES		:	<u><u>3,952.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 2000 X

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Defend</i>	\$ 2,168.00	✓
2	REAR BUMPER SPOILER <i>Defend</i>	\$ 666.00	✓
3	SPOILER TRIM <i>new</i>	\$ 210.00	+
4	REAR BUMPER SENSOR ?	TBC	?
5	REAR BUMPER CARRIER ?	\$ 541.00	?
6	REAR LID <i>Ryis</i>	\$ 2,351.00	+
7	PACKING ADHESIVE <i>new</i>	\$ 14.00	✓
8	"AUDI" EMBLEM <i>3 new</i>	\$ 105.00	✓
9	"QUATTRO" EMBLEM	\$ 81.00	✓
10	"A4" EMBLEM <i>new</i>	\$ 81.00	+
11	REAR NO. PLATE <i>new</i>	S/N \$ 25.00	✓
12	SUNRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		\$ 6,542.00	
TOTAL LABOUR CHARGES		\$ 3,952.00	
GRAND TOTAL		\$ 10,494.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 23/11/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised , 04 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant