

ASSIGNMENT

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

HP:

D.O.A:

Nature of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

2/1/18 @ 4:50

OLD driving out from slip road and TP making U-turn at the junction.

RECEIVED 17 JAN 2018

RECEIVED 02 MAR 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(

Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS 7918.00

Loss of Rental (LOR):

SS 1177.00

(

10 days)

2100 + 637

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

Legal Cost

SS

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 9097.00

Global Sum SS: 9000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 9000.00

Name 1:

HUI YANG MOTOR PTE LTD

Payee 2: (Strike off)

SS

Name 2:

Payee 3: (Strike off)

SS

Name 3:

ASS. REC. BY:

REF:

A/G /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN 71334Yr Regn: 05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Wish

c.c.

1797Colour: M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading: 40265

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: 7GE206035458Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NIL / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Davran

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 18/11/17D.O.I. 21/11/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/11 File pass to CarhomeL/S - \$7400+ (Red: \$4842.89 / 40%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG17022233/Kua3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-11-2017	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 4141P	Veh. Inspected	SLN 7133M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/11/2017	Inspection Date	21/11/2017
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

18/11/2017

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA WISH 1.8A - SLN7133M

1pc front LH door
1pc front LH door moulding
2pcs front LH door hing @\$132.55
1pc front LH door inner rubber
1pc front LH door inner lock
1pc front LH door glass mootor & gear
1pc front LH door frame sticker 1
1pc front LH door frame sticker 2
1pc rear LH door
1pc rear LH door moulding
2pcs rear LH door hinge @\$132.25
1pc rear LH door inner lock
1pc rear LH door inner rubber
1pc rear LH door frame sticker
1pc rear LH door glass mootor & gear
1pc rear LH door pillar
1pc rear LH door pillar inner panel
1pc LH side skirt
1pc LH side rocket panel
1pc rear LH fender
1pc rear LH fender petrol door
1pc rear bumper
1pc rear bumper LH side garnish
1pc rear bumper LH retainer 1
1pc rear bumper LH retainer 2

less 25% 2017

wiring
alignment
towing
tuffkote
spray painting
labour charges
Total

Not Authorised
C/L Rep & ?
Assembly After Painting
10 days

R ₁	\$ 1,218.25	✓
R ₂	\$ 181.45	✓
R	\$ 265.10	✓
SUL	\$ 371.45	✓
DD	\$ 561.60	✓
Dis	\$ 581.90	✓
R ₁	\$ 123.05	✓
R ₂	\$ 141.45	✓
R ₁	\$ 1,218.45	✓
R ₂	\$ 181.45	✓
Dis	\$ 264.50	✓
R	\$ 581.90	✓
SUL	\$ 371.45	✓
R ₁	\$ 172.50	✓
SM	\$ 581.90	✓
R ₁	\$ 631.35	✓
R	\$ 681.90	✓
Rollwrap	\$ 781.90	✓
R	\$ 631.35	✓
R ₁	\$ 972.50	✓
R ₂	\$ 358.25	✓
Any car	\$ 518.75	✓
S ₁	\$ 158.25	✓
C ₁	\$ 121.10	✓
C ₂	\$ 132.10	✓

\$ 11,803.85

\$ 2,950.96

\$ 8,852.89

\$ 120.00 301

\$ 60.00 ✓

\$ 60.00 301

\$ 150.00 1201

\$ 1,600.00 1201

\$ 1,400.00 1201

\$ 12,242.89

LKK Auto Consultants hereby notify the Reparer of the following:

- To resurvey damaged parts and estimate balance c/f
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer



輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) Fax: 64514658

Reg No. 201629438M

18/11/2017

Owner: SKYWAY MOTOR PTE LTD

Not Authored
L/Eng A 74001
10 days

ESTIMATE TO REPAIR TOYOTA WISH 1.8A - SLN7133M

1pc	front LH door	By S	1,218.25	✓
1pc	front LH door moulding	Ln S	181.45	X
2pcs	front LH door hinge @ \$132.55	R S	265.10	X
1pc	front LH door inner rubber	Ln S	371.45	X
1pc	front LH door inner lock	Del S	561.60	✓
1pc	front LH door glass motor & gear	Del S	581.90	✓
1pc	front LH door frame sticker 1	Ln S	123.05	✓
1pc	front LH door frame sticker 2	Ln S	141.45	✓
1pc	rear LH door	By S	1,218.45	✓
1pc	rear LH door moulding	Ln S	181.45	✓
2pcs	rear LH door hinge @ \$132.25	Del S	264.50	✓
1pc	rear LH door inner lock	R S	581.90	X
1pc	rear LH door inner rubber	Ln S	371.45	X
1pc	rear LH door frame sticker	Ln S	172.50	✓
1pc	rear LH door glass motor & gear	Ln S	581.90	✓
1pc	rear LH door pillar	R S	631.35	✓
1pc	rear LH door pillar inner panel	R S	681.90	X
1pc	LH side skirt	Del/waf S	781.90	✓
1pc	LH side rocket panel	R S	631.35	X
1pc	rear LH fender	R S	972.50	✓
1pc	rear LH fender petrol door	R S	358.25	X
1pc	rear bumper	my car S	518.75	✓
1pc	rear bumper LH side garnish	Ln S	158.25	X
1pc	rear bumper LH retainer 1	CRS S	121.10	✓
1pc	rear bumper LH retainer 2	CRS S	132.10	✓
less 25%			\$ 11,803.85	
			\$ 2,950.96	
balance c/t			\$ 8,852.89	
wiring		\$	120.00	30%
alignment		\$	60.00	✓
towing		\$	60.00	50%
tuffkote		\$	150.00	120%
spray painting		\$	1,600.00	1200%
labour charges		\$	1,400.00	1200%
Total			\$ 12,242.89	

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) Fax: 64514658

Reg No. 201629438M

18/11/2017

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA WISH 1.8A - SLN7133M

1pc front LH door
1pc front LH door moulding
2pes front LH door hinge @ \$132.55
1pc front LH door inner rubber
1pc front LH door inner lock
1pc front LH door glass motor & gear
1pc front LH door frame sticker 1
1pc front LH door frame sticker 2
1pc rear LH door
1pc rear LH door moulding
2pes rear LH door hinge @ \$132.25
1pc rear LH door inner lock
1pc rear LH door inner rubber
1pc rear LH door frame sticker
1pc rear LH door glass motor & gear
1pc rear LH door pillar
1pc rear LH door pillar inner panel
1pc LH side skirt
1pc LH side rocket panel
1pc rear LH fender
1pc rear LH fender petrol door
1pc rear bumper
1pc rear bumper LH side garnish
1pc rear bumper LH retainer 1
1pc rear bumper LH retainer 2

Not Authorized
L/By \$ 7400
10 days

Pr	\$	1,218.25	✓
Ln	\$	181.45	X
R	\$	265.10	X
Sn	\$	371.45	X
Del	\$	561.60	✓
O.I	\$	581.90	✓
Ar	\$	123.05	✓
Ar	\$	141.45	✓
Pr	\$	1,218.45	✓
Ar	\$	181.45	✓
Dr	\$	264.50	✓
R	\$	581.90	X
Ln	\$	371.45	X
Ar	\$	172.50	✓
Tm	\$	581.90	✓
R	\$	631.35	✓
R	\$	681.90	X
Del/mop	\$	781.90	✓
R	\$	631.35	X
Pr	\$	972.50	✓
R	\$	358.25	X
my cam	\$	518.75	✓
Sn	\$	158.25	X
CRMS	\$	121.10	✓
CRAS	\$	132.10	✓

\$ 11,803.85

less 25%

\$ 2,950.96

balance c/f

\$ 8,852.89

wiring
alignment
towing
tuffkote
spray painting
labour charges
Total

\$ 120.00 *30%*
\$ 60.00 ✓
\$ 60.00 *50%*
\$ 150.00 *12%*
\$ 1,600.00 *1200%*
\$ 1,400.00 *1200%*
\$ 12,242.89

Print Received Message

This mail is associated with :

*SLN7133M (9637631054SG)

[GBG4141P]

TP

SKYWAY MOTOR PTE LTD

Nov 18 2017 12:00AM

[Hovax Engineering And Services]

Hui Yang Motor Service

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 05/02/2018 13:28 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9097.00) - SLN7133M - Claim Handler: Lee, Ming-Yao

Approved:9097.00:Hi, Understand this is a private hire vehicle. Please get rental documents from third party since they are looking for compensation of loss of rental. Do follow the reasonable benchmark and their documents. Nonetheless, you hav

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 375721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Date: 01/01/2018

AIG Asia Pacific Insurance Pte Ltd

Motor Claims Department

78 Shenton Way

#08-16 AIG Building

Singapore 079120

**RE: ACCIDENT INVOLVING SLN7133M & GBG4141P ON 18-11-2017
ALONG TAMPINES AVE 1**

SETTLEMENT OF OUR CLAIM FOR SLN7133M

Lump sum repair cost as recommended by surveyor (TP0250)	\$ 7,918.00
11 days Loss of Rental @ \$107.00 per day (10 days repair + 1 Sunday)	\$ 1,177.00
TP Insurance Enquiry	\$ 2.00
Total	<u>\$ 9,097.00</u>

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,

Marco Neo

HUI YANG MOTOR PTE LTD

DID: 64515752

Fax: 64514658

email: hui_yang_motor@hotmail.com

Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Tuesday, 2 January 2018 4:53 PM
To: hkgoh@hovax.com.sg
Subject: ACCIDENT INVOLVING GBG 4141P & SLN 7133M ON 18/11/2017



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG17022233/Kua3

02 JANUARY 2018

HOVAX ENGINEERING AND SERVICES
9002 TAMPINES STREET 93
#03-22
TAMPINES INDUSTRIAL PARK A
SINGAPORE 528836

Dear Sir/Madam,

ACCIDENT INVOLVING GBG 4141P & SLN 7133M ON 18/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com


AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, Serway Motor Pte Ltd hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all my/our correspondences with any party in connection with my/our claim arising from an accident involving my/our motor vehicle registration number SLN 7153M and other vehicles registration number GBG 4141P along Tampines Avenue 1 on 18/11/2017

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.



Signature of registered owner

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, HUI YANG MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$9,000.00 (Global Sum) for vehicle no. SLN 7133M that was damaged pursuant to the accident which occurred on 18/11/2017 (date) along SLIP ROAD TO TAMPINES AVE 1 (location) involving vehicle no/s GBG 4141P.

This is pursuant to the inspection conducted on 21/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SKYWAY MOTOR PTE LTD ("the third party claimant") of vehicle no. SLN 7133M make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLN 7133M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 02 (day) of 03 (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

HUI YANG MOTOR PTE LTD

Bill To:

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#08-16 AIG Building
Singapore 079120

TAX INVOICE

TP Claim Invoice No: TP0250
Bill Date: 01/01/2018

	Description	Amount
	Date of Accident : 18/11/2017 Owner : SKYWAY MOTOR PTE LTD Vehicle No : <u>SLN7133M</u> Make & Model : <u>TOYOTA WISH 1.8X</u>	
	<u>Lump Sum repair cost as recommended by surveyor</u>	\$ 7,400.00
	Sub-Total :	\$ 7,400.00
	Add 7% GST :	\$ 518.00
	Total Amount SGD :	\$ 7,918.00

Reg No.:201629438M

GST No:201629438M

HUI YANG MOTOR PTE LTD



Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax : 64514658

Tax Invoice

Bill To:

HUI YANG MOTOR PTE LTD

GST Reg No: 19-9904194-N

Invoice No :	CR002094
Date :	20-11-17
Page :	1

Ship To:

HUI YANG MOTOR PTE LTD
SIN MING AUTOCARE
BLK 176 SIN MING DRIVE
#04-02
SINGAPORE 575721

Attn:**Phone:****Fax:**

SalesPerson	P.O. Number	Date Shipped	Shipped Via	Terms
	RA02986			Net 30th after

Description	Amount (\$\$)
RENTAL CHARGES (11 DAYS X \$100) FROM 20/11/17 TO 01/12/17 WISH : SLN7141P RENTAL AGREEMENT : RA02986 DRIVEN BY : MARTIN JAYA BIN INDRA EDDY YOUR REF : SLN7133M	\$1,100.00

Memo:

Total	\$1,100.00
Freight	\$0.00
Add: GST	\$77.00
Total Inc GST	\$1,177.00
Less: Deposit	\$0.00
Balance Due	\$1,177.00

Authorised Signatory



HIRER'S PARTICULARS	
Owner's Vehicle No.:	SLN 7133M
Model:	Wish
Name:	INDRAN JAYA
Address:	BLK 877A LAMKINES AVE 8 # 04-41 (S21877)
Office Tel:	Residence Tel:
Occupation	Hp / Pgr No: 10045730
P.P / LC No.:	Nationality:
Date of Birth:	Place of Birth:
Dr. Licence No.	
Date of Issue:	Country of Issue:



ADDITIONAL DRIVER'S PARTICULARS	
Name:	
Address:	
Office Tel:	Residence Tel:
Occupation	Hp / Pgr No:
P.P / LC No.:	Nationality:
Date of Birth:	Place of Birth:
Dr. Licence No.	
Date of Issue:	Country of Issue:

IMPORTANT: The vehicle will not be insured after the expiry of the hire period and in case of any accident the Hirer will be liable for all consequences.

RENTAL VEHICLE PARTICULARS		
Rental Vehicle No.:	SLN 7141 P	
Model:	Wish	
Collection Out	Date & Time	Mileage Out
	24/11/17 3:105	32861
Return In	Date & Time	Mileage In
	01/12/17 17:00	41868
Petrol Level 		

RENTAL CHARGES		
Months @ \$	per month	
Weeks @ \$	per week	
1 Days @ \$ 100	per day	1100.00
Hours @ \$	per hour	

ADDITIONAL CHARGES		
PETROL TOP-UP CHARGES		
MISC		
TOTAL CHARGES (incl 7% GST)	1177	00
PAYMENT MODE		
☐ Master		
☐ VISA		
☐ Cash		
☐ Others		



Remarks: PH Detail - OK

CHECKED OUT BY	11/11/17 9005 5555	CHECKED IN BY	SULAIMAN
----------------	--------------------	---------------	----------

I have read and agree to the terms and conditions on both sides of this agreement.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-173347

Date of Request: 20/11/2017

Your Ref No: Online Purchase

Hui Yang Motor Pte Ltd
176 Sin Ming Drive #04-02
Sin Ming AutoCare
Singapore 575721

Dear Sir/Madam,

Enquiry Date 20/11/2017
Enquiry By Bel Chew Shu Jing
TP Vehicle No. GBG4141P
Accident Date 18/11/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Nov 2017 Edit Reg		21 Nov 2017 00:00 Edit Adj Rpt	\$47,400.00 Edit Estimates	\$47,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Hovax Engineering And Services, Co. Reg. No.: 52837079X		
Main Claimant:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Vehicle Reg. No.:	SLN7133M	Date of Loss:	18/11/2017 00:00 - :59
Claim Type:	TP / 9637631054SG	Policy/Cover Note No.:	1700037956
Vehicle Reg. No. (Insured):	GBG4141P	Policy No. (Claimant):	A28795104MCX
	Excess:		
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/11/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (05/02/2018): Alert - Adj Mandate Approved (\$9097.00) - SLN7133M - Claim Handler: Lee, Ming-Y...
- AIG_SG (22/11/2017): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN7133M (9637631054SG)
[GBG4141P]
TP
SKYWAY MOTOR PTE LTD
Nov 18 2017 12:00AM
[Hovax Engineering And Services]
Hui Yang Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	13/12/17 10:57	Video - Accident From: OO - Reg. No: GBG4141P, Claimant: HOVAX ENGINEERING AND SERVICES													Load MP4			
2	13/12/17 10:57	Video - Accident From: OO - Reg. No: GBG4141P, Claimant: HOVAX ENGINEERING AND SERVICES													Load MP4			
3	02/01/18 12:09	OI - Video - Accident From: OO - Reg. No: GBG4141P, Claimant: HOVAX ENGINEERING AND SERVICES													Load MP4			
Letters/Correspondences															1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown													Edit			
Assessment Reports															1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	22/11/17 09:20	Accident Statement From: SC - Reg. No: GBG4141P, Claimant: HOVAX ENGINEERING AND SERVICES													Load HTM			
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	01/02/18 17:43	General View													Load JPG	☒		
2	01/02/18 17:43	General View													Load JPG	☒		
3	01/02/18 17:43	General View													Load JPG	☒		
4	01/02/18 17:43	General View													Load JPG	☒		
5	01/02/18 17:43	General View													Load JPG	☒		
6	01/02/18 17:43	General View													Load JPG	☒		
7	01/02/18 17:43	General View													Load JPG	☒		
8	01/02/18 17:43	General View													Load JPG	☒		
9	01/02/18 17:43	General View													Load JPG	☒		
10	01/02/18 17:43	General View													Load JPG	☒		
11	01/02/18 17:43	General View													Load JPG	☒		
12	01/02/18 17:43	General View													Load JPG	☒		
13	01/02/18 17:43	General View													Load JPG	☒		
14	01/02/18 17:43	General View													Load JPG	☒		
15	01/02/18 17:43	General View													Load JPG	☒		
16	01/02/18 17:43	Chassis Number													Load JPG	☒		
17	01/02/18 17:43	General View													Load JPG	☒		
18	01/02/18 17:43	General View													Load JPG	☒		
19	01/02/18 17:43	General View													Load JPG	☒		
20	01/02/18 17:43	General View													Load JPG	☒		
21	01/02/18 17:43	General View													Load JPG	☒		

22	01/02/18 17:43	Odometer Reading	1	Load JPG	☒
23	01/02/18 17:45	Reinspection Photo	1	Load JPG	☒
24	01/02/18 17:45	Reinspection Photo	1	Load JPG	☒
25	01/02/18 17:45	Reinspection Photo	1	Load JPG	☒
Documentation					
			1 per page	☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/11/17 20:06	ACKNOWLEDGEMENT EMAIL TO AIG DD 21.11.2017	1	Load PDF	
2	21/11/17 20:06	NOTIFICATION FROM WORKSHOP + TP ESTIMATE	1	Load PDF	
3	21/11/17 20:06	EMAIL FROM AIG DD 21.11.2017	1	Load PDF	
4	24/11/17 15:41	TP ESTIMATE - MARKED	1	Load PDF	
5	24/11/17 15:41	TP GIA REPORT	1	Load PDF	
6	22/01/18 12:33	RENTAL RECEIPT	1	Load PDF	
7	22/01/18 12:33	GIA SEARCH	1	Load PDF	
8	05/03/18 14:38	WORKSHOP INVOICE	1	Load PDF	
9	05/03/18 14:38	AUTHORISATION TO ACT FORM	1	Load PDF	
10	05/03/18 14:38	Release Voucher	1	Load PDF	
11	05/03/18 14:38	LETTER TO OI	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBG4141P (Insd veh)	Model:	TOYOTA WISH 1.8 X (A)
	SLN7133M (TP veh)		
Date of Accident:	18/11/2017		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	13,099.89
Final Repair Cost	:	\$	9,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	11 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	9,000.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____100____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No:	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hui Yang Motor Pte Ltd	:	\$ 9,000.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

05 Mar
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17022233/KUA3Q2

Date: 05/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700037956
 Claimant Vehicle No: SLN7133M Insured Vehicle No: GBG4141P
 Date of Loss: 18/11/2017 Nature of Claim: TP Claim No: 9637631054SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN7133M
 Make & Model: TOYOTA WISH, 1.8 X (A) Engine No: 2ZR1837203
 Reg. Date: 15/05/2017 (Man. Year: 2016) Chassis No: ZGE206035458
 Colour: Metallic Silver Odometer: 40265 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Davanti 9 mm Rear Left Side: Davanti 9 mm
 Front Right Side: Davanti 9 mm Rear Right Side: Davanti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,852.89	6,562.20	2,290.69	25.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	2,660.00	730.00	21.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,242.89	9,222.20	3,020.69	24.67
Approved Total (Overridden) (S\$)		7,400.00		
(S\$)	12,242.89	7,400.00	4,842.89	39.56
+ GST 7.00/7.00% (S\$)	857.00	518.00	339.00	39.56
Nett Amount (S\$)	13,099.89	7,918.00	5,181.89	39.56
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,097.00		
Global Sum Settlement (S\$)		9,000.00		

INSPECTION

Date of Assignment: 21/11/2017
 Date Inspected: 21/11/2017 Inspected At:

HUI YANG MOTOR PTE LTD
BLOCK 176 SIN MING DRIVE #04-02 SIN
MING AUTOCARE
SINGAPORE 575721

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent	1,218.25 FL	*1,218.25 FL
2	1		*FRONT LH DOOR MOULDING	Serviceable	181.45 FL	*- FL
3	2		*FRONT LH DOOR HING	Repair	265.10 FL	*- FL
4	1		*FRONT LH DOOR INNER RUBBER	Serviceable	371.45 FL	*- FL
5	1		*FRONT LH DOOR INNER LOCK	Dented	561.60 FL	*561.60 FL
6	1		*FRONT LH DOOR GLASS MOTOR & GEAR	Distorted	581.90 FL	*581.90 FL
7	1		*FRONT LH DOOR FRAME STICKER 1	Necessary	123.05 FL	*123.05 FL
8	1		*FRONT LH DOOR FRAME STICKER 2	Necessary	141.45 FL	*141.45 FL
9	1		*REAR LH DOOR	Bent	1,218.45 FL	*1,218.45 FL
10	1		*REAR LH DOOR MOULDING	Buckled	181.45 FL	*181.45 FL
11	2		*REAR LH DOOR HINGE	Distorted	264.50 FL	*264.50 FL
12	1		*REAR LH DOOR INNER LOCK	Repair	581.90 FL	*- FL
13	1		*REAR LH DOOR INNER RUBBER	Serviceable	371.45 FL	*- FL
14	1		*REAR LH DOOR FRAME STICKER	Necessary	172.50 FL	*172.50 FL
15	1		*REAR LH DOOR GLASS MOTOR & GEAR	Jammed	581.90 FL	*581.90 FL
16	1		*REAR LH DOOR PILLAR	Bent	631.35 FL	*631.35 FL
17	1		*REAR LH DOOR PILLAR INNER PANEL	Repair	681.90 FL	*- FL
18	1		*LH SIDE SKIRT	Dented / Warped	781.90 FL	*781.90 FL
19	1		*LH SIDE ROCKER PANEL	Repair	631.35 FL	*- FL
20	1		*REAR LH FENDER	Bent	972.50 FL	*972.50 FL
21	1		*REAR LH FENDER PETROL DOOR	Repair	358.25 FL	*- FL
22	1		*REAR BUMPER	Mtg Cracked	518.75 FL	*518.75 FL
23	1		*REAR BUMPER LH SIDE GARNISH	Serviceable	158.25 FL	*- FL
24	1		*REAR BUMPER LH RETAINER 1	Cracked	121.10 FL	*121.10 FL
25	1		*REAR BUMPER LH RETAINER 2	Cracked	132.10 FL	*132.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	11,803.85	8,202.75
- List Item Discount on L Items 25.00/20.00% (S\$)	2,950.96	1,640.55

Total Parts (S\$)	8,852.89	6,562.20
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRING	New	120.00	30.00
2	ALIGNMENT	New	60.00	60.00
3	TOWING	New	60.00	50.00
4	TUFFKOTE	New	150.00	120.00
5	SPRAY PAINTING	New	1,600.00	1,200.00
6	LABOUR CHARGES	New	1,400.00	1,200.00
Gross Labour Cost (S\$)			3,390.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >