

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1148/2017/JT 30-Nov-17 CHANG 1 SLF 672 L Audi A1 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system. (S/N)	\$ 1,000.00	\$ 1,000.00 ✓
2	To renew front lock carrier and align to position. Repair LHS A-pillar.	\$ 2,700.00	\$ 1,750.00 ✓
3	To respray LHS A-pillar.	\$ 800.00	\$ 500.00 ✓ <u>\$ 3,250.00</u>
<u>Parts</u>			
1	FRONT WHEEL HOUSING LINER - LH <i>Cracked.</i>	\$ 146.00	\$ 116.80 ✓
2	WHEEL HOUSING LINER ATTACHEMENT PARTS <i>me</i>	\$ 33.00	\$ 26.32 ✓
3	FRONT LOCK CARRIER <i>Cracked</i>	\$ 886.00	\$ 708.40 ✓
4	COOLANT <i>me</i>	\$ 132.00	\$ 105.28 ✓
GRAND TOTAL		: \$ 5,697.00	\$ 4,206.80

For Premium Automobiles Pte Ltd

Authorised Signature