

Not Authorized
1/15/2017

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB7764C - CANDY
KL1LA69RJB107638
CHEVROLET
EPICA 2.0
20.11.2017
AIG

PART		LIST	
1	1	Rear Bumper	\$ <i>Bu/nd</i> 1,202.00 ✓
2	1	Rear Bumper Beam	\$ <i>R</i> 239.94 X
3	1	Rear Bumper Centre Absorber	\$ <i>Sn</i> 260.00 X
4	1	Rear Bumper Side Retainer RH	\$ <i>Sn</i> 68.76 X
5	1	Rear Bumper Side Retainer LH	\$ <i>Dis</i> 68.76 ✓
6	1	Rear Bumper Reflectors LH	\$ <i>CM</i> 119.74 ✓
7	1	Rear Bumper Tow Hook Cover	\$ <i>Sn</i> 93.00
8	1	Rear End Panel Outer	\$ <i>R</i> 623.76
9	1	Rear End Panel Inner Trim	\$ <i>Sn</i> 263.84
10	1	Bootlid	\$ <i>R</i> 973.00
11	1	Bootlid inner trim board	\$ <i>Sn</i> 400.00
12	1	Bootlid Weatherstrip	\$ <i>Sn</i> 344.28
13	1	Bootlid Lock - Top	\$ <i>R</i> 466.56 X
14	1	Bootlid 'CHEVROLET' Badge	\$ <i>na</i> 120.62
15	1	Bootlid Logo	\$ <i>na</i> 138.84
16	1	Bootlid 'EPICA LT' Badge	\$ <i>na</i> 119.84
17	1	Bootlid Reflector Centre	\$ <i>Sn</i> 217.97
18	1	Bootlid Reflector RH	\$ <i>Sn</i> 128.40
19	1	Bootlid Reflector LH	\$ <i>Sn</i> 128.40
20	1	Rear Tail Lamp LH	\$ <i>Sn</i> 479.30
21	1	Rear Tail Lamp Panel LH	\$ <i>R</i> 359.00
22	1	Rear Fender LH	\$ <i>R</i> 1,145.00
23	1	Rear Fender Inner Trim LH	\$ <i>Sn</i> 418.44

TOTAL	\$	8,379.45
10%	\$	837.95
	\$	7,541.51

Special Nett

1 1Set Licence Plate With Holder \$ *Sn* 60.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-228**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7764C - AIG

2	1Set Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 <i>X</i>
3	1Set Rear Bumper Parking Sensor	\$	<i>Pol/Shot</i> 300.00 <i>✓</i>
4	1Set Rear Bumper Fastener Clip	\$	<i>nn</i> 44.00 <i>✓</i>
5	1Set Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00
6	1Set Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00
7	1 Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00
8	1 Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 30.00
9	2 Rear Windscreen Sealant	\$	<i>nn</i> 80.00
10	1 Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00
11	1 Spare Tyre	\$	<i>sn</i> 180.00
12	1 Spare Wheel Rim	\$	<i>sn</i> 126.74

TOTAL	\$	1,050.74
TOTAL PARTS	\$	8,592.25

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,700.00 *2001*

To Check Electrical Lighting Concerned.

\$ 170.00 *101*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 *X*

Putty And Spray Painting Of The Affected
Portion.

\$ 2,800.00 *2001*

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

To transfer of end panel fittings and conduct
water seepage test.

\$ *nn* 170.00 *X*

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ *nn* 170.00 *X*

To transfer of boot fittings and conduct water
seepage test.

\$ *nn* 170.00 *X*

Towing fees

\$ *nn* 120.00 *X*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-228**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7764C - AIG

To transfer of Fender fittings, attachments and
perform water seepage test.

\$ *nn* 170.00 X

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To check steering geometry and computer
wheel alignment

\$ *nn* 220.00 X

	\$	7,410.00
TOTAL	\$	16,002.25

Repair Days**10 Days***1 1/2 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: