

SI REC BY: REF: 03/CTU7022248/Grb52 Special Instructions:

ASSIGNMENT (Office)
From (Person): Jowyn Tay of CTL Date/Time: 22.11.2017 11:48am

Estimated Cost: Bill to:

OD/TP/W3/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JSh 6387 Insured: GBE 6930B

at Workshop m/s Our Bro's Tel: 6636 1338

of 10 Kaki Bukit Rd 2 #03-37 90217013

Policy No: DMCVSN1711421700 Claim No: 91M17D06665C02

Sum Insured: Excess:

Make of Veh: D.O.A. 16.11.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp 23.11.2017 @ morning

Date/Time: 22.11.2017 130pm Person Contacted: Syarifah Vehicle: D/L OUT FTM

Date/Time	Action/Instruction (✓) Estimate
-----------	---------------------------------

	JSh 6387 - x
--	--------------

	GBE 6930B - NA /CTU7022248/Y3 Out 16.11.17
--	--

22/11/18	submit LIS \$2050. @ 3 days (Red. \$5920, 81%.)
----------	---

	Finalise amount unconfirm, already offer w/s. w/s not agree
--	---

PRS

Xlec.

REF. CTR

mermen

ASSIGNMENT

Report No. _____ Date **23-11-2017**

Estimated Cost: _____

QD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. **JS61 6387**

at Workshop/mis **Our BM's**

of **10 Kaki Bukit Rd 2 #03-37**

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Veh. _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value: **\$6000**

IDAO Accident Report: Consistent? : Yes or No

GIA / PR: Beant: Consistent? : Yes or No

Est. Repairs: **3** days Res.: Yes or No

Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Vehicle No. **JS61 6387** Vr Reg: **14 Aug 2017**

Type: M/Car / M/Lyde / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make **KTM 200 RC** cc: **199**

Colour **Black** A/C: Insured / Std / NI / NA

Sp. Reading **5948** T. Radio: Insured / Std / NI / NA

Eng No: _____

C No: **PN6JYC40XFK027301**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In ☒ Good / Jammed / Leaked / Burnt or

Brake: In ☒ Good / Jammed / Leaked / Burnt or

Mod: ☒ S/Rim / STD A/Rim or

Tyre Size: F: **110/70 R17**

R: **150/60 R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **MRF**

Front: _____ Rear: _____

R. Bal: **5** mm R. Bal: **5** mm

L. Bal: _____ mm L. Bal: _____ mm

D.O.A. _____ D.O.I. **23-11-17**

Survey held at **w/s** **5:30 pm**

Des. of Damages ☒ Front ☒ Rear ☒ N/S / U/C / Rooftop or

ant.

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

\$2050. **weeramani4029@yahoo.com.sg**

RECEIVED 22 NOV 2018

20/11/2018

Date/Time File Pass to: _____

fupist ☐ : Prel. Report

☒ : Final Report

Date/Time File Return to: _____

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Survey Fee: **200**

Transport: _____

Add Fee: ☐ Site Insp: \$ _____

☐ Interview: \$ _____

☐ Tech. Insp: \$ _____

☐ Witnessing: \$ _____

Report Format: **TP**

Lump Sum: **2050.00**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17022248/rb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 22-11-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 6930B	Veh. Inspected	JSG 6387	
Policy No.	DMCVSN1711421700	Coverage (\$)	0.00	
Claim No.	SNM17D06665C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	22/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/11/2017	Inspection Date	23/11/2017	
Survey held at	OUR BRO'S WORKSHOP 10 KAKIT BUKIT ROAD 2 #03-38 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2017		22 Nov 2017 11:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIGNAGE WORKSHOP PTE LTD		
Main Claimant:	PUVANESWARAN PILLAI ARUTSELVAN,	ID:	G2838903K
Vehicle Reg. No.:	JSG6387	Date of Loss:	16/11/2017 09:00 - :59
Claim Type:	TP / SNM17D06665C02	Policy/Cover Note No.:	DMCVSN1711421700 (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
Vehicle Reg. No. (Insured):	GBE6930B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Our Bro's Workshop (s) Pte Ltd (HQ) 10 Kaki Bukit Road 2, #03-37/38 First East Centre, 417868 Kaki Bukit - Tel: 66361338		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/12/2017]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS AND LET US HAVE YOUR RECOMMENDATION ON COST OF REPAIRS.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



**SINGAPORE
POLICE FORCE**



T/20171116/2085

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

1 of 4

Report No: T/20171116/2085

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/11/2017 14:46	Vide Report No.:	Station Diary No.: 34
--	------------------	--------------------------

Informant's Particulars

Name of Informant: PUVANESWARAN PILLAI ARUTSELVAN			Address: C/O APT BLK A-10-11 JALAN SETIA, TAMAN SETIA TROIKA SKY GARDEN RESIDENCE, 81200 JOHOR BAHRU, JOHOR SINGAPORE		
ID Type / ID No.: FIN NO / G2838903K			Contact No.: Home/Office: Mobile: 0164976236		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 24	Date of Birth: 18/02/1993	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation: MECHANIC			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 16/11/2017 09:30	Type of Location: Straight Road
Location: Along Road 1 UBI ROAD 1				
ALONG UBI ROAD 1, INFRONT OF BLK 3006 Ubi Road 1.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE6930B	Lorry	NISSAN	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5	Silver	Slightly Damaged	1
JSG6387	Motorcycle	KTM	KTM RC 200	Black	Seriously Damaged	1



Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TEO MIN HUI	ID No.	G2989535Q
Related Vehicle	GBE6930B (Lorry)	Contact No.	96209237
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Rider			
Name	PUVANESWARAN PILLAI ARUTSELVAN	ID No.	G2838903K
Related Vehicle	JSG6387 (Motorcycle)	Contact No.	0164976236
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious

Brief Details.

On 16th November 2017 at about 9:30am, I was riding my motorcycle (KTM 200, JSG6387) along Ubi Avenue 3. At the traffic junction of Ubi Avenue 3 and Ubi Road 1, I made a left turn and continued my journey along Ubi Road 1 towards Ubi Avenue 2.

Suddenly, in front of Blk 3006 Ubi Road 1, a lorry (GBE6930B) came out of the carpark and turned right along Ubi Road 1 towards Ubi Avenue 3.

I made an emergency brake but I am unable to brake in time. As such, my motorcycle collided with the lorry. Upon collision, my motorcycle and I fell on my right. I then immediately stood up and began pushing my motorcycle to the side of the road before taking a rest.

The lorry stopped at the other lane towards Ubi Avenue 3 and the driver namely Teo Min Hui (G2989535Q, Hp: 96209237) alighted to assist me. We then exchanged particulars and took photos of the accident. My motorcycle sustained serious damages on the front right, while the lorry sustained only minor damages on its front right side.

I felt pain on my right hand, left leg and head immediately after the accident. I was in a state of shock as such, I did not call the police or the ambulance as I immediately called my boss once I rested on the side of the road.



**SINGAPORE
POLICE FORCE**



T/20171116/2085

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 4

Report No. T/20171116/2085

CONTINUATION OF REPORT

My motorcycle tow truck came a while later and brought my motorcycle to the workshop. I rode along in the tow truck towards the workshop too.

I am going to see the doctor after lodging this report.

That is all.



**SINGAPORE
POLICE FORCE**



T/20171116/2085

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

4 of 4

Report No. T/20171116/2085

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 2 NUR 'ASRI BIN AGUS

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SI ANG YI TING, STEPHANIE
Contact No.: 65476414

Authentication Stamp
NP168

Singapore Police Force

Signature Of Informant:

Date/Time:
16/11/2017 14:46

Classification Of Case:



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

E6RD1HCQ

No. Pendaftaran	: JS66387
No. IP	: 930216025237
Nama Pemilik Berdaftar	: PUVANESWARAN PILLAI A/L ARUTSELVAN
Alamat	: A-10-11 SKY GARDEN RESIDENCE JALAN SETIA TAMAN SETIA TROPIC A 81200 JOHOR BAHRU JOHOR
No. Chassis/No. Enjin	: PNGJYC40XFK027301 / 5-90617949
Buatan/Nama Model	: KTM / RC 200 (S) STD
Keupayaan Enjin	: 199
Bahan Bakar	: PETROL
Status Asal	: PEMASANGAN TEMPATAN
Kelas Kegunaan	: MOTOSIKAL
Jenis Badan/Tahun Dibuat	: MOTOSIKAL / 2017
Tarikh Pendaftaran	: 14/08/2017
B.D.M/B.G.K/BTM	: -
Syarat Pendaftaran 1	: -
Syarat Pendaftaran 2	: -
Syarat Pendaftaran 3	: -



Zurich Insurance Malaysia Berhad (8029-A)
 11th Floor, Menara Zurich, No. 12, Jalan Dewan Bahasa, 50460 Kuala Lumpur, Malaysia
 Tel: 03-2146 8000 Fax: 03-2142 5853 Call Centre: 1-300-888-622

CONFIRMATION OF PURCHASE OF INSURANCE

E-C/Note No : D13923-17000757
 Issue Date & Time : 12 AUG 2017 12:36:38pm
 Period of Cover : From 14 AUG 2017 To 13 AUG 2018
 Vehicle Registration No. : JSG6387
 Make of Vehicle : KTM RC 200 (S) STD
 Engine No. : 5-90617949 Chassis No. : PNGJYC40XFK027301
 Capacity : 199.00 CC Year of Make : 2017
 Insured Name : PUVANESWARAN PILLAI A/L ARUTSELVAN
 Address : A-10-AA SKY GARDEN RESIDENCE JALAN SETIA TAMAN SETIA
 TROPIKA, 81200, TAMPOI, JOHOR DARUL TAKZIM
 NRIC/Business Reg No. : 930218-02-5237
 Type of Cover : V-CO MOTOR COMPREHENSIVE
 Use of Vehicle : MOTORCYCLE FOR PRIVATE USE
 HP Owner : AEON CREDIT SERVICE (M) BHD
 Sum Insured (RM) : 18,000.00
 Transaction Type : New

Sum Insured	(RM)	18,000.00	Premium	(RM)	427.40
Loading %		0.00 %	Loading Amount	(RM)	0.00
All Rider (Y/N)		Y	All Rider Amt	(RM)	213.70
NCD %		0.000000 %	NCD Amt	(RM)	0.00
			Basic Net	(RM)	641.10
Tuition Load %		0 %	Tuition Load Amt	(RM)	0.00
			Extra Coverage	(RM)	0.00
GST		6.00 %	GST	(RM)	38.47
			Stamp Duty	(RM)	10.00
			Cycle PAC	(RM)	13.78
Act Premium	(RM)	69.90	Payable Premium	(RM)	703.35

<u>Extra Benefits</u>	<u>Extra Sumin (RM)</u>	<u>Extra Premium (RM)</u>
ALL RIDERS	0.00	0.00
Cycle PAC (including premium for extra coverage whenever is applicable, GST and stamp duty)	5,500.00	13.78

Named Drivers
 ALL RIDERS

Agent : D13923-000 DOUGLAS HONG TECK CHEN
 Tel No : 07-3534236

THIS IS A COMPUTER GENERATED FORM, SIGNATURE IS NOT REQUIRED.

**ZURICH****Zurich Insurance Malaysia Berhad** (8029-A)11th Floor, Menara Zurich, No. 12, Jalan Dewan Bahasa, 50460 Kuala Lumpur, Malaysia
Tel: 03-2146 8000 Fax: 03-2142 5863 Call Centre: 1-300-888-622**MOTORCYCLE
MOTORSIKAL****THE SCHEDULE**

ORIGINAL COPY

JADUAL

SALINAN ASAL

Agent Code (Kod Ejen)	D13923-000 (JOHOR BHARU) DOUGLAS HONG TECK CHEN		Date (Tarikh)	12 AUG 2017		
Replacing Cover Note No. (Mengantikan Note Undang No.)	D13923-17000757		Receipt No. (No. Resit)			
Policy No. (No. Polisi)	501700115455-00		ACT (ACT)	RM	69.90	
The Policyholder (Yang Dinsuranskan)	PUVANESWARAN PILLAI A/L ARUTSELVAN		Basic Premium	RM	427.40	
Address (Alamat)	A-10-AA SKY GARDEN RESIDENCE JALAN SETIA TAMAN SETIA TROPIKA, 81200 TAMPOI, JOHOR DARUL TAKZIM		Loading: 0.00%	RM	0.00	
Business Reg. No. (No. Sykt.)			All Riders	RM	213.70	
I/C No. New (No. K/P Baru)	930218-02-5237	Old I/C No. (No. K/P Lama)	NCD: 0.00%	RM	0.00	
Business / Profession (Perniagaan / Pekerjaan)	OTHERS		Extra Cover	RM	0.00	
Hire Purchase Owners (Pemilik Sewa Beli)	AEON CREDIT SERVICE (M) BHD		Gross Premium	RM	641.10	
Employer / Lessors (Majikan / Pemajak)			GST: 6.00%	RM	38.47	
Period of Insurance (Tempoh Insurans)	(a) From (Dari) : 14 AUG 2017 To (Hingga) : 13 AUG 2018 Time : 12:01AM To Midnight (Termasuk kedua-dua tarikh) (b) Any subsequent period for which you shall pay and we shall agree to accept a renewal premium Sebarang tempoh selanjutnya untuk mana anda membayar dan kami bersetuju menerima premium pembaharuan		Stamp Duty (DUTI SETEM)	RM	10.00	
The Motor Vehicle (Kenderaan Motor)	Any of the following (Mana-mana daripada yang berikut):		Total Premium (JUMLAH)	RM	689.57	
Registration No. (No. Pendaftaran)	Make (Buatan & Jenis Badan)	Type of Body (Jenis Badan)	Cubic Capacity (Keupayaan Enjin)	Year of Manufacture (Tahun Diperbuat)	Seating Capacity Including Driver (Muatan Tempat Duduk termasuk Pemandu)	Your Estimate of Value Including Accessories (Nilai Anggaran Anda termasuk Aksesori)
JSG6387	KTM RC 200	MOTORCYCLE	199.00 CC	2017	2	RM18,000.00
Date of Signature of Proposal and Declaration (Tarikh Cadangan dan Perakuan Ditandatangani)			EXCESS : All Claims : RM 150.00 (LEBIHAN)	Engine (Enjin) : 5-90617949 CHASSIS (Casis) : PNGJYC40XFK027301		
Subject to the terms and conditions of the Policy and endorsement as numbered below : Tertakluk kepada peraturan-peraturan dan syarat-syarat Polisi dan pengendornan seperti disenaraikan di bawah :						
Named Driver : 1) ALL RIDERS Include Endorsement No. 03,15,94,107,FINANCIALSERVICESACT2013						
Additional Extra Coverage/Endorsements :- Code Description 03 ALL RIDERS			Value 0.00	Premium 213.70		

LEGISLATION:-

Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore Motor Vehicles (Third Party Risks and Compensation) Rules (Republic of Singapore) Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam (the reference to legislation under the heading "Avoidance of Certain Terms and Right of Recovery" is limited to Section 94, 95 and 96 of the Road Transport Act 1987 (Malaysia) Section 7, 8 and 9 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

UNDANG-UNDANG:-

Akta Pengangkutan Jalan Raya, 1987 Malaysia, Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, Peraturan Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) 1980 Republik Singapura, Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam (rujukan kepada undang-undang di bawah tajuk "Pengelakan Peraturan - Peraturan Dan Hak Tuntutan Tertentu" adalah terhad kepada Seksyen 94, 95 dan 96 Akta Pengangkutan Jalan Raya, 1987 Malaysia, Seksyen 7, 8 dan 9 Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, dan Seksyen 7 Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam).

**Limits of Liability:-
Had Tanggungan:**

Limit of the amount of the Company's Liability under Section 1-3	RM50.00
Had jumlah tanggungan Syarikat di bawah Seksyen 1-3	
Limit of the amount of the Company's Liability under Section 11-1(a)	Unlimited
Had jumlah tanggungan Syarikat di bawah Seksyen 11-1(a)	
Limit of the amount of the Company's Liability under Section 11-1(b)	RM3,000,000.00
Had jumlah tanggungan Syarikat di bawah Seksyen 11-1(b)	

**Limitation as to Use
Had Penggunaan**As shown in the Certificate of Insurance
Seperti ditunjukkan dalam Sijil Insurans**Geographical Area
Had Wilayah**Malaysia, Republic of Singapore and Negara Brunei Darussalam
Malaysia, Republik Singapura dan Negara Brunei Darussalam**Authorised Driver
Pemandu Yang Dibenarkan**As shown in the Certificate of Insurance
Seperti ditunjukkan dalam Sijil InsuransFor and on behalf of / Untuk dan bagi pihak
Zurich Insurance Malaysia BerhadDavid Fike
President, General Insurance.



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/4866/6387/TP/11.17

Invoice No. : 4866

Date : 24 January 2018

To: Puvaneswaran Pillai Arutselvan
c/o 10 Kaki Bukit Road 2
#03-37/38
First East Centre
Singapore 417868

INVOICE	
PARTICULARS	AMOUNT
Vehicle No. : JSG 6387 Make/Model : KTM RC200	
☒ Inspection of Vehicle	)
☒ Appraisal Report	)
☒ 29 Colored Photographs	) SGD 574.00
☒ Transport charges	)
☒ Re-inspection fee	)
☐ Disbursements	)
☐ Others (Specify)	)
Total	SGD 574.00

Dollars: **Five Hundred and Seventy-Four Only**

(Cheque should be crossed and make payable to "Kelvin Automotive Appraising Services")


Kelvin Automotive Appraising Services



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference
Vehicle Number



KAAS/TA/4866/6387/TP/11.17
JSG 6387

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
LIST ITEMS:-					
1	1 pair	Front fork assy -	Buckled	\$ 1,400.00	\$ 1,400.00
2	1 pc	Front brake disc	Distorted	\$ 325.00	\$ 325.00
3	1 pc	Front under bracket	Buckled	\$ 395.00	\$ 395.00
4	1 pc	Front upper clamp	Buckled	\$ 315.00	\$ 315.00
5	1 pc	Front windshield	Broken	\$ 255.00	\$ 255.00
6	1 pc	Headlamp assy	Broken	\$ 900.00	\$ 900.00
7	1 pc	Head fairing	Broken	\$ 650.00	\$ 650.00
8	1 pc	Instrumental panel	Not Working	\$ 565.00	\$ 565.00
9	1 pair	Handlebar	Buckled	\$ 78.00	\$ 78.00
10	1 pair	Handlebar grip	Damaged	\$ 56.00	\$ 56.00
11	1 pair	Handlebar balancer	Damaged	\$ 40.00	\$ 40.00
12	1 pc	LH clutch control lever	Buckled	\$ 37.00	\$ 37.00
13	1 pc	RH brake control lever	Buckled	\$ 39.00	\$ 39.00
14	1 pair	Wing mirror w/ arm	Broken	\$ 320.00	\$ 320.00
15	1 pc	Front fender	Deformed	\$ 210.00	\$ 210.00
16	2 pcs	Front (side) fairing @S\$450.00	Cracked	\$ 900.00	\$ 900.00
17	1 pair	Front (under) fairing @S\$220.00	Broken	\$ 440.00	\$ 440.00
18	1 set	Rear fairing	Damaged	\$ 450.00	Repair
19	1 pair	Pillion rider foot rest	Broken	\$ 80.00	\$ 80.00
20	1 pair	Pillion rider foot rest support bracket	Buckled	\$ 270.00	\$ 270.00
Less 10%				\$ 7,725.00	\$ 7,725.00
SPECIAL NETT ITEMS:-				\$ 7,725.00	\$ 6,547.50
21	1 pc	Front wheel rim	Distorted	\$ 650.00	\$ 650.00
22	1 pc	Front tyre @-50% depreciation	Scratched	\$ 360.00	\$ 180.00
23	1 set	Decorative stickers	Necessary	\$ 350.00	\$ 350.00
24	1 pc	Front no. plate sticker	Necessary	\$ 35.00	\$ 20.00
2606.28 20% : 2050				\$ 1,395.00	\$ 1,200.00
Sub - Total				\$ 9,120.00	\$ 7,747.50

ASSESSMENT SUMMARY

Damages sustained were consistent with the accident report.



(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Our Bro's Workshop (S) Pte Ltd** is \$ 10,970.00 .
We have adjusted the cost to \$ 9,357.50 and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of \$ 7,500.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **10** working days.

29 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **4866** for our services rendered and
we thank you for engaging our services.

Kelvin Automotive Appraising Services



KELVIN TEO

Licensed Automotive Appraiser



Nitec in Automotive Technology

Dip MS




MSAAA

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.









...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2017		22 Nov 2017 11:48 Edit Adj Rpt	S\$2,050.00 Edit Estimates	S\$2,050.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SIGNAGE WORKSHOP PTE LTD , Co. Reg. No.: -		
Main Claimant:	PUVANESWARAN PILLAI ARUTSELVAN , ID: G2838903K		
Vehicle Reg. No.:	JSG6387	Date of Loss:	16/11/2017 09:00 - :59 [3 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM17D06665C02	Policy/Cover Note No.:	DMCVSN1711421700 (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
Vehicle Reg. No. (Insured):	GBE6930B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Our Bro's Workshop (s) Pte Ltd (HQ) 10 Kaki Bukit Road 2, #03-37/38 First East Centre, 417868 Kaki Bukit - Tel: 66361338		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/12/2017]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS AND LET US HAVE YOUR RECOMMENDATION ON COST OF REPAIRS.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***JSG6387 (SNM17D06665C02)**
[GBE6930B]
TP
PUVANESWARAN PILLAI ARUTSELVAN
Nov 16 2017 9:00AM
[SIGNAGE WORKSHOP PTE LTD]
Our Bro's Workshop (s) Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View In Browser ▼](#)

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/11/18 17:00	General View	 Load JPG	☒
2	03/11/18 17:00	General View	 Load JPG	☒
3	03/11/18 17:00	General View	 Load JPG	☒
4	03/11/18 17:00	General View	 Load JPG	☒
5	03/11/18 17:00	General View	 Load JPG	☒
6	03/11/18 17:00	General View	 Load JPG	☒
7	03/11/18 17:00	General View	 Load JPG	☒
8	03/11/18 17:00	General View	 Load JPG	☒
9	03/11/18 17:00	General View	 Load JPG	☒
10	03/11/18 17:00	General View	 Load JPG	☒
11	03/11/18 17:00	General View	 Load JPG	☒
12	03/11/18 17:00	General View	 Load JPG	☒
13	03/11/18 17:00	General View	 Load JPG	☒
14	03/11/18 17:00	General View	 Load JPG	☒
15	03/11/18 17:00	General View	 Load JPG	☒
16	03/11/18 17:00	General View	 Load JPG	☒
17	03/11/18 17:00	General View	 Load JPG	☒
18	03/11/18 17:00	General View	 Load JPG	☒
19	03/11/18 17:00	General View	 Load JPG	☒
20	03/11/18 17:00	General View	 Load JPG	☒
21	03/11/18 17:00	General View	 Load JPG	☒
22	03/11/18 17:00	General View	 Load JPG	☒
23	03/11/18 17:00	General View	 Load JPG	☒
24	03/11/18 17:00	General View	 Load JPG	☒
25	03/11/18 17:00	General View	 Load JPG	☒
26	03/11/18 17:00	General View	 Load JPG	☒
27	03/11/18 17:00	General View	 Load JPG	☒
28	03/11/18 17:00	General View	 Load JPG	☒
29	03/11/18 17:00	General View	 Load JPG	☒
30	03/11/18 17:00	General View	 Load JPG	☒
31	03/11/18 17:00	General View	 Load JPG	☒
32	03/11/18 17:00	General View	 Load JPG	☒
33	03/11/18 17:00	General View	 Load JPG	☒
34	03/11/18 17:00	General View	 Load JPG	☒
35	03/11/18 17:00	General View	 Load JPG	☒

Photos/Images			3 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	03/11/18 17:00	General View	 Load JPG	☒
37	03/11/18 17:00	General View	 Load JPG	☒
38	03/11/18 17:00	General View	 Load JPG	☒
39	03/11/18 17:00	General View	 Load JPG	☒
40	03/11/18 17:00	General View	 Load JPG	☒
41	03/11/18 17:00	General View	 Load JPG	☒
42	03/11/18 17:00	General View	 Load JPG	☒
43	03/11/18 17:00	General View	 Load JPG	☒
44	03/11/18 17:00	General View	 Load JPG	☒
45	03/11/18 17:00	General View	 Load JPG	☒
46	03/11/18 17:00	General View	 Load JPG	☒
47	03/11/18 17:00	General View	 Load JPG	☒
48	03/11/18 17:00	General View	 Load JPG	☒
49	03/11/18 17:00	General View	 Load JPG	☒
50	03/11/18 17:00	General View	 Load JPG	☒
51	03/11/18 17:00	General View	 Load JPG	☒
52	03/11/18 17:00	General View	 Load JPG	☒
53	03/11/18 17:00	General View	 Load JPG	☒
54	03/11/18 17:00	General View	 Load JPG	☒
55	03/11/18 17:00	General View	 Load JPG	☒
56	03/11/18 17:00	General View	 Load JPG	☒
57	03/11/18 17:00	General View	 Load JPG	☒
58	03/11/18 17:00	General View	 Load JPG	☒
59	03/11/18 17:00	General View	 Load JPG	☒
60	03/11/18 17:00	General View	 Load JPG	☒
61	03/11/18 17:00	General View	 Load JPG	☒
62	03/11/18 17:00	General View	 Load JPG	☒
63	03/11/18 17:00	General View	 Load JPG	☒
64	03/11/18 17:00	General View	 Load JPG	☒
65	03/11/18 17:00	General View	 Load JPG	☒
66	03/11/18 17:00	General View	 Load JPG	☒
67	03/11/18 17:00	General View	 Load JPG	☒
68	03/11/18 17:00	General View	 Load JPG	☒
69	03/11/18 17:00	Odometer Reading	 Load JPG	☒
70	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
71	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
72	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
73	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
74	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
75	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
76	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
77	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
78	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
79	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
80	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
81	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
82	03/11/18 17:01	Dismantled Parts	 Load JPG	☒
83	03/11/18 17:01	Dismantled Parts	Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	03/11/18 17:01	Dismantled Parts	Load JPG	✓
85	03/11/18 17:01	Dismantled Parts	Load JPG	✓
86	03/11/18 17:01	Dismantled Parts	Load JPG	✓
87	03/11/18 17:01	Dismantled Parts	Load JPG	✓
88	03/11/18 17:01	Dismantled Parts	Load JPG	✓
89	03/11/18 17:01	Dismantled Parts	Load JPG	✓
90	03/11/18 17:01	Dismantled Parts	Load JPG	✓
91	03/11/18 17:01	Dismantled Parts	Load JPG	✓
92	03/11/18 17:01	Dismantled Parts	Load JPG	✓
93	03/11/18 17:01	Dismantled Parts	Load JPG	✓
94	03/11/18 17:01	Dismantled Parts	Load JPG	✓
95	03/11/18 17:01	Dismantled Parts	Load JPG	✓
96	03/11/18 17:01	Dismantled Parts	Load JPG	✓
97	03/11/18 17:01	Dismantled Parts	Load JPG	✓
98	03/11/18 17:01	Dismantled Parts	Load JPG	✓
99	03/11/18 17:01	Dismantled Parts	Load JPG	✓
100	03/11/18 17:01	Dismantled Parts	Load JPG	✓
101	03/11/18 17:01	Dismantled Parts	Load JPG	✓
102	03/11/18 17:01	Dismantled Parts	Load JPG	✓
103	03/11/18 17:01	Dismantled Parts	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/11/17 11:49	E-filed GIA report OF GBE6930R (INSURED)	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/17 16:59	Police Report	Load PDF	
2	29/11/17 16:59	INSURANCE POLICY OWNERSHIP	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17022248/GRBS2
Date: 29/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.
Policy No: DMCVSN1711421700
Claimant Vehicle No: JSG6387
Insured Vehicle No: GBE6930B
Date of Loss: 16/11/2017
Nature of Claim: TP
Claim No: SNM17D06665C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JSG6387
Make & Model: KTM 200 EGS, 193cc (M)
Reg. Date: 14/08/2017 (Man. Year: 2017)
Colour: Black
Engine Capacity: 199 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price
Engine No: 590617949
Chassis No: PNGJYC40XFK027301
Odometer: 5948 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70R17 Rear Tyre Size: 150/60R17
Front Left Side: MRF 5 mm Rear Left Side: MRF 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,120.00	2,356.28	6,763.72	74.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	250.00	1,600.00	86.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,970.00	2,606.28	8,363.72	76.24
Approved Total (Overridden) (S\$)		2,050.00		
Nett Amount (S\$)	10,970.00	2,050.00	8,920.00	81.31

INSPECTION

Date of Assignment: 22/11/2017
Date Inspected: 23/11/2017 Inspected At: Our Bro's Workshop (s) Pte Ltd (HQ)
10 Kaki Bukit Road 2, #03-37/38 First East Centre
Singapore 417868
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Nov 2018)	
Parts:	N/A	KTM 200 EGS 193cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JSG6387)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PAIR FRONT FORK ASSY	Not Necessary	1,400.00 F	*- FL
2	1		*FRONT BRAKE DISC	Not Necessary	325.00 F	*- FL
3	1		*FRONT UNDER BRACKET	Not Necessary	395.00 F	*- FL
4	1		*FRONT UPPER CLAMP	Not Necessary	315.00 F	*- FL
5	1		*FRONT WINDSHIELD	Broken	255.00 F	*66.00 FL
6	1		*HEADLAMP ASSY	Broken	900.00 F	*181.00 FL
7	1		*HEAD FAIRING	Broken	650.00 F	*54.00 FL
8	1		*INSTRUMENTAL PANEL	Cracked	565.00 F	*265.20 FL
9	1		*PAIR HANDLEBAR	Bent	78.00 F	*78.00 FL
10	1		*PAIR HANDLEBAR GRIP	Cut	56.00 F	*56.00 FL
11	1		*PAIR HANDLEBAR BALANCER	Not Necessary	40.00 F	*- FL
12	1		*LH CLUTCH CONTROL LEVER	Not Necessary	37.00 F	*- FL
13	1		*RH BRAKE CONTROL LEVER	Not Necessary	39.00 F	*- FL
14	1		*PAIR WING MIRROR W/ARM	Broken	320.00 F	*125.00 FL
15	1		*FRONT FENDER	Cut	210.00 F	*79.00 FL
16	2		*FRONT (SIDE) FAIRING	Cut	900.00 F	*520.00 FL
17	1		*PAIR FRONT (UNDER) FAIRING	Cracked	440.00 F	*280.00 FL
18	1		*SET REAR FAIRING	Repair	450.00 F	*- FL
19	1		*PAIR PILLION RIDER FOOT REST	Broken	80.00 F	*40.00 FL
20	1		*PAIR PILLION RIDER FOOT REST SUPPORT BRACKET	Buckled	270.00 F	*135.00 FL
21	1		*FRONT WHEEL RIM	Cut	650.00 FS	*350.00 FS
22	1		*FRONT TYRE	Scratched	360.00 FS	*100.00 FS
23	1		*SET DECORATIVE STICKERS	Necessary	350.00 FS	*200.00 FS
24	1		*FRONT NO. PLATE STICKER	Necessary	35.00 FS	*15.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc,

Sub Total (S\$)	9,120.00	2,544.20
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	187.92

Total Parts (S\$)	9,120.00	2,356.28
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REPLACE DAMAGED PARTS.	New	800.00	150.00
2	TO CHECK WIRING AND REWIRE.	New	100.00	0.00
3	TO REALIGN FRONT FORK.	New	200.00	60.00
4	TO DO BODY FRAME ALIGNMENT.	New	180.00	0.00
5	TOWING CHARGES.	New	100.00	40.00
6	TO ANTI-RUST.	New	120.00	0.00
7	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.	New	350.00	0.00
Gross Labour Cost (\$\$)			1,850.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >