

REC. BY:

REF:

CS/MSG17022262/Tlg22

Special Instruction:

SURVEYOR

Munim

Taufik

ASSIGNMENT (Office)

From (Person):

Vimmala

of

MSG1

Date/Time:

22.11.2017 11:20am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIX 9786L

Insured:

at Workshop m/s

Hitachi Capital

Tel:

6466 3022

of

No. 8 Fourth Lok Yang Road

Policy No:

MSD/VPCP/17-001491

Claim No:

MSG/V/17-001788

Sum Insured:

Excess:

\$ 300.00

Make of Veh:

(Client's Record)

D.O.A

15/11/2017

CA / ~~REP~~ / REP. / REV 24 HRS

After 3pm

H.O.D. Endorsement:

Date/Time:

22.11.2017 1206pm

Person Contacted:

Szu Mei

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SIX 9786L - CS/MSG17022262/Tlg22

DCA: 15/11/17

23/11/17 @ 1.43pm Visit to Vimmala via Munim.

23/11/17 @ 2.04pm Huay Nt informed C/A via Munim.

23/11/17 @ 3.26pm Informed Mr Poon C/A & Ex. \$300 by email.

30/8/18 C/O confirmed with Jamilah final Ag @ 2953.40, 7 days.

(Red to 8357.70, 64%)

Barnett

Taufik

REF:

MS16

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop mis _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

\$300

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

\$35k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

7

days

Res.: _____

Yes or No

Lum Sum: _____

%

3 Val: _____

Yes or No

CA / ☒ REV / REP. / 24 HRS

after 3 pm

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SJX 9786L

Yr Regn: 2010 July

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Mazda 3

c.c 1598

Colour: _____

8/na

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

178775

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JM6BL10Z1A-052839

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

205/55R16

R: _____

27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

6

Rear

6

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

22/11/17 @ 1730

Survey held at _____

Hitachi Capital

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction:

531067B

JP-AXA

RECEIVED 30 AUG 2010

Jumanta
30/8/2018

Date/Time: File Pass to?

☐

: Prel. Report

1) 30/8/2018

☐

: Final Report

Date/Time: File Return to?

2) _____

Days Of Repair: _____

7

Resurvey No. of Trip: _____

1

Survey Fee: _____

Transportation: _____

_____ \$ + RS _____ \$

Phone: _____

Others: _____

Add Fee: ☐

Site Insp \$

☐

Interview \$

☐

Tech. Insp \$

☐

Weekend \$

Report Format: _____

MER-OD

Lump Sum / I.B.I: (\$ _____)

2953.40

TOTAL

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17022262/T1qb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-11-2017



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJX 9786L
Policy No.	MSD/VPCP/17-001491	Coverage (\$)	0.00
Claim No.	MSC/V/17-001788	Excess (\$)	300.00
Assign From	MERIMEN (VIMMALA)	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/11/2017	Inspection Date	22/11/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Nov 2017 Sendback Est	21 Nov 2017 20:34 \$48,311.10	22 Nov 2017 11:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	SUMITOMO WAREHOUSE (S) PTE LTD, Co. Reg. No.: 198803232E		
Vehicle Reg. No.:	SJX9786L	Date of Loss:	15/11/2017 20:00 - :59
Claim Type:	OD / MSC/V/17-001788	Policy/Cover Note No.:	MSD/VPCP/17-001491 (Comprehensive) Coverage: 28/07/2017 - 27/07/2018
		Excess:	\$4300.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/11/2017]		
Driver/Custodian:	ITO RYOSUKE (40 / Male), NRIC: G3096092R, Tel: +6596748563		
Adj Asg. Remarks:	Please revert first.		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 30 August 2018 10:25 AM
To: 'Jamilah, Binte MohdKassim'; CS A Team; SUR; Admin A; Taufikh (LKKAUTO); Rasul (LKKAUTO)
Cc: HengCheong, Poon
Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT

Dear Jamilah,

WITHOUT PREJUDICE

SJX 9786L – confirm final fig \$2,953.40 before excess \$300.00 & GST and 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Sent: Friday, 24 August 2018 4:11 PM
To: CS A Team <cs-a@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: HengCheong, Poon <poonhengcheong@hcspl.com.sg>
Subject: FW: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT

Dear All,

We still have the following cases not finalised.

From Grant dated 10/04/2018:

- 1) SJT4932K TP/LONPAC (DOA:05/01/2017) Emailed 06/03/2017 – Pending finalise confirmation
- 2) SLF4119S TP/AXA (DOA:10/06/2017) Emailed 23/08/2017 – Pending finalise confirmation
- 3) SLG9186J TP/FIRST CAPITAL (DOA:25/02/2017) Emailed 17/05/2017 (pass part invoice to taufikh 13/12/17) – Pending finalise confirmation
- 4) SLG9670C TP/INDIA (DOA:31/08/2017) Emailed 08/03/2018 – Pending finalise confirmation
- 5) SLB7916J TP/FIRST CAPITAL (DOA:22/07/2017) Emailed 02/03/2018 – Pending finalise confirmation
- 6) SKW6478P TP/AXA (DOA:22/07/2017) Emailed 02/03/2018 – Pending finalise confirmation
- 7) SBD3828P TP/INDIA (DOA:29/09/2017) Emailed 22/03/2018 – Pending finalise confirmation
- 8) SLC2109A TP/AXA (DOA:15/11/2017) Emailed 22/03/2018 – Pending finalise confirmation
- 9) SKW6474A TP/AXA (DOA:10/11/2017) Emailed 03/04/2018 – Pending finalise confirmation
- 10) SLD6534Z OD/MSIG (DOA:17/11/2017) Emailed 10/02/2018 – Pending finalise confirmation
- 11) GBB7266U OD/MSIG (DOA:03/10/2017) Emailed 17/01/2018 – Pending finalise confirmation
- 12) SKT6452D OD/MSIG (DOA:11/12/2017) Emailed 21/03/2018 – Pending finalise confirmation
- 13) SJE7642G OD/MSIG (DOA:23/11/2017) Emailed 21/03/2018 – Pending finalise confirmation
- 14) SJX9786L OD/MSIG (DOA:15/11/2017) Emailed 21/03/2018 – Pending finalise confirmation

Appreciate your immediate action.

Please let us have your finalisations latest by **28/08/2018**.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 23 November, 2017 3:26 PM
To: poonhengcheong@hcspl.com.sg
Cc: SUR
Subject: VEHICLE SJX 9786L (DOA: 15/11/2017)

Dear Mr Poon,

As spoken with you.

As instructed by our client **MSIG Insurance**, please proceed to repair the insured vehicle **SJX 9786L (Excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		[I]
1	20 Nov 2017 10:49	Cim Veh Model Changed	(202148) MAZDA 3 1.6 (A).		Vimmala D/O Raja Singam
2	20 Nov 2017 10:49	Cim Created	Reg No: SJX9786L. Acct Date: 2017/11/15. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MTJ117152173		[I] Vimmala D/O Raja Singam
3	20 Nov 2017 10:51	Cim Registration Modified	Pol No:->MSD/VPCP/17-001491.		[I] Vimmala D/O Raja Singam
4	21 Nov 2017 20:26	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.		[I] Grant Chong
5	21 Nov 2017 20:34	Cim Submitted	8311.10.		[R] Grant Chong
6	22 Nov 2017 07:32	Cim Registration Modified	Init.Est.:->8,000 - 9,000.		[I] Vimmala D/O Raja Singam
7	22 Nov 2017 07:32	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert first.		[I] Vimmala D/O Raja Singam
8	22 Nov 2017 07:32	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/11/23		[I] Vimmala D/O Raja Singam
9	22 Nov 2017 07:32	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Vimmala D/O Raja Singam
10	22 Nov 2017 10:21	Assignment 1st Accessed			[A] Pauline Soh Li Ping
11	22 Nov 2017 11:11	Adj Assignment Cancelled	IHS APPT FULL		[I] Vimmala D/O Raja Singam
12	22 Nov 2017 11:11	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment		[I] Vimmala D/O Raja Singam
13	22 Nov 2017 11:12	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert first.		[I] Vimmala D/O Raja Singam
14	22 Nov 2017 11:12	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/11/23		[I] Vimmala D/O Raja Singam
15	22 Nov 2017 11:12	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Vimmala D/O Raja Singam
16	22 Nov 2017 11:40	Assignment 1st Accessed			[A] CATHERINE CHONG KAI LING
17	22 Nov 2017 14:32	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH		[A] CATHERINE CHONG KAI LING
18	23 Nov 2017 13:39	Adj Rpt Initiated			[A] SHIAU CHAN
19	23 Nov 2017 13:43	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/22		[A] SHIAU CHAN
20	23 Nov 2017 13:43	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/22		[A] SHIAU CHAN
21	23 Nov 2017 13:47	Adj Mandate Request	Cur.Reg:2973.20:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
22	23 Nov 2017 14:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/22		[I] Eng Huey Ni
23	23 Nov 2017 14:04	Adj Mandate Set	Approved:2973.20.		[I] Eng Huey Ni

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 23 Nov 2017

Preliminary Advice

Vehicle No	: SJX9786L	Accident Date	: 15/11/2017
Make	: MAZDA 3	Policy No.	: MSD/VPCP/17-001491
Assignment Date	: 22/11/2017	Excess	: S\$300.00
Date of Inspection	: 22/11/2017	Est. Duration of Repair	: 7.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,311.10
Revised Amount	:S\$	2,954.50
Check Items (Estimated)	:S\$	18.70
Total	:S\$	2,973.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	21,287.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,713.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	3232E
Vehicle Details	
Vehicle No.	SJX9786L
Vehicle to be Exported	No
Intended De-registration Date	23 Nov 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 1.6L SDN
Primary Colour	Silver
Manufacturing Year	2010
Engine No.	Z6865499
Chassis No.	JM6BL10Z1A0152839
Maximum Power Output	77.0 kW (103 bhp)
Open Market Value	\$19,342.00
Original Registration Date	28 Jul 2010
First Registration Date	28 Jul 2010
Transfer Count	0
Actual ARF Paid	\$19,342.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Jul 2020
PARF Rebate Amount	\$11,605.00
Intended COE Rebate Details	
COE Expiry Date	27 Jul 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$36,162.00
COE Rebate Amount	\$9,682.00
Total Rebate Amount	\$21,287.00

The information contained herein is correct as at 23 Nov 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/11/2017 17:42
Date Of Accident	15/11/2017 20:20
Exact Location Of Accident	ORCHARD ROAD AROUND ROYAL THAI EMBASSY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX9786L
Insured/Policyholder	
Name Of Registered Owner	SUMITOMO WAREHOUSE (S) PTE LTD
Co Reg No	198803232E
Email Address	COLIN@SUMIMOTO-WAREHOUSE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-68612358

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	ITO RYOSUKE
Passport No/FIN	G3096092R
Date Of Birth	28/01/1977
Occupation	INDOOR
Date Of Driving Pass	23/03/2015
Driving Experience	2 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96748563
Fax Number	
Contact Number	
Email Address	ITO@SUMIMOTO-WAREHOUSE.COM.SG

Address
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD3165Y
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver CHIN YONG KIAT
NRIC/Passport Number
Contact Number 84444979
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

R.2 to
16 Nov 2017
15:07

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stopped at traffic light on Orchard road near Far East shopping Centre, and found ~~there~~ that my lane ^{was} ~~was~~ only for right turn only. (I wanted to go straight)

I was the first car on my lane and when I checked back side during red light, there were a few cars behind me and also at left lane.

I signaled first, and when the traffic light changed to green, I confirmed some car on the left lane ~~passed~~ my car, I double confirmed the left lane was vacant.

~~Then I started to move and go straight~~

Then I carefully and gradually started to move to left lane and when I reached about a half a lane.

SHD 3165Y crashed into middle of ~~my~~ left side of my car.

Both of us stopped immediately and exchanged contact details. At the same time I asked the driver why he did not see in front, I also told him I was signaling to left and was driving very slow (this was just after traffic light changed to green).

DECLARATION

I/We declare the foregoing particulars are true in every respect. He did not answer to my question, just repeating he was driving straight.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:

12.21a
16 NOV 2017

15:32

HITACHI
 Inspire the Next

 INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/17-001491	Date of Loss:	15/11/2017
Vehicle Reg. No.:	SJX9786L	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SUMITOMO WAREHOUSE (S) PTE LTD		
Driver:	ITO RYOSUKE		

Make/Model:	MAZDA 3, 1.6 (A)	Vehicle Reg. Date:	28/07/2010
Vehicle Colour:	SILVER		
Engine No:	Z6865499	Chassis No:	Z6865499
Odometer:	70000 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Tanphk 97495749
Ex \$300 Revent
Resurvey before paint
6-7 days
23/11/17
sur@klauto.com

 Description of Accident/Loss: **PLEASE REFER TO THE ATTACHED.**

 Present Location: **HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)**
COST OF CLAIMS

	Amount
Parts	3,081.10
Miscellaneous Items	0.00
Labour	5,230.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	8,311.10
- Excess (S\$)	300.00
(S\$)	8,011.10
+ GST 7.00% (S\$)	560.78
Nett Amount (S\$)	8,571.88

WKS Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

 This claim is handled by: **GRANT CHONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Nov 2017)

Parts: 144 MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SJX9786L/21/11/2017 20:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear bumper	0.00	0.00	*370.00 F <i>Rx</i>
2	10		*Rear bumper clips	0.00	0.00	*25.00 F <i>xm</i>
3	1		*Rear bumper retainer LH outer	0.00	0.00	*17.00 F <i>xm</i>
4	1		*Rear fender LH	0.00	0.00	*380.00 F <i>Rx</i>
5	1		*Rear fender shield LH	0.00	0.00	*20.00 F <i>xm</i>
6	10		*Rear fender shield clips LH	0.00	0.00	*20.00 F <i>xm</i>
7	1		*Rear door LH	0.00	0.00	*450.00 F <i>bl</i>
8	1		*Rear door sticker set LH	0.00	0.00	*45.00 F <i>u</i>
9	2		*Rear door hinge top and bottom LH	0.00	0.00	*70.00 F <i>Rx</i>
10	1		*Rear door checker LH	0.00	0.00	*20.00 F <i>Rx</i>
11	1		*Front door LH	0.00	0.00	*450.00 F <i>Rx</i>
12	1		*Front door sticker set LH	0.00	0.00	*36.00 F <i>xm</i>
13	1		*Rear RIM LH	0.00	0.00	*400.00 F <i>u</i>
14	1		*Rear tyre LH	0	0.00	*450.00 FS <i>xm</i>
15	1		*Rear windscreen moulding set	0.00	0.00	*48.00 F <i>xm</i>
16	1		*Rer windscreen sealant	0	0.00	*45.00 FS <i>xm</i>

F=Franchise part. S=SpecNett.

Sub Total (S\$) **2,846.00**
 + Margin on L,N Items 10.00% (S\$) **235.10**

Total Parts (S\$) **3,081.10**

Hitachi Capital Asia Pacific Pte. Ltd/SJX9786L/21/11/2017 20:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New 800	2,000.00
2	Putty, blend and paint affected area	New 900	1,800.00
3	Check Wiring, and ensure proper function	New 30	80.00
4	Remove & reinstall bumper sensors	New 30	120.00
5	Cavity Treatment on New Parts	New 40	120.00
6	Conduct four wheel alignment / side slip test	New 80	150.00
7	Remove, replace & balance rim / tire	New 30	50.00
8	Remove & re-install Rear Windscreen	New x	180.00
9	Transfer front and rear door lock & mechanism to new door	New 60	250.00
10	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New x	200.00
11	Remove Upholstery Trim and Cushion	New x	280.00
Gross Labour Cost (S\$)			5,230.00

Hitachi Capital Asia Pacific Pte. Ltd/SJX9786L/21/11/2017 20:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

HITACHI
 Inspire the Next

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/17-001491	Date of Loss:	15/11/2017
Vehicle Reg. No.:	SJX9786L	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SUMITOMO WAREHOUSE (S) PTE LTD		
Driver:	ITO RYOSUKE		
Make/Model:	MAZDA 3, 1.6 (A)	Vehicle Reg. Date:	28/07/2010
Vehicle Colour:	SILVER		
Engine No:	Z6865499	Chassis No:	Z6865499
Odometer:	70000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	PLEASE REFER TO THE ATTACHED.		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

Tanfik 97495749
 Ex \$ 300 Resent
 Repairing before paint
 6-7 days
 sur@klauto.com

COST OF CLAIMS	Amount
Parts	3,081.10
Miscellaneous Items	0.00
Labour	5,230.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	8,311.10
- Excess (S\$)	300.00
(S\$)	8,011.10
+ GST 7.00% (S\$)	560.78
Nett Amount (S\$)	8,571.88

This claim is handled by: GRANT CHONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Nov 2017)
 Parts: 144 MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SJX9786L/21/11/2017 20:34
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear bumper	0.00	0.00	X*370.00F <i>Ry</i>
2	10		*Rear bumper clips	0.00	0.00	X *25.00F X
3	1		*Rear bumper retainer LH outer	0.00	0.00	X *17.00F ?
4	1		*Rear fender LH	0.00	0.00	X *380.00F <i>Ry</i>
5	1		*Rear fender shield LH	0.00	0.00	> *20.00F ✓
6	10		*Rear fender shield clips LH	0.00	0.00	X *20.00F X
7	1		*Rear door LH	0.00	0.00	✓ *450.00F <i>bt</i>
8	1		*Rear door sticker set LH	0.00	0.00	444 *45.00F <i>ab</i> ✓
9	2		*Rear door hinge top and bottom LH	0.00	0.00	X *70.00F <i>Ry</i>
10	1		*Rear door checker LH	0.00	0.00	X *20.00F <i>Ry</i>
11	1		*Front door LH	0.00	0.00	X *450.00F <i>Ry</i>
12	1		*Front door sticker set LH	0.00	0.00	X *36.00F X
13	1		*Rear RIM LH	0.00	0.00	✓ *400.00F <i>ab</i> ✓
14	1		*Rear tyre LH	0	0.00	X *450.00FS X
15	1		*Rear windscreen moulding set	0.00	0.00	X *48.00F X
16	1		*Rer windscreen sealant	0	0.00	X *45.00FS X

F=Franchise part. S=SpecNet.

Sub Total (S\$) 2,846.00
 + Margin on L,N Items 10.00% (S\$) 235.10

Total Parts (S\$) 3,081.10

Hitachi Capital Asia Pacific Pte. Ltd/SJX9786L/21/11/2017 20:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

higher Reentry before paint
24/11/17 @ 1730

parts \$894 + 10% = \$983.40

labour \$1970

** Total P/P \$2953.40 @ 7 day \$*

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New 800	2,000.00
2	Putty, blend and paint affected area	New 900	1,800.00
3	Check Wiring, and ensure proper function	New 30	80.00
4	Remove & reinstall bumper sensors	New 30	120.00
5	Cavity Treatment on New Parts	New 40	120.00
6	Conduct four wheel alignment / side slip test	New 80	150.00
7	Remove, replace & balance rim / tire	New 30	50.00
8	Remove & re-install Rear Windscreen	New X	180.00
9	Transfer front and rear door lock & mechanism to new door	New 60	250.00
10	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New X	200.00
11	Remove Upholstery Trim and Cushion	New X	280.00
Gross Labour Cost (S\$)			5,230.00

Hitachi Capital Asia Pacific Pte. Ltd/SJX9786L/21/11/2017 20:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax: 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Depo Direct: 6417 5751 / 5743 9328



Depo Direct: 6305 9810

Depo Direct: 6325 9811

Depo Direct: 6417 9792



Depo Direct: 6417 9794

Depo Direct: 6417 9785

Depo Direct: 6417 9798

Depo Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

HITACHI CAPITAL ASIA PACIFIC PTE LTD
NO.8 FOURTH LOK YANG ROAD

SINGAPORE 629705
TEL: 64663022 FAX: 68966591
ATTN: GRANT

TAX INVOICE : AR201711-13737
DATE : 23/11/2017
CUSTOMER ID : HI1001
VEH REG. NO. : SJX9786L
TERMS : 30 days
PO NO. : 102919
PAGE NO. : Page 1 of 1
CURR : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
BBY2-73-02XJ MZ3 SD 09--	RR.DOOR LH	PA PL3-H1-03B	1	450.00	450.00
9965-87-6560 MZ3 BL 09--	SPORT RIM 16"	PA PL3-F1-09B	1	400.00	400.00

SUB-TOTAL : 850.00
ADD GST 7.00 % 59.50

E & OE

TOTAL AMOUNT S\$: 909.50

[P] 23/11/2017 2:44:32PM

[E] 23/11/2017 2:40:43PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: KOW



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M


Audi
Dept Direct: 6417 8791 / 8748 8630



Dept Direct: 6305 9810

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 8794

Dept Direct: 6417 9793

Dept Direct: 6417 9795

Dept Direct: 6417 9793

Wiper blade: NWS (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

HITACHI CAPITAL ASIA PACIFIC PTE LTD
NO.8 FOURTH LOK YANG ROAD

SINGAPORE 629705
TEL : 64663022 FAX : 68966591
ATTN : GRANT

TAX INVOICE : AR201711-13787
DATE : 23/11/2017
CUSTOMER ID : HIT001
VEH REG. NO. : SJX9786L
TERMS : 30 days
PO NO. : 102919
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	BBM4-50-8W2 MZ3 SD 09--	RR.DOOR LH TOP STRIPE	U1	1	12.00	12.00
2	BBM4-50-8W4A MZ3 BL 09--	RR.DOOR LH PILLAR STRIPE	U1	1	20.00	20.00
3	BBM4-50-8W6A MZ3 SD 09--	RR.DOOR LH QUATER STRIPE	U1	1	12.00	12.00

rear
door
striker
set

SUB-TOTAL : 44.00
ADD GST 7.00 % 3.08

E. & O.E

TOTAL AMOUNT S\$: 47.08

[P] 23/11/2017 3:22:03PM

[E] 23/11/2017 3:19:31PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.


Sales Executive : KOW



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order


Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Nov 2017 Sendback Est	21 Nov 2017 20:34 S\$8,311.10	22 Nov 2017 11:12 Edit Adj Rpt	S\$2,953.40 Edit Estimates	S\$2,953.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	SUMITOMO WAREHOUSE (S) PTE LTD. Co. Reg. No.: 198803232E								
Vehicle Reg. No.:	SJX9786L	Date of Loss:	15/11/2017 20:00 - :59 [87 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / MSC/V/17-001788	Policy/Cover Note No.:	MSD/VPCP/17-001491 (Comprehensive) Coverage: 28/07/2017 - 27/07/2018						
		Excess:	S\$300.00						
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/12/2017]								
Driver/Custodian:	ITO RYOSUKE (40 / Male), NRIC: G3096092R, Tel: +6596748563								
Adj Asg. Remarks:	Please revert first.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (31/08/2018): SJX9786L (MSC/V/17-001788) - MSIG_SG (15/05/2018): SJX9786L (MSC/V/17-001788) - MSIG_SG (23/11/2017): Alert - Adj Mandate Approved (S\$2973.20) - SJX9786L - Claim Handler: Vimmala D/O...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJX9786L (MSC/V/17-001788)
 OD
 Nov 15 2017 8:00PM
[SUMITOMO WAREHOUSE (S) PTE LTD]
 Hitachi Capital Asia Pacific Pte. Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print	
1	16/11/17 18:02	Accident Statement	Load HTM		
2	21/11/17 20:34	Repairer Estimates	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	23/11/17 13:43	Adjuster Immediate Advice	Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print	
1	16/11/17 17:52	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
2	16/11/17 17:52	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
3	16/11/17 17:52	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
4	16/11/17 17:52	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
5	16/11/17 17:52	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
6	16/11/17 17:52	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
7	16/11/17 17:52	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
8	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
9	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
10	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
11	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
12	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
13	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
14	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
15	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
16	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
17	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
18	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
19	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
20	16/11/17 17:53	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	23/11/17 13:44	Odometer Reading	Load JPG	☒	
2	23/11/17 13:44	Chassis Number	Load JPG	☒	
3	23/11/17 13:44	General View	Load JPG	☒	
4	23/11/17 13:44	General View	Load JPG	☒	
5	23/11/17 13:44	General View	Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
6	23/11/17 13:44	General View	 Load JPG	☒
7	23/11/17 13:44	General View	 Load JPG	☒
8	23/11/17 13:44	General View	 Load JPG	☒
9	23/11/17 13:44	General View	 Load JPG	☒
10	23/11/17 13:44	General View	 Load JPG	☒
11	23/11/17 13:44	General View	 Load JPG	☒
12	23/11/17 13:44	General View	 Load JPG	☒
13	23/11/17 13:44	General View	 Load JPG	☒
14	23/11/17 13:44	General View	 Load JPG	☒
15	23/11/17 13:44	General View	 Load JPG	☒
16	23/11/17 13:44	General View	 Load JPG	☒
17	23/11/17 13:44	General View	 Load JPG	☒
18	23/11/17 13:44	General View	 Load JPG	☒
19	23/11/17 13:44	General View	 Load JPG	☒
20	23/11/17 13:44	General View	 Load JPG	☒
21	23/11/17 13:44	General View	 Load JPG	☒
22	23/11/17 13:44	General View	 Load JPG	☒
23	23/11/17 13:44	General View	 Load JPG	☒
24	23/11/17 13:44	General View	 Load JPG	☒
25	30/08/18 10:21	Reinspection Photo	 Load JPG	☒
26	30/08/18 10:21	Reinspection Photo	 Load JPG	☒
27	30/08/18 10:21	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	16/11/17 17:56	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/11/17 13:46	WORKSHOP ESTIMATE	 Load PDF	
2	31/08/18 11:27	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	16/11/17 18:02	Accident Statement	 Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	16/11/17 17:52	Accident Photo	 Load JPG	☒
2	16/11/17 17:52	Accident Photo	 Load JPG	☒
3	16/11/17 17:52	Accident Photo	 Load JPG	☒
4	16/11/17 17:52	Accident Photo	 Load JPG	☒
5	16/11/17 17:52	Accident Photo	 Load JPG	☒
6	16/11/17 17:52	Accident Photo	 Load JPG	☒
7	16/11/17 17:52	Accident Photo	 Load JPG	☒
8	16/11/17 17:53	Accident Photo	 Load JPG	☒
9	16/11/17 17:53	Accident Photo	 Load JPG	☒
10	16/11/17 17:53	Accident Photo	 Load JPG	☒
11	16/11/17 17:53	Accident Photo	 Load JPG	☒
12	16/11/17 17:53	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
13	16/11/17 17:53	Accident Photo	 Load JPG	☒
14	16/11/17 17:53	Accident Photo	 Load JPG	☒
15	16/11/17 17:53	Accident Photo	 Load JPG	☒
16	16/11/17 17:53	Accident Photo	 Load JPG	☒
17	16/11/17 17:53	Accident Photo	 Load JPG	☒
18	16/11/17 17:53	Accident Photo	 Load JPG	☒
19	16/11/17 17:53	Accident Photo	 Load JPG	☒
20	16/11/17 17:53	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	16/11/17 17:56	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17022262/T1QBE2

Date: 31/08/2018

REFERENCE

Insured/Claimant: SUMITOMO WAREHOUSE (S) PTE LTD

Policy No: MSD/VPCP/17-001491

Date of Loss: 15/11/2017

Nature of Claim: OD

Claim No: MSC/V/17-001788

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJX9786L

Make & Model: MAZDA 3, 1.6 (A)

Reg. Date: 28/07/2010 (Man. Year: 2010)

Colour: Silver

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$35,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: Z6865499

Chassis No: JM6BL10Z1A0152839

Odometer: 178775 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,081.10	983.40	2,097.70	68.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,230.00	1,970.00	3,260.00	62.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,311.10	2,953.40	5,357.70	64.46
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	8,011.10	2,653.40	5,357.70	66.88
+ GST 7.00/7.00% (S\$)	560.78	185.74	375.04	66.88
Nett Amount (S\$)	8,571.88	2,839.14	5,732.74	66.88

INSPECTION

Date of Assignment: 22/11/2017 Present Location:

Date Inspected: 22/11/2017 Inspected At:

Hitachi Capital Asia Pacific Pte. Ltd (HQ)

Hitachi Capital Asia Pacific Pte. Ltd (HQ)

No 8 Fourth Lok Yang Road

Singapore 629705

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2018)
Parts: 144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJX9786L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear bumper (WCP)	Repair	370.00 F	*- F
2	10		*Rear bumper clips (WCP)	Not Necessary	25.00 F	*- F
3	1		*Rear bumper retainer LH outer (WCP)	Not Necessary	17.00 F	*- F
4	1		*Rear fender LH (WCP)	Repair	380.00 F	*- F
5	1		*Rear fender shield LH (WCP)	Not Necessary	20.00 F	*- F
6	10		*Rear fender shield clips LH (WCP)	Not Necessary	20.00 F	*- F
7	1		*Rear door LH (WCP)	Bent	450.00 F	*450.00 F
8	1		*Rear door sticker set LH (WCP)	Necessary	45.00 F	*44.00 F
9	2		*Rear door hinge top and bottom LH (WCP)	Repair	70.00 F	*- F
10	1		*Rear door checker LH (WCP)	Repair	20.00 F	*- F
11	1		*Front door LH (WCP)	Repair	450.00 F	*- F
12	1		*Front door sticker set LH (WCP)	Not Necessary	36.00 F	*- F
13	1		*Rear RIM LH (WCP)	Cut	400.00 F	*400.00 F
14	1		*Rear tyre LH	Not Necessary	450.00 FS	*- FS
15	1		*Rear windscreen moulding set (WCP)	Not Necessary	48.00 F	*- F
16	1		*Rear windscreen sealant	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,846.00	894.00
+ Margin on L,N Items 10.00/10.00% (S\$)	235.10	89.40
Total Parts (S\$)	3,081.10	983.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,000.00	800.00
2	Putty, blend and paint affected area	New	1,800.00	900.00
3	Check Wiring, and ensure proper function	New	80.00	30.00
4	Remove & reinstall bumper sensors	New	120.00	30.00
5	Cavity Treatment on New Parts	New	120.00	40.00
6	Conduct four wheel alignment / side slip test	New	150.00	80.00
7	Remove, replace & balance rim / tire	New	50.00	30.00
8	Remove & re-install Rear Windscreen	New	180.00	0.00
9	Transfer front and rear door lock & mechanism to new door	New	250.00	60.00
10	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New	200.00	0.00
11	Remove Upholstery Trim and Cushion	New	280.00	0.00
Gross Labour Cost (S\$)			5,230.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >