

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	10	SET BUMPER LOWER REAR CLIP	Reviewing	66	NECESSARY	
	11	EXHAUST MOUNTING REAR	Reviewing	0	SERVICEABLE	
	12	SET BOOT FINISHER CLIP	Reviewing	0	NOT NECESSARY	
	13	BOOT STICKER "TRANS-CAP"	Reviewing	0	NOT NECESSARY	
	14	BOOT STICKER "6555-3333"	Reviewing	0	NOT NECESSARY	
	15	BOOT INNER TRIM CLIP	Reviewing	0	NOT NECESSARY	
	16	SET FENDER WHEELARCH REAR RH CLIP	Reviewing	0	NOT NECESSARY	
	17	SET FENDER WHEELARCH REAR LH CLIP	Reviewing	0	NOT NECESSARY	
	18	FENDER INNER TRIM CLIP LH	Reviewing	0	NOT NECESSARY	
	19	FENDER INNER TRIM CLIP LH	Reviewing	0	NOT NECESSARY	
	20	TALLAMP CLIP RH	Reviewing	0	NOT NECESSARY	
	21	TALLAMP CLIP LH	Reviewing	0	NOT NECESSARY	
	22	REAR WINDSCREEN SEALANT	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LBT PRICE	DEPR./ BITTR%	DISC CUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	45	1			EXHAUST CAP REAR			Repair	0		0		0	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	600	0	0	Reviewing		
	2		PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	500	0	0	Reviewing		
	3		TO RUST-PROOFING OF THE AFFECTED AREAS.	30	0	0	Reviewing		
	4		TO REINSTALL REAR BUMPER PARKING SENSOR.	60	0	0	Reviewing		
	5		TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	60	0	0	Reviewing		
	6		TO REPAIR AND REALIGN REAR EXHAUST PIPE.	0	0	0	Reviewing		
	7		TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	0	0	0	Reviewing		
	8		TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	9		TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	10		TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	0	0	0	Reviewing		
	11		TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	12		TOWING FEES.	0	0	0	Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC QUNTY%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	12	1			BUMPER BEAM BRACKET RH REAR			Repair	0		0		0	Reviewing	
	13	1			BOOT REAR (DISC 10%)			Bent	2585.41		0		2585.41	Reviewing	
	14	1			BOOT FINISHER			Serviceable	0		0		0	Reviewing	
	15	1			BOOT WEATHERSTRIP			Serviceable	0		0		0	Reviewing	
	16	1			BOOT REFLECTOR LAMP LH			Serviceable	0		0		0	Reviewing	
	17	1			BOOT REFLECTOR LAMP RH			Serviceable	0		0		0	Reviewing	
	18	1			BOOT BADGE "RENAULT" (DISC 10%)			Necessary	202.82		0		202.82	Reviewing	
	19	1			BOOT BADGE (DISC 10%)			Necessary	202.82		0		202.82	Reviewing	
	20	1			BOOT STRUT LH			Serviceable	0		0		0	Reviewing	
	21	1			BOOT STRUT RH			Serviceable	0		0		0	Reviewing	
	22	1			BOOT HINGE LH			Repair	0		0		0	Reviewing	
	23	1			BOOT HINGE RH			Repair	0		0		0	Reviewing	
	24	1			BOOT INNER TRIM			Serviceable	0		0		0	Reviewing	
	25	1			BOOT SWITCH			Serviceable	0		0		0	Reviewing	
	26	1			BOOT LOCK			Repair	0		0		0	Reviewing	
	27	1			BOOT LOCK CATCH			Repair	0		0		0	Reviewing	
	28	2			LICENCE PLATE LAMP			Serviceable	0		0		0	Reviewing	

ASSESSMENT INFORMATION

CATEGORY

POLICY INFORMATION

FNOL INFORMATION

POST SURVEY INFORMATION

Engine Capacity

1995 cc

License Type



Sum Insured

0

License Issue Date

mm/dd/yyyy

Market Value

0

License Expiration Date

mm/dd/yyyy

Address

BLK 690E WOODLANDS DRIVE
75, 735690, Singapore

Address type

Personal Correspondence

Gender

Male

Marital status

Unknown

Identification #

S1613759F

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	11/5/18 11:20 AM	5700	5700	Open	Share	Clone
TAY Ernest	11/28/17 10:18 AM	7159.5	7159.5	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 22, 2018
Immediate Advice (with mandate) dd 110818.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 11, 2018
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 11, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	March 2, 2018
Preliminary Advice.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	November 28, 2017
GIA REPORT OF SHC5918J (TP) 1.pdf	Reports & Statement	GIA Report	KADRI Maleen	November 23, 2017
ESTIMATE.pdf	Letters and Correspondence	Others	KADRI Maleen	November 23, 2017
EMAIL.pdf	Letters and Correspondence	Workshop	KADRI Maleen	November 23, 2017
GIA REPORT OF SJR4655X (INSD).PDF	Reports & Statement	GIA Report	KADRI Maleen	November 23, 2017
GIA REPORT OF SHC5918J (TP).PDF	Reports & Statement	GIA Report	KADRI Maleen	November 23, 2017