

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5918J -

AAD1711-204

*Not Authorized
Assembly B4 paint*

Vehicle No.:	SHC5918J - JHOW
Chassis No.:	VF1ABL15AUC280982
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	19.11.2017
Third Party Insurer :	<i>PXA</i>

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>Not list</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>Sm</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$ <i>Sm</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$ <i>Sm</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$ <i>Sm</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$ <i>Sm</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$ <i>Sm</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$ <i>Sm</i> 43.61 X
10	1 BUMPER BEAM REAR	\$ <i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ 225.95 7
12	1 BUMPER BEAM BRACKET RH REAR	\$ 225.95 7
13	1 BOOT REAR	\$ <i>Bu</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$ <i>Sm</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$ <i>Sm</i> 323.05 X
16	1 BOOT REFLECTOR LAMP LH	\$ <i>Sm</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$ <i>Sm</i> 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$ <i>Ne</i> 225.36 ✓
19	1 BOOT BADGE	\$ <i>Ne</i> 225.36 ✓
20	1 BOOT STRUT LH	\$ <i>Sm</i> 276.08 X
21	1 BOOT STRUT RH	\$ <i>Sm</i> 276.08 X
22	1 BOOT HINGE LH	\$ <i>R</i> 367.84 X
23	1 BOOT HINGE RH	\$ <i>R</i> 367.84 X
24	1 BOOT INNER TRIM	\$ <i>Sm</i> 586.45 X
25	1 BOOT SWITCH	\$ <i>Sm</i> 168.13 X
26	1 BOOT LOCK	\$ <i>R</i> 202.67 X
27	1 BOOT LOCK CATCH	\$ <i>Ne</i> 74.40 X
28	2 LICENCE PLATE LAMP	\$ <i>Sm</i> 50.52 X
29	2 BOOT RUBBER PLUG	\$ <i>Sm</i> 221.81 X
30	1 FENDER PANEL INNER TRIM REAR LH	\$ <i>Sm</i> 671.45 X
31	1 FENDER PANEL REAR LH	\$ <i>R</i> 3,299.13 X
32	1 WHEELARCH REAR LH	\$ <i>Sm</i> 543.47 X
33	1 FENDER PANEL INNER TRIM REAR RH	\$ <i>Sm</i> 671.45 X
34	1 FENDER PANEL REAR RH	\$ <i>R</i> 3,299.13 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-204

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5918J -

35	1	WHEELARCH REAR RH	\$	Sn	543.47	X
36	1	TAILLAMP RH	\$	Sn	552.55	X
37	1	TAILLAMP PANEL RH	\$	R	986.70	X
38	1	TAILLAMP LH	\$	Sn	552.55	X
39	1	TAILLAMP PANEL LH	\$	R	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	X
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	na	30.00	
13	1	BOOT STICKER "6555-3333"	\$	na	30.00	
14	1	BOOT INNER TRIM CLIP	\$	na	45.00	
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	
19	1	TAILLAMP CLIP RH	\$	na	5.00	
20	1	TAILLAMP CLIP LH	\$	na	5.00	
21	2	REAR WINDSCREEN SELANT	\$	na	80.00	
22	1	WINDSCREEN MOULDING	\$	na	100.00	
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-204

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5918J -

25	1	SPARE TYRE	\$	<i>Sm</i> 330.00 <i>X</i>
			TOTAL	\$ 2,225.02
			TOTAL PARTS	\$ 34,507.07
		Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>600</i>
		Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>500</i>
		To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>300</i>
		To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
		To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>600</i>
		To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
		To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
		To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
		To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
		To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00 <i>X</i>
		To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
		Towing Fees	\$	<i>nn</i> 120.00 <i>X</i>
		To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
		To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-204

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5918J -

TOTAL	\$	11,160.00
Over All Total	\$	45,667.07

**(PARTS BY PARTS)
Repair Days**

~~15 Days~~

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: