

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05672

Vehicle Insured : GBE2609G
Accident Date : 18-Nov-2017

Date : 21-Nov-2017

Our Ref : 217177 (AXA) / CHAN

PAGE : 1

WEE CHOON BENG
BLK 247 BUKIT BATOK EAST AVE 5
#08-70
Singapore 650247

Not Authorized
11 Nov @ 7
Recovery After Paint 3 days

ESTIMATED COST OF REPAIR FOR M/BENZ E200 1.8 CGI SKT8138Z

1 pc	Front bumper fascia	Pr 1,651.00	✓
1 pc	Frt o/s bumper parking sensor	nd / Sen 291.00	✓
1 pc	O/s bumper parking sensor O rg	Pr 24.00	✓
1 pc	Front o/s bumper side retainer	Sn 83.00	X
2 pcs	Front bumper lower side mouldg @ S\$ 95.00	Pr 190.00	✓
1 pc	Front o/s bumper sponge	95.00	✓
1 pc	Front o/s bumper inner parts	Sn 97.00	X
10 pcs	Front bumper inner part rivet @ S\$ 3.50	Pr 35.00	✓
1 pc	O/s headlamp	Pr 1,284.00	✓
1 pc	Front o/s fender	Pr 1,106.00	X
		4,856.00	
Less 10% :		485.60	

4,370.40

To diagnostic programme headlamp system

12d
250.00

To putty and spray replaced parts

44d 700.00

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

30d 800.00

Total : S\$ 6,120.40

Singapore Dollars Six Thousand One Hundred and Twenty and Cents Forty Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: