

22/03/2007

SS. REC. BY:

REF: CS/EG117022277/Uqbn2

Special Instruction:

Surveyor: Marius

ASSIGNMENT (Office)

From (Person): Yee Pei Yi of EG1 Date/Time: 22/12/07 9:30am

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBK 1746T Insured: GBA 4541Aat Workshop m/s San Hock Hin Tel: 6281 6520 x20of No. 6 Defu Lane 4Policy No: _____ Claim No: GBA4541A / RH/p

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 22/12/07
(Client's Record)CA / REV / REP. / REV 24 HRS wp

H.O.D. Endorsement: _____

Date/Time: 22/12/07 10:29am Person Contacted: Raymond Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBK 1746T - CF/TL 16022673 / Uq392 DOA: 19/11/06
	GBA 4541A - CF/ALG 07002318 / 82 DOA: 02.10.07
23/11/07	22/11/07 revised to Bohaini by email.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: FBK1746T
 at Workshop m/s 3414
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 7200
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 G/A / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBK1746T Yr Regn: 4 / 15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha YBR125 C.C. 124
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 2-2381 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: LBPRE10100025-3735
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or other
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 2.75-18
 R: 3.00-18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or metzler
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 22/11/17 D.O.I. 22/11/17
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
by 8 nls body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/11/17 3546 net 3654

8/1/18 4/5 @ 2100 conf. with Raymond.
Chex & 1331, 39%

RECEIVED 09 JAN 2018

Date/Time, File Pass to?



Preli. Report

1) 20/11/17

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

) \$ + RS \$

) Photos

) Others

Report Format: TPLump Sum / B.I. (\$ 2100)

TOTAL

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17022277/Uqb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 22-11-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 4541A	Veh. Inspected	FBK 1746T
Policy No.		Coverage (\$)	0.00
Claim No.	GBA4541A/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/11/2017	Inspection Date	22/11/2017
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Cath): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		

Surveyor (Maven): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓		
---	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓		
✓		
✓		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓		
---	--	--

Check By:

Cath 03/11/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 22 November, 2017 9:13 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GBA4541A / TP : FBK1746T/LKK / DOA : 12/11/2017
Attachments: FBK1746T - ESTIMATE n SAS.pdf; FBK1746T - PRS FORM.pdf; RE: Accident Involving FBK1746T & GBA4541A on 12/11/2017 (85.9 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **BAN HOCK HIN CO., PTE LTD**,

ADDRESS : NO 6 DEFU LANE 4
SINGAPORE 539410

PERSON TO CONTACT : RAYMOND @ 6821 6520 X 220

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re AG, one of the world's leading risk carriers.

ERGO

Date: 21.11.2017
Our Reference: GBA 4541A/RH/pl
Your Reference: FBK 1746T

To: BAN HOCK HIN CO. PTE LTD

Sent via Fax

or

Email

raymond@bhh.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: FBK 1746T
Insured's Vehicle: GBA 4541A
Date Of Accident: 12.11.2017


We acknowledge receipt of your request for PRS on: 21.11.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☒ Our Insured's driver has not reported the accident to us to date.
- ☒ Others: OFFICER-IN-CHARGE - SIT1

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 23 November, 2017 2:21 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; assignments
Subject: RE: GBA4541A / TP : FBK1746T/LKK / DOA : 12/11/2017
Attachments: CSEGI117022277Uqb.pdf

Dear Rohaini,

Enclosed herewith preliminary advice of FBK 1746T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 22 November, 2017 10:32 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: GBA4541A / TP : FBK1746T/LKK / DOA : 12/11/2017

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 22 November, 2017 9:13 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GBA4541A / TP : FBK1746T/LKK / DOA : 12/11/2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **BAN HOCK HIN CO., PTE LTD,**



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBA4541A/RH/pl

Date: 23rd November 2017

Our Ref: CS/EGI7022277/Uqb

The Motor Claims Department
ERGO Insurance

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. FBK 1746T

We thank you for the instruction on 22/11/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/11/2017 at the premises of M/s BAN HOCK HIN and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,431.00</u>
Revised Estimate Amount	: S\$ <u>2,992.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Lump Sum Repair Estimate Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:


The vehicle sustained damages at the front portion and n/s body.

Comments/ Present Status:

Damages consistent.

Days of repair: 4 days.

We have NOT authorize repair.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	0288K

Vehicle Details

Vehicle No.	FBK1746T
Vehicle to be Exported	No
Intended De-registration Date	23 Nov 2017
Vehicle Make	YAMAHA
Vehicle Model	YBR125
Primary Colour	Red
Manufacturing Year	2015
Engine No.	E3F5E038541
Chassis No.	LBPREF101000053735
Maximum Power Output	-
Open Market Value	\$1,900.00
Original Registration Date	13 Apr 2015
First Registration Date	13 Apr 2015
Transfer Count	1
Actual ARF Paid	\$285.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	12 Apr 2025
COE Category	D - Motorcycle
COE Period(Years)	10
QP Paid	\$4,800.00
COE Rebate Amount	\$3,546.00
Total Rebate Amount	\$3,546.00

The information contained herein is correct as at 23 Nov 2017

OK

Enquire Transfer Fee

Vehicle Details	
Vehicle No.	FBK1746T
Vehicle Type	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	YAMAHA
Vehicle Model	YBR125
Chassis No.	LBPRE101000053735
Propellant	Petrol
Engine No.	E3F5E038541
Engine Capacity	124 cc
Maximum Power Output	-
Maximum Laden Weight	320 kg
Unladen Weight	114 kg
Year Of Manufacture	2015
Original Registration Date	13 Apr 2015
Lifespan Expiry Date	-
COE Category	D - Motorcycle
Quota Premium	\$4,800.00
COE Expiry Date	12 Apr 2025
Road Tax Expiry Date	12 Apr 2018
Inspection Due Date	12 Apr 2018
Intended Transfer Date	22 Nov 2017
CO2 Emission	-
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee (s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	
Amount Payable	
	<div><div>Amount Before GST (S\$)</div><div>GST Amount (S\$)</div><div>Amount After GST (S\$)</div></div>
Transfer Fee	<div>11.00-11.00</div>
Total Amount Payable	11.00

You may print this page for reference.



(1)

**Region's Best SME Bank**

1-Day Express Account Opening, 4-Hour Loan Approval. Best Regional SME Bank 2016 - 2017

OPEN

Bike model

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▾

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Yamaha YBR125 (/listing/usedbike/yamaha-yamaha-ybr125/4596/)



(/listing/usedbike/yamaha-yamaha-ybr125/4596/)

see\$5600

Reg : 03/04/2013

Type: Street Bikes

124cc

Visit us at Hua Chin Motor. Well maintained condition. Address: 50 Bukit Batok Street 23 #02-02 Midview Building S(659578) Tel: 68966619. We accept trade ins as well as flexible loans!

Posted on : 22/11/2017

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-YBR125/4596/)

Yamaha YBR125 (/listing/usedbike/yamaha-yamaha-ybr125/4585/)



(/listing/usedbike/yamaha-yamaha-ybr125/4585/)

see\$3300

Reg : 06/12/2011

Type: Street Bikes

124cc

5347km

CERTIFICATE OF INSURANCETHE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189) OF THE REPUBLIC OF SINGAPORE
THE ROAD TRANSPORT ACT 1987 OF MALAYSIATHE AGREEMENT BETWEEN THE MINISTER FOR FINANCE (SINGAPORE) AND THE MOTOR INSURERS' BUREAU OF SINGAPORE DATED 22 FEBRUARY 1975
THE AGREEMENT BETWEEN THE MINISTER OF TRANSPORT (MALAYSIA) AND THE MOTOR INSURERS' BUREAU OF WEST MALAYSIA DATED 15 JANUARY 1968
ANY SUBSEQUENT REVISIONS TO THE ABOVE ACTS AND AGREEMENTS

- CERTIFICATE No. AVFMSB0000621700 ChaNo: LBPRE101000053735
1. Index Mark and Registration Number of Vehicle FBK 1746 T
 2. Name of Policyholder BAN HOCK HIN CO PTE LTD
 3. Effective Date of Commencement of Insurance for the purposes of the Ordinance 11 February 2017
10 February 2018
 4. Date of Expiry of Insurance
 5. Persons or Classes of Persons entitled to drive* (For certificate references MX1 and MX4, see overleaf)
ANY PERSON WHO IS UNDER THE POLICYHOLDER &/OR HIRER'S EMPLOYMENT AND IS DRIVING ON THEIR ORDER OR WITH THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use* (For certificate reference MX1, see overleaf)

USE ONLY FOR THE POLICYHOLDER &/OR HIRER'S BUSINESS OR PROFESSION.

THE POLICY DOES NOT COVER:

1. USE FOR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED-TESTING.
2. USE WHILST DRAWING A TRAILER EXCEPT THE TOWING (OTHER THAN FOR REWARD) OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.
3. USE FOR THE CARRIAGE OF PASSENGERS FOR HIRE OR REWARD BY ANY PERSON TO WHOM THE VEHICLE IS HIRED.

Type of Cover : Third Party

* Limitations rendered inoperative by Section 79 of the Road Traffic Ordinance 1958 (Malaysia) or Section 7 of the Motor Vehicle (Third-Party Risks and Compensation) Ordinance 1960 (Republic of Singapore) are not to be included under the headings.

I/WE HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and The Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Republic of Singapore)



Approved Insurers

Examined By



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

ERGO INSURANCE PTE LTD

302 ORCHARD ROAD
#09-01 TIONG BUILDING
SINGAPORE 238862

MOTOR CLAIMS DEPT

VEHICLE NO. : FBK1746T
MAKE/MODEL : YAM / YBR125

NO. : 32158

DATE : 21/11/2017
CLAIM NO. : 11063
POLICY NO. : AVFMSB0000621700

FROM : RAYMOND

Not Aduh
hcr
h/s \$2100
22/11/17
4 day
change the up

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 25363	REPLACE	1.00	\$18.00	18.00
2	BAR HANDLE P/N: 42062	REPLACE	1.00	\$69.00	69.00
3	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	180.00
4	COVER TANK SIDE RH (BLACK) P/N: 54477	REPLACE	1.00	\$98.00	98.00
5	COWLING FRONT (RED) P/N: 42639	REPLACE	1.00	\$276.00	276.00
6	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00
7	CROWN HANDLE P/N: 28100	REPLACE	1.00	\$75.00	75.00
8	FORK FRONT ASSY LH P/N: 56248	REPLACE	1.00	\$625.00	625.00
9	FORK FRONT ASSY RH P/N: 53204	REPLACE	1.00	\$625.00	625.00
10	GRIP HANDLE SET (GPR) F2 P/N: 45347	REPLACE	1.00	\$14.00	14.00
11	HEADLIGHT ASSY P/N: 50950	REPLACE	1.00	\$320.00	320.00
12	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	5.00	\$35.00	175.00
13	LAMP SIGNAL FRONT RH P/N: 42003	REPLACE	1.00	\$55.00	55.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 20021-1-0383
ISO 9001: 2008

S/N	Description	Action	Qty	Unit Price	Amount
14	LENS SIGNAL FRONT LH P/N: 54334	REPLACE	1.00	\$10.00	CU7 10.00 ✓
15	LEVER CLUTCH P/N: 52644	REPLACE	1.00	\$13.00	CU7 13.00 ✓
16	METER ASSY P/N: 50954	REPLACE	1.00	\$328.00	17 328.00 X
17	MIRROR LH P/N: 49947	REPLACE	1.00	\$80.00	800 80.00 X
18	MIRROR RH P/N: 54029	REPLACE	1.00	\$80.00	320 80.00 ✓
19	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	70.0 14.00 ✓
20	STAY HEADLAMP P/N: 45750	REPLACE	1.00	\$68.00	327 68.00 ✓
21	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$68.00	22 68.00 ✓
22	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$10.00	22 10.00 85N ✓
23	TRANSPORT CHARGES P/N: 07169 - TOW BACK BIKE FOR ACCIDENT REPAIR. - DELIVER BIKE BACK TO OUTLET.	X	1.00	\$35.00	35.00 ✓

SUB TOTAL

\$3,431.00

GST @ 7 %

\$240.17

GRAND TOTAL

\$3,671.17

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

217048

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759


CERT NO.: 2002-1-2383
ISO 9001: 2008

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI17022277/Uqbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 11-01-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 4541A	Veh. Inspected	FBK 1746T	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBA4541A/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	22/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA YBR125	c.c	124	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	LBPREF101000053735	Colour	RED	
Odometer	52381	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	2.75-18	METZELER	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	3.00-18	METZELER	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/11/2017	Inspection Date	22/11/2017	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 1746T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	AXLE WHEEL FRONT	NECESSARY	18.00	18.00
1	BAR HANDLE	BENT	69.00	69.00
1	BRACKET UNDER FORK	BENT / TWISTED	180.00	180.00
1	COVER TANK SIDE RH (BLACK)	CUT	98.00	98.00
1	COWLING FRONT (RED)	CRACKED	276.00	276.00
1	CRASH BAR	BENT	195.00	195.00
1	CROWN HANDLE	TWISTED	75.00	75.00
1	FORK FRONT ASSY LH	BENT / TWISTED	625.00	625.00
1	FORK FRONT ASSY RH	BENT / TWISTED	625.00	625.00
1	GRIP HANDLE SET (GPR) F2	NOT NECESSARY	14.00	-
1	HEADLIGHT ASSY	CRACKED	320.00	320.00
1	LAMP SIGNAL FRONT RH	CUT	55.00	55.00
1	LENS SIGNAL FRONT LH	CUT	10.00	10.00
1	LEVER CLUTCH	CUT	13.00	13.00
1	METER ASSY	NOT NECESSARY	328.00	-
1	MIRROR LH	SERVICEABLE	80.00	-
1	MIRROR RH	BROKEN	80.00	80.00
1	RUBBER FOOTREST FRONT	TORN	14.00	14.00
1	STAY HEADLAMP	BENT	68.00	68.00
1	STEERING CONE SET	NECESSARY	68.00	68.00
	LESS 10% DISCOUNT		-	-278.90
			3,211.00	2,510.10
SPECIAL NETT ITEMS				
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT (SN)	NECESSARY	10.00	8.00
			10.00	8.00
LABOUR				
	LABOUR-FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.		175.00	160.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSPORT CHARGES-TOW BACK BIKE FOR ACCIDENT REPAIR. -DELIVER BIKE BACK TO OUTLET.		35.00	35.00
			210.00	195.00
GRAND TOTAL			3,431.00	2,713.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS/EG117022277/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.