

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHB670K

Ref. No

TAX/11/17/2127

Reg. Date

11/12/2015

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS

Name of Driver

: LUEN CHI KEUNG

Type of Accident

SIDE SWIPE

Date / Time of Accident

21/11/2017 09:15:00 AM

Accident Reported Date / Time :

21/11/2017 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024093207

Special Instruction to ARC, if any :

SJE8846D - CHINA TAIPING - LKK / RESUM after synt

Prepared Date

21/11/2017 10:32:55 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U505766976 Mileage

Work Shop :

Repair Completed Date / Time:

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

338.00

0.00

Total Spray Painting Charges

378.00

0.00

Total Material Charges

2,062.86

2,062.86

Other Charges

240.00

0.00

TOTAL

3,018.86

0.00

Lum Sum Total

0.00

0.00

No. of Repair Days

3.00

0.00 2 days - P/

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

: 21/11/2017 04:07:16 PM

01/01/1900 12:00:00 AM

21/11/17 81620

Prepared / Adjusted Date

Remarks

Prepared Date : 21/11/2017 04:07:11 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	338.00	0.00
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REPSRAY FRONT BUMPER	378.00	0.00			
Total Spray Painting & Panel Beating	378.00	0.00			

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted	by Surveyor,	if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00	30	and the second
TO REPLACE SUNDRY PARTS	100.00	0.00	20	
TO WASH AND VACUUM	60.00	0.00	40	
Total Other Costs	240.00	0.00		

Page:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen	Surveyor Approved	Photos Attached
52119- 47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Reptace	No
81170- 47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No
TOTAL MATERIALS							1,212.18	1,212.18		
	TOTAL MATERIALS(Discounted)							2,062.86	2,062.86	100

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check	100
TOTAL SUPPLEMENTARY MATERIALS									Company of	- 100

TAX/11/17/2127