

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

Not Authorized
L/S 82800/2
4 days
vehicle. 4 days
22/11/17

ABWIN 諭輝

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 21/11/2017
TP Vehicle No. : SCV-8181-G
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

Owner : CITICOAT PTE. LTD.
MSIG INSURANCE (SINGAPORE) PTE LTD

Certificate No. : A 28834191

Accident Date: 18/11/2017

Vehicle No. : GBD-4301-K

Make & Model : TOYOTA DYNA 150 MANUAL 3SEATER

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	FRONT BUMPER	344 \$383.00	—
1	FRONT BUMPER BRACKET RH	117 \$165.30	a
1	FRONT BUMPER BRACKET LH	117 \$165.30	x
1	RH HEADLAMP	one \$608.72	—
1	LH HEADLAMP	117 \$608.72	x
1	RH HEADLAMP BRACKET	117 \$95.00	x
1	LH HEADLAMP BRACKET	117 \$95.00	x
1	RH HEADLAMP MOULDING 22.50	70.00 \$135.00	—
1	RH HEADLAMP PANEL	117 \$159.00	x
1	LH HEADLAMP MOUNDING	117 \$53.87	x
1	FRONT GRILLE	117 \$419.56	x
1	FRONT GRILLE MOULDING	117 \$29.85	x
1	FRONT LOGO	117 \$75.90	x
1	FRONT PANEL "DYNA"	117 \$53.50	x
1	FRONT PANEL	117 \$917.89	x
1	RH FRONT DOOR 1649.10	20/34 \$1,703.68	—
1	RH FRONT DOOR STEP GARNISH	117 \$195.00	x
1	RH FRONT DOOR STEP PANEL	117 \$290.21	x
Sub Total		\$6,154.50	
Discount 25% on Parts		(\$1,538.63)	
		\$4,615.88	

2663.32
25%
1997.49

Special Nett

1	FRONT NUMBER PLATE	117 \$65.00	x
1	FRONT DOOR RH STICKER	one \$65.00	30
Sub Total		\$130.00	

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,500.00	700
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	800

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 21/11/2017
TP Vehicle No. : SCV-8181-G
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

Owner : CITICOAT PTE. LTD.
MSIG INSURANCE (SINGAPORE) PTE LTD
Certificate No. : A 28834191
Vehicle No. : GBD-4301-K
Make & Model : TOYOTA DYNA 150 MANUAL 3SEATER

Accident Date: 18/11/2017

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO CHECK ALL NECESSARY WIRINGS	\$150.00	20
	Sub Total	\$3,150.00	
	Sub Total	\$7,895.88	3547.49
	GST 7%	\$552.71	2837
	Total	\$8,448.59	