

22/03/2002

ASS. REC. BY:

REF: CS/FCU7022291 / Amber

Special Instruction:

Survivor: Taulich.

ASSIGNMENT (Office)

From (Person): CWS Karen Tan

of FCI

Date/Time: 21.11.2017 4:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDV 3223 R

Insured:

SHA 7256H

at Workshop m/s

Performance

Tel:

6319 074

of

308 Alexandra Road

Policy No:

Claim No:

D7010820MF5H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/12/017

CA / REV / REP. / REV 24 HRS. DS.

23.11.2017 @ Morning

H.O.D. Endorsement:

Date/Time: 22/11/2017 9:26am

Person Contacted:

Caroline

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SDV 3223 R. X

SHA 7256H - CS/FCU7002105 / K1312

DA 010217

Tanpin

PC1

Date

23-11-2017

SDV 3223R

2011 Sep

Estimated Cost

QD TP WS TP RES CD RES EVA INV MM

Truck/Trailer No

SDV 3223R

at/where damaged

Performance

at

303 Alexandra Rd

Insured

Policy No

Damage No

Sum Insured


Excess

Claims Record

Make of car

Policy Condition

morning



Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value

DAC Accident Report

Consistent? : Yes or No

GLA / PF Seen

Consistent? : Yes or No

Est. Repairs

days

Rest

Yes or No

Lim Sum

%

3 Val

Yes or No

CA / REV / REP / 24 HRS (DS)

Date

Person Contacted

Vehicle IN / OUT

Gang

Truck/Trailer

Make

BMW 523F

2497

Colour

Black

AC Insured Std N/A

Se Reading

96731

T-Pact Insured Std N/A

Eng No

Ch No

WBAFP32080C868 246

Gen Cond Good / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brakes Inorder / Jammed / Leaked / Burnt or

Modif Nil / Body - STD A/Rim or

Tyre Size

F

245/45 R18

R

" "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Continental

Front

Rear

R.Bal

6

mm

R.Bal

6

L.Bal

6

L.Bal

6

D.O.A

D.O.A

23/11/17 @ 1230

Surveyed at

PML

Des of Damages Frt / Rear / O/S / N/S / U/O / Rooftop or

N/S Frt & o/s

The U/O Chassis frame Body Structure affected due to collision

Date Time Action Instruction

27/11/17 email preli to Karen.

26/2. 922,178.85 7 days email to Corinne.

2/3/18 Partby Part 22,178.85 (\$12,560, 0.36%)

2/3/18 File pass to typist

File Time File Passed



Preli. Report

Final Report

Date Time File Received

Days Of Repair

Resurvey No. of Trip

Add Fee



See Fee

S

See Fee

S

See Fee

S

See Fee

S

Receipt Received

P/P

Long Sum

Survey Fee

Transport Fee

24x15 =

170x360

90

90

69

582

659

5/3/18

699



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022291/gb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7256H	Veh. Inspected	SDV 3223R
Policy No.		Coverage (\$)	0.00
Claim No.	D17010820MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	21/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/11/2017	Inspection Date	23/11/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. :

CS/FCI/702291/T/1nb

Policy Type: OD / (TP) TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

C Reference No.
C Customer Code
N Assign From
C Assign Date
C Veh No (Inspected)
C Veh No (Insured)
C D.O.A
C Policy No
C Claim No
C Insurance Authorisation (CA /REV/REP)
C Report Type
C Weekend Charges
N Survey held at/Repairer
C Excess

Y-Date	N-Date	Y-Date	N-Date
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No
C Regn Month/Year
N Vehicle Type
N Make & Model
C Engine Capacity. (C.C)
N Colour
C Odometer. (Sp.Reading)
C Chassis No
N General Condition
N Steering
N Brake
N Modification (Modi)
C Tyre Size
N Tyre Make
C Tyre Balance
C Date of Inspection
N Survey held
N Des.of Damages

/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

--	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition
C Market Value for OD cases
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C Days of repair
C Finalised Amount
C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

--	--	--	--

Check By:

RFA

2/3/2018

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2018

Taufikh (LKK Auto)

From: Taufikh (LKK Auto) [taufikh@lkkauto.com]
Sent: Monday, 26 February 2018 6:03 PM
To: 'PBSP'
Cc: 'SUR'
Subject: RE: FINAL REPORT / SDV3223R

Hi Caroline,

COR \$22,178.85 ,7days.

Regards
Taufikh
Lkk Auto

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Saturday, 24 February 2018 11:37 AM
To: Taufikh (LKK Auto); SUR
Subject: Re: FINAL REPORT / SDV3223R

Dear Taufikh

As requested, please see attached and kindly confirm COR.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Taufikh (LKK Auto) <taufikh@lkkauto.com>
Sent: Thursday, 22 February 2018 6:44:42 PM
To: PBSP
Subject: RE: FINAL REPORT / SDV3223R

Hi Caroline,

Can forward the resurvey photos and before paint?

Regards
Taufikh
Lkk Auto

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Monday, 22 January 2018 4:54 PM
To: taufikh@lkkauto.com; SUR
Subject: FINAL REPORT / SDV3223R

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Norrita (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 22 January 2018 4:54 PM
To: Taufikh (LKKAUTO); SUR
Subject: FINAL REPORT / SDV3223R
Attachments: Final Report SDV3223R.pdf; Final Report SDV3223R_2.pdf

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 10,862.00 ✓
Total Parts : 11,316.85 ✓
Total Labour & Parts : 22,178.85

Repair days: 7

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



bmw 523

Price Range

Depreciation

2011

Vehicle Type

Home » Used Cars » CSH Motors (S) Pte Ltd » BMW 5 Series 523i

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

BMW 5 Series 523i

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price \$77,800

Depreciation \$15,870 /yr

View models with similar depreciation

Reg Date 30-Sep-2011
(3yrs 7mths 3days COE left)

Manufactured 2011

Mileage -

Transmission Auto

Engine Cap 2,497 cc

Road Tax \$1,796 /yr

Power 150.0 kW (201 bhp)
View specs of the BMW 5 Series Sedan (2010-2017)

Curb Weight 1,650 kg

Features Powerful And Fuel Efficient 6 Cylinder Engine, 6 Speed
Auto Transmission, Comfort Access, ABS, Airbags,
Cruise Control, Climate Control, DRL, PDC.

Accessories Premium Leather Seats. Front/Rear Sensors. Xenon
Lights. I-Drive. Electric Memory Seats. Automatic
Headlights. Cruise Control. Bluetooth.

Description Gong Xi Fa Cai. Call Us Now! Down Payment At \$9500
Only! Monthly From \$1077! Well Maintained By Owner!
High Loan Available. The Most Popular BMW F10
5-Series Model Sought After! Call Now To View!



COE \$65,589

OMV \$41,598

ARF \$41,598

Dereg Value \$50,597 as of today (change)

No. of Owners 2



Seller Information

Company

Address

Location

Office No

Contact Person(s)

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7789H

Vehicle Details

Vehicle No.: SDV3223R
Vehicle to be Exported: No
Intended De-registration Date: 26 Feb 2018
Vehicle Make: B.M.W.
Vehicle Model: 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour: Black
Manufacturing Year: 2011
Engine No.: 08777877N52B25AF
Chassis No.: WBAFP32080C868246
Maximum Power Output: 150.0 kW (201 bhp)
Open Market Value: \$48,780.00
Original Registration Date: 29 Sep 2011
First Registration Date: 29 Sep 2011
Transfer Count: 0
Actual ARF Paid: \$48,780.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Sep 2021
PARF Rebate Amount: \$31,707.00

Intended COE Rebate Details

COE Expiry Date: 28 Sep 2021
COE Category: E - Open Category
COE Period(Years): 10

QP Paid:	\$67,000.00
COE Rebate Amount:	\$23,514.00
Total Rebate Amount:	\$55,221.00

The information contained herein is correct as at 26 Feb 2018

OK

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	21-11-2017	Our Ref No. D17010820MFSH
Accident Date	18-11-2017	Claim Type. Third Party
Insured Vehicle	SHA7256H	Third Party Vehicle. SDV3223R
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 63190174	Fax No. 64794601
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230465)



PRI Documents



Close



PRI Header Details

Claim No	D17010820MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PEI LIMITE
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORM Mobile: 63190174 , Phone: 63190174 , Fax: EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7256H	TP Vehicle No	SDV32
PRI Recieved Date	21-11-2017 06:14:31 PM	Surveyor Appointed Date	21-11-2017 04:21:49 PM	Surveyor Accept Date	21-11-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	21-11-2017	Upload Survey Report *:	
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Monday, 27 November, 2017 4:31 PM
To: 'Claim Workflow System'
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010820MFSH/1
Attachments: SDV 3223R.pdf

Dear Karen,

Enclosed herewith preliminary advise of vehicle SDV 3223R.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 22 November, 2017 9:28 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010820MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 21 November, 2017 4:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010820MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010820MFSH

Date: 27-11-2017

Our Ref: CS/FCI17022291/T1gb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SDV 3223R

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23-11-2017 at the premises of M/s PERFORMANCE MOTORS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>33,573.18</u>
Revised Estimate Amount	: S\$ <u>10,882.90</u>
"Check" Items Amount	: S\$ <u>14,787.20</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s front and o/s body.



Yours faithfully

Mohamed Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2017 12:57
Date Of Accident	18/11/2017 10:25
Exact Location Of Accident	20 COUNTRYSIDE ROAD S (789786)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDV3223R
Insured/Policyholder	
Name Of Registered Owner	SEE LAY CHOO
NRIC No	S1587789H
Email Address	SHIRLEY@LIANYICK.COM.SG
Mobile Phone No	(LOCAL) +65-96910332
Alternative Phone No	OFFICE-84993245

Vehicle Particulars

Manufacturer	BMW
Model	523
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100427786
Cover Note Number	

Driver

Name of Driver	LIM SU ZHEN YVONNE
NRIC No	S8821144H
Date Of Birth	16/06/1988
Occupation	INDOOR
Date Of Driving Pass	07/04/2007
Driving Experience	10 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84993245
Fax Number	
Contact Number	
EMail Address	UTTER.VONN@GMAIL.COM

Address	115 MARIAM WAY
Postcode	508618
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7256H
Vehicle Make/Model/Colour	COMFORT DELGRO BLUE TAXI
Details Of Properties	
Name of Driver	CHUNG CHAN HONG
NRIC/Passport Number	S0578330E
Contact Number	90705857
Address	BLK 432A YISHUN AVE 1#07-523
Postcode	761432
Insurance Company Name	FIRST CAPITAL INSURANCE LTD
Nature Of Damage	LEFT RIGHT
No. Of Passenger (Including Driver)	1

Details of Witness

Name	CEDRIC/MATHI/GUNA
Phone Number	97961179/94723225/81660038
Email Address	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time: *[Signature]* 20 NOV 2017 11am
 Driver's Signature (If driver is not the policyholder) / Date & Time: *[Signature]* 20 NOV 2017 10am
 Witnessed By Reporting Centre Personnel: *[Signature]* 20/11/17 11:30
 GARY POH CHAI HOON
 Performance Motors Limited
 303 Alexandra Road
 Singapore 159841

Sketch Plan



Sketch Plan Pg. 2


Describe Circumstances of the Accident


Car parked outside 20 country side Road (Private estate), on 18 NOV 2017. At approx 3.30am neighbours notified us that a taxi have banged onto the BMW car (SDV3223R). Witness names have been provided on page 1, as they heard the bang and the taxi have parked near their house as it is also damaged at the wheels and can't be driven further. Traffic police responded to the neighbour's call, Sgt Alif at 4.10am. No report taken as police advised the ^{taxi} driver is at fault, no alcohol found. Probably just sleepy and driver claim he was trying to pick up something. However, he have a police report after for claim's with comfort delco to ensure claims can be expedited and smooth. Report¹⁰ given on page 1 if required.

Damage : • Car sway to the left side hitting kerb.
• Taxi hit the driver side wheel, door, mirror, came off, bumper, struts, wheels badly aligned hitting the bumper, check signal lights, door,

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time
20 NOV 2017
11am

 - 20 NOV 2018
Driver's Signature (if driver is not the policyholder) / Date & Time

GARY POH CHAI HOON
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Witnessed by Reporting Centre Personnel

To whom it may concern,

I, Madam See Lay Choo, Nric No. S1587789H, Authorized,

My Daughter ,Ms Lim Su Zhen, Nric No. of S8821144H,

To act on behalf of me; for all things that need to this report and for AIG authorised dealer
Progressive automotive Pte Ltd, On the accident reporting.

Thank you for the kind attention given .

Yours Sincerely

A handwritten signature in black ink, appearing to read 'See Lay Choo', with a large, sweeping loop at the end.

See Lay Choo

Hp . 96910332

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Page No. :

Estimate No. : b1 44898
Date Estimated : 20/11/2017
Prepared By : Gary Poh Chai Hoon

REPAIR FOR -
See Lay Choo
115 Mariah Way

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 508618

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	ORIGINAL PRICE	DISC. %	NETT
SDV3223R	C868246	29/09/2011	523iA	0			
DESCRIPTION							
To make good the front bumper, front RH fender, front RH door include removing attachments to facilitate repairs and knocking out dents caused by the accident					2550.00		2,550.00 ✓
To spray paint front bumper, front RH fender and front RH door and RH wingmirror cover					2594.00		2,594.00 ✓
# To conduct checks on all doors and boot lid central locking system for proper function					150.00		150.00 (A)
To tow accident vehicle to PML workshop.					195.00		195.00 ✓
To replace front RH wheel rim include balancing (1x)					80.00		80.00 ✓
To replace front LH wheel rim include balancing (1x)					80.00		80.00 ✓
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (2x)					902.00		902.00 ✓
To remove and install front suspension for inspection include replacement of damaged parts					2256.00		2,256.00 ✓
* To replace electromechanical power steering include programming, initializing steering column adjustment and conducting checks for proper function					752.00		752.00 (A)
# To diagnose and replace park assistant ultrasonic converter include programming and conducting checks for proper function					150.00		150.00 (A)
# To remove and install brake discs, brake pads, brake hoses and brake calipers include bleeding of brake system, conduct brake tests and checks for leak					853.00		853.00 (A)
# To check electrical wiring system at the front section for proper function include adjustment of headlights					150.00		150.00 (A)
Sundries					150.00		150.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HEX NUT WITH FLANGE M16X1.5-10 ZNN1 *	9.65	2.00		19.30 (A)
# HEX NUT WITH FLANGE M16X1.5-10 ZNN1 *	9.65	1.00		9.65 (A)
WISHBONE TOP	529.00	1.00		529.00
RH TENSION STRUT W/RUBBER MOUNTING ✓	480.90	1.00		480.90
# CONTROL ARM CAMBER CORRECTION-30MIN *	687.65	1.00		687.65 (A)
RH WISHBONE W/RUBBER MOUNTING ✓	577.05	1.00		577.05
WHEEL HUB WITH BEARING FRT	503.00	1.00		503.00
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	4.00		30.80 (A)
FRT RH CARRIER	599.70	1.00		599.70
FRT GUIDE SUPPORT	144.15	1.00		144.15
FRT RH SPRING STRUT	586.20	1.00		586.20
FRONT SWING SUPPORT	107.90	1.00		107.90
RH TIE ROD	297.70	1.00		297.70
EXCH STEERING BOX ELECTR.	4,369.95	1.00		4,369.95
# SELF-LOCKING HEX NUT *	2.70	1.00		2.70 (A)
# ALLOY RIM 8JX18 V SPOKE STY 328 *	919.90	1.00		919.90 (A)
ALLOY RIM 8JX18 V SPOKE STY 328	919.90	1.00		919.90
# HEX NUT WITH FLANGE *	3.05	2.00		6.10 (A)
RH WINGMIRROR COVER (PRIMED)	141.60	1.00		141.60
# RH ADDITIONAL TURN INDICATOR LAMP *	81.65	1.00		81.65 (A)
# ULTRASONIC CONVERTER PARK ASSISTANT *	302.05	1.00		302.05 (A)

SUPPLEMENTARY ITEMS

Total Labour :	10,862.00
Total Parts :	11,316.85
Total Labour & Parts :	22,178.85
Deduction for Excess :	0.00
Total Repair Costs less Excess:	22,178.85
GST @7%:	1,552.52
Grand Total :	23,731.37

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

#CAR 115 H
20 NOV 2017

REC: G. Supri

Estimate No. : b1 44898
Date Estimated : 20/11/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

See Lay Choo
115 Mariam Way

Singapore 508618

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDV3223R	C868246	29/09/2011	523iA	0

DESCRIPTION

VALUE

To replace front bumper, right front fender, and right front door and right mirror cover and attachment include knocking cause by the accident

✓ 2550 300.00

painting front bumper, right front fender, right front door, right mirror cover.

82594 ✓

2593 2,882.00

To carry out body cavity preservation.
(Per panel).

200. 236.00

To tow accident vehicle to PML workshop.

✓ 195.00

To replace right front rim including balancing. (1x).

880.00 ✓

x79 94.00

To replace left front rim including balancing. (1x).

880.00 ✓

x79 94.00

To replace right front tyre continental v245/45/18

un X 340 80%? 425.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (2x).

✓ 902 1,062.00

To remove and install front suspension for inspection and replace damaged parts.

✓ 2256 2,655.00

To remove and install power steering pump, power steering rack and pinion to facilitate repairs.

4517 531.00

Sundries.

8150.00 ✓

7 150.00

Total Labour 1: 11,724.00

DESCRIPTION

QTY PRIC

VALUE

FRONT AXLE SUPPORT X 1

1 1,799.00

529 1,799.00

WISHBONE TOP 2 X 1

1 529.00

529 1,058.00

LH TENSION STRUT W/RUBBER MOUNTING X 1

1 480.90

480.90

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44898
Date Estimated : 20/11/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDV3223R	C868246	29/09/2011	523ia	0

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
RH TENSION STRUT W/RUBBER MOUNTING ? bt ✓	1	480.90 ✓	480.90 ✓
LH WISHBONE W/RUBBER MOUNTING ? Kun ✓	1	577.05 ✓	577.05
RH WISHBONE W/RUBBER MOUNTING ? bt ✓	1	577.05 ✓	577.05 ✓
WHEEL HUB WITH BEARING FRT ? bt ✓	1	503.00 ✓	503 ✓ 1,006.00
FRT RH CARRIER ? bt ✓	1	453.70 599.70 ✓	453.70
FRT GUIDE SUPPORT ? bt ✓	2	144.15 ✓	288.30
FRT LH SPRING STRUT ? Kun ✓	1	586.20 ✓	586.20
FRT RH SPRING STRUT ? bt ✓	1	586.20 ✓	586.20
SPRING PAD LOWER Kun ✓	2	15.15	30.30
SPRING PAD UPPER Kun ✓	2	17.80	35.60
FRONT SWING SUPPORT ? bt ✓	2	107.90 ✓	215.80
STABILIZER FRT W/RUBBER MOUNTING Kun ✓	1	457.85	457.85
LH TIE ROD Kun ✓	1	297.70 ✓	297.70
RH TIE ROD ? bt ✓	1	297.70 ✓	297.70
EXCH STEERING BOX ELECTR. ? bt ✓	1	4,369.95 ✓	4,369.95
ALLOY RIM 8JX18 V SPOKE STY 328 ant ✓	2	919.90 ✓	1,839.80
HUB CAP WITH CHROME EDGE (BMW) next Kun ✓	2	23.75	47.50
FRT RH DOOR Rx ✓	1	1,689.00	1,689.00
FRT RH FENDER Rx ✓	1	842.30	842.30
FRT BUMPER TRIM PRIMED (PDC) Rx ✓	1	1,246.40	1,246.40
RH WINGMIRROR COVER (PRIMED) ant ✓	1	141.60 ✓	141.60
FRT RH COVER F REAR WHEELHOUSE Kun ✓	1	124.00	124.00
FRT RH WHEEL ARCH COVER Kun ✓	1	124.00	124.00

Total Parts : 19,652.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

23/11/17 @ 1230
Tanjah
92493749

by this

28/11/17

Tanjah & Lkkauto.com
⑦ - 8 days

Labour 1	:	11,724.00
Parts	38717.70 :	19,652.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,196.38
Grand Total	:	33,573.18

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Supplementary

3362.80

711.420.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44898
Date Estimated : 20/11/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
See Lay Choo
115 Mariam Way

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 508618

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SDV3223R	C868246	29/09/2011	523ia	0

Supplementary

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# To conduct checks on all doors and boot lid central locking system for proper function	150.00		150.00
# To diagnose and replace park assistant ultrasonic converter include programming and conducting checks for proper function	150.00		150.00
# To remove and install brake discs, brake pads, brake hoses and brake calipers include bleeding of brake system, conduct brake tests and checks for leak	853.00		853.00
# To check electrical wiring system at the front section for proper function include adjustment of headlights	150.00		150.00

To replace electromechanical power steering include programming, initializing steering column adjustment and conducting checks for proper function. # 752 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# HEX NUT WITH FLANGE M16X1.5-10 ZNN1 *	9.65	2.00		19.30 ne ✓
# HEX NUT WITH FLANGE M16X1.5-10 ZNN1 *	9.65	1.00		9.65 ne ✓
# CONTROL ARM CAMBER CORRECTION-30MIN *	687.65	1.00		687.65 bt ✓
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	4.00		30.80 ne ✓
# SELF-LOCKING HEX NUT *	2.70	1.00		2.70 ne ✓
# ALLOY RIM 8JX18 V SPOKE STY 328 * Fit LK	919.90	1.00		919.90 ext ✓
# HEX NUT WITH FLANGE *	3.05	2.00		6.10 ne ✓
# RH ADDITIONAL TURN INDICATOR LAMP *	81.65	1.00		81.65 ext ✓
# ULTRASONIC CONVERTER PARK ASSISTANT *	302.05	1.00		302.05 ne ✓

Total Labour : 1,303.00
Total Parts : 2,059.80
Total Labour & Parts : 3,362.80

3140 90



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale des Experts en Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022291/T1nbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 07-03-2018



Code : FCI2

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SHA 7256H	Veh. Inspected	SDV 3223R
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17010820MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	21/11/2017

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 523i	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAFP32080C868246	Colour	BLACK
Odometer	96731	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	CONTINENTAL	6 mm
L/H Front Tyre	245/45 R18	CONTINENTAL	6 mm
R/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm
L/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND N/S FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	18/11/2017	Inspection Date	23/11/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days for Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDV 3223R

Qty	Description of Parts	Condition	Estimate Price Workshop (\$)	Estimate Price Roadside (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	FRONT AXLE SUPPORT (SN)	NOT NECESSARY	1,799.00	-
2	WISHBONE TOP (SN)	BENT-1PC ONLY	1,058.00	529.00
1	LH TENSION STRUT W/RUBBER MOUNTING (SN)	NOT NECESSARY	480.90	-
1	RH TENSION STRUT W/RUBBER MOUNTING (SN)	BENT	480.90	480.90
1	LH WISHBONE W/RUBBER MOUNTING (SN)	NOT NECESSARY	577.05	-
1	RH WISHBONE W/RUBBER MOUNTING (SN)	BENT	577.05	577.05
2	WHEEL HUB WITH BEARING FRT (SN)	BENT-1PC ONLY	1,006.00	503.00
1	FRT RH CARRIER (SN)	BENT	599.70	599.70
2	FRT GUIDE SUPPORT (SN)	BENT	288.30	144.15
1	FRT LH SPRING STRUT (SN)	NOT NECESSARY	586.20	-
1	FRT RH SPRING STRUT (SN)	BENT	586.20	586.20
2	SPRING PAD LOWER (SN)	NOT NECESSARY	30.30	-
2	SPRING PAD UPPER (SN)	NOT NECESSARY	35.60	-
2	FRONT SWING SUPPORT (SN)	BENT-1PC ONLY	215.80	107.90
1	STABILIZER FRT W/RUBBER MOUNTING (SN)	NOT NECESSARY	457.85	-
1	LH TIE ROD (SN)	NOT NECESSARY	297.70	-
1	RH TIE ROD (SN)	BENT	297.70	297.70
1	EXCH STEERING BOX ELECTR (SN)	BENT	4,369.95	4,369.95
2	ALLOY RIM 8JX18 V SPOKE STY 328 (SN)	CUT	1,839.80	1,839.80
2	HUB CAP WITH CHROME EDGE (BMW) (SN)	NOT NECESSARY	47.50	-
1	FRT RH DOOR (SN)	TO REPAIR SEE LABOUR	1,689.00	-
1	FRT RH FENDER (SN)	TO REPAIR SEE LABOUR	842.30	-
1	FRT BUMPER TRIM PRIMED (PDC) (SN)	TO REPAIR SEE LABOUR	1,246.40	-
1	RH WINGMIRROR COVER (PRIMED) (SN)	CUT	141.60	141.60
1	FRT RH COVER F REAR WHEELHOUSE (SN)	NOT NECESSARY	124.00	-
1	FRT RH WHEEL ARCH COVER (SN)	NOT NECESSARY	124.00	-
2	HEX NUT WITH FLANGE M16X1.5-10 ZNN1 (SN) (ADDITIONAL)	NECESSARY	19.30	19.30

Report Ref No. CS/FCI17022291/T1nbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimated Price (S)	Actual Price (S)
1	HEX NUT WITH FLANGE M16X1.5-10 ZNN1 (SN) (ADDITIONAL)	NECESSARY	9.65	9.65
1	CONTROL ARM CAMBER CORRECTION-30MIN (SN) (ADDITIONAL)	BENT	687.65	687.65
4	SPHERICAL COLLAR SCREW M12X1.25X45 @\$7.70 (SN) (ADDITIONAL)	NECESSARY	30.80	30.80
1	SELF-LOCKING HEX NUT (SN) (ADDITIONAL)	NECESSARY	2.70	2.70
2	HEX NUT WITH FLANGE (SN) (ADDITIONAL)	NECESSARY	6.10	6.10
1	RH ADDITIONAL TURN INDICATOR LAMP (SN) (ADDITIONAL)	CUT	81.65	81.65
1	ULTRASONIC CONVERTER PARK ASSISTANK (SN) (ADDITIONAL)	NOT WORKING	302.05	302.05
			21,088.70	11,466.85
LABOUR				
TO REPLACE FRONT BUMPER, RIGHT FRONT FENDER, AND RIGHT FRONT DOOR AND RIGHT MIRROR COVER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT RH DOOR, FRT RH FENDER AND FRT BUMPER TRIM PRIMED (PDC).			3,400.00	2,550.00
PAINTING FRONT BUMPER, RIGHT FRONT FENDER, RIGHT FRONT DOOR, RIGHT MIRROR COVER.			2,882.00	2,594.00
TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)		NOT NECESSARY	236.00	-
TO TOW ACCIDENT VEHICLE TO PML WORKSHOP.			195.00	195.00
TO REPLACE RIGHT FRONT RIM INCLUDING BALANCING (1X).			94.00	80.00
TO REPLACE LEFT FRONT RIM INCLUDING BALANCING (1X).			94.00	80.00
TO REPLACE RIGHT FRONT TYRE CONTINENTAL V245/45/18.		NOT NECESSARY	425.00	-
TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS (2X).			1,062.00	902.00
TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION AND RPELACE DAMAGED PARTS.			2,655.00	2,256.00
TO REMOVE AND INSTALL POWER STEERING PUMP, POWER STEERING RACK AND PINION TO FACILITATE REPAIRS.		NOT NECESSARY	531.00	-

Report Ref No. CS/FC117022291/T1nbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Part	Condition	Estimated By Workshop (\$)	Est. Adjusted (\$)
	TO CONDUCT CHECKS ON ALL DOORS AND BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION. (ADDITIONAL)		150.00	150.00
	TO REPLACE ELECTROMECHANICAL POWER STEERING INCLUDE PROGRAMMING, INITIALIZING STEERING COLUMN ADJUSTMENT AND CONDUCTING CHECKS FOR PROPER FUNCTION. (ADDITIONAL)		752.00	752.00
	TO REMOVE AND INSTALL BRAKE DISCS, BRAKE PADS, BRAKE HOSES AND BRAKE CALIPERS INCLUDE BLEEDING OF BRAKE SYSTEM, CONDUCT BRAKE TESTS AND CHECKS FOR LEAK. (ADDITIONAL)		853.00	853.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDE ADJUSTMENT OF HEADLIGHTS. (ADDITIONAL)		150.00	150.00
	TO DIAGNOSE AND REPLACE PARK ASSISTANCE ULTRASONIC CONVERTER INCLUDE PROGRAMMING AND CONDUCTING CHECKS FOR PROPER FUNCTION. (ADDITIONAL)		150.00	150.00
			13,629.00	10,712.00
GRAND TOTAL			34,717.70	22,178.85

RECOMMENDED COST OF REPAIRS

22,178.85

Report Ref No. CS/FCI17022291/T1nbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.