

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44898
Date Estimated : 20/11/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
See Lay Choo
115 Mariam Way

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 508618

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SDV3223R	C868246	29/09/2011	523ia	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To conduct checks on all doors and boot lid central locking system for proper function	150.00		150.00
# To diagnose and replace park assistant ultrasonic converter include programming and conducting checks for proper function	150.00		150.00
# To remove and install brake discs, brake pads, brake hoses and brake calipers include bleeding of brake system, conduct brake tests and checks for leak	853.00		853.00
# To check electrical wiring system at the front section for proper function include adjustment of headlights	150.00		150.00

To replace electromechanical power steering include programming, initializing steering column adjustment and conducting checks for proper function. # 752 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HEX NUT WITH FLANGE M16X1.5-10 ZNN1 *	9.65	2.00		19.30 rec ✓
# HEX NUT WITH FLANGE M16X1.5-10 ZNN1 *	9.65	1.00		9.65 rec ✓
# CONTROL ARM CAMBER CORRECTION-30MIN *	687.65	1.00		687.65 bt ✓
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	4.00		30.80 new ✓
# SELF-LOCKING HEX NUT *	2.70	1.00		2.70 new ✓
# ALLOY RIM-8JX18-V-SPOKE STY-328 * Part L1	919.90	1.00		919.90 cut ✓
# HEX NUT WITH FLANGE *	3.05	2.00		6.10 new ✓
# RH ADDITIONAL TURN INDICATOR LAMP *	81.65	1.00		81.65 cut ✓
# ULTRASONIC CONVERTER PARK ASSISTANT *	302.05	1.00		302.05 new ✓

Total Labour : 1,303.00
Total Parts : 2,059.80
Total Labour & Parts : 3,362.80

3194.90