

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9981D - III****AAD1711-203***Not Authored**1/1/17*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHB9981D - CANDY**  
 VF1ABL15AUC273530  
 RENAULT  
 LATITUDE  
 19.11.2017  
**III**

| PART |   |                                 | LIST |                         |
|------|---|---------------------------------|------|-------------------------|
| 1    | 1 | BUMPER COVER FRT                | \$   | <i>Bulld</i> 1,259.42 ✓ |
| 2    | 1 | BUMPER SPOILER FRT              | \$   | <i>Sm</i> 181.75 X      |
| 3    | 1 | BUMPER FOG LAMP GRILLE LH       | \$   | <i>Sm</i> 207.22 X      |
| 4    | 1 | BUMPER RETAINER FRT LH          | \$   | <i>Dis</i> 151.41 ✓     |
| 5    | 1 | BUMPER RETAINER FRT RH          | \$   | <i>Sm</i> 151.41 X      |
| 6    | 1 | BUMPER SUPPORT FRT LH           | \$   | <i>Sm</i> 123.88 X      |
| 7    | 1 | BUMPER SUPPORT FRT RH           | \$   | <i>Sm</i> 123.88 X      |
| 8    | 1 | BUMPER BEAM FRT                 | \$   | <i>R</i> 914.08         |
| 9    | 1 | RADAITOR GRILLE                 | \$   | <i>Sm</i> 1,707.78      |
| 10   | 1 | RADAITOR GRILLE BADGE 'RENAULT' | \$   | <i>nn</i> 225.36        |
| 11   | 1 | RADAITOR GRILLE FRAME           | \$   | <i>Sm</i> 1,353.75      |
| 12   | 1 | AIR CLEANER LOWER               | \$   | <i>Sm</i> 352.64        |
| 13   | 1 | AIR CLEANER HOSE                | \$   | <i>Sm</i> 76.14         |
| 14   | 1 | BONNET                          | \$   | <i>R</i> 1,941.63       |
| 15   | 1 | BONNET HINGE LH                 | \$   | <i>R</i> 348.31         |
| 16   | 1 | BONNET STRUT LH                 | \$   | <i>Sm</i> 88.61         |
| 17   | 1 | HEADLAMP LH                     | \$   | <i>Sm</i> 1,184.43      |
| 18   | 1 | HEADLAMP PANEL FRT LH           | \$   | <i>R</i> 152.15         |
| 19   | 1 | FENDER PANEL FRT LH             | \$   | <i>Bul</i> 783.83       |
| 20   | 1 | FENDER INSULATOR LH             | \$   | <i>Sm</i> 130.84        |
| 21   | 1 | WHEELARCH FRT LH                | \$   | <i>Sm</i> 278.84        |
| 22   | 1 | DOOR MIRROR LH                  | \$   | <i>Sm</i> 1,483.40      |
| 23   | 1 | DOOR MIRROR GLASS LH            | \$   | <i>Sm</i> 148.20        |
| 24   | 1 | DOOR MIRROR BACK COVER LH       | \$   | <i>Sm</i> 218.46        |
| 25   | 1 | DOOR PANEL FRT LH               | \$   | <i>R</i> 2,844.66       |
| 26   | 1 | DOOR HINGE UPPER LH             | \$   | <i>R</i> 274.50         |
| 27   | 1 | DOOR HINGE LOWER LH             | \$   | <i>R</i> 300.55         |

|              |    |           |
|--------------|----|-----------|
| <b>TOTAL</b> | \$ | 17,007.13 |
| <b>10%</b>   | \$ | 1,700.71  |
|              | \$ | 15,306.42 |

**Special Nett**

**TRANS-CAB AUTO SERVICES PTE LTD**

AAD1711-203

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB 9981D - III**

|    |      |                              |    |                    |
|----|------|------------------------------|----|--------------------|
| 1  | 1SET | FRONT BUMPER CLIP            | \$ | <i>nn</i> 66.00 ✓  |
| 2  | 1SET | WHEELARCH CLIP LH            | \$ | <i>nn</i> 66.00 X  |
| 3  | 1    | TOW COVER FRT                | \$ | <i>nn</i> 14.50 X  |
| 4  | 1    | CAP HUB LH FRT               | \$ | <i>nn</i> 35.00 X  |
| 5  | 1    | RIM LH FRT                   | \$ | <i>nn</i> 385.00 X |
| 6  | 1    | TYRE LH FRT                  | \$ | <i>nn</i> 330.00 X |
| 7  | 1SET | BUMPER SUPPORT FRT CLIP LH   | \$ | <i>nn</i> 9.80 X   |
| 8  | 1SET | BUMEP R RETAINER FRT CLIP LH | \$ | <i>nn</i> 12.50 X  |
| 9  | 1    | DOOR STICKER "Trans-cab"     | \$ | <i>nn</i> 80.00 X  |
| 10 | 1    | DOOR STICKER "Classic"       | \$ | <i>nn</i> 30.00 X  |

|                    |    |                  |
|--------------------|----|------------------|
| <b>TOTAL</b>       | \$ | <b>1,028.80</b>  |
| <b>TOTAL PARTS</b> | \$ | <b>16,335.22</b> |

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *400*

To Check Electrical Lighting Concerned.

\$ 170.00 *150*

Putty and spray painting of the affected portion.

\$ 3,000.00 *440*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 *30*

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *nn* 170.00 X

|                       |    |                  |
|-----------------------|----|------------------|
| <b>TOTAL</b>          | \$ | <b>6,700.00</b>  |
| <b>Over All Total</b> | \$ | <b>23,035.22</b> |

**(PARTS BY PARTS) Repair Days**

- the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**10 Days***2 days*