

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	10	SET BUMPER LOWER REAR CLIP	Reviewing	66	NECESSARY	
	11	EXHAUST MOUNTING REAR	Reviewing	0	SERVICEABLE	
	12	SET BOOT FINISHER CLIP	Reviewing	0	NOT NECESSARY	
	13	BOOT STICKER "TRANS-CAB"	Reviewing	0	NOT NECESSARY	
	14	BOOT STICKER "6555-3333"	Reviewing	0	NOT NECESSARY	
	15	BOOT INNER TRIM CLIP	Reviewing	0	NOT NECESSARY	
	16	SET FENDER WHEELARCH REAR RH CLIP	Reviewing	0	NOT NECESSARY	
	17	SE FENDER WHEELARCH REAR LH CLIP	Reviewing	0	NOT NECESSARY	
	18	TAILLAMP CLIP RH	Reviewing	0	NOT NECESSARY	
	19	TAILLAMP CLIP LH	Reviewing	0	NOT NECESSARY	
	20	REAR WINDSCREEN SEALANT	Reviewing	0	NOT NECESSARY	
	21	WINDSCREEN MOULDING	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	7		TO DROP REAR EXHAUST BOX. RENEW THE SAME. TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	0	0	0	Reviewing		
	8		TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	9		TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing		
	10		TOWING FEE.	0	0	0	Reviewing		
	11		TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	0	0	0	Reviewing		
	12		TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	0	0	0	Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRI/ BTR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	12	1			BUMPER BEAM BRACKET RH REAR			Repair	0		10		0	Reviewing	
	13	1			BOOT REAR			Repair	0		10		0	Reviewing	
	14	1			BOOT FINISHER			Serviceable	0		10		0	Reviewing	
	15	1			BOOT WEATHERSTRIP			Serviceable	0		10		0	Reviewing	
	16	1			BOOT REFLECTOR LAMP LH			Serviceable	0		10		0	Reviewing	
	17	1			BOOT REFLECTOR LAMP RH			Serviceable	0		10		0	Reviewing	
	18	1			BOOT BADGE "RENAULT"			Serviceable	0		10		0	Reviewing	
	19	1			BOOT BADGE			Serviceable	0		10		0	Reviewing	
	20	1			BOOT SWITCH			Serviceable	0		10		0	Reviewing	
	21	1			BOOT LOCK			Repair	0		10		0	Reviewing	
	22	1			BOOT LOCK CATCH			Repair	0		10		0	Reviewing	
	23	2			LICENCE PLATE LAMP			Serviceable	0		10		0	Reviewing	
	24	2			BOOT RUBBER PLUG			Serviceable	0		10		0	Reviewing	
	25	1			FENDER PANEL REAR LH			Repair	0		10		0	Reviewing	
	26	1			WHEELARCH REAR LH			Serviceable	0		10		0	Reviewing	
	27	1			FENDER PANEL REAR RH			Repair	0		10		0	Reviewing	
	28	1			WHEELARCH REAR RH			Serviceable	0		10		0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured		0	License Issue Date		mm/dd/yyyy
Market Value		0	License Expiration Date		mm/dd/yyyy
			Address	Singapore	
			Address type	Personal Correspondence	v
			Gender	Unknown	v
			Marital status	Unknown	v
			Identification #	51182493E	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	7/25/18 5:24 PM	1850	1850	Open	Share	Clone
ANG Flossie	11/23/17 9:41 AM	2334.57	2334.57	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKK RESURVEY PHOTO-AFTER REPAIR.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 10, 2018
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 26, 2018
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 26, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	July 26, 2018
Immediate Advice (with mandate) dated 26.07.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 26, 2018
LKK SURVEY PHOTO.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 26, 2018
PRAF and COE rebate form.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 26, 2018
Preliminary Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 23, 2017
SHC5312G TP GIA REPORT.pdf	Reports & Statement	GIA Report	DHIWAR Namrata	November 23, 2017
SJZ1028J INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	November 23, 2017
TP SHC5312G EST.pdf	Forms / Claim Documents	Estimate / Quotation	DHIWAR Namrata	November 23, 2017
TP-SHC5312G/LKK EMAIL.pdf	Other	Other	DHIWAR Namrata	November 23, 2017