

SJV7558C

TP/AIG

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761

TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg

GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 20/11/2017

Estimate No: ES1791339/WS

Date: 24 Nov 2017

Policy No: 5040883560-07

Veh Reg No: **SJV7558C**

Make/Model: TOYOTA VIOS J AUTO

Chassis No: MR053HY9305139185

Engine No: 1NZX967726

Reg. Date: 17/12/2009

Estimate Repair Cost to Vehicle No :SJV7558C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR LH DOOR	813.70	1 PC	By 813.70	✓
2 REAR LH DOOR INNER RUBBER	165.60	1 PC	165.60	?
3 REAR LH DOOR FRAME STICKER	57.80	1 PC	Mr 57.80	✓
4 REAR LH FENDER	989.60	1 PC	By 989.60	✓
5 REAR WINDSCREEN MOULDING	109.20	1 PCS	Mr 109.20	✓
6 REAR BUMPER	477.60	1 PC	By 477.60	✓
7 REAR BUMPER LH SIDE RETAINER	84.90	1 PC	By 84.90	✓
8 REAR BUMPER CLIPS	3.89	6 PCS	Mr 23.34	✓
9 FRONT LH TYRE RIM	218.90	1 PCS	Red 218.90	508sn
10 FRONT LH SHOCK ABSORBER	397.84	1 PC	397.84	?
11 FRONT LH KNUCKLE ARM	393.10	1 PC	393.10	?
12 FRONT LH WHEEL BEARING	145.80	1 PC	145.80	?
13 FRONT LH LOWER ARM	882.20	1 PC	882.20	?
14 REAR LH WHEEL BEARING	667.70	1 PC	667.70	?
15 REAR LH TYRE RIM	218.90	1 PCS	1 Red 218.90	✓
			5,646.18	
		Less 25%	1,411.55	4,234.64
Special Net				
16 FRONT LH TYRE	150.00	1 PC	Per 150.00	508sn
17 REAR WINDSCREEN GUM	40.00	1 PC	Mr 40.00	✓
			190.00	190.00
Labour				
18 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
19 REMOVE AND REFIX SEAT, CARPET, TOP-ROOF LINING	120.00	1 LA	120.00	100

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP-AIG
Claim Type: Third Party
Accident Date: 20/11/2017

Estimate No: ES1791339/WS
Date: 24 Nov 2017
Policy No: 5040883560-07
Veh Reg No: SJV7558C
Make/Model: TOYOTA VIOS J AUTO
Chassis No: MR053HY9305139185
Engine No: 1NZX967726
Reg. Date: 17/12/2009

Estimate Repair Cost to Vehicle No :SJV7558C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
20 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMP , REAR LH DOOR ATTACHMENTS, TO CUTTING, WELDING AND RENEW REAR LH FENDER, TO KNOCK AND REPAIR REAR LH WHEEL BEARING AND REALIGN THE SAME	980.00	1 LA	980.00	980.00
21 PUTTY AND RESPRAY ON REAR LH DOOR, REAR LH FENDER, REAR BUMPER, FUEL DOOR PANEL, REAR LH WHEEL HOUSING AND ALL AFFECTED AREA	900.00	1 LA	900.00	900.00
22 REMOVE AND REFIX FRONT AND REAR LH UNDER CARRIAGE	300.00	1 LA	300.00	300.00
23 RUSTPROOFING	60.00	1 LA	60.00	60.00
24 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	60.00
			2,540.00	2,540.00
			Total	S\$ 6,964.64
			Add GST @ 7%	487.52
			Total Amount Payable	S\$ 7,452.16

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____