

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP AIG

Claim Type: Third Party

Accident Date: 20/11/2017

TP Veh Reg No: SLG6253T

Estimate No: ES1791458/WS

Date: 28 Dec 2017

Policy No:

Veh Reg No: SDL8138Z

Make/Model: MITSUBISHI LANCER
 1.6 GLX 5MT

Chassis No: JMYSNCS3AAU000283

Engine No: 4G18KD4575

Reg. Date: 01/04/2010

Estimate Repair Cost to Vehicle No :SDL8138Z

Description	U/Price	Quantity	List Price	Amount
Net Price			SS	SS
1 FRONT BUMPER	646.00	1 PC	646.00	—
2 FRONT BUMPER SIDE RETAINER RH	41.00	1 PC	41.00	—
3 FRONT BUMPER LOWER SKIRT	602.00	1 PC	602.00	X
4 FRONT BUMPER CLIP	3.50	6 PC	21.00	—
5 HEADLAMP RH	314.00	1 PC	314.00	7
			1,624.00	
		Less 10%	162.40	1,461.60
Special Net				
6 FRONT RH FENDER MOULDING	120.00	1 PC	120.00	120.00
Labour				
7 REMOVE AND REFIX FRT BUMPER ASSY, GARNISH, HEADLAMP, LOWER SKIRT, KNOCK AND REPAIR FRT RH FENDER AND RE-ALIGN TO SAME	350.00	1 LA	350.00	300
8 PUTTY AND RESPRAY ON FRT BUMPER, REINFORCEMENT, FRT RH FENDER AND ALL AFFECTED AREAS	480.00	1 LA	480.00	400
			830.00	830.00

Total SS 2,411.60

Add GST @ 7% 168.81

Total Amount Payable SS 2,580.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE