

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05671

Vehicle Insured : SLH7610J
Accident Date : 19-Nov-2017

Date : 21-Nov-2017

Our Ref : 217176 (AIG) / CHAN

PAGE : 1

M/S LOUIS BUS TRANSPORT SERVICES
514 PASIR RIS STREET 52
#05-93
Singapore 510514

*Not Notified
11 Nov 87
Henry Ate Paim*

ESTIMATED COST OF REPAIR FOR MIT.ROSA 3.0 PC3092J

1 pc	Front body panel	<i>B</i>	2,995.22	✓
1 pc	Front body panel "FUSO" sticker	<i>m</i>	93.52	✓
1 pc	Front body panel logo	<i>m</i>	59.96	✓
1 pc	Front w/s glass rubber	<i>m</i>	371.39	✓
1 pc	N/s headlamp		882.04	?
1 pc	N/s signal lamp	<i>cm</i>	225.91	✓
1 pc	N/s headlamp top moulding	<i>cm</i>	169.36	✓
1 pc	Front bumper	<i>B</i>	1,877.40	✓
1 pc	Front n/s bumper bracket		352.61	?
1 pc	Front n/s bumper foglamp		583.11	?
1 pc	Front n/s bumper foglamp cover	<i>cm</i>	87.16	✓
1 pc	Front n/s mirror stand	<i>R</i>	586.98	X

8,284.66

Less 25% : 2,071.16

6,213.50

To rewire damaged parts and refocus headlamp beam.

20.00 ✓

To remove & refix front windscreen glass and conduct water leak test.

200.00 *120*

To remove air con condenser, pipes and drier, vacuum and to recharge gas

120.00 *100*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH7610J

Page : 2

To apply undersealing	300 60.00
To remove front instrument panel assy and rewiring	200.00 ✓
To putty and spray replaced parts	800.00 500
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	800 1,200.00
Total :	----- S\$ 8,813.50 =====

Singapore Dollars Eight Thousand Eight Hundred
and Thirteen and Cents Fifty Only