

Ala
22/11 or 23/11
wed or thurs

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

*Not Authorised
T/loss*

13/11/2017

Owner: MKM CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA RUSH - SLN9370G

1pc	rear spare tyre cover inner	CID \$	481.90	✓
1pc	rear spare tyre cover outer	CM \$	891.75	—
1pc	rear spare tyre bracket	B \$	471.25	✓
1pc	rear tailgate	R \$	978.10	✓
2pcs	rear tailgate hinge @\$177.45	R \$	354.90	✓
1pc	rear tailgate inner lock	T \$	381.90	✓
1pc	rear tailgate inner rubber	\$	371.75	✓
1pc	rear tailgate inner garnish	\$	561.60	✓
1pc	rear tailgate wiper motor	S \$	581.90	X
2pcs	rear taillamp @\$374.45	MS CR \$	748.90	✓
1pc	rear bumper	B \$	881.10	✓
2pcs	rear bumper side retainer @\$132.25	D \$	264.50	✓
2pcs	rear bumper side reflector @\$141.40	MS CM \$	282.80	✓
1pc	rear bumper number plate lamp @\$83.10	CM \$	166.20	✓
2pcs	rear bumper side garnish @\$174.25	\$	348.50	✓
1pc	rear end panel	B \$	781.90	✓
1pc	rear end panel inner garnish	P \$	371.80	✓
1pc	rear float panel	BT \$	971.25	✓
1pc	rear exhaust box	B \$	780.10	✓
2pcs	rear exhaust box mounting @\$61.10	D \$	122.20	✓
1pc	front bonnet	B \$	972.85	✓
2pcs	front bonnet hinge @\$131.35	R \$	262.70	X
1pc	front bonnet inner lock	D \$	271.85	✓
1pc	front centre grille	CR \$	182.10	✓
1pc	front centre grille "TOYOTA" logo	R \$	61.75	✓
2pcs	front headlamp @\$921.10	cls m/cr \$	1,842.20	✓
1pc	front bumper	B \$	995.45	✓
1pc	front bumper towing cover	m \$	121.25	✓
1pc	front bumper side retainer @\$141.40	cls D \$	282.80	✓
1pc	front bumper RH fog lamp	\$	374.50	✓
1pc	front bumper reinforcement	B \$	581.90	✓
1pc	front support panel	B \$	972.85	✓
2pcs	front support panel side garnish @\$141.40	cls CR \$	282.80	✓

balance c/f

\$ 17,999.30



輝 陽 汽 車 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

13/11/2017

Owner: MKM CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA RUSH - SLN9370G

balance b/f		\$ 17,999.30
1pc	front support panel centre pillar	<i>Bu</i> \$ 371.85 ✓
1pc	front air-con condensor	<i>Pu</i> \$ 971.50 ✓
1pc	front air-con condensor pipe 1	\$ 161.60 ?
1pc	front air-con condensor pipe 2	\$ 182.25 ?
1pc	front radiator	\$ 1,218.20 ?
1pc	front radiator top hose	<i>Sm</i> \$ 131.35 ✓
1pc	front radiator lower hose	<i>Sm</i> \$ 141.45 ✓
1pc	front radiator cowling	<i>Sm</i> \$ 374.85 ✓
1pc	front radiator cowling motor	\$ 581.90 ?
1pc	front radiator cowling fan	\$ 181.60 ?
1pc	front radiator spare tank	<i>Sm</i> \$ 331.35 ✓
1pc	front fuel filter	<i>Sm</i> \$ 391.60 ✓
1pc	front RH fender	<i>Bu</i> \$ 581.10 ✓
		\$ 23,619.90
less 25%		\$ 5,904.98
		\$ 17,714.93
remove & refix rear windscreen glass		\$ 120.00 ✓
sealant		\$ 60.00 <i>4000</i>
tuffkote		\$ 120.00 ✓
wiring		\$ 120.00 <i>400</i>
spray painting		\$ 1,800.00 <i>16000</i>
labour charges		\$ 1,600.00 <i>15000</i>
Total		
		\$ 21,534.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

