

ASS. REC. BY:

REF: CS/GAL7022318 (Ug)bn2 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Sharon Ng of GAL Date/Time: 22.11.2017

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLK 8803Y Insured:

at Workshop m/s Peggsus Tel: 6858 1846

of 51 Defu Lane 10

Policy No: Claim No: SLK 8803Y

Sum Insured: Excess: \$2000.00

Make of Veh: D.O.A. 20.11.2017
(Client's Record)

CA/REV/REP./REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22.11.2017 4:52pm Person Contacted: Alvin Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 8803Y x
12/12/17 @ 2.09pm	revised to Sharon by email.

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

① 71 WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 88031at Workshop m/s Pegasus

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 200

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: #72k.

IDAC Accident Report: _____ Consistent? : Yes or No

① 71 / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 3 days Res.: Yes or NoSum Sum: 1.21 % 3 Val.: Yes or No

① 71 REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLK 88031 Yr Regn: 2 17Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Mercedes C.C. 1496Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 13606 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8H0138283Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 20/11/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frnt.
The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 11/12/17

Date / Time Action / Instruction

3/1/18 conf. and 2/5 \$2300 with Sam.
(U/C to 2227.49, 55%)

RECEIVED 10 JAN 2018

Date/Time, File Pass to?

1) 10/1/18

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) \$ + RS \$ _____

) Photos

) Other

Report Format: 07Lump Sum / I.B.A. (\$) 2300

TOTAL

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI17022318/Uqb

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 22-11-2017



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLK 8803Y
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	2,000.00
Assign From SHARON NG	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/11/2017	Inspection Date
Survey held at	51 DEFU LANE 10	
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No. 91/11707318/Agb
Policy Type: OD/ TP / TP RES / TL / EVA

Suk 8803Y

Case Handler

Typist

Admin (Cather): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Mwan): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓		
---	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓		
✓		
✓		
✓		
✓		
✓		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓		
---	--	--

Check By:

Cather 10/01/18

Case Handler

Date

Catherine Chong (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Wednesday, 22 November, 2017 4:04 PM
To: SUR
Cc: assignments
Subject: FW: OD survey for SLK8803Y DOA: 20.11.2017
Attachments: 22112017103603.pdf; 22112017103029.pdf

Dear Catherine

Please conduct OD survey and authorize if damages are consistent.

Excess \$2000.

Regards
Sharon

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]
Sent: Wednesday, November 22, 2017 10:32 AM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: Cheewee tay <cheewee.tay@grabtaxi.com>; Lawrence Sim <lawrencesim@pegasusengrg.com.sg>
Subject: OD survey for SLK8803Y DOA: 20.11.2017

Dear Sharon and Kelvyna,

We refer to the above subject matter.

We enclose the following relevant supporting documents for your attention:

- a. Repair Estimate
- b. GIA Report
- c. Driver's IC & Driving Licence

Kindly arrange the Insured vehicle to be surveyed as soon as possible. The vehicle is in our workshop.

Thanks & Regards,

Alvin Low
-CO

Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 12 December, 2017 2:09 PM
To: Admin-D (LKKAUTO); 'Ng, Sharon'; SUR
Cc: assignments
Subject: RE: OD survey for SLK8803Y DOA: 20.11.2017
Attachments: CSGAI17022318Uqh3.pdf

Dear Sharon,

Enclosed herewith preliminary advice of SLK 8803Y.
We have authorised repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 22 November, 2017 4:54 PM
To: 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: OD survey for SLK8803Y DOA: 20.11.2017

Dear Sharon,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon [<mailto:Sharon.Ng@sg.gaig.com>]
Sent: Wednesday, 22 November, 2017 4:04 PM
To: SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: FW: OD survey for SLK8803Y DOA: 20.11.2017

Dear Catherine

Please conduct OD survey and authorize if damages are consistent.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 12 December 2017

Our Ref: CS/GAI17022318/Uqb

The Motor Claims Department
Great American Insurance Company

Attn: Sharon

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLK 8803Y .


We thank you for the instruction on 22/11/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/12/2017 at the premises of M/s PEGASUS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,077.49</u> .
Revised Estimate Amount	: S\$ <u>2,911.24</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>72,000.00</u> .
Salvage Value	: S\$ <u>45,732.00</u> .
Nett Value	: S\$ <u>26,268.00</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

We have authorise repair.

Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	7200G
Vehicle Details	
Vehicle No.	SLK8803Y
Vehicle to be Exported	Yes
Intended De-registration Date	21 Nov 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour	Grey
Manufacturing Year	2016
Engine No.	P520424736
Chassis No.	JM6BN22A8H0138283
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$14,777.00
Original Registration Date	02 Feb 2017
First Registration Date	02 Feb 2017
Transfer Count	0
Actual ARF Paid	\$9,777.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	01 Feb 2027
PARF Rebate Amount	\$7,332.00
Intended COE Rebate Details	
COE Expiry Date	01 Feb 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$48,000.00
COE Rebate Amount	\$38,400.00
Total Rebate Amount	\$45,732.00

The information contained herein is correct as at 21 Nov 2017

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	7200G
Vehicle Details	
Vehicle No.	SLK8803Y
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour	Grey
Manufacturing Year	2016
Engine No.	P520424736
Chassis No.	JM6BN22A8H0138283
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$14,777.00
Original Registration Date	02 Feb 2017
First Registration Date	02 Feb 2017
Transfer Count	0
Actual ARF Paid	\$9,777.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	01 Feb 2027
PARF Rebate Amount	\$7,332.00
Intended COE Rebate Details	
COE Expiry Date	01 Feb 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$48,000.00
COE Rebate Amount	\$43,872.00
Total Rebate Amount	\$51,204.00

The information contained herein is correct as at 11 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2017 14:37
Date Of Accident	20/11/2017 13:40
Exact Location Of Accident	ECP TOWARDS CITY DIRECTION (BEFORE FORT ROAD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8803Y
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98235008
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 SEDAN L SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	MTGRAB20170184

Driver

Name of Driver	LEOW QING LONG (LIAO QINGLONG)
NRIC No	S8400425A
Date Of Birth	02/01/1984
Occupation	OUTDOOR
Date Of Driving Pass	07/04/2005
Driving Experience	12 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84848184
Fax Number	
Contact Number	
Email Address	ERICLEOW999@GMAIL.COM

Address	BLOCK 499C TAMPINES AVENUE 9 #08-256
Postcode	523499
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 20.11.2017 at about 1342hrs, I was driving my vehicle (A: SLK8803Y) along the 1st lane of ECP towards City direction (before Fort Road). Vehicle (B: SHB6610U) ahead made a sudden stopped, I immediately applied on my brake to avoid collision but to no avail. My vehicle's front portion hit onto the rear portion of vehicle B. No injury arises out of the accident. Vehicle A: No passenger onboard Vehicle B: Unaware number of passenger

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB6610U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	HOR SZE CHIN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/11/17 @ 1300hrs


Reporting Centre Personnel's Signature
Name: Sam Low
NRIC/FIN No.: S8859896B

SKETCH PLAN

ECP towards City direction (Before Fort Road)

A: SLK8803Y

B: SHB6610U



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Sam Low
NRIC/FIN No.: S8859896B

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE #16-01
CENTENNIAL TOWER
SINGAPORE 039190

Attn :
Tel : 4/5 \$2300
Fax :

3 Day
Authorized
Make
Excess \$2000
Take photo & keep copy

Quotation No : QO17/11-1117	Quotation Date : 21/11/2017	Terms :
Vehicle No : SLK8803Y	Chassis No : JM6BN22A8H0138283	Cover Note No :
Model : MAZDA 3		Date of Accident :
Remarks : COVER NOTE NO: MTGRAB20170184 , DATE OF ACCIDENT: 20.11.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BONNET - REPAIR <i>n</i>	1	400.0000	400.00 <i>X</i>
2	FRONT SUPPORT PANEL - FIBRE <i>11</i>	1	220.0000	220.00 <i>X</i>
3	FRONT SUPPORT PANEL - METAL - REPAIR <i>n</i>	1	55.0000	55.00 <i>X</i>
4	RADIATOR GRILLE <i>11</i>	1	60.0000	60.00 <i>X</i>
5	RADIATOR GRILLE CHROME GARNISH <i>0/5 cm</i>	2	75.0000	150.00 <i>IPC</i>
6	RADIATOR GRILLE CHROME GARNISH BASE <i>0/5 cm</i>	2	9.0000	18.00 <i>IPC</i>
7	RADIATOR GRILLE INNER SIDE BRACKET <i>Yw1</i>	2	7.0000	14.00 <i>—</i>
8	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIP <i>ner</i>	2	2.0000	4.00 <i>—</i>
9	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIP HOLDER <i>ner</i>	2	7.0000	14.00 <i>—</i>
10	RADIATOR GRILLE SIDE COVER <i>0/5 to 11</i>	2	7.0000	14.00 <i>IPC</i>
11	RADIATOR GRILLE OUTER GARNISH <i>DD/se</i>	1	140.0000	140.00 <i>—</i>
12	RADIATOR GRILLE OUTER GARNISH RIVETS <i>ner</i>	4	4.0000	16.00 <i>—</i>
13	RADIATOR GRILLE OUTER GARNISH SUPPORT TOP COVER <i>cre</i>	1	45.0000	45.00 <i>—</i>
14	RADIATOR GRILLE EMBLEM BADGE <i>ner</i>	1	25.0000	25.00 <i>—</i>
15	RADIATOR GRILLE CLIPS <i>ner</i>	6	1.5000	9.00 <i>—</i>
16	RADIATOR GRILLE OUTER GARNISH CLIPS <i>ner</i>	3	1.5000	4.50 <i>—</i>
17	FRONT LICENCE PLATE GARNISH <i>DIS</i>	1	29.0000	29.00 <i>—</i>
18	FRONT BUMPER <i>DD/se</i>	1	384.4500	384.45 <i>—</i>
19	FRONT BUMPER SIDE RETAINER <i>11</i>	2	10.0000	20.00 <i>X</i>
20	FRONT BUMPER REINFORCEMENT <i>DD</i>	1	450.0000	450.00 <i>?</i>
21	FRONT BUMPER REINFORCEMENT COVER <i>To 11</i>	1	15.0000	15.00 <i>?</i>
22	FRONT BUMPER REINFORCEMENT COVER CLIPS <i>ner</i>	4	1.5000	6.00 <i>—</i>
23	FRONT BUMPER CLIPS <i>ner</i>	10	1.5000	15.00 <i>—</i>
24	FRONT BUMPER LOWER SUPPORT GARNISH <i>11</i>	1	35.0000	35.00 <i>X</i>

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190 Attn : Tel : Fax :
---	---

Quotation No : QO17/11-1117	Quotation Date : 21/11/2017	Terms :
Vehicle No : SLK8803Y	Chassis No : JM6BN22A8H0138283	Cover Note No :
Model : MAZDA 3	Date of Accident :	
Remarks : COVER NOTE NO: MTGRAB20170184 , DATE OF ACCIDENT: 20.11.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
25	FRONT BUMPER AIR GUIDE <i>1 1</i>	2	22.0000	44.00 <i>X</i>
26	FRONT BUMPER LOWER SPLASHIELD COVER <i>1 1</i>	1	45.0000	45.00 <i>X</i>
27	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS <i>1 1</i>	8	1.5000	12.00 <i>X</i>
28	O/S FRONT BUMPER INDICATOR LIGHT <i>1 1</i>	1	65.0000	65.00 <i>X</i>
29	FRONT BUMPER INDICATOR LIGHT GARNISH <i>1 1</i>	1	12.0000	12.00 <i>X</i>
30	FRONT BUMPER INDICATOR LIGHT GARNISH EXTENSION <i>1 1</i>	1	8.0000	8.00 <i>X</i>
31	O/S FRONT BUMPER TOW COVER <i>1 1</i>	1	8.0000	8.00 <i>X</i>
32	HEADLAMP <i>o/s cr</i>	2	400.0000	800.00 <i>720</i>
33	MARK UP 15% ITEM (1-32)	1	470.5400	470.54
34	FRONT LICENCE PLATE	1	30.0000	30.00 <i>Set</i>
35	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00 <i>20</i>
36	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	700.0000	700.00 <i>450</i>
37	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	680.0000	680.00 <i>500</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total 5,077.49
GST(7.00%) 355.42
Total (SGD) 5,432.91

P-1670.95
152
7921.59

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

2891.59
2317



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI17022318/Uqbn2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 12-01-2018



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLK 8803Y
Policy No.	MTGRAB20170184	Coverage (\$)	0.00
Claim No.	SLK8803Y	Excess (\$)	2,000.00
Assign From	SHARON NG	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0138283	Colour	GREY
Odometer	53606	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/11/2017	Inspection Date	11/12/2017
Survey held at	51 DEFU LANE 10		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$72,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 8803Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET (WCP)	TO REPAIR SEE LABOUR	400.00	-
1	FRONT SUPPORT PANEL-FIBRE (WCP)	NOT NECESSARY	220.00	-
1	FRONT SUPPORT PANEL-METAL (WCP)	TO REPAIR SEE LABOUR	55.00	-
1	RADIATOR GRILLE (WCP)	NOT NECESSARY	60.00	-
2	RADIATOR GRILLE CHROME GARNISH @\$75.00 (WCP)	O/S CRACKED	150.00	75.00
2	RADIATOR GRILLE CHROME GARNISH BASE @\$9.00 (WCP)	O/S CRACKED	18.00	9.00
2	RADIATOR GRILLE INNER SIDE BRACKET @\$7.00 (WCP)	TWISTED	14.00	14.00
2	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIP @\$2.00 (WCP)	NECESSARY	4.00	4.00
2	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIP HOLDER @\$7.00 (WCP)	NECESSARY	14.00	14.00
2	RADIATOR GRILLE SIDE COVER @\$7.00 (WCP)	O/S TORN	14.00	7.00
1	RADIATOR GRILLE OUTER GARNISH (WCP)	DENTED / DEFORMED	140.00	140.00
4	RADIATOR GRILLE OUTER GARNISH RIVETS @\$4.00 (WCP)	NECESSARY	16.00	16.00
1	RADIATOR GRILLE OUTER GARNISH SUPPORT TOP COVER (WCP)	CRACKED	45.00	45.00
1	RADIATOR GRILLE EMBLEM BADGE (WCP)	NECESSARY	25.00	25.00
6	RADIATOR GRILLE CLIPS @\$1.50 (WCP)	NECESSARY	9.00	9.00
3	RADIATOR GRILLE OUTER GARNISH CLIPS @\$1.50 (WCP)	NECESSARY	4.50	4.50
1	FRONT LICENCE PLATE GARNISH (WCP)	DISTORTED	29.00	29.00
1	FRONT BUMPER (WCP)	DENTED / DEFORMED	384.45	384.45
2	FRONT BUMPER SIDE RETAINER @\$10.00 (WCP)	NOT NECESSARY	20.00	-
1	FRONT BUMPER REINFORCEMENT (WCP)	DENTED	450.00	450.00
1	FRONT BUMPER REINFORCEMENT COVER (WCP)	TORN	15.00	15.00
4	FRONT BUMPER REINFORCEMENT COVER CLIPS @\$1.50 (WCP)	NECESSARY	6.00	6.00
10	FRONT BUMPER CLIPS @\$1.50 (WCP)	NECESSARY	15.00	15.00
1	FRONT BUMPER LOWER SUPPORT GARNISH (WCP)	NOT NECESSARY	35.00	-
2	FRONT BUMPER AIR GUIDE @\$22.00 (WCP)	NOT NECESSARY	44.00	-
1	FRONT BUMPER LOWER SPLASHIELD COVER (WCP)	NOT NECESSARY	45.00	-

Report Ref No. CS/GAI17022318/Uqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS @\$1.50 (WCP)	NOT NECESSARY	12.00	-
1	O/S FRONT BUMPER INDICATOR LIGHT (WCP)	NOT NECESSARY	65.00	-
1	FRONT BUMPER INDICATOR LIGHT GARNISH (WCP)	NOT NECESSARY	12.00	-
1	FRONT BUMPER INDICATOR LIGHT GARNISH EXTENSION (WCP)	NOT NECESSARY	8.00	-
1	O/S FRONT BUMPER TOW COVER (WCP)	NOT NECESSARY	8.00	-
2	HEADLAMP @\$400.00 (WCP)	O/S CRACKED	800.00	400.00
	COST PLUS 15%		470.54	249.29
			3,607.49	1,911.24
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENCE PLATE (SN)	BENT	30.00	30.00
			30.00	30.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT SUPPORT PANEL-METAL.		700.00	450.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		680.00	500.00
			1,440.00	970.00
	GRAND TOTAL		5,077.49	2,911.24
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00
	LESS EXCESS			-2,000.00
	NETT LIABILITY			300.00

Report Ref No. CS/GAI17022318/Uqbn2


CHUA KANG SENG
 Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.