

ASS. REC BY

REF

CS/FCL17022329 / Atbn2

Issued to agent

Subject

ASSIGNMENT Officer

From (Person)

CWS Karen Tan

FCL

Date/Time

22.11.2017 6:52pm

Estimated Cost

BRIW

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SHD 571P

Insured

SH B 4466H

at Workshop mit

SM Automotiv

Tel

6747 9241

of

Blk 1 Kaki Bukit Ave 6 #01-43

Policy No

Claim No

D17010848MFSH

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

21.11.2017

CA / REV / REP. / REV 24 HRS '09

H.O.D. Endorsement

Date/Time

Person Connected

Subyi

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 571P - CS / FCL 17023057 / Atbn2

D.O.A: 10.214

SHB 4466H - CCH / 17023232 / M111113

D.O.A: 21.11.17

lump Sum \$4200 (Red: 93/0.90:68%)

5/12-

Revert prec advse via email

Surrey

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SG0571P Yr Regn: 2006 FebType: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios cc 1497Colour: White A/C Insured / Std / NI / NASp. Reading: 206802 T. Radio: Insured / Std / NI / NA

Eng No: _____

C/No: MR053HY4204173159Gen. Cond: Good Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R15R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ContinentalFront 06 mm Rear 06 mmR/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.J. 22/11/17Survey held at S.MDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAXA.FCL

RECEIVED 04 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report1) H/R Typist

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transaction: _____

Report Format: TPLump Sum / I.B.I. (\$) 4200Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)1) S + R.S. \$

2) Photos

3) Others

3x15: 45

170+45

50

50

73

388



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022329/Atb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4466H	Veh. Inspected	SGD 571P
Policy No.		Coverage (\$)	0.00
Claim No.	D17010848MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/11/2017	Inspection Date	22/11/2017
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Your Ref: D17010848MFSH

Date: 5/12/2017

Our Ref: CS/FCI17022329/Atbn2

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGD 571P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 220/11/2017 at the premises of M/s SM Automotive at and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 13,510.90</u>
Revised Estimate Amount	: <u>S\$ 5,254.10</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>


Description of Damage:
The vehicle sustained damages
At rear portion.

Repair days: 6

Yours faithfully

Adrian

Motor Surveyor



First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	21-11-2017	Our Ref No. D17010848MFSH
Accident Date	21-11-2017	Claim Type. Third Party
Insured Vehicle	SHB4466H	Third Party Vehicle. SGD571P
Survey Location	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43	
Contact Person.	SUKYI	
Contact No.	67479241/ 91911877	Fax No. 67417276
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SM AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230500)



PRI Documents



Close



PRI Header Details

Claim No	D17010848MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & SM
Workshop Name	SM AUTOMOTIVE (Contact Person : SUKYI)	Survey Location & Contact Details	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 Mobile: 91911877 , Phone: 67479241 , Fax: EmailId: ADMIN@NHTMOTOR.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB4466H	TP Vehicle No	SGD57
PRI Recieved Date	22-11-2017 12:31:20 AM	Surveyor Appointed Date	22-11-2017 06:52:35 PM	Surveyor Accept Date	22-11-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-11-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 5 December, 2017 3:16 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010848MFSH/1
Attachments: PRELI ADVISED SGD 571P.pdf

"Without prejudice"

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SGD 571P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 22 November, 2017 7:21 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010848MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 22 November, 2017 6:52 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010848MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	3611J

Vehicle Details

Vehicle No.	SGD571P
Vehicle to be Exported	No
Intended De-registration Date	21 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	VIOS 1.5E A
Primary Colour	White
Manufacturing Year	2005
Engine No.	1NZX370568
Chassis No.	MR053HY4204173159
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$12,903.00
Original Registration Date	08 Feb 2006
First Registration Date	08 Feb 2006
Transfer Count	1
Actual ARF Paid	\$14,194.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	07 Feb 2021
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$26,900.00
COE Rebate Amount	\$17,293.00
Total Rebate Amount	\$17,293.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.



Toyota Vios 1.5A E Sports \$25,888 \$8,450 /yr 23-Mar-2010 1,497 cc 114,279 km Sedan Available

(High Specification Sport Model!) 1st Owner Car. Accident Free Unit With Original Body Work. Enjoy Free 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance Coverage. STA/VICOM/AA/...

Sincere Motoring Pte Ltd

Posted: 20-Nov-2017 Tags: 2010 Toyota Vios, 2010 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A E (OPC) (New 5-yr COE) - N.A 14-Dec-2007 1,497 cc - Sedan SOLD

One Owner, Vehicle In Original Paint From Day 1, Low Mileage 71067Km Done. Full Service From Agent. Please Call To Make Appointment.

Posted: 20-Nov-2017 Tags: 2007 Toyota Vios, 2007 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A E (COE till 03/2022) - N.A 20-Mar-2007 1,497 cc - Sedan SOLD

Posted: 20-Nov-2017 Tags: 2007 Toyota Vios, 2007 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A E (COE till 03/2021) \$22,800 \$6,840 /yr 23-Mar-2006 1,497 cc - Sedan Available

Super Well Kept With Original Paintwork Since Day 1. Tip Top Condition.

JDM Cars

Posted: 20-Nov-2017 Tags: 2006 Toyota Vios, 2006 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A E (COE till 11/2022) \$34,800 \$6,980 /yr 16-Nov-2007 1,497 cc - Sedan Available

Down Payment \$2800! Lowest Monthly \$588 Onward. Interest 3.88% Per Annum At GV In House Loan 100% Approval. 2 Years Warranty By GV In House Workshop. New Fully Pure Leather Seat And New \$2k Metallic P...

GV Credit Pte Ltd

Posted: 20-Nov-2017 Tags: 2007 Toyota Vios, 2007 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A J (New 5-yr COE) \$33,800 \$6,760 /yr 20-Feb-2008 1,497 cc 103,258 km Sedan Available

Posted: 20-Nov-2017 Tags: 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A E - N.A 22-Dec-2008 1,497 cc - Sedan SOLD

Low KMileage Done Of 60000KM And Last Maintained By Borneo Motors. Guaranteed PARF Of \$5917. Cheaper Than Renting A Car. Hurry Up Or You Be Missing This Superb Buy.

Ka-Hup Vehicles Trading

Posted: 20-Nov-2017 Tags: 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A E \$25,800 \$9,760 /yr 19-Nov-2009 1,497 cc 116,000 km Sedan Available

100% Selling Cheap! Major Accident Free. Reliable And Responsive! Buy With A Peace Of Mind! Call Now To Make Your Appointment!

Mayfair Motoring

Posted: 20-Nov-2017 Tags: 2009 Toyota Vios, 2009 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A E \$50,800 \$9,580 /yr 13-Aug-2012 1,497 cc 90,000 km Sedan Available

Selling Cheap! Well Maintained And 100% Original Mileage! Fully Serviced By Workshop! Comes With TRD Bodykit. Super Fuel Efficient And Sporty. Call Now To Make Your Appointment!

Mayfair Motoring

Posted: 20-Nov-2017 Tags: 2012 Toyota Vios, 2012 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A E (COE till 05/2026) \$51,998 \$6,100 /yr 06-Jul-2006 1,497 cc 90,128 km Sedan Available

Genuine Low Mileage! Most Reasonable Price In Market! New Paintwork! Guarantee Best Buy! New 6 Months Road Tax! Servicing Just Done! Test Drive Now! View To Believe! Down Payment \$5,998 Easy Approval ...

Posted: 20-Nov-2017 Tags: 2006 Toyota Vios, 2006 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)



Toyota Vios 1.5A E (New 5-yr COE) \$34,800 \$6,960 /yr 27-Feb-2008 1,497 cc - Sedan Available

Down Payment \$2800! Lowest Monthly \$588 Onward. Interest 3.88% Per Annum At GV In House Loan 100% Approval. 2 Years Warranty By GV In House Workshop. New Fully Pure Leather Seat And New \$2k Metallic P...

GV Credit Pte Ltd

Posted: 20-Nov-2017 Tags: 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota, Vios, Vios, Used Toyota

[Details](#)

[Compare](#)

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883
 Email: SM_AUTOMOTIVE@HOTMAIL.COM
 Tel: (65) 6747 9241 Fax: (65) 6741 7276
 RCB No.: 53231488C

ONG YONG SIANG

21/11/2017

Blk C, 1 Kaki Bukit Ave 6
 # 01-43
 Singapore 417883

TP 1st Cap.
 Denise

Accident date: 21/11/2017

Estimated repair cost for vehicle no: SGD571P TOYOTA VIOS 1.5 E A '06

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Buckled</i>		\$590.10 ✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$123.05	\$246.10 +
3	1	Rear Boot Lid Emblem Logo <i>new</i>		\$42.50 ✓
4	1	Rear Boot Lid E Logo <i>new</i>		\$28.70 ✓
5	1	Rear Boot Lid 1.5 Logo <i>new</i>		\$28.70 ✓
6	1	Rear Boot Lid Vvti Logo		\$36.10 ✓
7	1	Rear Boot Lid Vios Logo		\$43.55 ✓
8	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00 +
9	1	Rear Boot Lid Inner Lock <i>new</i>		\$182.25 ✓
10	1	Rear Boot Lid Inner Rubber <i>new</i>		\$161.40 ✓
11	1	Rear Boot Lid Camera <i>new</i>		\$550.00 +
12	2	Rear Tail Lamp <i>cracked</i>	\$281.45	\$562.90 ✓
13	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
14	2	Rear Tail Lamp Panel <i>RH Dented</i>	\$189.90	\$379.80 + 189.90
15	1	Rear Bumper <i>Deformed</i>		\$391.40 ✓
16	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 30
17	2	Rear Bumper Side Retainer <i>new</i>	\$121.25	\$242.50 64.
18	1	Rear Bumper Reverse Sensor <i>new</i>		\$350.00 250 (SN)
19	2	Rear Fender Inner Trim Board <i>new</i>	\$314.40	\$628.80 +
20	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00 +
21	1	Rear End Panel <i>Dented</i>		\$781.90 666
22	1	Rear End Panel Top Garnish <i>Dented</i>		\$281.45 67.80
23	1	Rear Spare Tyre Panel <i>Rp 15</i>		\$681.75 +
24	1	Rear Spare Tyre Panel Top Cover <i>Dented</i>		\$289.95 165
25	2	Rear Spare Tyre Panel Top Side Sponge <i>RH torn</i>	\$382.20	\$764.40 + 151.30
26	1	Rear Spare Tyre Panel & End Panel Sealant <i>not new</i>		\$450.00 +
27	1	Rear Exhaust <i>Bent</i>		\$781.45 465.20
28	1	Rear Centre Exhaust <i>new</i>		\$787.20 +

3898.80
 2924.10

S.N: 250

Subtotal :- \$9,520.90

Labour charges

To remove & refit cushion	\$280.00 60
To remove & refit reverse sensor	\$100.00 60
To remove & refit rear camera	\$180.00 4
To remove & refit rear & centre exhaust	\$380.00 80
To check wiring	\$100.00 30
Tuff kote	\$150.00 40
Panel beating	\$1,400.00 700
Spray painting	\$1,400.00 900

Subtotal :- \$3,990.00

Total:- \$13,510.90

total - 5254.10

4/c: 4.2k
06 days

4.2k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022329/Atbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4466H	Veh. Inspected	SGD 571P	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010848MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	22/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053HY4204173159	Colour	WHITE	
Odometer	206802	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	CONTINENTAL	6 mm	
L/H Front Tyre	195/55 R15	CONTINENTAL	6 mm	
R/H Rear Tyre	195/55 R15	CONTINENTAL	6 mm	
L/H Rear Tyre	195/55 R15	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/11/2017	Inspection Date	22/11/2017	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 571P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	BUCKLED	590.10	590.10
2	REAR BOOT LID HINGE @\$123.05	NOT NECESSARY	246.10	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	42.50	42.50
1	REAR BOOT LID E LOGO	NECESSARY	28.70	28.70
1	REAR BOOT LID 1.5 LOGO	NECESSARY	28.70	28.70
1	REAR BOOT LID VVTI LOGO	NECESSARY	36.10	36.10
1	REAR BOOT LID VIOS LOGO	NECESSARY	43.55	43.55
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BOOT LID INNER LOCK	DAMAGED	182.25	182.25
1	REAR BOOT LID INNER RUBBER	CUT	161.40	161.40
1	REAR BOOT LID CAMERA	NOT NECESSARY	550.00	-
2	REAR TAIL LAMP @\$281.45	CRACKED	562.90	562.90
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP PANEL @\$189.90	O/S DENTED	379.80	189.90
1	REAR BUMPER	DEFORMED	391.40	391.40
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER @\$121.25	NECESSARY	242.50	64.00
2	REAR FENDER INNER TRIM BOARD @\$314.40	NOT NECESSARY	628.80	-
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	104.00	-
1	REAR END PANEL	DENTED	781.90	666.00
1	REAR END PANEL TOP GARNISH	DEFORMED	281.45	67.80
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	681.75	-
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	289.95	165.00
2	REAR SPARE TYRE PANEL TOP SIDE SPONGE @\$382.20	O/S TORN	764.40	151.30
1	REAR SPARE TYRE PANEL & END PANEL SEALANT	NOT NECESSARY	450.00	-
1	REAR EXHAUST	BENT	781.45	465.20
1	REAR CENTRE EXHAUST	NOT NECESSARY	787.20	-
	LESS 25% DISCOUNT		-	-974.70
			9,170.90	2,924.10

Report Ref No. CS/FCI17022329/Atbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	250.00
			350.00	250.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION.		280.00	60.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	60.00
	TO REMOVE & REFIT REAR CAMERA.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.		380.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	50.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		1,400.00	900.00
	SPRAY PAINTING.		1,400.00	900.00
			3,990.00	2,080.00
	GRAND TOTAL		13,510.90	5,254.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00

Report Ref No. CS/FCI17022329/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.