

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST1711-101

DATE : 22-Nov-2017

POLICY NO. : DIRECT ASIA MT/00361728

VEHICLE REG. NO. : SJP5082C

VEHICLE MAKE : BMW 320I AT 2.0L

TO Motor Claim Department

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Tel: 1800-880-4741

Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 1,180.00	\$ 1,180.00
2	Front Bumper Clips	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer LH	1	\$ 40.00	\$ 40.00
Total Spare Parts				\$ 1,270.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
4	Spray painting Front Bumper	1	\$ 300.00	\$ 300.00
5	Repair and Replace Affected Accident Parts	1	\$ 300.00	\$ 300.00
6	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 630.00
Amount Before Excess				\$ 1,900.00
Add GST @ 7%				133.00
Total Amount Payable				\$ 2,033.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.