

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

Attn: Motor Claim Department

Tel : 6338 7288 Fax : 6880 4838

Dear Sir/Madam,

Accident Repair On : SJF8949K

Model : HONDA CRV 2.4L AT

Policy No : GA059385/1

Chassis No : JHLRE48508C210482

Year Of Make : 2008

Date / Time Of Accident : 10/11/2017 at 1130Hrs

Location : CTE LEADING TO JALAN BUKIT MERAH

Date: 23/11/2017

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle:

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Tailgate	1	580.00	old	580.00
2 Tailgate moulding chrome	1	150.00	new	150.00
3 Tailgate hinge LH	1	25.00	new	25.00
4 Tailgate hinge RH	1	25.00	new	25.00
5 Tailgate stand absorber LH	1	90.00	new	90.00
6 Tailgate stand absorber RH	1	90.00	new	90.00
7 Tailgate inner trim	1	125.00	new	125.00
8 Tailgate lock assy	1	75.00	new	75.00
9 Tailgate striker	1	18.00	new	18.00
10 Tailgate weatherstrip	1	40.00	new	40.00
11 Tailgate emblem	1	15.00	new	15.00
12 Tailgate lettering "CRV"	1	15.00	new	15.00
13 Tailgate lower cover	1	150.00	new	150.00
14 Tailgate pull handle pocket	1	15.00	new	15.00
15 Tailgate handle switch button	1	65.00	new	65.00
16 Rear windscreen	1	650.00	new	650.00
17 Rear windscreen moulding set	1	30.00	new	30.00
18 Rear tail lamp assy RH	1	195.00	new	195.00
19 Rear tail lamp panel RH	1	75.00	new	75.00
20 Rear bumper	1	160.00	new	160.00
21 Rear bumper side retainer LH	1	10.00	new	10.00
22 Rear bumper side retainer RH	1	10.00	new	10.00
23 Rear bumper reflector RH	1	15.00	new	15.00
24 Rear bumper side cover RH	1	40.00	new	40.00
25 Rear bumper under cover	1			
26 Rear fender RH	1	590.00		590.00
27 Rear fender inner RH	1			
28 Rear fender shield RH	1			
29 Rear fender quarter glass RH	1	250.00		250.00
30 Rear fender quarter glass moulding upper RH	1	30.00		30.00
31 Rear fender quarter glass moulding lower RH	1	85.00		85.00
32 Rear fender lower guard RH	1	30.00		30.00
33 Rear fender wheel arch protector RH	1	35.00		35.00

34	Rear fender inner upper trim RH	X one	1		
35	Rear fender inner lower trim RH	one	1	125.00	125.00
36	Spare tyre cover board	X one	1		
37	spare tyre box	X	1	250.00	250.00
38	Spare tyre panel	X	1		
39	Rear door RH	X one	1	520.00	520.00
40	Rear door weatherstrip RH	X one	1	65.00	65.00
41	Rear door glass outer moulding chrome RH	X one	1	55.00	55.00
42	Rear door pillar frame sticker RH	X one	1	20.00	20.00
43	Rear exhaust assembly	X one	1	320.00	320.00
44	Rear exhaust tips chrome	X one	1	65.00	65.00
45	Rear end panel	X one	1	185.00	185.00
46	Rear end panel top garnish	X one	1	45.00	45.00
47	Rear wheel rim RH	X one	1	720.00	720.00
48	Rear axle assembly	X one	1	580.00	580.00
49	Rear absorber RH	X one	1	120.00	120.00
50	Rear absorber mounting RH	X one	1	35.00	35.00
				Sub-Total:	6,643.00
				Total Parts :	6,643.00

Special Nett Items

1	Rear bumper sensors	1	250.00	250.00
2	Rear tail lamp holder clips	5	2.00	10.00
3	Rear bumper clips	10	1.00	10.00
4	Rear fender shield clips	10	1.00	10.00
5	Rear wheel arch protector clips	10	2.00	20.00
6	Rear number plate with casing	1	35.00	35.00
7	Rear tyre RH	1	185.00	185.00
			Total Nett Items:	520.00

Accident Vehicle Of : SJF8949K

Page : 2 of 2

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged & necessary parts, to panel beat, cut & weld if necessary, to realign all panels and reinstall all replacement parts.	2,200.00
2	Provide skill labour & material to putty all replaced & repaired parts, to respray using 2K paint with oven spray booth facilities	1,600.00
3	Provide skill labour to disconnect & check electrical wiring, harness, wyre sockets, etc. test & rectify for proper functioning	30.00
4	Provide skill labour to check and re-adjust all wheel alignment.	60.00
5	Provide skill labour to dismantle and transfer tailgate fitting and facilitate repair	60.00
6	Provide skill labour to remove & refit cushions, seats, backrest, inner trim, garnish, rooflining and upholstery to facilitate repairs	180.00
7	Provide skill labour to remove and replace bumper sensors	40.00
8	Provide skill labour to remove and replace rear windscreen	150.00
9	Provide skill labour to remove and replace quarter glass	80.00
10	Provide skill labour to remove and replace/refit whole rear with axle undercarriage	250.00
11	Provide skill labour to remove and replace exhaust pipe/system to facilitate repair	80.00
12	Provide skill labour to mount vehicle onto chassis alignment bench (and Fender pillar)	250.00
13	Provide skill labour to remove and replace fuel tank ficture and attachment	50.00
13	Provide skill labour to remove and refit rear end panel lining and garnish to facilitate repair.	80.00
14	Provide skill labour to remove and refit spare tyre panel lining and garnish to facilitate repair.	80.00
		2450
Total Labour:		5,060.00

Total Parts:	6,643.00
Total Nett Items:	520.00
	<u>12,223.00</u>
GST 7%	855.61
Grand Total:	<u>13,078.61</u>

Estimate Repair Duration (include 1 day for re-survey & 1 day for parts ordering) 18 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Survey attended by:

Name : _____

Company : _____

Date : _____

Time : _____

Contact No : _____

Email : _____

Estimator : Wen zheng

Parts - 3390.00

Labour - 2750.00

MISC - 270.00

Total: \$6410.00