

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4

#02-37 Premier @ Kaki Bukit

Singapore 415875

Tel : 94513429

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Department

Estimate

Date : 23.11.2017

Vehicle No. : SJA 2040Y

Make/Model : Toyota Altis

Chassis/Eng# :

Accident Date : 21.11.2017

01) Boot lid	3 surf / 3uc	\$	680.50	✓
02) Boot lid reflector lh	11	\$	220.50	X
03) 1.6 logo	rec	\$	45.80	✓
04) Toyota logo	rec	\$	48.30	✓
05) Corolla logo	rec	\$	35.80	✓
06) ALTIS logo	rec	\$	42.80	✓
07) Boot lid lock	7w1	\$	280.50	✓
08) boot lid lock panel	rear end panel	\$	450.80	✓
09) Boot lid weatherstrip	7w1	\$	150.80	✓
10) Rear bumper	7.5	\$	488.50	580.50
11) Rear bumper reinforcement	sponge, surf / 7w1	\$	366.10	380.50
12) Rear bumper retainer lh	rec	\$	55.80	✓
13) Rear bumper clips	rec	\$	50	60.00
14) Rear bumper bracket lh	rec	\$	45.80	✓
15) Rear bumper	retainer of	\$	68.90	✓
16) Tail lamp assy lh	cre	\$	421.60	488.90
17) Rear panel	floor panel R	\$	780.90	X
		\$	4,417.10	
		Less 25%	\$	(1,104.27)
			\$	3,312.83

S/Nett

1 set	18) Reverse Sensor	shut	\$	250.00	2005.00
1 set	19) Reverse camera	shut	\$	350.00	3005.00
	19) Rear number plate	11	\$	65.00	X
			\$	665.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4

#02-37 Premier @ Kaki Bukit

Singapore 415875

Tel : 94513429

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Department

Estimate

Date : 23.11.2017

Vehicle No. : SJA 2040Y

Make/Model : Toyota Altis

Chassis/Eng# :

Accident Date : 21.11.2017

Labour charges

20) To checking	\$	100.00	30
21) To dismantle & refix reverse sensor	\$	60.00	50
22) to apply anti rust chemical	\$	100.00	60
23) To knock out dent on affected areas (rear fender lh) and renew parts	\$	1,000.00	750
24) To putty & respray painting	\$	1,200.00	1000
	\$	<u>2,460.00</u>	

Not Altis

4812.5

2/5 # 3810/1

5-dy.

23/11/17

take photo After Repair

Ref: 6256356/

Sub Total \$ 6,437.83

for JA AUTOCARE PTE LTD