

INS. CASE OWNER:

CC 6 / CTI1702

2352, F h63n2

LKK:
IDAC:

ASSIGNMENT

Surveyor:

FSC

DOI:

27/11/14

Date / Time:

27/11/14

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SEA 7565

Name of Insured:

TW PREMIUM ACCOMPANIED BY

Insured Tel No.:

HP:

Excess Sec II :\$

D.O.A.:

27/11/14

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SAFARUIN B W MUSTAFA

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SNM130671602

Policy No.:

DMHUSN7151700

Make / Model:

TOYOTA

Place of Accident:

UAMBAS RD / JUNGKUN WOODHARD
ARE 9.

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKD 518E



INSRS:

WSP:

Tel:

Liability:

RMKS:

Alan's



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
27/11/14	SKD 518E - X	Non-Reporting ltr (1st):	
27/11/14	SEA 7565 - 28/11/2011 27/11/14 14/12/14	Non-Reporting ltr (2nd):	
27/11/14	SEA 7565 - 28/11/2011 27/11/14 14/12/14	Non-Reporting ltr (Final):	
27/11/14	ORIGINAL TP LOD IN.	Notification ltr (if non-pickup):	
27/11/14	CALL OI.	Call OI:	
27/11/14	AFTER CALL LTR TO OI: 14/12/14 VIC	After call ltr to OI:	
27/11/14	CALL OI. NO RESPONSE. THE REQUESTED. OLD	Documentation Check List: Handler Typist	
27/11/14	REPAIR - ENDED TP. SEND LETTER TO OI.	Notification ltr (if non-pickup)	
27/11/14	TP REPORT FOR WANDER.	After call ltr to OI:	
27/11/14	REPORT DONE. SEND WANDER TO OI.	Authorisation To Act:	
27/11/14	RESEND WANDER TO OI.	Release Voucher:	
27/11/14	PENDING OI HUPAC AGREEMENT.	Final Repair Bill:	
27/11/14	SEND REMINDER TO OI FOR AGREEMENT SO THAT TO SETTLE	Car Rental Invoice:	
27/11/14	THIS CLEAR-CUT CASE. (TO CALL THEM UP MORE EFFICIENT)	Towing Invoice:	
27/11/14	SEND REMINDER TO OI FOR WANDER APPROVAL	LTA / GIA:	
27/11/14	SETTLE TP CLAIM AS PER CT'S INSTRUCTION AS SOON AS POSSIBLE.	Medical Bill:	
27/11/14	OI APPROVED WANDER.	PIR:	
27/11/14	SEND 1ST OFFER TO TP.	Mandate/Reject Instruction:	
27/11/14	BY IN. TP ACCEPTED OFFER.	LOD	
27/11/14	PRELIMINARY ADVICE Date/Time: 27/11/14 Sent By: b3	Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: 49	SS 6,550.00 (6 days)	Reduction: 34 %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.:	27
Repair Cost: (w/lt)	SS 7,008.50		
Loss of Rental (LOR):	SS 1,440.00 (8 days) X \$180		
Loss of Use (LOU):	SS - (\$ x days)		
Loss of Income (LOI):	SS - (\$ x days)		
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐			[Tick only one]
GLA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 8,450.50	Global Sum \$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 8,450.50	Name 1:	ALAN'S UNITED AUTO PRT LTD
Payee 2: (Strike if N.A.)	SS -	Name 2:	
Payee 3: (Strike if N.A.)	SS -	Name 3:	

ASS. REC. BY:

REF: CT21

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKD 52185

Yr Regn:

10, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

C.C. 2362

Colour:

m. Black

A/C: Insured / Std / NI / NA

Sp. Reading

243408

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ACU 30 - 0075PPF

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rtm / STD AIRtm or

Tyre Size:

F:

245/50R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

4 mm

R/Bal.

3 mm

L/Bal.

4 mm

L/Bal.

3 mm

D.O.A.

20/11/17

D.O.I.

22/11/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/11 File pass to Corbin

Hs \$6,550.00

Cmp: \$3,458.77 (34%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI17022352/Khb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date : 23-11-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKA 756S	Veh. Inspected	SKD 5218E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	23/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/11/2017	Inspection Date	22/11/2017	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTI17022352/Khb3

Date: 23.11.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKD5218E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.11.2017 at the premises of M/s Alan's United Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	10,008.77
Revised Estimate Amount	: S\$	7,438.56
"Check" Items Amount	: S\$	1,795.62
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport
/Company Cert No.: S8013419C

Owner ID Type: Singapore NRIC

Owner Name: SYED FADZLEIGH BIN SHAFARI

Registered Address: APT BLK 803 WOODLANDS STREET 81 #06-57 SINGAPORE 730803

Mailing Address: -

Birth Date: 20 May 1980

Vehicle Particulars

Vehicle No.: SKD5218E

Previous Vehicle No.: -

Effective Date of Ownership: 19 Dec 2011

Original Regn Date: 09 Oct 2007

Registration Date: 09 Oct 2007

Year of Manufacture: 2007

Vehicle Type: Passenger Station Wagon/Jeep/Land Rover

Vehicle Scheme: -

Vehicle Attachment 1: With Sun Roof

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Make: TOYOTA

Vehicle Model: HARRIER 2.4 A

Primary Colour: Black

Secondary Colour: -

Passenger Capacity: 4

Chassis No.: ACU300075997

Engine No.: 2AZB285917

Engine Capacity /Power Rating: 2362 cc / -

Maximum Power Output: 118.0 kW (158 bhp)

Propellant: Petrol

Kh

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05673

Date : 21-Nov-2017

PAGE : 1

Not Authorised
11 May 87
Presing After Point
IER 2.4 SKD5218E

```
=====
=====
```

```
1 pc Rear bumper reverse sensor(set
1 pc Rear w/s glass sealant
```

20.00, X

Con't Page 2 . . .

Acknowledged by Reparer

Signature: _____

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKA756S

Page : 2

To remove & refix rear windscreen
glass and conduct water leak test.

1201
150.00

To remove roof lining, front and
rear seats, trim board and carpet

100.00 601

To apply undersealing

NA X 100.00 601 X

To remove and renew rear exhaust
silencer box & centre exhaust pipe

120.00 101

To putty and spray replaced parts

900.00 8601

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 8001

Total : S\$10,008.77
=====

Singapore Dollars Ten Thousand and Eight and
Cents Seventy Seven Only

6570.00 ✓ok

P 6252.93

SN 740.00

L 1740.00

8232.93

1646.59

6586.34

Renewal As before
700.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05673

Vehicle Insured : SKA756S
Accident Date : 20-Nov-2017

Date : 21-Nov-2017

Our Ref : 217178 (CHINA) / CHAN

PAGE : 1

SYED FADZLEIGH BIN SHAFARI
BLK 803 WOODLANDS STREET 81
#06-57
Singapore 730803

*Not Authorised
11 Nov 87
Pehngy After Point
6 days*

ESTIMATED COST OF REPAIR FOR TOYOTA HARRIER 2.4 SKD5218E

1 pc	Rear bumper fascia		<i>Pr</i>	752.20	✓
1 pc	Rear bumper sponge			111.40	✓
1 pc	Rear bumper reinforcement			458.50	✓
2 pcs	Rear bumper reflector	<i>MSM</i> @ S\$126.80		253.60	<i>ok</i> ✓
2 pcs	Rear bumper side retainer	@ S\$ 39.10	<i>Pr</i>	78.20	✓
4 pcs	Rear bumper clip	@ S\$ 3.80	<i>Pr</i>	15.20	✓
1 pc	Rear end panel			630.10	✓
1 pc	End panel top garnish			282.50	✓
1 pc	Rear o/s chassis lower bracket		<i>Pr</i>	287.80	✓
1 pc	Rear exhaust silencer box		<i>Pr</i>	616.90	✓
1 pc	Rear exhaust chrome pipe		<i>Pr</i>	168.30	✓
2 pcs	Rear exhaust mounting	@ S\$ 26.30	<i>Pr</i>	52.60	✓
1 pc	Centre exhaust pipe		<i>Pr</i>	2,636.90	✓
1 pc	Tail gate		<i>Pr</i>	1,582.20	✓
1 pc	Tail gate "RX350" emblem		<i>Pr</i>	60.60	✓
1 pc	Tail gate "LEXUS" emblem		<i>Pr</i>	78.30	✓
				8,065.30	
Less 10% :				806.53	

1 pc Rear bumper reverse sensor(set)
1 pc Rear w/s glass sealant

Pr 7,258.77
300.00 sn 7
Pr 40.00 60.00 sn

To rewire damaged parts and refocus
headlamp beam.

20.00 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKA756S

Page : 2

To remove & refix rear windscreen
glass and conduct water leak test.

1200
150.00

To remove roof lining, front and
rear seats, trim board and carpet

100.00 600

To apply undersealing

100.00 600

To remove and renew rear exhaust
silencer box & centre exhaust pipe

120.00 1000

To putty and spray replaced parts

900.00 6600

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 8000

Total : S\$10,008.77
=====

Singapore Dollars Ten Thousand and Eight and
Cents Seventy Seven Only

Shu Pei (LKKAUTO)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 27 November, 2017 9:39 AM
To: Shu Pei (LKKAUTO)
Cc: Shu Pei (LKKAUTO)
Subject: CTP REF NO. SNM17D06716C02 LKK REF NO. CC6/CT117022352/KHB3 - ACCIDENT INVOLVING SKA756S AND SKD5218E ON 20 NOVEMBER 2017
Attachments: TayHP_SNM17D06716C02-SKA756S-LKKDirectSettlementAccidentLtr_CLCR95.978.pdf; GIA REPORT SKA756S.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and your email dated 24 November 2017.

We enclosed herewith a copy of our Insured GIA Report & Letter to our Insured for your attention.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE, LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.taiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM17D06716/C02/6**

Date : **27 NOVEMBER 2017**

via Ordinary & Registered Mail

**TW PREMIUM AUTOMOBILE PTE LTD
210 TURF CLUB ROAD
LOT A8 THE GRANDSTAND CARMALL
SINGAPORE 287995**

Dear Sir / Madam

**ACCIDENT INVOLVING SKA756S AND SKD5218E ON 20 NOVEMBER 2017
ALONG GAMBAS AVE EXIT WOODLANDS AVE 12**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SKD5218E**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIC
Ref : CC6/CTI17022352/KHB3
Contact No : 6841-2096
via Email : shupeil@lkkauto.com

CC : Agent - (AN0590A) - TECK WEI CREDIT PTE LTD

F01/LKKDS-2013



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17022352/Khb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-04-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKA 756S	Veh. Inspected	SKD 5218E
Policy No.	DMHCSN1715751700	Coverage (\$)	0.00
Claim No.	SNM17D06716C02/6	Excess (\$)	0.00
Assign From		Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	ACU300075997	Colour	METALLIC BLACK
Odometer	243408	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/50 R20	FALKEN	4 mm
L/H Front Tyre	245/50 R20	FALKEN	4 mm
R/H Rear Tyre	245/50 R20	FALKEN	3 mm
L/H Rear Tyre	245/50 R20	FALKEN	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/11/2017	Inspection Date	22/11/2017
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 5218E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER FASCIA	BUCKLED	752.20	752.20
1	REAR BUMPER SPONGE	CRACKED	111.40	111.40
1	REAR BUMPER REINFORCEMENT	BENT	458.50	458.50
2	REAR BUMPER REFLECTOR @\$126.80	O/S MTG CRACKED / N/S SERVICEABLE	253.60	126.80
2	REAR BUMPER SIDE RETAINER @\$39.10	SERVICEABLE	78.20	-
4	REAR BUMPER CLIP @\$3.80	NECESSARY	15.20	15.20
1	REAR END PANEL	TO REPAIR SEE LABOUR	630.10	-
1	END PANEL TOP GARNISH	SERVICEABLE	282.50	-
1	REAR O/S CHASSIS LOWER BRACKET	BENT	287.80	287.80
1	REAR EXHAUST SILENCER BOX	BENT	616.90	616.90
1	REAR EXHAUST CHROME PIPE	DENTED	168.30	168.30
2	REAR EXHAUST MOUNTING @\$26.30	CRACKED	52.60	52.60
1	CENTRE EXHAUST PIPE	BENT	2,636.90	2,636.90
1	TAIL GATE	BENT	1,582.20	1,582.20
1	TAIL GATE "RX350" EMBLEM	NECESSARY	60.60	60.60
1	TAIL GATE "LEXUS" EMBLEM	NECESSARY	78.30	78.30
	LESS 10% DISCOUNT		-806.53	-694.77
			7,258.77	6,252.93
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
			360.00	240.00
<u>LABOUR</u>				
	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM.	NOT NECESSARY	20.00	-
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET.		100.00	60.00

Report Ref No. CC6/CTI17022352/Khb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERSEALING.	NOT NECESSARY	100.00	-
	TO REMOVE AND RENEW REAR EXHAUST SILENCER BOX & CENTRE EXHAUST PIPE.		120.00	100.00
	TO PUTTY AND SPRAY REPLACED PARTS.		900.00	660.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,000.00	800.00
			2,390.00	1,740.00
GRAND TOTAL			10,008.77	8,232.93
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,550.00

Report Ref No. CC6/CTI17022352/Khb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.