

INS. CASE OWNER:

CC 3 / CTI170 22354, 16p3s2

LKK:  
IDAC:

Surveyor:

VSC

DOI:

ASSIGNMENT

22/11/17

Date / Time:

22/11/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKG 479K

Name of Insured:

JOHARI AMIT

Insured Tel No.:

HP: 96433700

Excess Sec II :SS

D.O.A: 2-11-17

Is driver the owner?

( YES / NO )

Nature of Accident:

Claim No.:

SNM 1700674202/9

Policy No.:

OMPLSN3039541705

Make / Model:

M-Benz C180K

Place of Accident:

Junction of Church St &amp; Cecil St.

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHE 5903B



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

22/11/17  
CHY

SHE 5903B - CTI170 22354 / 16p3s2 : 22/11/17

SKG 479K - X

\* video provided by insurer.

Based on OI CCTV footage, TP swerved into al lane and collided vehicle.

Potential Reject case.

13/22017 @  
3:53pm

Spoke to OI (Mr Johari) confirmed accident details and mentioned that TP encroached into his lane and collided onto his vehicle. Informed abt TP claim aware of NCD issue and agree to settle. Send email rejection approval to CTI.

20/22017

Send email to TP reject.

20/22017

File pass to insurers to close.

Reject Case  
By (staff): ZMN  
Approved by: YLW  
Date: 28-12-17

PRELIMINARY ADVICE Date/Time:

22/11

Sent By:

Hun

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

RECEIVED 27 DEC 2017

COPY SENT  
22/11/17

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$400.00

ASS. REC. BY:

REF: CT21

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cob

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S4C 5903B Yr Regn: 03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Peregrine Longitude c.c. 1995Colour M. White / Red A/C: Insured / Std / NI / NASp. Reading 256728 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: V1-1 ABL 15 AUG 281409Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: Giti 215/60R16R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 7 mmL/Bal. 9 mm L/Bal. 7 mmD.O.A. 21/11/17 D.O.I. 22/11/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/11/17 File pass to C.A. team  
\$1485.45

( P/p: \$1485.45 / Red: \$21,525.76 / 94% )

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: \_\_\_\_\_

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI17022354/Kpa3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 23-11-2017	
			Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKG 479K	Veh. Inspected	SHC 5903B	
Policy No.	DMPCSN3039541705	Coverage (\$)	0.00	
Claim No.	SNM17D06742C02/9	Excess (\$)	0.00	
Assign From		Assign Date	23/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	21/11/2017	Inspection Date	22/11/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5903B -****AAD1711-241***Not Ashank  
Penny B4 nam*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHC5903B - CANDY**  
VF1ABL15AUC281409  
RENAULT  
LATITUDE  
21.11.2017  
**CHINA TAIPING**

**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>R</i> 1,259.42 <i>X</i>
2	1	BUMPER SPOILER FRT	\$	<i>S</i> 181.75
3	1	BUMPER FOG LAMP GRILLE LH	\$	<i>S</i> 207.22
4	1	BUMPER RETAINER FRT LH	\$	<i>S</i> 151.41
5	1	BUMPER RETAINER FRT RH	\$	<i>S</i> 151.41
6	1	BUMPER SUPPORT FRT LH	\$	<i>S</i> 123.88
7	1	BUMPER SUPPORT FRT RH	\$	<i>S</i> 123.88
8	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
9	1	RADAIOR GRILLE	\$	<i>S</i> 1,707.78
10	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>R</i> 225.36
11	1	RADAIOR GRILLE FRAME	\$	<i>S</i> 1,353.75
12	1	FRAME FULL SUPPORT PANEL	\$	<i>S</i> 615.90
13	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
14	1	BONNET	\$	<i>R</i> 1,941.63
15	1	HEADLAMP LH	\$	<i>S</i> 1,184.43
16	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15
17	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 <i>✓</i>
18	1	FENDER INSULATOR LH	\$	<i>S</i> 130.84
19	1	WHEELARCH FRT LH	\$	<i>S</i> 278.84
20	1	DOOR MIRROR LH	\$	<i>S</i> 1,483.40
21	1	DOOR MIRROR GLASS LH	\$	<i>S</i> 148.20
22	1	DOOR MIRROR BACK COVER LH	\$	<i>S</i> 218.46
23	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
24	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50
25	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55

<b>TOTAL</b>	\$	<b>16,847.12</b>
<b>10%</b>	\$	<b>1,684.71</b>
	\$	<b>15,162.41</b>

**Specical Nett**

1	1SET	FRONT BUMPER CLIP	\$	<i>R</i> 66.00 <i>X</i>
2	1SET	WHEELARCH CLIP LH	\$	<i>R</i> 66.00 <i>X</i>

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1711-241**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5903B -**

3	1	TOW COVER FRT	\$	<i>sn</i> 14.50 X
4	1	CAP HUB LH FRT	\$	<i>sn</i> 35.00 X
5	1	RIM LH FRT	\$	<i>sn</i> 385.00 X
6	1	TYRE LH FRT	\$	<i>sn</i> 330.00 X
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	<i>nn</i> 9.80 X
8	1SET	BUMEPR RETAINER FRT CLIP LH	\$	<i>nn</i> 12.50 X
9	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 X
10	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 X

<b>TOTAL</b>	<b>\$</b>	<b>1,028.80</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>16,191.21</b>

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *3000*

To Check Electrical Lighting Concerned.

\$ 170.00 *100*

Putty and spray painting of the affected portion.

\$ 3,000.00 *4000*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

Towing Fees

\$ *nn* 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 *300*

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *nn* 170.00 X

<b>TOTAL</b>	<b>\$</b>	<b>6,820.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>23,011.21</b>

**(PARTS BY PARTS) Repair Days****10 Days***2 days*

- LKK Auto Consultants hence notify the Repairer of the following:
- To display damaged part(s) during survey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC3/CTI17022354/Kpa3

Date: 23.11.2017

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC 5903B**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/11/2017 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	23,011.21
Revised Estimate Amount	: S\$	1,485.45
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
N/S Front Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KENNETH KONG  
Licensed Appraiser



## Zaini (LKK Auto)

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Thursday, 14 December, 2017 2:19 PM  
**To:** Zaini (LKK Auto); Admin A; Hsiao Tong (LKKAuto)  
**Cc:** Irene Tay; Alfred Toh; Hwang Shiang Yi; Chee So Chow; KKLau  
**Subject:** Accident Involving SKG479K (OI : CTI - SNM17D06742C02/9) AND SHC5903B (TP : LKK REF - CC3/CTI17022354/Kpa3) on 21/11/2017  
**Attachments:** SKG479K.mp4

LKK REF - CC3/CTI17022354/Kpa3  
CTI REF - SNM17D06742C02/9 (SKG479K)

Dear Zaini

We refer to your email of 13 December 2017 pertaining to the above matter.

Please proceed to reject the third party claim in the first instance.

Regards

Alfred Toh  
Senior Executive  
Claims Department  
China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
#15-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID : +65 6389 6183  
FAX: +65 6224 7175/6224 7478  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Zaini (LKK Auto) [mailto:Zaini@lkkauto.com]  
**Sent:** Wednesday, December 13, 2017 4:13 PM  
**To:** Joel Goh <joel.goh@sg.cntaiping.com>  
**Cc:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>  
**Subject:** RE: Direct Settlement - Accident Involving SKG479K (OI : CTI - SNM17D06742C02/9) AND SHC5903B (TP : LKK REF - CC3/CTI17022354/Kpa3) on 21/11/2017

Your Ref: SNM17D06742C02/9  
Our Ref: CC3/CTI17022354/Kpa3

Dear Joel,

**ACCIDENT INVOLVING VEHICLES SKG 479K(OI) AND SHC 5903B(TP) ON 21/11/2017**

We refer to the above matter.

TP reported that he was travelling straight within his lane when OI swerved into his lane and collided onto his left side front portion. No photos or CCTV footage provided by TP till date.

OI reported that he was travelling within his lane when TP collided onto his right side portion of his vehicle. Enclosed copy of OI CCTV footage as attached for your easy review.

Based on OI CCTV footage, after review, we observed OI vehicle was travelling within his lane when TP vehicle encroached into his lane which resulted in the collision.

We had spoken to the Insured where he confirmed that at the material time, he was travelling at the said location as reported when TP vehicle encroached into his lane and collided onto the right portion of his vehicle. OI further mentioned that his PD recovery claim against TP is still in the process and will revert for any update.

Based on the OI CCTV footage and accident scenario, we are of the view that OI version is more credible.

As such, we intend to reject the TP claim.

For your approval and/or further instructions please.

Thank you.

Best Regards,

**Zaini Kusaini** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841-2132 | email: [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com) | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joel Goh [<mailto:joel.goh@sg.cntaiping.com>]

**Sent:** Friday, 24 November, 2017 2:30 PM

**To:** Mei Kwan (LKKAuto)

**Cc:** Hsiao Tong (LKKAuto); Zaini (LKK Auto); Admin A

**Subject:** RE: Direct Settlement - Accident Involving SKG479K (OI : CTI - SNM17D06742C02/9) AND SHC5903B (TP : LKK REF - CC3/CTI17022354/Kpa3) on 21/11/2017

Dear Mei Kwan

Attached our insured accident report and video footage for your attention.

Best Regards

Joel Goh

Claims Executive (Motor Division)

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-02

Springleaf Tower Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6184

Fax: 6224 7175 / 6224 7478

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

[joel.goh@sg.cntaiping.com](mailto:joel.goh@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any*



## Zaini (LKK Auto)

---

**From:** Zaini (LKK Auto)  
**Sent:** Wednesday, 20 December, 2017 3:42 PM  
**To:** 'claims@transcab.com.sg'  
**Cc:** Hsiao Tong (LKKAuto); 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; 'Zhe Wei' (zhewei.kek@transcab.com.sg)  
**Subject:** Your ref: SHC 5903B\_ACCIDENT INVOLVING VEHICLES SKG 479K AND SHC 5903B ON 21/11/2017  
**Attachments:** SKG479K.MP4

Your ref: SHC 5903B  
Our ref: CC3/CTI17022354/Kpa3

"WITHOUT PREJUDICE"

Dear Sirs,

### ACCIDENT INVOLVING VEHICLES SKG 479K AND SHC 5903B ON 21/11/2017

We refer to the above matter.

Please be informed that our principal had further reviewed the matter and based on the available information and evidence at hand, our principal is in the view that our Insured is not liable of the accident.

Based on the accident scenario and CCTV footage after review, our principal are in view that our insured's vehicle was travelling within his lane when your client's vehicle encroached into his lane and resulted in the collision.

In view of the above and with our principal's instruction, we regret to inform you that we are unable to further look into your claim.

As such, we will close file in our end.

Thank you.

Best Regards,

**Zaini Kusaini** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841-2132 | email: [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com) | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17022354/Kka3s2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 04-01-2018		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKG 479K	Veh. Inspected	SHC 5903B	
Policy No.	DMPCSN3039541705	Coverage (\$)	0.00	
Claim No.	SNM17D06742C02/9	Excess (\$)	0.00	
Assign From		Assign Date	22/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC281409	Colour	METALLIC WHITE / RED	
Odometer	256728	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	GITI	9 mm	
L/H Front Tyre	215/60R16	GITI	9 mm	
R/H Rear Tyre	215/60R16	GOODYEAR	7 mm	
L/H Rear Tyre	215/60R16	GOODYEAR	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/11/2017	Inspection Date	22/11/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5903B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,259.42	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.22	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT LH	SERVICEABLE	123.88	-
1	BUMPER SUPPORT FRT RH	SERVICEABLE	123.88	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'	NOT NECESSARY	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	DOOR MIRROR LH	SERVICEABLE	1,483.40	-
1	DOOR MIRROR GLASS LH	SERVICEABLE	148.20	-
1	DOOR MIRROR BACK COVER LH	SERVICEABLE	218.46	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-

Report Ref No. CC3/CT117022354/Kka3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,684.71	-78.38
			15,162.41	705.45
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET WHEELARCH CLIP LH (SN)	NOT NECESSARY	66.00	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	SET BUMPER SUPPORT FRT CLIP LH (SN)	NOT NECESSARY	9.80	-
1	SET BUMPER RETAINER FRT CLIP LH (SN)	NOT NECESSARY	12.50	-
1	DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	30.00	-
			1,028.80	-
	<b><u>LABOUR</u></b>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT, BUMPER BEAM FRT, FRAME FULL SUPPORT BRACKET, BONNET, HEADLAMP PANEL FRT LH, DOOR PANEL FRT LH, DOOR HINGE UPPER LH AND DOOR HINGE LOWER LH.		2,800.00	300.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			6,820.00	780.00
	<b>GRAND TOTAL</b>		<b>23,011.21</b>	<b>1,485.45</b>

Report Ref No. CC3/CT117022354/Kka3s2



RECOMMENDED COST OF REPAIRS			1,485.45
-----------------------------	--	--	----------

Report Ref No. CC3/CT117022354/Kka3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.