

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5903B -**AAD1711-241***Not Notified**Presum B4 party*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5903B - CANDY

VF1ABL15AUC281409

RENAULT

LATITUDE

21.11.2017

CHINA TAIPING**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>R</i> 1,259.42	<i>X</i>
2	1	BUMPER SPOILER FRT	\$	<i>Su</i> 181.75	<i>X</i>
3	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Su</i> 207.22	
4	1	BUMPER RETAINER FRT LH	\$	<i>Su</i> 151.41	
5	1	BUMPER RETAINER FRT RH	\$	<i>Su</i> 151.41	
6	1	BUMPER SUPPORT FRT LH	\$	<i>Su</i> 123.88	
7	1	BUMPER SUPPORT FRT RH	\$	<i>Su</i> 123.88	
8	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	<i>X</i>
9	1	RADAITOR GRILLE	\$	<i>Su</i> 1,707.78	
10	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>nn</i> 225.36	
11	1	RADAITOR GRILLE FRAME	\$	<i>Su</i> 1,353.75	
12	1	FRAME FULL SUPPORT PANEL	\$	<i>Su</i> 615.90	
13	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
14	1	BONNET	\$	<i>R</i> 1,941.63	<i>X</i>
15	1	HEADLAMP LH	\$	<i>Su</i> 1,184.43	
16	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	
17	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83	
18	1	FENDER INSULATOR LH	\$	<i>Su</i> 130.84	
19	1	WHEELARCH FRT LH	\$	<i>Su</i> 278.84	
20	1	DOOR MIRROR LH	\$	<i>Su</i> 1,483.40	<i>X</i>
21	1	DOOR MIRROR GLASS LH	\$	<i>Su</i> 148.20	
22	1	DOOR MIRROR BACK COVER LH	\$	<i>Su</i> 218.46	
23	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66	
24	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50	
25	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55	

TOTAL	\$	16,847.12
10%	\$	1,684.71
	\$	15,162.41

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00	<i>X</i>
2	1SET	WHEELARCH CLIP LH	\$	<i>nn</i> 66.00	<i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-241**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5903B -

3	1	TOW COVER FRT	\$	<i>Sm</i> 14.50 X
4	1	CAP HUB LH FRT	\$	<i>Sm</i> 35.00 X
5	1	RIM LH FRT	\$	<i>Sm</i> 385.00 X
6	1	TYRE LH FRT	\$	<i>Sm</i> 330.00 X
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	<i>nn</i> 9.80 X
8	1SET	BUMEPR RETAINER FRT CLIP LH	\$	<i>nn</i> 12.50 X
9	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 X
10	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 X

TOTAL	\$	1,028.80
TOTAL PARTS	\$	16,191.21

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *3000*

To Check Electrical Lighting Concerned.

\$ 170.00 *100*

Putty and spray painting of the affected portion.

\$ 3,000.00 *4800*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

Towing Fees

\$ *nn* 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 *300*

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *nn* 170.00 X

TOTAL	\$	6,820.00
Over All Total	\$	23,011.21

(PARTS BY PARTS) Repair Days**10 Days***2 days*