



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20171101/0719		LOCATION OF FIRE: Along SLE towards CTE Before Woodlands Avenue 2 exit Singapore	
FIRE REPORTED ON : 01 November 2017			
TIME OF CALL : 18:10:12 hrs			
STATION COVERAGE : Woodlands Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of a Honda car (EW8382P) along the road shoulder, near lamp post no. 618 at the above said location.			
METHOD OF EXTINGUISHMENT: By SCDF crew using compressed air foam and hose reel jet from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating in the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine was damaged. The front part of the car, including the windscreen, was also damaged. The dashboard and interior of the car sustained heat and smoke damage. SCDF crew forced the bonnet open for firefighting.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY: YAZEED B ABD RAHMAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.