

Estimate Report

Page 3 of 4

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
48	2		*FRONT DRIVESHAFT OIL SEAL LH & RH	0.00	NN	0.00 2X *36.00 F X
49	1		*FRONT STEERING RACK COMPLETE	0.00	bt	0.00 1,000.00 F ✓
50	1		*REAR CROSSMEMBER ASSY	0.00	bt	0.00 1,400.00 F ✓
51	2		*REAR WHEEL BEARING WITH HUB LH & RH	0.00	bt	0.00 540.00 F ✓
52	2		*REAR ABSORBER LH & RH	0.00	bt	0.00 150.00 F hpc
53	2		*REAR ABS CABLE LH & RH	0.00	syc	0.00 400.00 F X
54	2		*FRONT WHEEL KUNCKLE LH & RH	0.00	bt	0.00 760.00 F ✓
55	2		*FRONT WHEEL BEARING WITH HUB LH & RH	0.00	bt	0.00 500.00 F ✓
56	2		*FRONT ABS CABLE LH & RH	0.00	syc	0.00 500.00 F X
57	1		*ENGINE MOUNTING RH	0.00	dis	0.00 220.00 F ✓
58	1		*ENGINE MOUNTING FRONT CENTER	0.00	syc	0.00 70.00 F X
59	1		*ENGINE MOUNTING REAR CENTER	0.00	dis	0.00 70.00 F ✓
60	1		*GEARBOX MOUNTING LH	0.00	syc	0.00 70.00 F X
61	1		*ENGINE LOWER OIL SUMP -CHECK PRICE	0.00	syc	0.00 -F X
62	2		*FRONT STEEL RIM	0	0.00	0 360.00 FS ✓
63	2		*REAR STEEL RIM	0	0.00	0 360.00 FS ✓
64	2		*FRONT TYRE	0	0.00	0 160 -FS ✓
65	2		*REAR TYRE	0	0.00	0 160 -FS ✓
66	2		*FRONT DOOR COMPANY STICKER BLACK	0	NN	0 60.00 FS
67	2		*REAR STEEL RIM COVER	0	0.00	0 260.00 FS ✓
68	2		*FRONT STEEL RIM COVER	0	0.00	0 260.00 FS ✓
69	1		*ENGINE LOWER OIL SUMP SEALANT	0	NN	0 60.00 FS X
70	1		*ENGINE FLUID	0	NN	0 80.00 FS X
71	1		*NUMBER PLATE FRONT	0	0.00	0 35.00 FS X

F=Franchise part. S=Specialty damaged part(s) during resurvey

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey and spray painting
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Sub Total (\$\$) 15,990.00
 + Margin on L,N Items 15.00% (\$\$) 2,177.25
 Total Parts (\$\$) 18,167.25

Ah Lim Motor Company/GBC3594T/22/11/2017 15:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	30 40.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	100 120.00
3	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	60 80.00
4	TO REMOVE AND REPLACE ENGINE MOUNTING AND GEARBOX MOUNTING	New	2 150 180.00
5	TO REMOVE AND REPLACE ENGINE LOWER OIL SUMP	New	X? 180 180.00
6	TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. (FRONT)	New	450 500.00
7	TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. (REAR)	New	200 300.00
8	TO REMOVE AND REINSTALL REAR BUMPER SENSORS.	New	60 80.00
9	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	120 180.00
10	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL; HEADLAMP LOWER SIDE BRACKET; BUMPER REINFORCEMENT. TO KNOCK & REPAIR FRONT DOOR LH & RH; FRONT WHEELHOUSE SIDE PANEL LH & RH; FRONT CHASSIS FRAME LH & RH	New	800 1,000.00
11	TO SPRAY FRONT BUMER TOP SIDE GARNISH LH & RH; FRONT BONNET; FRONT FENDER X2; RADIOAOTR SUPPORT PANEL; HEADLAMP LOWER SIDE BRACKET X2; FRONT DOOR X2; WHEELHOUSE SIDE PANEL X2; CHASSIS FRAME X2	New	900 1,400.00
Gross Labour Cost (\$\$)			4,060.00

Ah Lim Motor Company/GBC3594T/22/11/2017 15:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110
TEL: 62239433 FAX: 62234190
ATTN: Motor Claim Department

Estimate No: MC0912607
Date: 08 Dec 2017
Policy No: DMCPHQ17-000117
Veh Reg No: GBC3594T
Make/Model: NISSAN NV200 1.5L MT
ABS AIRBAG2WD 6DR

Your Ref No: -
Claim Type: Own Damage
Accident Date: 18/11/2017

Estimate Repair Cost to Vehicle No :GBC3594T

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
SPARE PARTS				
1 A/C COMPRESSOR BELTING <i>dfs</i>		1 PC	38.00 ✓	
2 A/C COMPRESSOR ASSY <i>dfs</i>		1 PC	1,200.00 ✓	
3 FRONT BUMPER LOWER COVER CENTRE <i>dfs</i>		1 PC	150.00 ✓	
4 FRONT BUMPER LOWER COVER CENTRE CLIPS X 4 <i>nuc</i>		4 PC	8.00 ✓	
5 POWER STEERING FLUID <i>X. NN</i>		1 PC	40.00 X	
			1,436.00	
	Add 15%		215.40	1,651.40

LABOUR

6 TO REMOVE AND REPLACE A/C COMPRESSOR, A/C COMPRESSOR BELTING	1 PC	120.00 <i>100</i>	120.00
--	------	-------------------	--------

Resnu
01/12/2017

Amount Before Excess	S\$ 1,771.40
GST Amount	S\$ 124.00
Total Amount payable	S\$ 1,895.40

The above vehicle was surveyed by LKK - MR MA on 23/11/2017

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : EQ INSURANCE COMPANY LIMITED
 5 MAXWELL ROAD
 #17-00 TOWER BLOCK MND COMPLEX
 SINGAPORE 069110
 TEL: 62239433 FAX: 62234190
 ATTN: Motor Claim Department

Claim No: MC0912607
 Ref No: MF0910773
 Date: 26 Jan 2018
 Policy No: DMCPhQ17-000117
 Veh Reg No: GBC3594T
 Make/Model: NISSAN NV200 1.5L MT
 ABS AIRBAG2WD 6DR

Your Ref No: -
 Claim Type: Own Damage
 Accident Date: 18/11/2017

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):GBC3594T

Description	U/Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 FRONT BUMPER		1 PC	280.00	
2 FRONT BUMPER SIDE RETAINERS LH & RH		2 PC	36.00	
3 FRONT BUMPER CLIPS		12 PC	24.00	
4 ENGINE UNDER COVER		1 PC	150.00	
5 RADIATOR SUPPORT PANEL LOWER		1 PC	150.00	
6 RADIATOR SUPORT PANEL SIDE RH		1 PC	45.00	
7 RADIATOR ASSY		1 PC	400.00	
8 A/C CONDENSER		1 PC	450.00	
9 FRONT FENDER LH & RH		2 PC	590.00	
10 FRONT FENDER COWLING LH & RH		2 PC	190.00	
11 FRONT FENDER COWLING CLIPS		20 PC	40.00	
12 REAR BUMPER		1 PC	450.00	
13 REAR BUMPER SIDE RETAINER LH		1 PC	25.00	
14 FRONT CROSSMEMBER COMPLETE		1 PC	350.00	
15 FRONT STABILISER BAR LINK LH & RH		2 PC	56.00	
16 FRONT LOWER ARM WITH ABLL JOINT LH		1 PC	130.00	
17 FRONT LOWER ARM WITH BALL JOINT RH		1 PC	130.00	
18 FRONT ABSORBER LH & RH		2 PC	260.00	
19 FRONT ABSORBER TOP MOUNTING LH & RH		2 PC	130.00	
20 FRONT ABSORBER TOP MOUNTING BEARING LH & RH		2 PC	160.00	
21 FRONT STEERING RACK COMPLETE		1 PC	1,000.00	
22 REAR CROSSMEMBER ASSY		1 PC	1,400.00	
23 REAR WHEEL BEARING WITH HUB LH & RH		2 PC	540.00	
24 REAR ABSORBER LH		1 PC	75.00	
25 FRONT WHEEL KUNCKLE LH & RH		2 PC	760.00	
26 FRONT WHEEL BEARING WITH HUB LH & RH		2 PC	500.00	
27 ENGINE MOUNTING RH		1 PC	220.00	
28 ENGINE MOUNTING REAR CENTER		1 PC	70.00	
29 A/C COMPRESSOR BELTING		1 PC	38.00	
30 A/C COMPRESSOR ASSY		1 PC	1,200.00	
31 FRONT BUMPER LOWER COVER CENTRE		1 PC	150.00	
32 FRONT BUMPER LOWER COVER CENTRE CLIPS X 4		4 PC	8.00	
			10,007.00	
			1,501.05	11,508.05
Special Nett				
33 FRONT STEEL RIM		2 PC	360.00	
34 REAR STEEL RIM LH		1 PC	180.00	

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel. 6483 1244 Fax 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALIZATION

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110
TEL: 62239433 FAX: 62234190
ATTN: Motor Claim Department

Claim No: MC0912607
Ref No: MF0910773
Date: 26 Jan 2018
Policy No: DMCPHQ17-000117
Veh Reg No: GBC3594T
Make/Model: NISSAN NV200 1.5L MT
ABS AIRBAG2WD 6DR

Your Ref No: -
Claim Type: Own Damage
Accident Date: 18/11/2017

DRAFT FINALIZATION

Repair Cost to Vehicle No (For Finalization):GBC3594T

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
35 FRONT TYRE LH & RH (80% OF 80 PER TYRE)		2 PC	128.00	
36 REAR TYRE LH (80% OF 80 PER TYRE)		1 PC	64.00	
37 REAR STEEL RIM COVER LH		1 PC	130.00	
38 FRONT STEEL RIM COVER LH & RH		2 PC	260.00	
				1,122.00
LABOUR				
39 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	30.00	
40 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
41 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	60.00	
42 TO REMOVE AND REPLACE ENGINE MOUNTING AND GEARBOX MOUNTING		1 PC	150.00	
43 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. (FRONT)		1 PC	450.00	
44 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. (REAR)		1 PC	250.00	
45 TO REMOVE AND REINSTALL REAR BUMPER SENSORS.		1 PC	60.00	
46 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	120.00	
47 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, HEADLAMP LOWER SIDE BRACKET, BUMPER REINFORCEMENT. TO KNOCK & REPAIR FRONT DOOR LH & RH, FRONT WHEELHOUSE SIDE PANEL LH & RH, FRONT CHASSIS FRAME LH & RH		1 PC	800.00	
48 TO SPRAY FRONT BUMPER TOP SIDE GARNISH LH & RH, FRONT BONNET, FRONT FENDER X2, RADIATOR SUPPORT PANEL, HEADLAMP LOWER SIDE BRACKET X2, FRONT DOOR X2, WHEELHOUSE SIDE PANEL X2, CHASSIS FRAME X2		1 PC	900.00	
49 TO REMOVE AND REPLACE A/C COMPRESSOR, A/C COMPRESSOR BELTING		1 PC	100.00	
				3,020.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110
TEL: 62239433 FAX: 62234190
ATTN: Motor Claim Department

Claim No: MC0912607
Ref No: MF0910773
Date: 26 Jan 2018
Policy No: DMCPhQ17-000117
Veh Reg No: GBC3594T
Make/Model: NISSAN NV200 1.5L MT
ABS, AIRBAG2WD 6DR

Your Ref No: -
Claim Type: Own Damage
Accident Date: 18/11/2017

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):GBC3594T

Total	S\$ 15,650.05
Lump Sum Less 20%	-3,130.01
Amount Before Excess	S\$ 12,520.04
Less Rounding	-20.04
Amount Before Excess	S\$ 12,500.00
Less Excess	S\$ 3,500.00
Amount Before GST	S\$ 9,000.00
Add GST @ 7%	630.00
Total Amount payable	S\$ 9,630.00

TOTAL: SINGAPORE DOLLAR NINE THOUSAND SIX HUNDRED THIRTY ONLY

The above vehicle was surveyed by LKK - MR MA on 23/11/2017

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

Estimate Report

Page 3 of 4

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
48	2		*FRONT DRIVESHAFT OIL SEAL-LH & RH	0.00	0.00	*36.00 F
49	1		*FRONT STEERING RACK COMPLETE	0.00	0.00	*1,000.00 F-plate
50	1		*REAR CROSSMEMBER ASSY	0.00	0.00	*1,400.00 F-plate
51	2		*REAR WHEEL BEARING WITH HUB LH & RH	0.00	0.00	*540.00 F
52	2		*REAR ABSORBER LH & RH	0.00	0.00	*150.00 F
53	2		*REAR ABS CABLE LH & RH	0.00	0.00	*400.00 F
54	2		*FRONT WHEEL KUNCKLE LH & RH	0.00	0.00	*760.00 F-plate
55	2		*FRONT WHEEL BEARING WITH HUB LH & RH	0.00	0.00	*500.00 F-plate
56	2		*FRONT ABS CABLE LH & RH	0.00	0.00	*500.00 F
57	1		*ENGINE MOUNTING RH	0.00	0.00	*220.00 F-plate
58	1		*ENGINE MOUNTING FRONT CENTER	0.00	0.00	*70.00 F
59	1		*ENGINE MOUNTING REAR CENTER	0.00	0.00	*70.00 F-plate
60	1		*GEARBOX MOUNTING LH	0.00	0.00	*70.00 F
61	1		*ENGINE LOWER OIL SUMP CHECK PRICE	0.00	0.00	*F
62	2		*FRONT STEEL RIM	0.00	0.00	*360.00 FS
63	2		*REAR STEEL RIM	0.00	0.00	*360.00 FS
64	2		*FRONT TYRE	0.00	0.00	*FS
65	2		*REAR TYRE	0.00	0.00	*FS
66	2		*FRONT DOOR COMPANY STICKER BLACK	0.00	0.00	*60.00 FS
67	2		*REAR STEEL RIM COVER	0.00	0.00	*260.00 FS
68	2		*FRONT STEEL RIM COVER	0.00	0.00	*260.00 FS
69	1		*ENGINE LOWER OIL SUMP SEALANT	0.00	0.00	*60.00 FS
70	1		*ENGINE FLUID	0.00	0.00	*80.00 FS
71	1		*NUMBER PLATE FRONT	0.00	0.00	*35.00 ES

F=Franchise part, S=SpclNett.

Sub Total (\$\$) 15,990.00
+ Margin on L,N Items 15.00% (\$\$) 2,177.25

Total Parts (\$\$) 18,167.25

Ah Lim Motor Company/GBC3594T/22/11/2017 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	120.00
3	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00
4	TO REMOVE AND REPLACE ENGINE MOUNTING AND GEARBOX MOUNTING	New	180.00
5	TO REMOVE AND REPLACE ENGINE LOWER OIL SUMP	New	180.00
6	TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. (FRONT)	New	500.00
7	TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. (REAR)	New	300.00
8	TO REMOVE AND REINSTALL REAR BUMPER SENSORS.	New	80.00
9	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	180.00
10	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL; HEADLAMP LOWER SIDE BRACKET; BUMPER REINFORCEMENT. TO KNOCK & REPAIR FRONT DOOR LH & RH; FRONT WHEELHOUSE SIDE PANEL LH & RH; FRONT CHASSIS FRAME LH & RH	New	1,000.00
11	TO SPRAY FRONT BUMPER TOP SIDE GARNISH LH & RH; FRONT BONNET; FRONT FENDER X2; RADIO/OTR SUPPORT PANEL; HEADLAMP LOWER SIDE BRACKET X2; FRONT DOOR X2; WHEELHOUSE SIDE PANEL X2; CHASSIS FRAME X2	New	1,400.00
Gross Labour Cost (\$\$)			4,060.00

Ah Lim Motor Company/GBC3594T/22/11/2017 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Nov 2017)

Parts: N/A NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/GBC3594T/22/11/2017 15:46

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*FRONT BONNET	R	0.00	0.00	X*400.00 F R
2	1		*FRONT BONNET-HINGE-LH	R	0.00	0.00	X*35.00 F R
3	1		*FRONT BONNET-HINGE-RH	R	0.00	0.00	X*35.00 F R
4	8		*FRONT BONNET-INSULATOR-CLIPS	NIN	0.00	0.00	X*12.00 F R
5	1		*FRONT GRILLE	SVC	0.00	0.00	X*190.00 F R
6	1		*FRONT GRILLE-CHROME-MOULDING LOWER	NIN	0.00	0.00	X*85.00 F
7	1		*FRONT GRILLE EMBLEM	NIN	0.00	0.00	X*45.00 F
8	6		*FRONT GRILLE-CLIPS	NIN	0.00	0.00	X*12.00 F R
9	1		*HEADLAMP LH	SVC	0.00	0.00	X*220.00 F
10	1		*HEADLAMP RH	SVC	0.00	0.00	X*220.00 F
11	2		*HEADLAMP LOWER SIDE BRACKET LH & RH	SVC	0.00	0.00	X*140.00 F R
12	2		*FRONT BUMPER TOP SIDE GARNISH LH & RH	SVC	0.00	0.00	X*320.00 F R
13	10		*FRONT BUMPER TOP-SIDE-GARNISH-CLIPS	NIN	0.00	0.00	X*20.00 F
14	1		*FRONT BUMPER	def	0.00	0.00	X*280.00 F def
15	2		*FRONT BUMPER SIDE RETAINERS LH & RH	dis	0.00	0.00	X*36.00 F dis
16	12		*FRONT BUMPER CLIPS	nee	0.00	0.00	X*24.00 F R
17	1		*FRONT BUMPER-TOW-COVER-LH	SVC	0.00	0.00	X*18.00 F R
18	1		*FRONT BUMPER SPONGE	SVC	0.00	0.00	X*125.00 F X
19	1		*FRONT BUMPER REINFORCEMENT	SVC	0.00	0.00	X*280.00 F
20	1		*ENGINE UNDER COVER	def	0.00	0.00	X*150.00 F
21	2		*FOGLAMP LH & RH	SVC	0.00	0.00	X*440.00 F
22	1		*RADIATOR SUPPORT-PANEL-TOPI	R	0.00	0.00	X*185.00 F
23	1		*RADIATOR SUPPORT PANEL LOWER	bt	0.00	0.00	X*150.00 F
24	1		*RADIATOR SUPPORT-PANEL-INNER-SIDE-AIR-GUIDE LH	SVC	0.00	0.00	X*25.00 F
25	1		*RADIATOR SUPPORT-PANEL-INNER-SIDE-AIR-GUIDE RH	SVC	0.00	0.00	X*25.00 F
26	2		*RADIATOR SUPORT PANEL SIDE LH & RH	SVC	0.00	0.00	X*90.00 F R
27	1		*INTERCOOLER ASSY	SVC	0.00	0.00	X*1,000.00 F
28	1		*RADIATOR ASSY	SVC	0.00	0.00	X*400.00 F R
29	1		*A/C CONDENSER	SVC	0.00	0.00	X*450.00 F R
30	2		*FRONT FENDER LH & RH	bt	0.00	0.00	X*590.00 F
31	2		*FRONT FENDER COWLING LH & RH	dis	0.00	0.00	X*190.00 F
32	20		*FRONT FENDER COWLING CLIPS	rec	0.00	0.00	X*40.00 F
33	1		*REAR BUMPER	def	0.00	0.00	X*450.00 F
34	1		*REAR BUMPER SIDE RETAINER LH	dis	0.00	0.00	X*25.00 F
35	1		*FRONT CROSSMEMBER COMPLETE	bt	0.00	0.00	X*350.00 F
36	1		*FRONT CROSSMEMBER SIDE-BRACKET-LH	R	0.00	0.00	X*75.00 F
37	1		*FRONT CROSSMEMBER SIDE BRACKET RH	R	0.00	0.00	X*75.00 F
38	1		*FRONT STABILISER-BAR-CHECK-PRICE	SVC	0.00	0.00	X*75.00 F
39	2		*FRONT STABILISER BAR LINK LH & RH	bt	0.00	0.00	X*56.00 F
40	1		*FRONT LOWER ARM WITH ABLL JOINT LH	bt	0.00	0.00	X*130.00 F
41	1		*FRONT LOWER ARM WITH BALL JOINT RH	bt	0.00	0.00	X*130.00 F
42	2		*FRONT ABSORBER LH & RH	bt	0.00	0.00	X*260.00 F
43	2		*FRONT ABSORBER TOP MOUNTING LH & RH	dis	0.00	0.00	X*130.00 F
44	2		*FRONT ABSORBER TOP MOUNTING BEARING LH & RH	nee	0.00	0.00	X*160.00 F
45	2		*FRONT-ABSORBER-DAMPER-LH-&RH	SVC	0.00	0.00	X*76.00 F
46	1		*FRONT-DRIVESHAFT-COMplete-LH	SVC	0.00	0.00	X*650.00 F
47	1		*FRONT-DRIVESHAFT-COMplete-RH-CHECK-PRICE	SVC	0.00	0.00	X*75.00 F

Ah Lim Motor Company/GBC3594T/22/11/2017 15:46. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2017 15:39 Sendback Est	22 Nov 2017 15:46 S\$22,227.25	22 Nov 2017 18:16 Edit Adj Rpt	S\$12,500.00 Edit Estimates	S\$12,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	EQUIP-DESIGN & SUPPLY PTE LTD, Co. Reg. No.: 197402224W, Tel: +6596641361		
Vehicle Reg. No.:	GBC3594T	Date of Loss:	18/11/2017 22:00 - :59 [69 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DM17H002612	Policy/Cover Note No.:	DMCPHQ17-000117 (Comprehensive)
		Excess:	S\$3,500.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Elaine Cheong - 6500 6772]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 01/12/2017]		
Driver/Custodian:	GUNASEKARAN NATHAN (40 / Male), NRIC: F8460778U, Tel: +6590032640		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- EQI_HQ (29/11/2017): Alert - Adj Mandate Approved (S\$14000.00) - GBC3594T - Claim Handler: Elaine Che...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBC3594T (DM17H002612)
OD
Nov 18 2017 10:00PM
[EQUIP-DESIGN & SUPPLY PTE LTD]
Ah Lim Motor Company

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page		☒			
No	Finalized On	Ah Lim Motor Company (AMK)							Thumbnail		Print			
1	22/11/17 15:46	Repairer Estimates							 Load HTM					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	24/11/17 16:47	Adjuster Immediate Advice							 Load HTM					
2	27/11/17 10:59	Adjuster Immediate Advice							 Load HTM					
Photos/Images									3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	23/11/17 18:49	General View							 Load JPG		☒			
2	23/11/17 18:49	General View							 Load JPG		☒			
3	23/11/17 18:49	General View							 Load JPG		☒			
4	23/11/17 18:49	General View							 Load JPG		☒			
5	23/11/17 18:49	General View							 Load JPG		☒			
6	23/11/17 18:49	General View							 Load JPG		☒			
7	23/11/17 18:49	General View							 Load JPG		☒			
8	23/11/17 18:49	General View							 Load JPG		☒			
9	23/11/17 18:49	General View							 Load JPG		☒			
10	23/11/17 18:49	General View							 Load JPG		☒			
11	23/11/17 18:49	General View							 Load JPG		☒			
12	23/11/17 18:49	General View							 Load JPG		☒			
13	23/11/17 18:49	General View							 Load JPG		☒			
14	23/11/17 18:49	General View							 Load JPG		☒			
15	23/11/17 18:49	General View							 Load JPG		☒			
16	23/11/17 18:49	General View							 Load JPG		☒			
17	23/11/17 18:49	General View							 Load JPG		☒			
18	23/11/17 18:49	General View							 Load JPG		☒			
19	23/11/17 18:49	General View							 Load JPG		☒			
20	23/11/17 18:49	General View							 Load JPG		☒			
21	23/11/17 18:49	General View							 Load JPG		☒			
22	23/11/17 18:49	General View							 Load JPG		☒			
23	23/11/17 18:49	General View							 Load JPG		☒			
24	23/11/17 18:49	General View							 Load JPG		☒			
25	23/11/17 18:49	General View							 Load JPG		☒			
26	23/11/17 18:49	General View							 Load JPG		☒			
27	23/11/17 18:49	General View							 Load JPG		☒			
28	23/11/17 18:49	General View							 Load JPG		☒			
29	23/11/17 18:49	General View							 Load JPG		☒			
30	23/11/17 18:49	General View							 Load JPG		☒			
31	23/11/17 18:49	General View							 Load JPG		☒			
32	23/11/17 18:49	General View							 Load JPG		☒			
33	23/11/17 18:49	General View							 Load JPG					

Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
				☒
34	23/11/17 18:49	General View	 Load JPG	☒
35	23/11/17 18:49	General View	 Load JPG	☒
36	23/11/17 18:49	General View	 Load JPG	☒
37	23/11/17 18:49	General View	 Load JPG	☒
38	23/11/17 18:49	General View	 Load JPG	☒
39	23/11/17 18:49	General View	 Load JPG	☒
40	23/11/17 18:49	General View	 Load JPG	☒
41	23/11/17 18:49	General View	 Load JPG	☒
42	23/11/17 18:49	General View	 Load JPG	☒
43	23/11/17 18:49	General View	 Load JPG	☒
44	23/11/17 18:49	General View	 Load JPG	☒
45	23/11/17 18:49	General View	 Load JPG	☒
46	23/11/17 18:49	General View	 Load JPG	☒
47	23/11/17 18:49	General View	 Load JPG	☒
48	23/11/17 18:49	General View	 Load JPG	☒
49	23/11/17 18:49	General View	 Load JPG	☒
50	23/11/17 18:49	General View	 Load JPG	☒
51	23/11/17 18:49	General View	 Load JPG	☒
52	23/11/17 18:49	General View	 Load JPG	☒
53	23/11/17 18:49	General View	 Load JPG	☒
54	23/11/17 18:49	General View	 Load JPG	☒
55	23/11/17 18:49	General View	 Load JPG	☒
56	23/11/17 18:49	General View	 Load JPG	☒
57	23/11/17 18:49	General View	 Load JPG	☒
58	23/11/17 18:49	General View	 Load JPG	☒
59	23/11/17 18:49	General View	 Load JPG	☒
60	23/11/17 18:49	General View	 Load JPG	☒
61	23/11/17 18:49	General View	 Load JPG	☒
62	24/07/18 19:13	Photo After Spray	 Load JPG	☒
63	24/07/18 19:13	Photo After Spray	 Load JPG	☒
64	24/07/18 19:13	Photo After Spray	 Load JPG	☒
65	24/07/18 19:13	Photo After Spray	 Load JPG	☒
66	24/07/18 19:13	Photo After Spray	 Load JPG	☒
67	24/07/18 19:13	Photo After Spray	 Load JPG	☒
68	24/07/18 19:13	Photo After Spray	 Load JPG	☒
69	24/07/18 19:13	Photo After Spray	 Load JPG	☒
70	24/07/18 19:13	Photo After Spray	 Load JPG	☒
71	24/07/18 19:13	Photo After Spray	 Load JPG	☒
72	24/07/18 19:13	Photo After Spray	 Load JPG	☒
73	24/07/18 19:13	Photo After Spray	 Load JPG	☒
74	24/07/18 19:13	Photo After Spray	 Load JPG	☒
75	24/07/18 19:13	Photo After Spray	 Load JPG	☒
76	24/07/18 19:13	Photo After Spray	 Load JPG	☒
77	24/07/18 19:13	Photo After Spray	 Load JPG	☒
78	24/07/18 19:13	Photo After Spray	 Load JPG	☒
79	24/07/18 19:13	Photo After Spray	 Load JPG	☒
80	24/07/18 19:13	Photo After Spray	 Load JPG	☒
81	24/07/18 19:13	Photo After Spray	 Load JPG	☒
82	24/07/18 19:13	Photo After Spray	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
83	24/07/18 19:13	Photo After Spray	 Load JPG	☒
84	24/07/18 19:13	Photo After Spray	 Load JPG	☒
85	24/07/18 19:13	Photo After Spray	 Load JPG	☒
86	24/07/18 19:13	Photo After Spray	 Load JPG	☒
87	24/07/18 19:13	Photo After Spray	 Load JPG	☒
88	24/07/18 19:13	Photo After Spray	 Load JPG	☒
89	24/07/18 19:13	Photo After Spray	 Load JPG	☒
90	24/07/18 19:13	Photo After Spray	 Load JPG	☒
91	24/07/18 19:13	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/18 09:59	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	20/11/17 14:14	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	20/11/17 14:06	Accident Photo	 Load JPG	☒
2	20/11/17 14:06	Accident Photo	 Load JPG	☒
3	20/11/17 14:06	Accident Photo	 Load JPG	☒
4	20/11/17 14:06	Accident Photo	 Load JPG	☒
5	20/11/17 14:06	Accident Photo	 Load JPG	☒
6	20/11/17 14:06	Accident Photo	 Load JPG	☒
7	20/11/17 14:06	Accident Photo	 Load JPG	☒
8	20/11/17 14:06	Accident Photo	 Load JPG	☒
9	20/11/17 14:06	Accident Photo	 Load JPG	☒
10	20/11/17 14:06	Accident Photo	 Load JPG	☒
11	20/11/17 14:06	Accident Photo	 Load JPG	☒
12	20/11/17 14:06	Accident Photo	 Load JPG	☒
13	20/11/17 14:06	Accident Photo	 Load JPG	☒
14	20/11/17 14:06	Accident Photo	 Load JPG	☒
15	20/11/17 14:06	Accident Photo	 Load JPG	☒
16	20/11/17 14:06	Accident Photo	 Load JPG	☒
17	20/11/17 14:06	Accident Photo	 Load JPG	☒
18	20/11/17 14:06	Accident Photo	 Load JPG	☒
19	20/11/17 14:06	Accident Photo	 Load JPG	☒
20	20/11/17 14:06	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	20/11/17 14:04	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.