

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		20	SPARE TYRE	Reviewing	0	SERVICEABLE	
		21	DAYS OF REPAIR	Reviewing	2		

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	 5	SET BUMPER RETAINER RH CLIP RR	Reviewing	0	NOT NECESSARY	
	 6	SET BUMPER BRACKET SIDE CLIP LH RR	Reviewing	0	NOT NECESSARY	
	 7	SET BUMPER RETAINER CLIP LH RR	Reviewing	0	NOT NECESSARY	
	 8	SET BUMPER LOWER REAR RIVET	Reviewing	0	NOT NECESSARY	
	 9	SET BUMPER LOWER REAR CLIP	Reviewing	66	NECESSARY	
	 10	EXHAUST MOUNTING REAR	Reviewing	0	SERVICEABLE	
	 11	SET BOOT FINISHER CLIP	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	2		PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	200	0	0	Reviewing	
	3		TO RUST-PROOFING OF THE AFFECTED AREAS.	0	0	0	Reviewing	
	4		TO REINSTALL REAR BUMPER PARKING SENSOR.	60	0	0	Reviewing	
	5		TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing	
	6		TO REPAIR AND REALIGN REAR EXHAUST PIPE.	0	0	0	Reviewing	
	7		TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	0	0	0	Reviewing	
	8		TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing	
	9		TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	0	0	0	Reviewing	
	10		TOWING FEES.	0	0	0	Reviewing	
	11		TO TRANSFER OF REAR WINSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	0	0	0	Reviewing	
	12		TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	0	0	0	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	10	1			BUMPER BEAM REAR			Bent	777.52		10		699.77
	11	1			BUMPER BEAM BRACKET LH REAR			Repair	0		10		0
	12	1			BUMPER BEAM BRACKET RH REAR			Bent	225.94		10		203.35
	13	1			BOOT REAR			Repair	0		10		0
	14	1			BOOT FINISHER			Serviceable	0		10		0
	15	1			BOOT WEATHERSTRIP			Serviceable	0		10		0
	16	1			BOOT REFLECTOR LAMP LH			Serviceable	0		10		0
	17	1			BOOT REFLECTOR LAMP RH			Serviceable	0		10		0
	18	1			BOOT BADGE 'RENAULT'			Serviceable	0		10		0
	19	1			BOOT BADGE			Serviceable	0		10		0
	20	1			BOOT SWITCH			Serviceable	0		10		0
	21	1			BOOT LOCK			Repair	0		10		0
	22	1			BOOT LOCK CATCH			Repair	0		10		0
	23	2			LICENCE PLATE LAMP			Serviceable	0		10		0

Save

Detailed Assessment

Inspection Date *

11/22/2017



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/60R16

Rear Tyre Size

215/60R16

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S1423876Z

POST SURVEY INF ...

Make

CATEGORY

POLICY INFORMAT... TPVD RENAULT

ASSESSMENT INFO... RENAULT

Model

CATEGORY

POLICY INFORMAT... LATITUDE

ASSESSMENT INFO... LATITUDE 2.0L DCI AUTO D/AB 4DR

Type

CATEGORY

POLICY INFORMAT...

ASSESSMENT INFO...

Type of Paint

CATEGORY

POLICY INFORMAT...

ASSESSMENT INFO...

Chassis No

CATEGORY

POLICY INFORMAT...

ASSESSMENT INFO...

Date of Birth

CATEGORY

FNOL INFORMATI...

POST SURVEY INF ...



mm/dd/yyyy

Age

CATEGORY

FNOL INFORMATI... 0

POST SURVEY INF...

Occupation

CATEGORY

Unknown

FNOL INFORMATI...

POST SURVEY INF...

Education Qualification

CATEGORY

Other

FNOL INFORMATI...

POST SURVEY INF...

Driving Experience

CATEGORY

Direct settlement

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Add

(1) TP: ARC (2) HEAD TO REAR

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
LOH Cynthia	11/24/17 5:15 PM	\$3,276.94	\$3,276.94	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Preliminary Advice.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	November 27, 2017
EMAIL.pdf	Forms / Claim Documents	Others	KUMAR Shailendra	November 24, 2017
ESTIMATE.pdf	Forms / Claim Documents	Estimate / Quotation	KUMAR Shailendra	November 24, 2017
SHD0179C TP GIA.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	November 24, 2017
Ltr to Insured- reported.docx	Letters and Correspondence	Policy Holders / Insured	KUMAR Shailendra	November 24, 2017

Direct settlement

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

Messages Invoices History Documents

(1) TP: ARC (2) HEAD TO REAR

Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	April 27, 2018
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	April 27, 2018