

ASS. REC. BY:

REF: CS/FCL1707363/Uwb02

Special Instruction:

Surveyor: MANS**ASSIGNMENT (Office)**From (Person): (WS) Ang Yin Min of FCL Date/Time: 22/12/07 540pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKK 3488T Insured: SHA 9296Dat Workshop m/s Hock Wah Tel: 6311 5655of Bik 3011 Bedok Ind Park E #012008Policy No: _____ Claim No: D17010847MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21.11.2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement: _____

Date/Time: 23/11/07 9.29am Person Contacted: MANS Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKK 3488T - ✓ / TP17028690 / TICC
	SHA 9296D - x
<u>24/11/17</u>	<u>Send preti revised to FCI</u>

Signature: *marcu*

REF:

FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SKK3488T*
 at Workshop m/s *hueleneb*
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *93*
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: *13* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SKK3488T* Yr Regn: *613*
 Type: *M* Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA*
 Make: *Audi A4* c.c. *1798*
 Colour: *Brown* A/C: Insured / Std / NI / NA
 Sp. Reading: *53237* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *WAUZZZ8K0DA203538*
 Gen. Cond: *Good* / Fair / Poor / Burnt
 Steering: *In order* / Jammed / Leaked / Burnt or
 Brake: *In order* / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: *225/50 R17*
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. *7* mm R/Bal. *7* mm
 L/Bal. *7* mm L/Bal. *7* mm
 D.O.A. *21/11/17* D.O.I. *23/11/17*
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rf. O/S.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *L7A 67095 dep 14h*
Sys. 7mth nett 25905

28/11/17 confirmed d/s @ 25,000 with no v.i.s (Red 42,424, 6312)

Date/Time. File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: *13*

Resurvey No. of Trip: *3*

Date/Time. File Return to?

2) *28/12- typist*

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format: *CWS*

Lump Sum / I.B.I. (\$ *25000/2*)

Survey Fee:

Transportation:

☐ S + RS. ☐ SI

☐ Photos

☐ Others

57 x 15 = 855

170 + 855

50

50 + 50 + 50

165

1390

5/1/18

Survey Department Check List (Case Handler)

Reference No. : CS/FCX 17022363/4vb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 28/01/17
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022363/Uvb

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 23-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9296D	Veh. Inspected	SKK 3488T
Policy No.		Coverage (\$)	0.00
Claim No.	D17010847MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	21/11/2017	Inspection Date	23/11/2017
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	21-11-2017	Our Ref No.	D17010847MFSH
Accident Date	21-11-2017	Claim Type.	Third Party
Insured Vehicle	SHA9296D	Third Party Vehicle.	SKK3488T
Survey Location	BLK 3011 BEDOK INDUSTRIAL PARK E BEDOK NORTH AVE 4#01-2008/10/12		
Contact Person.	MAVIS ER		
Contact No.	64415655/ 62438121	Fax No.	62438121
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HOCK WAH MOTOR WORKSHOP PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	AUNGYM		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230497)



PRI Documents



Close X

PRI Header Details

Claim No	D17010847MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & HO PTE LTD
Workshop Name	HOCK WAH MOTOR WORKSHOP PTE LTD (Contact Person : MAVIS ER)	Survey Location & Contact Details	BLK 3011 BEDOK INDUSTRIAL PARK E BEDOK 2008/10/12 Mobile: 62438121 , Phone: 64415655 , Fax: EmailId: MOTOR@HOCKWAH.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9296D	TP Vehicle No	SKK341
PRI Recieved Date	22-11-2017 12:28:06 AM	Surveyor Appointed Date	22-11-2017 05:40:41 PM	Surveyor Accept Date	22-11-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-11-2017	Upload Survey Report *:	
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 24 November, 2017 11:54 AM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010847MFSH/1, SKK 3488T
Attachments: SKK 3488T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKK 3488T
Date of survey: 23/11/2017
Number of days: 13 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 23 November, 2017 9:30 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010847MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 22 November, 2017 5:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; AUNGYINMIN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010847MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17010847MSFH
Our ref: CS/FCI17022363/Uvb

DATE: 24/11/2017

The Motor Claims Department
M/s First Capital Insurance Limited

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SKK 3488T


We thank for your instruction on 22/11/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 23/11/2017 at the premises of M/s HOCK WAH MOTOR WORKSHOP PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$67,424.00
Revised Estimate Amount	: S\$35,347.88
"Check" Items Amount	: S\$17,061.46
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Foreign Identification Number
Owner ID	0364R

Vehicle Details

Vehicle No.	SKK3488T
Vehicle to be Exported	No
Intended De-registration Date	23 Nov 2017
Vehicle Make	AUDI
Vehicle Model	A4 1.8 TFSI MU (NAVIGATION & XENON)
Primary Colour	Brown
Manufacturing Year	2013
Engine No.	CJE047811
Chassis No.	WAUZZZ8K0DA203538
Maximum Power Output	125.0 kW (167 bhp)
Open Market Value	\$36,797.00
Original Registration Date	28 Jun 2013
First Registration Date	28 Jun 2013
Transfer Count	1
Actual ARF Paid	\$33,516.00 16758

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Jun 2023
PARF Rebate Amount	\$25,137.00

Intended COE Rebate Details

COE Expiry Date	27 Jun 2023
COE Category	E - Open Category
COE Period(Years)	10

QP Paid	\$76,000.00
COE Rebate Amount	\$41,958.00
Total Rebate Amount	\$67,095.00

The information contained herein is correct as at 23 Nov 2017

OK

facebook

www.facebook.com/sgcarmart


 our official
Facebook page now!


Email Add

Sign Up New Ac

Forgot Passwor

Post an Advertisement

 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Cpe Renewal 2007 Honda Sitrion 1.8A RS2


 \$3900 Downpayment 10 Years
 Price \$700 Onwards 1 Year
 3 Month A 3 PM 10000000
 GV Credit Pte Ltd

 Lake View
 Credit Pte Ltd

view our cars

 > Low prices guaranteed
 > Specialist in Japanese cars
 > Easy loan approval
 > All terms are negotiable

Browse by Category

Sort by Date Posted

20 results/page

9 vehicles

Audi A4

Advanced Search

	Make	Model	Price	Depreciation	Eng Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi A4		Any	Any	2013	Any	Any	Any	Availa
	Audi A4	Audi A4 2.0A TFSI Quattro S-Tronic S-Line	\$113,800	\$15,040 /yr	29-Nov-2013	1,984 cc	22,000 km	Luxury	Availa
	\$12k Drive Away! Agent Unit! 2.0 Quattro S-Tronic With S-Line Kit Fully Serviced And Maintained By Audi! Extremely Under Utilized Unit. The Audi A4 Is The Perfect Car For Luxury, Comfort And Stylish R...								
	Dynamic Motoring								
	Posted: 14-Nov-2017 Tags: 2013 Audi A4, 2013 Audi A4, Audi A4, Audi A4, Audi, A4, A4, Used Audi								
	Audi A4	Audi A4 1.8A TFSI MU	\$94,000	\$13,910 /yr	25-Jun-2013	1,798 cc	46,000 km	Luxury	Availa
	Low Mileage At 46,000km. Serviced At Premium Automobiles. Rare Volcano Red With Upgraded 18" Sports Rims, Carbon Fibre Boot Lip Spoiler, Upgraded Sound System (hertz And Jbl Amplifier), Stage 1 Revo T...								
	Carro								
	Posted: 11-Nov-2017 Tags: 2013 Audi A4, 2013 Audi A4, Audi A4, Audi A4, Audi, A4, A4, Used Audi								
	Audi A4	Audi A4 1.8A TFSI MU	\$101,999	\$14,890 /yr	15-Aug-2013	1,798 cc	78,000 km	Luxury	Availa
	One Owner, Premium Pre-owned 110 Points Check, Flexible Finance Package And Trade In Can Be Arranged. Please SMS For For Viewing Appointment Or Further Enquiries. Thank You.								
	Premium Automobiles								
	Posted: 06-Nov-2017 Tags: 2013 Audi A4, 2013 Audi A4, Audi A4, Audi A4, Audi, A4, A4, Used Audi								
	Audi A4	Audi A4 2.0A TFSI Quattro S-Tronic S-Line	\$98,800	\$13,600 /yr	12-Jun-2013	1,984 cc	58,000 km	Luxury	Availa
	Fully Serviced And Maintained By Audi! 90% Loan Available! Original Prestige Condition With Beautiful Interior! Very Fuel Efficient. Regular Servicing Done! Smooth Responsive Engine And Gearbox! Desig...								
	Posted: 04-Nov-2017 Tags: 2013 Audi A4, 2013 Audi A4, Audi A4, Audi A4, Audi, A4, A4, Used Audi								

Car Buying

Car Selling

Car Aftermarket

 Buying a pre-owned car, be
 Unsure of its Condition

Car Ownership

On The Move

Lifestyle

Get. STA Car Evaluati



Audi A4 1.8A TFSI MU

\$93,800

\$13,370 /yr

28-Aug-2013

1,798 cc

83,000 km

Luxury

Availa

The Audi A4, Well Loved For It's Well-Proportioned Looks, Powerful Turbo Engines And Premium Feel Of It's Interior Thus Making This A Popular Choice For The Compact Executive Class. This Unit Is Well ...

Posted: 28-Oct-2017 Tags: 2013 Audi A4, 2013 Audi A4, Audi A4, Audi A4, Audi, A4, A4, Used Audi

 Audi A4 1.8A TFSI MU
 Attraction Plus

\$92,700

.260 /yr

28-Aug-2013

1,798 cc

92,000 km

Luxury

Availa



Facelifted Model. High Specs Attraction Plus Model. 01 Owner. Maintained By Premium Auto. 100% Accident Free. Meticulously Maintained On Both Interior And Exterior By Previous Owner. Quiet Engine And ...

Posted: 24-Oct-2017 Tags: 2013 Audi A4, 2013 Audi A4, Audi A4, Audi A4, Audi, A4, A4, Used Audi

De



Audi A4 1.8A TFSI MU Attraction Plus **\$103,800** \$15,300 /yr 13-Aug-2013 1,798 cc 74,000 km Luxury **Availa**

Superb Condition.Fully Agent Maintained Unit! Still Under Warranty! Only 1 Owner. Welcome STA Evaluation. Up To 80% Loan Available. Consignment Unit! Kindly Call/SMS For Viewing Appointment!

Prem Roy Motoring

Posted: 09-Oct-2017 Tags: 2013 Audi A4, 2013 Audi A4, Audi A4, Audi A4, Audi, A4, A4, Used Audi

De



Audi A4 2.0A TFSI Quattro S-tronic **\$105,099** \$14,890 /yr 13-Jun-2013 1,984 cc 89,000 km Luxury **Availa**

Premium Pre-owned 110 Points Check, Fle : Package And Trade-in Can Be Arranged. Please Call/SMS YC For Further Enquiries Or Appointment For Viewing.

Premium Automobiles

Posted: 05-Oct-2017 Tags: 2013 Audi A4, 2013 Audi A4, Audi A4, Audi A4, Audi, A4, A4, Used Audi

De



Audi A4 1.8A TFSI MU Attraction Plus **\$95,000** \$15,610 /yr 22-Feb-2013 1,798 cc 46,600 km Luxury **Availa**

Glacier White Exterior With Black Interior. Memory Electric Seat With Lumbar Support. LTA Approve Tinting. Just Service At 42200km. Under Use Airline Crew Car. 100% Accident Free. Please SMS/Whatsapp ...

Posted: 21-Sep-2017 Tags: 2013 Audi A4, 2013 Audi A4, Audi A4, Audi A4, Audi, A4, A4, Used Audi

De

Save this search criteria, to get email alerts whenever a match is found.

Reg No Model Price Depreciation Reg Cost Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports & station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi A4 Singapore, used Audi A4 Singapore, used Audi A4, used vehicles Singapore or even buy used Audi A4 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and us dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mov performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given th information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
 - New Car
 - Used Car
 - Sell Car
 - Motoring Directory
 - Products Guide
 - Article
 - Forum
 - Tool & Tip
- About
 - Career
 - Contact
 - Sitemap

- Consumer Safety and Rights lacking in Singapore - Ikea
- MCF Members Introduction
- Liverpool 2017/18: YNWA with Klopp

Username / Email Add

password Submit Qu

Connect Sign Up New Account
Forgot Password

audi a4 Price Range Depreciation 2013 Vehicle Type Submit Advanced Search

Home » Used Cars » Prem Roy Motoring » Audi A4 1.8A TFSI MU Attraction Plus

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Tyres



Audi A4 1.8A TFSI MU Attraction Plus

Overview Financial Accessories Similar Research Photos Map

RENTCARLEASE PTE LTD is affiliated with

PRM
Prem Roy Motoring Pte Ltd
DRIVE YOUR DREAM

COMPLETE CAR TRADE SOLUTIONS

Add to Shortlist Tweet Add to Compare Add a Note Report Error More Actions Share

CAR TRADE

Price	\$103,800
Depreciation	\$15,300 /yr View models with similar depreciation
Reg Date	13-Aug-2013 (5yrs 8mths 20days COE left)
Mileage	74,080 km (17.3k /yr)
Transmission	Auto
Engine Cap	1,798 cc
Road Tax	\$976 /yr
Power	125.0 kW (167 bhp) View specs of the Audi A4 (2008-2016)
Features	1.8 L Turbo Engine, 170 BHP, Paddle Shift, Audi Drive Select, Push Start/Stop Function, LED Daytime Running Light, 3 Zone Auto Aircon, Keyless Entry.
Accessories	Audi MMI With Navigation, Bluetooth Telephone, USB, SD Card. Audi Drive Select With Different Driving Modes. Original LED Lamp. Fog Lights.
Description	Superb Condition. Fully Agent Maintained Unit! Still Under Warranty! Only 1 Owner. Welcome STA Evaluation. Up To 80% Loan Available. Consignment Unit! Kindly Call/SMS For Viewing Appointment!
COE	\$77,600
OMV	\$36,135
ARF	\$32,589
Dereg Value	\$68,833 as of today (change)
No. of Owners	1
Type of Veh	Luxury Sedan
Category	PARF Car, Premium Ad Car
Availability	Available

Add to Shortlist Add to Compare Add a Note

Posted on: 09-Oct-2017 | Last Updated on: 09-Oct-2017

Tags: Audi A4, Audi A4, 2013 Audi A4, 2013 Audi A4, Audi, A4, A4, Used Audi

Upfront Payment [» more Financial info](#)


Transfer Fee	\$11	
Down Payment	\$41,520 (change)	Maximum 60% Loan
1st Instalment	\$1,071	
Total Upfront Payment	\$42,602 (excluding insurance)	

Estimates based on 60% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Audi A4 [» View All](#)

	Chrome Exhaust Tip \$48		Reverse Camera \$950
	Foot Pedals \$150		Carbon Fibre Spoiler \$320
	Car Mat From \$40		Bidded Carplate For Sale \$33,800

Compare




Seller Information

Company	Prem Roy Motoring » dealer's pricelist » 161 vehs sold 190 vehs available
Address	9 Tagore Lane #02-03 Search cars nearby this location
Location	9@ Tagore
Office No	66028046
Contact Person(s)	Peter 94570645 Kana 96435365

Company Profile

Used Car List





CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



Username / Email Add
 password
 [Sign Up New Account](#)
[Forgot Password](#)

audi a4

Home » Used Cars » Direct Owners » Audi A4 1.8A TFSI MU Attraction Plus

Tools & Tips

[Car Buying](#)

[Car Selling](#)

[Car Aftermarket](#)

[Car Ownership](#)

[On The Move](#)

[Lifestyle](#)

Audi A4 1.8A TFSI MU Attraction Plus

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

DIRECT OWNER

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#) [Share](#)

Car Details

Price **\$95,000**
Depreciation **\$15,610 /yr**
[View models with similar depreciation](#)

Reg Date **22-Feb-2013**
(5yrs 2mths 29days COE left)

Manufactured **2012**

Mileage **46,600 km (9.8k /yr)**

Transmission **Auto**

Engine Cap **1,798 cc**

Road Tax **\$976 /yr**

Power **125.0 kW (167 bhp)**
[View specs of the Audi A4 \(2005-2007\)](#)

Curb Weight **1,545 kg**

Features **1.8L Turbo Engine. 170Bhp. Paddle Shift. Cruise Control. Audi Drive Select. Push Start/Stop Function. LED Daytime Running Light. 3 Zone Auto Aircon.**

Accessories **Upgraded 18" Sports Rim. Reverse Camera. SD Card Reader. Audi Music Interface. Bluetooth. MMI GPS Navigation. DVD Player. Multi Function Steering Wheel.**

Description **Glacier White Exterior With Black Interior. Memory Electric Seat With Lumbar Support. LTA Approve Tinting. Just Service At 42200km. Under Use Airline Crew Car. 100% Accident Free. Please SMS/Whatsapp To Arrange For Car Viewing Or Test Drive. Will Reply And Arrange Once I'm Back To Singapore. Price Negotiable Plus Extra Accessories To Go With It.**

COE **\$92,667**

OMV **\$36,119**

ARF **\$26,119**

Dereg Value **\$68,233 as of today (change)**

No. of Owners **1**

Type of Veh **Luxury Sedan**

Category **PARF Car, Direct Owner Sale, Low Mileage Car**

Availability **Available**

DIRECT OWNER

[Add to Shortlist](#)

[Add to Compare](#)

[Add a Note](#)

Posted on: 21-Sep-2017 | Last Updated on: 18-Nov-2017

Tags: Audi A4, Audi A4, 2013 Audi A4, 2013 Audi A4, Audi, A4, A4, Used Audi



Seller Information

Contact Person(s) **Gavin**

Contact No. **96622089**

USEFUL FORMS

[» Indemnity form](#) [» Sales agreement](#)

[» Receipt](#) [» Hand-over form](#)

[» M01](#)

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Vehicle Number Plates

Your AUSPICIOUS & UNIQUE Vehicle No.
Do you know? We are Singapore's
with the most vehicle plate numbers for sale?
[Click here to see all Auspicious Numbers!](#)



21st ASIAN GAMES
Jakarta Palembang
2018

**ASIAN
GAMES
18.8.18**

[FIND OUT MORE](#)



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2017 14:49
Date Of Accident	21/11/2017 07:45
Exact Location Of Accident	ALONG UPPER CHANGI ROAD TOWARDS SIMEI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK3488T
Insured/Policyholder	
Name Of Registered Owner	VIJAYAN SUDHAKAR
NRIC No	G5810364R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92722014
Alternative Phone No	OTHERS-85719067
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 1.8 TFSI MU (NAVIGATION & XENON)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5063640778-03
Cover Note Number	10/01/2017-09/01/2018
Driver	
Name of Driver	SUDHAKAR INDU
NRIC No	G5833127P
Date Of Birth	11/12/1967
Occupation	INDOOR
Date Of Driving Pass	10/08/2006
Driving Experience	11 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-85719067
Fax Number	(LOCAL) +65-85719067
Contact Number	OTHERS-85719067
EEmail Address	INDU.SUDHAKAR@GMAIL.COM

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name SUDHAKAR INDU

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKK3488T

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name UDAY SUDHAKAR

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKK3488T

Were seat belts worn? YES


Was injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time: 21/11/17 15204RS

Radu Duakar

Driver's Signature
(If driver is not the policyholder)
Date & Time:

21/11/17 1520 HRS

dan

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : G5810364R
VIJAYAN SUDHAKAR
NO 8 PARI DEDAP WALK
#14-11 TANAMERA CREST
SINGAPORE 486061
TEL : FAX :
PH : 92722014
ATTN :

Term:

ESTIMATE BILL

Number : EB00004668
Date : 21/11/2017
Case No : AD00009406
Vehicle No : SKK3488T
Chassis : WAUZZZ8K0DA20353:
Year of Mfr : 2013
Policy No : 5063640778-03
Model : AUDI A4 1.8 TFSI MU
(NAVIGATION &

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BATTERY SENSOR <i>an</i>	1.0	492.15	0	492.15
2	FRONT WINDSCREEN <i>one</i>	1.0	968.65	0	968.65
3	FRONT WINDSCREEN MOULDING <i>new</i>	2.0	49.65	0	99.30
4	FRONT BONNET <i>3uc</i>	1.0	2,025.75	0	2,025.75
5	FRONT BONNET HINGE LH <i>new</i>	1.0	54.70	0	54.70
6	FRONT BONNET HINGE RH <i>new</i>	1.0	54.70	0	54.70
7	FRONT BONNET TOP LOCK & FRONT BONNET OPEN HANDLER <i>new/one</i>	1.0	103.95	0	103.95
8	FRONT BONNET LOWER LOCK <i>new</i>	1.0	160.00	0	160.00
9	FRONT BONNET STOPPER <i>new</i>	2.0	10.50	0	21.00
10	FRONT BONNET INSULATOR <i>To 1</i>	1.0	246.20	0	246.20
11	FRONT BONNET INSULATOR CLIPS <i>new</i>	5.0	2.50	0	12.50
12	FRONT BONNET SHOCK ABSORBER <i>an</i>	1.0	87.35	0	87.35
13	FRONT BONNET RUBBER <i>To 1</i>	1.0	19.95	0	19.95
14	FRONT SUPPORT PANEL <i>3uc/one</i>	1.0	800.75	0	800.75
15	FRONT SUPPORT PANEL TOP GARNISH <i>an</i>	1.0	91.35	0	91.35
16	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>an</i>	8.0	2.50	0	20.00
17	FRONT HEADLIGHT LH (ASSEMBLY) <i>holder one</i>	1.0	1,861.05	0	1,861.05
18	FRONT HEADLIGHT RH (ASSEMBLY) <i>3 no</i>	1.0	1,861.05	0	1,861.05
19	FRONT HEADLIGHT LOWER BRACKET LH <i>an</i>	1.0	87.50	0	87.50
20	FRONT HEADLIGHT LOWER BRACKET RH <i>one</i>	1.0	87.50	0	87.50
21	FRONT HEADLIGHT BULB HID RH <i>an</i>	1.0	500.45	0	500.45
22	FRONT HEADLIGHT ECU RH <i>an</i>	1.0	478.05	0	478.05
23	FRONT SUPPORT PANEL TOP AIR DUST <i>D.S</i>	1.0	102.20	0	102.20
24	FRONT AIR CLEARING HOUSING <i>an</i>	1.0	321.85	0	321.85
25	FRONT WHEEL HOUSING RH (ASSEMBLY) <i>N</i>	1.0	1,978.65	0	1,978.65
26	FRONT FENDER LH <i>3uc</i>	1.0	744.40	0	744.40
27	FRONT FENDER RH <i>10/15uc</i>	1.0	744.40	0	744.40
28	FRONT FENDER SHIELD LH <i>an</i>	1.0	177.25	0	177.25
29	FRONT FENDER SHIELD RH <i>To 1</i>	1.0	177.25	0	177.25
30	FRONT FENDER SHIELD CLIPS <i>new</i>	8.0	2.50	0	20.00
31	FRONT SUPPORT INNER CENTER SIDE GARNISH LH <i>an</i>	1.0	25.90	0	25.90
32	FRONT SUPPORT INNER CENTER SIDE GARNISH RH <i>To 1</i>	1.0	25.90	0	25.90
33	FRONT INTANK COOLER <i>an</i>	1.0	329.30	0	329.30

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD



CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : G5810364R
VIJAYAN SUDHAKAR
NO 8 PARI DEDAP WALK
#14-11 TANAMERA CREST
SINGAPORE 486061
TEL : FAX :
PH : 92722014
ATTN :

ESTIMATE BILL

Number : EB00004668
Date : 21/11/2017
Case No : AD00009406
Vehicle No : SKK3488T
Chassis : WAUZZZ8K0DA20353:
Year of Mfr 2013
Policy No 5063640778-03
Model : AUDI A4 1.8 TFSI MU
(NAVIGATION &

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
34	FRONT AIR CON CONDENSOR <i>11</i>	1.0	813.45	0	813.45
35	FRONT RADIATOR <i>11</i>	1.0	728.25	0	728.25
36	FRONT RADIATOR BRACKET LH <i>11</i>	1.0	2.50	0	2.50
37	FRONT RADIATOR BRACKET RH <i>11</i>	1.0	2.50	0	2.50
38	FRONT RADIATOR FAN & MOTOR <i>11</i>	1.0	744.40	0	744.40
39	FRONT RADIATOR COWLING <i>11</i>	1.0	270.65	0	270.65
40	FRONT AIR CON FAN & MOTOR <i>11</i>	1.0	642.85	0	642.85
41	FRONT BONNET CABLE <i>11</i>	1.0	35.95	0	35.95
42	FRONT GRILLE & FRONT GRILLE CHROME <i>one</i>	1.0	829.60	0	829.60
43	FRONT GRILLE CHROME LOGO <i>one</i>	1.0	93.65	0	93.65
44	FRONT HEADLIGHT NOZZEL RH <i>3/20</i>	1.0	178.95	0	178.95
45	FRONT HEADLIGHT NOZZEL COVER <i>70.1</i>	1.0	41.10	0	41.10
46	FRONT HEADLIGHT NOZZEL PIPE <i>70.1</i>	1.0	192.95	0	192.95
47	FRONT HEADLIGHT NOZZEL JOINT <i>one</i>	1.0	20.75	0	20.75
48	FRONT ENGINE MOULDING <i>Mountings 11</i>	2.0	526.15	0	1,052.30
49	FRONT BUMPER <i>D.J</i>	1.0	1,794.25	0	1,794.25
50	FRONT BUMPER SIDE RETAINER LH <i>11</i>	1.0	25.55	0	25.55
51	FRONT BUMPER SIDE RETAINER RH <i>D.J</i>	1.0	25.55	0	25.55
52	FRONT BUMPER BRACKET LH <i>11</i>	1.0	157.75	0	157.75
53	FRONT BUMPER BRACKET RH <i>Bar</i>	1.0	157.75	0	157.75
54	FRONT BUMPER REINFORCEMENT <i>Bar</i>	1.0	677.70	0	677.70
55	FRONT BUMPER SPONGE <i>70.1</i>	3.0	89.20	0	267.60
56	FRONT BUMPER FOG LAMP & FOG LAMP BRACKET LH <i>11</i>	1.0	204.65	0	204.65
57	FRONT BUMPER FOG LAMP & FOG LAMP BRACKET RH <i>5/20</i>	1.0	204.65	0	204.65
58	FRONT BUMPER FOG LAMP GRILLE LH <i>MB</i>	1.0	98.65	0	98.65
59	FRONT BUMPER FOG LAMP GRILLE RH <i>70.1</i>	1.0	98.65	0	98.65
60	FRONT BUMPER CENTER LOWER GRILLE <i>70.1</i>	1.0	98.65	0	98.65
61	FRONT ENGINE LOWER DUST COVER <i>11</i>	1.0	484.75	0	484.75
62	FRONT BUMPER TOWING COVER <i>70.1</i>	1.0	36.70	0	36.70
63	FRONT LOWER ARM RH <i>11</i>	1.0	540.20	0	540.20
64	FRONT KNUCKLE ARM RH <i>11</i>	1.0	1,197.25	0	1,197.25
65	FRONT SHOCK ABSORBER RH <i>11</i>	1.0	1,437.85	0	1,437.85
66	FRONT SHOCK ABSORBER MOULDING RH <i>11</i>	1.0	52.10	0	52.10
67	FRONT WHEEL BEARING RH <i>11</i>	1.0	625.95	0	625.95

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD



CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : G5810364R
VIJAYAN SUDHAKAR
NO 8 PARI DEDAP WALK
#14-11 TANAMERA CREST
SINGAPORE 486061
TEL : FAX :
PH : 92722014
ATTN :

ESTIMATE BILL

Number : EB00004668
Date : 21/11/2017
Case No : AD00009406
Vehicle No : SKK3488T
Chassis : WAUZZZ8K0DA203531
Year of Mfr : 2013
Policy No : 5063640778-03
Model : AUDI A4 1.8 TFSI MU
(NAVIGATION &

Term:

Sn	DESCRIPTION	QTY	U PRICE	XENON DISC	AMOUNT
68	FRONT UPPER ARM RH 11	1.0	540.20	0	540.20
69	FRONT CONTROL ARM 11	2.0	1,003.25	0	2,006.50
70	FRONT DOOR OUTER CHROME RH 11	1.0	229.60	0	229.60
71	FRONT DOOR OUTER TOP CHROME RH 11	1.0	467.85	0	467.85
72	FRONT ROOF LINING waped / DIS 1140	1.0	1,572.35	0	1,572.35
73	FRONT ROOF LAMP 11	1.0	178.65	0	178.65
74	FRONT ROOF AIR BAG LH Hand	1.0	1,557.95	0	1,557.95
75	FRONT ROOF AIR BAG RH Hand	1.0	1,557.95	0	1,557.95
76	FRONT DASHBOARD To 11	1.0	4,369.85	0	4,369.85
77	FRONT DASHBOARD AIR BAG Hand	1.0	3,665.70	0	3,665.70
78	FRONT STEERING WHEEL 11	1.0	2,522.55	0	2,522.55
79	FRONT STEERING WHEEL CONTROL PANEL LH 11	1.0	783.75	0	783.75
80	FRONT STEERING WHEEL CONTROL PANEL RH 11	1.0	783.75	0	783.75
81	FRONT STEERING AIR BAG Agmb	1.0	3,086.85	0	3,086.85
82	FRONT STEERING CLOCK SENSOR Agmb 480	1.0	976.75	0	976.75
83	FRONT AIR BAG ECU Agmb 1790	1.0	1,796.50	0	1,796.50
84	FRONT AIR BAG IMPACT SENSOR Agmb	2.0	251.05	0	502.10
85	FRONT SEAT BELT LH Agmb	1.0	829.60	0	829.60
86	FRONT SEAT BELT RH Agmb	1.0	829.60	0	829.60
87	FRONT SEAT BELT BUCKLE LH 11	1.0	205.55	0	205.55
88	FRONT SEAT BELT BUCKLE RH 11	1.0	202.55	0	202.55
89	FRONT DRIVE SHELF RH 11	1.0	2,700.80	0	2,700.80
List Price - Parts Sub Total					59,984.00
90	FRONT NUMBER PLATE Bel	1.0	30.00	0	30.00
91	FRONT NUMBER PLATE HOLDER 11	1.0	30.00	0	30.00
92	FRONT TYRE RH 11	1.0	680.00	0	680.00
93	RADIATOR COOLANT 11	1.0	120.00	0	120.00
94	FRONT CHASSIS LH - REPAIR 11 X	1.0			
95	FRONT CHASSIS RH - REPAIR 11 X	1.0			
96	FRONT DOOR RH - REPAIR 11 X	1.0			
Special Nett Price - Parts Sub Total					860.00
Parts Total					60,844.00
97	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	2,800.00	1200	2,800.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD



CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : G5810364R
VIJAYAN SUDHAKAR
NO 8 PARI DEDAP WALK
#14-11 TANAMERA CREST
SINGAPORE 486061
TEL : FAX :
PH : 92722014
ATTN :

ESTIMATE BILL

Number : EB00004668
Date : 21/11/2017
Case No : AD00009406
Vehicle No : SKK3488T
Chassis : WAUZZZ8K0DA20353;
Year of Mfr : 2013
Policy No : 5063640778-03
Model : AUDI A4 1.8 TFSI MU
(NAVIGATION &

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
98	LABOUR TO REMOVE & REFIT DASHBOARD	260	600.00	0	600.00
99	SPRAY PAINT ON THE AFFECTED AREAS	1200	1,600.00	0	1,600.00
100	TO SERVICE & TOP-UP AIR-CON GAS	100	180.00	0	180.00
101	TO REMOVE & REFIT WINDSCREEN	120	180.00	0	180.00
102	ANTI-RUST COATING	100	450.00	0	450.00
103	TO REMOVE & REFIT UNDERCARRIAGE	112X	450.00	0	450.00
104	COMPUTERISED SETTING	60	120.00	0	120.00
105	WIRING	30	80.00	0	80.00
106	WHEEL ALIGNMENT	1.0	120.00	0	120.00
Labour 1 Sub Total					6,580.00
3070					
L & K Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : SEVENTY-TWO THOUSAND ONE HUNDRED FORTY-THREE AND CENTS SIXTY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		67,424.00
			GST 7.00%		4,719.68
			TOTAL		72,143.68

Date of accident : 21/11/2017 07:45 AM. Place : ALONG UPPER CHANGI ROAD TOWARDS SIMEI

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD



CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

NO.

SKK 34887

Date:

Audi A4 1.8 2013 model
W A U 7 7 7 P K U D A 2 0 3 5 3 8

Front windscreen - 1062

Sunroof - 2262

headlamp RH - 2038

Front support panel - 878

Front Lender RH - 822

Front grille assy - 899

Front bumper - 1954

Roof lining - 1740

Roof Air bag RH - 1687

Dashboard - 4920

passenger Air bag - 3970

steering Air bag - 3343

Steering Air bag clock sensz - 856

Air bag ECU - 1790

Seat belt driver - 925

Seat belt buckle RH - 168



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobiles

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022363/Uvbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-01-2018



Code : FCI2

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SHA 9296D	Veh. Inspected	SKK 3488T
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17010847MFSH	Excess (\$)	0.00
Assign From	AUNG YIN MIN	Assign Date	22/11/2017

2. Vehicle Particulars & Condition

Make & Model	AUDI A4 (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WAUZZZ8K0DA203538	Colour	BROWN
Odometer	53237	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	BRIDGESTONE	7 mm
L/H Front Tyre	225/50 R17	BRIDGESTONE	7 mm
R/H Rear Tyre	225/50 R17	BRIDGESTONE	7 mm
L/H Rear Tyre	225/50 R17	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/11/2017	Inspection Date	23/11/2017
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 3488T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BATTERY SENSOR	NOT NECESSARY	492.15	-
1	FRONT WINDSCREEN	CRACKED	968.65	968.65
2	FRONT WINDSCREEN MOULDING @\$49.65	NECESSARY	99.30	99.30
1	FRONT BONNET	BUCKLED	2,025.75	2,025.75
1	FRONT BONNET HINGE LH	BENT	54.70	54.70
1	FRONT BONNET HINGE RH	BENT	54.70	54.70
1	FRONT BONNET TOP LOCK & FRONT BONNET OPEN HANDLER	TWISTED / CRACKED	103.95	103.95
1	FRONT BONNET LOWER LOCK	TWISTED	160.00	160.00
2	FRONT BONNET STOPPER @\$10.50	NECESSARY	21.00	21.00
1	FRONT BONNET INSULATOR	TORN	246.20	246.20
5	FRONT BONNET INSULATOR CLIPS @\$2.50	NECESSARY	12.50	12.50
1	FRONT BONNET SHOCK ABSORBER	NOT NECESSARY	87.35	-
1	FRONT BONNET RUBBER	TORN	19.95	19.95
1	FRONT SUPPORT PANEL	BUCKLED / CRACKED	800.75	800.75
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	91.35	-
8	FRONT SUPPORT PANEL TOP GARNISH CLIPS @\$2.50	NOT NECESSARY	20.00	-
1	FRONT HEADLIGHT LH (ASSEMBLY)	HOLDER CRACKED	1,861.05	1,861.05
1	FRONT HEADLIGHT RH (ASSEMBLY)	BROKEN	1,861.05	1,861.05
1	FRONT HEADLIGHT LOWER BRACKET LH	NOT NECESSARY	87.50	-
1	FRONT HEADLIGHT LOWER BRACKET RH	CRACKED	87.50	87.50
1	FRONT HEADLIGHT BULB HID RH	NOT NECESSARY	500.45	-
1	FRONT HEADLIGHT ECU RH	NOT NECESSARY	478.05	-
1	FRONT SUPPORT PANEL TOP AIR DUST	DISTORTED	102.20	102.20
1	FRONT AIR CLEARING HOUSING	NOT NECESSARY	321.85	-
1	FRONT WHEEL HOUSING RH (ASSEMBLY)	TO REPAIR SEE LABOUR	1,978.65	-
1	FRONT FENDER LH	BUCKLED	744.40	744.40
1	FRONT FENDER RH	DENTED / BUCKLED	744.40	744.40
1	FRONT FENDER SHIELD LH	NOT NECESSARY	177.25	-

Report Ref No. CS/FCI17022363/Uvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER SHIELD RH	TORN	177.25	177.25
8	FRONT FENDER SHIELD CLIPS @\$2.50	NECESSARY	20.00	20.00
1	FRONT SUPPORT INNER CENTER SIDE GARNISH LH	NOT NECESSARY	25.90	-
1	FRONT SUPPORT INNER CENTER SIDE GARNISH RH	TORN	25.90	25.90
1	FRONT INTANK COOLER	NOT NECESSARY	329.30	-
1	FRONT AIR CON CONDENSOR	NOT NECESSARY	813.45	-
1	FRONT RADIATOR	NOT NECESSARY	728.25	-
1	FRONT RADIATOR BRACKET LH	NOT NECESSARY	2.50	-
1	FRONT RADIATOR BRACKET RH	NOT NECESSARY	2.50	-
1	FRONT RADIATOR FAN & MOTOR	NOT NECESSARY	744.40	-
1	FRONT RADIATOR COWLING	NOT NECESSARY	270.65	-
1	FRONT AIR CON FAN & MOTOR	NOT NECESSARY	642.85	-
1	FRONT BONNET CABLE	NOT NECESSARY	35.95	-
1	FRONT GRILLE & FRONT GRILLE CHROME	CRACKED	829.60	829.60
1	FRONT GRILLE CHROME LOGO	NECESSARY	93.65	93.65
1	FRONT HEADLIGHT NOZZEL RH	BROKEN	178.95	178.95
1	FRONT HEADLIGHT NOZZEL COVER	TORN	41.10	41.10
1	FRONT HEADLIGHT NOZZEL PIPE	TORN	192.95	192.95
1	FRONT HEADLIGHT NOZZEL JOINT	CRACKED	20.75	20.75
2	FRONT ENGINE MOUNTINGS @\$526.15	NOT NECESSARY	1,052.30	-
1	FRONT BUMPER	DISTORTED	1,794.25	1,794.25
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	25.55	-
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	25.55	25.55
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	157.75	-
1	FRONT BUMPER BRACKET RH	BENT	157.75	157.75
1	FRONT BUMPER REINFORCEMENT	BENT	677.70	677.70
3	FRONT BUMPER SPONGE @\$89.20	TORN	267.60	267.60
1	FRONT BUMPER FOG LAMP & FOG LAMP BRACKET LH	NOT NECESSARY	204.65	-
1	FRONT BUMPER FOG LAMP & FOG LAMP BRACKET RH	BROKEN	204.65	204.65
1	FRONT BUMPER FOG LAMP GRILLE LH	MISSING	98.65	98.65
1	FRONT BUMPER FOG LAMP GRILLE RH	TORN	98.65	98.65
1	FRONT BUMPER CENTER LOWER GRILLE	TORN	98.65	98.65
1	FRONT ENGINE LOWER DUST COVER	NOT NECESSARY	484.75	-

Report Ref No. CS/FC117022363/Uvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER TOWING COVER	TORN	36.70	36.70
1	FRONT LOWER ARM RH	NOT NECESSARY	540.20	-
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	1,197.25	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	1,437.85	-
1	FRONT SHOCK ABSORBER MOULDING RH	NOT NECESSARY	52.10	-
1	FRONT WHEEL BEARING RH	NOT NECESSARY	625.95	-
1	FRONT UPPER ARM RH	NOT NECESSARY	540.20	-
2	FRONT CONTROL ARM @\$1003.25	NOT NECESSARY	2,006.50	-
1	FRONT DOOR OUTER CHROME RH	NOT NECESSARY	229.60	-
1	FRONT DOOR OUTER TOP CHROME RH	NOT NECESSARY	467.85	-
1	FRONT ROOF LINING	WARPED / DISTORTED	1,572.35	1,572.35
1	FRONT ROOF LAMP	NOT NECESSARY	178.65	-
1	FRONT ROOF AIR BAG LH	ACTIVATED	1,557.95	1,557.95
1	FRONT ROOF AIR BAG RH	ACTIVATED	1,557.95	1,557.95
1	FRONT DASHBOARD	TORN	4,369.85	4,369.85
1	FRONT DASHBOARD AIR BAG	ACTIVATED	3,665.70	3,665.70
1	FRONT STEERING WHEEL	NOT NECESSARY	2,522.55	-
1	FRONT STEERING WHEEL CONTROL PANEL LH	NOT NECESSARY	783.75	-
1	FRONT STEERING WHEEL CONTROL PANEL RH	NOT NECESSARY	783.75	-
1	FRONT STEERING AIR BAG	ACTIVATED	3,086.85	3,086.85
1	FRONT STEERING CLOCK SENSOR	ACTIVATED	976.75	480.00
1	FRONT AIR BAG ECU	ACTIVATED	1,796.50	1,790.00
2	FRONT AIR BAG IMPACT SENSOR @\$251.05	ACTIVATED	502.10	502.10
1	FRONT SEAT BELT LH	ACTIVATED	829.60	829.60
1	FRONT SEAT BELT RH	ACTIVATED	829.60	829.60
1	FRONT SEAT BELT BUCKLE LH	NOT NECESSARY	205.55	-
1	FRONT SEAT BELT BUCKLE RH	NOT NECESSARY	202.55	-
1	FRONT DRIVE SHELF RH	NOT NECESSARY	2,700.80	-
	LESS 5% DISCOUNT		-	-1,762.52
			59,984.00	33,487.78
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	30.00	20.00

Report Ref No. CS/FCI17022363/Uvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE HOLDER (SN)	NOT FITTED	30.00	-
1	FRONT TYRE RH (SN)	NOT NECESSARY	680.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	120.00	60.00
1	FRONT CHASSIS LH (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	FRONT CHASSIS RH (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR RH (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
			860.00	80.00
	LABOUR			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF FRONT WHEEL HOUSING RH (ASSEMBLY), FRONT CHASSIS LH, FRONT CHASSIS RH AND FRONT DOOR RH.		2,800.00	1,200.00
	LABOUR TO REMOVE & REFIT DASHBOARD.		600.00	260.00
	SPRAY PAINT ON THE AFFECTED AREAS.		1,600.00	1,200.00
	TO SERVICE & TOP-UP AIR-CON GAS.		180.00	100.00
	TO REMOVE & REFIT WINDSCREEN.		180.00	120.00
	ANTI-RUST COATING.		450.00	100.00
	TO REMOVE & REFIT UNDERCARRIAGE.	NOT NECESSARY	450.00	-
	COMPUTERISED SETTING.		120.00	60.00
	WIRING.		80.00	30.00
	WHEEL ALIGNMENT.	REPEATED	120.00	-
			6,580.00	3,070.00
GRAND TOTAL			67,424.00	36,637.78

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			25,000.00
---	--	--	------------------

Report Ref No. CS/FC117022363/Uvbe2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.