



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 4289 S** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAILDOOR, TAILDOOR SPOILER)	\$600.00	450
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAILDOOR, TAILDOOR SPOILER)	\$600.00	500
3	To check wiring	\$50.00	20
4	To remove & refit rear windscreen to assist work load	\$120.00	80
5	To remove & refit taildoor glass to assist work load	\$120.00	X
6	To transfer boot mechanism to new boot	\$120.00	X
<div><div><p>LKK Auto Consultants hence notify the Repairer of the following:</p><ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company<p>Acknowledged by Repairer</p><p>Signature:</p><p>Date:</p></div><div><p>23/11/2017</p><p>29/11/17.</p></div></div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.