

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD265L -

Not Authored
Presumy B4 pain

AAD1711-244

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD265L - CANDY
VF1ABL15AUC282380
RENAULT
LATITUDE
21.11.2017
AIG

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Dis / CNA</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Dis</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Bu</i> 225.95 ✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1	BOOT REAR	\$	<i>Bu</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$	<i>Sm</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05 X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>ner</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>ner</i> 225.36 ✓
20	1	BOOT STRUT LH	\$	<i>Sm</i> 276.08
21	1	BOOT STRUT RH	\$	<i>Sm</i> 276.08
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84
24	1	BOOT INNER TRIM	\$	<i>Sm</i> 586.45
25	1	BOOT SWITCH	\$	<i>Sm</i> 168.13
26	1	BOOT LOCK	\$	<i>R</i> 202.67
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2	LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52
29	2	BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sm</i> 671.45
31	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
32	1	WHEELARCH REAR LH	\$	<i>Sm</i> 543.47
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Sm</i> 671.45
34	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-244**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD265L -

35	1	WHEELARCH REAR RH	\$
36	1	TAILLAMP RH	\$
37	1	TAILLAMP PANEL RH	\$
38	1	TAILLAMP LH	\$
39	1	TAILLAMP PANEL LH	\$
40	1	OUTER PANEL REAR (End Panel)	\$
41	1	OUTER PANEL REAR (End Panel)TRIM	\$
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$
43	1	SPARE WHEEL PANEL TRIM	\$
44	1	EXHAUST REAR	\$
45	1	EXHAUST CAP REAR	\$

<i>Sn</i>	543.47	X
<i>Sn</i>	552.55	X
<i>R</i>	986.70	X
<i>mt/cm</i>	552.55	✓
<i>R</i>	986.70	X
<i>R</i>	1,471.77	✓
<i>cm</i>	404.56	✓
<i>R</i>	2,189.88	X
<i>Sn</i>	612.21	X
<i>R</i>	7,489.05	X
<i>R</i>	230.49	X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET	PARKING AID	\$
2	1SET	REAR BUMPER CLIP	\$
3	1SET	BUMPER BRACKET CTR CLIP	\$
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$
5	1SET	BUMEPR RETAINER RH CLIP RR	\$
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$
7	1SET	BUMEPR RETAINER CLIP LH RR	\$
8	1SET	BUMPER LOWER REAR RIVET	\$
9	1SET	BUMPER LOWER REAR CLIP	\$
10	1	EXHAUST MOUNTING REAR	\$
11	1SET	BOOT FINISHER CLIP	\$
12	1	BOOT STICKER "Trans-cab"	\$
13	1	BOOT STICKER "6555-3333"	\$
14	1	BOOT INNER TRIM CLIP	\$
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$
17	1	FENDER INNER TRIM CLIP LH	\$
18	1	FENDER INNER TRIM CLIP LH	\$
19	1	TAILLAMP CLIP RH	\$
20	1	TAILLAMP CLIP LH	\$
21	2	REAR WINDSCREEN SELANT	\$
22	1	WINDSCREEN MOULDING	\$
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$

<i>mis/shot</i>	700.00	✓
<i>nn</i>	66.00	✓
<i>nn</i>	33.00	✓
<i>nn</i>	10.00	X
<i>nn</i>	20.00	X
<i>nn</i>	10.00	X
<i>nn</i>	20.00	X
<i>nn</i>	22.00	X
<i>nn</i>	66.00	✓
<i>Sn</i>	17.82	X
<i>nn</i>	24.20	X
<i>nn</i>	30.00	✓
<i>nn</i>	30.00	✓
<i>nn</i>	45.00	X
<i>nn</i>	35.00	X
<i>nn</i>	35.00	X
<i>nn</i>	28.00	X
<i>nn</i>	28.00	X
<i>nn</i>	5.00	X
<i>nn</i>	5.00	✓
<i>nn</i>	80.00	X
<i>nn</i>	100.00	X
<i>nn</i>	100.00	X
<i>Sn</i>	385.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-244

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD265L -

25	1	SPARE TYRE	\$	330.00	X
			TOTAL	\$	2,225.02
			TOTAL PARTS	\$	34,507.07
Putty And Spray Painting Of The Affected Portion.			\$	4,500.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same			\$	4,200.00	600
To Rust-Proofing Of The Affected Areas.			\$	170.00	601
To reinstall rear bumper parking sensor.			\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.			\$	170.00	601
To repair and realign rear exhaust pipe.			\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.			\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.			\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.			\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.			\$	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.			\$	380.00	X
Towing Fees			\$	120.00	X
To transfer of rear windscreen fittings and conduct water seepage test.			\$	170.00	X
To check steering geometry and computer wheel alignment			\$	220.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD265L -

TOTAL	\$	11,160.00
Over All Total	\$	45,667.07

(PARTS BY PARTS)**Repair Days****15 Days***3 days*