

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44922
Date Estimated : 22/11/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Gan Susan (Yan Susan)
979A Buangkok Crescent
#15-145

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 531979

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKG1193C	DX49596	31/07/2012	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace nozzle chain windshield washer system include conducting checks for leak and proper function	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.25	4.00		5.00 <i>new</i>
# SUPPORT *	16.20	1.00		16.20 <i>new</i>
# NOZZLE CHAIN WINDSHIELD WASHER SYST *	203.40	1.00		203.40 <i>dis</i>
# HEADLIGHT GASKET SET *	30.75	1.00		30.75 <i>new</i>

Total Labour :	150.00
Total Parts :	255.35
Total Labour & Parts :	405.35