

S. REC. BY:

REF: CS / ECL17022372 / Kvbek Special Instruction:

Surveyor: Kenneth. ASSIGNMENT (Office)

From (Person): Yee Pei Li of ECL Date/Time: 23-11-2017 11am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 59R Insured: YM 7736X

at Workshop m/s Trans Cab Tel: 6213 0993

of No. 2 AMK St 62

Policy No: Claim No: YM7736X / SE

Sum Insured: Excess:

Make of Veh: D.O.A. 21-11-2017  
(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

Date/Time: 23-11-2017 1131AM Person Contacted: Joing How Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 59R - X
	YM 7736X - X
24/11/17	Email preli revised to Pei Li
13/6/18	16588-2P (Red 51, 674-76, 761)

REF: F61

## ASSIGNMENT

From \_\_\_\_\_ Date **23/11/2017**

Estimated Cost: \_\_\_\_\_

OD ☒ TS / WS / TP RES / OD RES / EVA / INV / MVTo inspect vehicle No: **SHD 59R**at Workshop no: **Trans Cab**of **No. 2 AMK St 63**

Insured \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: **09** days Res: Yes or NoLump Sum: **113.1**% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Van No: **SHD 59R** Reg: **02 16**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Perant Latitude** Yr: **1995**Colour: **White IR** A/C: \_\_\_\_\_ Insured / Std / NI / NASp. Reading: **209433** T-Radio: Insured / Std / NI / NA

Eng. No: \_\_\_\_\_

Ch. No: **VIFIABL15Auc 282639**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ Nil / S/Rim / STD A/Rim orTyre Size: **R: 1511R 215/60R16****King R: King**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: **7** mmL/Bal: **7** mmD.O.A: **21/11/17**

Survey held at: \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

**cls body**

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

**24/11 File pass to Carhome**

RECEIVED 13 JUN 2018

Date/Time File Pass to:

☐

Preli. Report

☐

Final Report

Date/Time File Return to:

**13/6- typist**Days Of Repair: **9**Resurvey No. of Trip: **1**

Survey Fee

Transportation

Fuel

Other

Add Fee:

☐

Site Insp: \$

☐

Inter. Insp: \$

☐

Tech. Insp: \$

☐

Rep. Insp: \$

Report Format: **TP**Lump Sum / L.B. \$ **16,588.29****350****350**

## Survey Department Check List (Case Handler)

Reference No. : **CS EGI 17022372 Kvb**

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** **13/6/18**  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17022372/Kvb

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 23-11-2017



Code : EGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 7736X	Veh. Inspected	SHD 59R
Policy No.		Coverage (\$)	0.00
Claim No.	YM7736X/SE	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	23/11/2017

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	21/11/2017	Inspection Date	23/11/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**Catherine Chong (LKK Auto)**

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Thursday, 23 November, 2017 11:00 AM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : YM7736X / TP : SHD59R/LKK / DOA : 21/11/2017  
**Attachments:** YM7763X - SAS.pdf; SHD59R - SAS.pdf; SHD59R - ESTIMATE.pdf; SHD59R - PRS FORM.pdf

Dear Ashley,

Please assist to conduct these surveys:-

NO	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	SHD 59R	TRANS-CAB SERVICES PTE LTD @ 2 ANG MO KIO STREET 63	NG JOING HOW @ 6213 0993 / 6213 0998	YM7763X/SE	STEVE	DOA: 21.11.2017 WP

**Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.**

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Kindly acknowledge receipt.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 24 November, 2017 2:33 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR  
**Subject:** RE: YM7736X / TP : SHD59R/LKK / DOA : 21/11/2017  
**Attachments:** SHD 59R PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SHD 59R  
Date of survey: 23/11/2017  
Number of days: 9 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 23 November, 2017 11:22 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>  
**Cc:** SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Subject:** RE: YM7736X / TP : SHD59R/LKK / DOA : 21/11/2017

Dear Pei Li,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Thursday, 23 November, 2017 11:00 AM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** OI : YM7736X / TP : SHD59R/LKK / DOA : 21/11/2017

Dear Ashley,

Please assist to conduct these surveys:-

NO	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	SHD 59R	TRANS-CAB SERVICES PTE LTD @ 2 ANG MO KIO STREET 63	NG JOING HOW @ 6213 0993 / 6213 0998	YM7763X/SE	STEVE	DOA: 21.11.2017 WP

**Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.**

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

**Kindly acknowledge receipt.**

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198I

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 6256431

Your ref: YM7763X/SE  
Our ref: CS/EG117022372/Kvb

Date: 24/11/2017

The Motor Claims Department  
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SHD 59R**


We thank you for your instruction on 23/11/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle c  
23/11/2017 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD  
and have the following to report:-

Workshop Estimate Amount	: S\$	68,263.05
Revised Estimate Amount	: S\$	19,194.81
"Check" Items Amount	: S\$	14,045.60
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

**Description of Damage:**

The vehicle sustained damages at the  
o/s body



Comments/Present Status:  
Damages Consistent

Yours faithfully,

Kenneth Kong  
**Licensed Appraiser**



## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Company
Owner ID	3878K
<b>Vehicle Details</b>	
Vehicle No.	SHD59R
Vehicle to be Exported	Yes
Intended De-registration Date	22 Nov 2017
Vehicle Make	RENAULT
Vehicle Model	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour	Red
Manufacturing Year	2015
Engine No.	M9R8839C002989
Chassis No.	VF1ABL15AUC282639
Maximum Power Output	127.0 kW (170 bhp)
Open Market Value	\$19,998.00
Original Registration Date	04 Feb 2016
First Registration Date	04 Feb 2016
Transfer Count	0
Actual ARF Paid	\$19,998.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	03 Feb 2024
PARF Rebate Amount	\$14,998.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	03 Feb 2024
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$43,040.00
COE Rebate Amount	\$33,353.00
<b>Total Rebate Amount</b>	<b>\$48,351.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Nov 2017

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/11/2017 17:48
Date Of Accident	21/11/2017 10:15
Exact Location Of Accident	TANJONG PAGAR ROAD TOWARDS MAXWELL MARKET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD0059R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	CHERN WEI PONG
NRIC No	S7140086G
Date Of Birth	14/11/1971
Occupation	OUTDOOR
Date Of Driving Pass	31/01/1992
Driving Experience	25 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97967310
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 642 ANG MO KIO AVENUE 5 #02-3051
Postcode	560642
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES EAST NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 263 TAMPINES STREET 21 #01-128 , POSTCODE: 520263 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7839999 - FAX NO: 67832500
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT: T20171121/2092

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM7763X
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	LEE KUENG HOCK
NRIC/Passport Number	S1535143H
Contact Number	81613329
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name

Phone Number

Email Address

[illegible]

Name CHERN WEI PONG

Approximate Age

### Injuries Sustain

Injured person in which vehicle? SHD0059R

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to police report -

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20171121/2092

1 of 3

Police Station Of Origin:  
Tampines East NPP  
263 Tampines Street 21 #01-138  
SINGAPORE 520263  
Tel No: 1800-7839999

Report No. T/20171121/2092

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/11/2017 14:47	Vide Report No.:	Station Diary No.: 23
--	------------------	--------------------------

## Informant's Particulars

Name of Informant: CHERN WEI PONG			Address: APT BLK 642 ANG MO KIO AVENUE 5 #02-3051 SINGAPORE 560642	
ID Type / ID No.: NRIC NO / S7140086G			Contact No.: Home/Office: Mobile: 87870092	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 46	Date of Birth: 14/11/1971	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3	Date of Expiry:

## General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 21/11/2017 10:15	Type of Location: Straight Road
Location: Along Road 1 TANJONG PAGAR ROAD  towards Maxwell Market				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SHD59R	Car	RENAULT		Red	Seriously Damaged	0
YM7763X	Lorry	MITSUBISHI	FUSO	White	Slightly Damaged	2

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20171121/2092

2 of 3

Report No. T/20171121/2092

Police Station Of Origin:  
Tampines East NPP  
263 Tampines Street 21 #01-138  
SINGAPORE 520263  
Tel No: 1800-7839999

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	CHERN WEI PONG	ID No.	S7140086G
Related Vehicle	SHD59R (Car)	Contact No.	87870092
Hospital/Clinic	SUNSHINE CLINIC FAMILY PARCTICE & SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	21/11/2017	Date Discharge	21/11/2017
No. of Days granted Medical Leave	05	Degree of Injury	Slight
<b>Driver</b>			
Name	LEE KUENG HOCK	ID No.	S1535143H
Related Vehicle	YM7763X (Lorry)	Contact No.	81613329
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 21.11.2017 at about 1015hrs, I was travelling inside my taxi alone along Tanjong Pagar Rd towards Maxwell market direction on lane 1 of a 2 lane road. As I was travelling, a lorry YM7763X side swipe from my right from the right rear passenger's door to the front bumper. I was in a daze, however do not required any Ambulance Service. The other driver wrote down his particulars and thereafter left the scene.

I waited for the tow truck to tow away my vehicle and I proceeded to Sunshine Clinic Family Practice & Surgery to seek medical treatment and was given 5 days of out patient leave. I have front built-in car camera.

JA  
S7140086G





**SINGAPORE  
POLICE FORCE**



T/20171121/2092

3 of 3

Report No. T/20171121/2092

Police Station Of Origin:  
Tampines East NPP  
263 Tampines Street 21 #01-138  
SINGAPORE 520263  
Tel No: 1800-7839999

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt TAN HOCK CHYE *[Signature]* 8395 TH 52

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

21/11/2017 14:47

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

Classification Of Case:

SN 102

Authentication Stamp  
NP168



**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD59R - ERGO**

AAD1711-247

*Not Authored*  
*Recovery B4 pain* 8/6588.28

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHD59R - JHOW**  
 VF1ABL15AUC282639  
 RENAULT  
 LATITUDE  
 21.11.2017  
**ERGO**

**PART****LIST**

1	1	BUMPER COVER FRT	\$	CM 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$	SL 394.68 X
3	1	BUMPER BEAM FRT	\$	R 914.08 X ✓
4	1	BUMPER SPOILER FRT	\$	SL 181.75 X
5	1	BUMPER UNDERTRAY FRT	\$	SL 472.83 X
6	1	BUMPER GRILLE LOWER FRT	\$	SL 266.80 X
7	1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.22 X
8	1	BUMPER RETAINER FRT RH	\$	CM 151.41 ✓
9	1	BUMPER BRACKET FRT RH	\$	SL 181.75 X
10	1	HEADLAMP RH	\$	my car 1,184.43 ✓
11	1	HEADLAMP PANEL FRT RH	\$	R 152.15 X ✓
12	1	FENDER PANEL FRT RH	\$	R 783.83 ✓
13	1	FENDER INSULATOR RH	\$	D 130.84 ✓
14	1	FENDER BRACKET FRT RH	\$	R 34.14 ✓
15	1	WHEELARCH FRT RH	\$	T 278.84 ✓
16	1	WHEEL HOUSING PANEL FRT RH	\$	R 4,682.09 X ✓
17	1	LOWER ARM FRT RH	\$	SL 685.76 X
18	1	KUNCKLE ARM FRT RH	\$	SL 846.98 X
19	1	KUNCKLE HUB+BEARING RH	\$	SL 497.69 X
20	1	ABSORBER FRT RH	\$	SL 360.54 X
21	1	STEERING PINION RACK	\$	R 4,413.11 X ✓
22	1	WIPER RESERVOIR	\$	SL 348.25 X
23	1	WIPER RESERVOIR NECK	\$	SL 136.11 X
24	1	WIPER RESERVOIR MOTOR	\$	SL 270.06 X
25	1	RADAITOR GRILLE	\$	SL 1,707.78 X
26	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	SL 173.36 X
27	1	RADAITOR GRILLE FRAME	\$	SL 1,353.75 X
28	1	FRAME FULL SUPPORT PANEL	\$	SL 615.90 X
29	1	FRAME FULL SUPPORT BRACKET	\$	R 89.79 X ✓
30	1	BONNET	\$	R 1,941.63 X ✓
31	1	DOOR MIRROR RH	\$	SL 1,483.40 ✓
32	1	DOOR MIRROR GLASS RH	\$	242.33 X
33	1	DOOR MIRROR BACK COVER RH	\$	218.46 X
34	1	DOOR MIRROR LAMP RH	\$	194.18 X

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1711-247**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD59R - ERGO**

35	1	CHASSIS PANEL REINFORCEMENT FRT RH	\$	R	1,095.24	✓	Ⓟ
36	1	DOOR HINGE PILLAR PANEL OUTER FRT RH	\$	R	2,896.14	✗	Ⓟ
37	1	DOOR HINGE PILLAR PANEL INNER FRT RH	\$	R	1,542.15	✗	Ⓟ
38	1	DOOR PANEL FRT RH	\$	CRH	2,844.66	✓	
39	1	DOOR FRAME PANEL FRT RH	\$	NSP	5,550.98	X	
40	1	DOOR HINGE UPPER RH	\$	R	274.50	✓	
41	1	DOOR HINGE LOWER RH	\$	R	300.55	✓	
42	1	DOOR CHECK FRT RH	\$	DIS	194.77	✓	
43	1	DOOR LOCK FRT RH	\$	CM	908.75	✓	
44	1	DOOR CATCH FRT RH	\$	DIS	131.23	✓	
45	1	DOOR GRAB HANDLE FRT RH	\$	M1	210.96	✓	
46	1	DOOR HANDLE OUTER FRT RH	\$	M1	477.76	✓	
47	1	DOOR HANDLE CAP FRT RH	\$	M1	35.52	✓	
48	1	DOOR HANDLE SEAL FRT RH	\$	R	7.89	✓	
49	1	DOOR HANDLE COVER FRT RH	\$	M1	13.22	✓	
50	1	DOOR HANDLE MODULE FRT RH	\$	SL	133.60	✗	
51	1	DOOR REGULATOR FRT RH	\$	SL	505.19	✗	
52	1	DOOR REGULATOR MOTOR FRT RH	\$	R	796.46	✗	
53	1	DOOR REGULATOR GUIDE FRT RH	\$	SL	120.97	✗	
54	1	DOOR GLASS FRT RH	\$	BR	625.96	✓	
55	1	DOOR CASING FRT RH	\$	R	1,509.06	✗	
56	1	DOOR WATER SHIELD FRT RH	\$	R	184.32	✗	
57	1	DOOR CASING LIGHT	\$	SL	82.49	✗	
58	1	DOOR FINISHER FRT RH	\$	SL	515.06	✗	
59	1	DOOR MOULDING FRT RH	\$	M17	176.82	✓	
60	1	DOOR FINISHER INNER FRT RH	\$	SL	323.44	✗	
61	1	DOOR FINISHER BRACKET INNER FRT RH	\$	SL	46.97	✗	
62	1	DOOR WHETHERSTRIP FRT RH	\$	CM	410.27	✓	
63	1	DOOR SEAL LOWER FRT RH	\$	SL	91.17	✗	
64	1	DOOR SEAL FRT RH	\$	SL	72.82	✗	
65	1	DOOR GLASS RUNNER SEAL FRT RH	\$	SL	626.36	✗	
66	1	DOOR WAIST SEAL OUTER FRT RH	\$	SL	291.27	✗	
67	1	DOOR WAIST SEAL INNER FRT RH	\$	SL	122.15	✗	
68	1	CENTRE PILLAR OUTER RH	\$	R	880.14	✗	Ⓟ
69	1	CENTER PILLAR REINFORCEMENT RH	\$	R	1,176.15	✗	Ⓟ
70	1	CENTER PILLAR INNER RH	\$	R	907.76	✗	Ⓟ
71	1	ROCKER PANEL OUTER RH	\$	R	987.49	✗	Ⓟ
72	1	DOOR PANEL REAR RH	\$	R	2,844.66	✓	
73	1	DOOR GUIDE REAR RH	\$	SL	176.82	✗	
74	1	DOOR HINGE UPPER RH	\$	R	274.50	✗	Ⓟ
75	1	DOOR HINGE LOWER	\$	R	300.55	✗	Ⓟ
76	1	DOOR CHECK REAR RH	\$	SL	203.06	✗	

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1711-247**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD59R - ERGO**

77	1	DOOR GRAB HANDLE REAR RH	\$	210.96	X
78	1	DOOR HANDLE OUTER REAR RH	\$	126.49	✓
79	1	DOOR HANDLE CAP REAR RH	\$	35.52	
80	1	DOOR HANDLE SEAL REAR RH	\$	7.89	
81	1	DOOR HANDLE COVER REAR RH	\$	13.22	
82	1	DOOR HANDLE MODULE REAR RH	\$	133.60	
83	1	DOOR FINISHER REAR RH	\$	423.10	
84	1	DOOR MOULDING REAR RH	\$	176.82	
85	1	DOOR SEAL REAR RH	\$	162.02	
86	1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69	
87	1	FENDER PANEL REAR RH	\$	3,299.13	Ⓢ

<b>TOTAL</b>	\$	<b>62,648.61</b>
<b>10%</b>	\$	<b>6,264.86</b>
	\$	<b>56,383.75</b>

**Specical Nett**

1	1SET	WHEELARCH CLIP FRT RH	\$	66.00	✓
2	1SET	FRONT BUMPER CLIP	\$	66.00	✓
3	1SET	BUMPER SUPPORT FRT CLIP RH	\$	9.80	X
4	1SET	BUMEPR RETAINER FRT CLIP RH	\$	12.50	X
5	1	RIM RH FRT	\$	385.00	X
6	1	TYRE RH FRT	\$	330.00	X
7	1	DOOR STICKER "Trans-cab"	\$	80.00	60sn
8	1	DOOR STICKER "Classic"	\$	30.00	15sn
9	1	DOOR STICKER "6555-3333"	\$	80.00	60sn

<b>TOTAL</b>	\$	<b>1,059.30</b>
<b>TOTAL PARTS</b>	\$	<b>57,443.05</b>

To Check Electrical Lighting Concerned. \$ 170.00 3rd

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 4,200.00 110d

Putty and spray painting of the affected portion. \$ 4,500.00 132d

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test. \$ 170.00 X

To transfer of tire, rim and on wheel balancing. \$ 170.00 X

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1711-247**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD59R - ERGO**

To check steering geometry and computer wheel alignment	\$	220.00	600
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	1200
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1200
Towing fees	\$	120.00	500
To rust-proofing of the affected areas.	\$	170.00	1200
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X

<b>TOTAL</b>	<b>\$</b>	<b>10,820.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>68,263.05</b>

**(PARTS BY PARTS) Repair Days****15 Days**

9 days

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17022372/Kvbe2

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 14-06-2018



Code : EGI

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	YM 7736X	Veh. Inspected	SHD 59R
Policy No.		Coverage (\$)	0.00
Claim No.	YM7736X/SE	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	23/11/2017

**2. Vehicle Particulars & Condition**

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1ABL15AUC282639	Colour	WHITE / RED
Odometer	209433	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	7 mm
L/H Front Tyre	215/60 R16	FALKEN	7 mm
R/H Rear Tyre	215/60 R16	LING LONG	8 mm
L/H Rear Tyre	215/60 R16	LING LONG	8 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	21/11/2017	Inspection Date	23/11/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>9 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 59R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER FRT	CRACKED	1,259.42	1,259.42
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.22	-
1	BUMPER RETAINER FRT RH	CRACKED	151.41	151.41
1	BUMPER BRACKET FRT RH	SERVICEABLE	181.75	-
1	HEADLAMP RH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	FENDER INSULATOR RH	DISTORTED	130.84	130.84
1	FENDER BRACKET FRT RH	BENT	34.14	34.14
1	WHEELARCH FRT RHR	TORN	278.84	278.84
1	WHEEL HOUSING PANEL FRT RH	TO REPAIR SEE LABOUR	4,682.09	-
1	LOWER ARM FRT RH	SERVICEABLE	685.76	-
1	KNUCKLE ARM FRT RH	SERVICEABLE	846.98	-
1	KNUCKLE HUB+BEARING RH	NOT NECESSARY	497.69	-
1	ABSORBER FRT RH	SERVICEABLE	360.54	-
1	STEERING PINION RACK	TO REPAIR SEE LABOUR	4,413.11	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	173.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-

Report Ref No. CS/EGI17022372/Kvbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	DOOR MIRROR RH }	MISSING	1,483.40	1,483.40
1	DOOR MIRROR GLASS RH }		242.33	-
1	DOOR MIRROR BACK COVER RH }		218.46	-
1	DOOR MIRROR LAMP RH }		194.18	-
1	CHASSIS PANEL REINFORCEMENT FRT RH	TO REPAIR SEE LABOUR	1,095.24	-
1	DOOR HINGE PILLAR PANEL OUTER FRT RH	TO REPAIR SEE LABOUR	2,896.14	-
1	DOOR HINGE PILLAR PANEL INNER FRT RH	TO REPAIR SEE LABOUR	1,542.15	-
1	DOOR PANEL FRT RH	CRACKED	2,844.66	2,844.66
1	DOOR FRAME PANEL FRT RH	NO SUCH PARTS	5,550.98	-
1	DOOR HINGE UPPER RH	BENT	274.50	274.50
1	DOOR HINGE LOWER RH	BENT	300.55	300.55
1	DOOR CHECK FRT RH	DISTORTED	194.77	194.77
1	DOOR LOCK FRT RH	CRACKED	908.75	908.75
1	DOOR CATCH FRT RH	DISTORTED	131.23	131.23
1	DOOR GRAB HANDLE FRT RH	MISSING	210.96	210.96
1	DOOR HANDLE OUTER FRT RH	MISSING	477.76	477.76
1	DOOR HANDLE CAP FRT RH	MISSING	35.52	35.52
1	DOOR HANDLE SEAL FRT RH	NECESSARY	7.89	7.89
1	DOOR HANDLE COVER FRT RH	MISSING	13.22	13.22
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	SERVICEABLE	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR GLASS FRT RH	BROKEN	625.96	625.96
1	DOOR CASING FRT RH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD FRT RH	SERVICEABLE	184.32	-
1	DOOR CASING LIGHT	SERVICEABLE	82.49	-
1	DOOR FINISHER FRT RH	SERVICEABLE	515.06	-

Report Ref No. CS/EG117022372/Kvbe2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR MOULDING FRT RH	MISSING	176.82	176.82
1	DOOR FINISHER INNER FRT RH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER FRT RH	SERVICEABLE	46.97	-
1	DOOR WEATHERSTRIP FRT RH	CUT	410.27	410.27
1	DOOR SEAL LOWER FRT RH	SERVICEABLE	91.17	-
1	DOOR SEAL FRT RH	SERVICEABLE	72.82	-
1	DOOR GLASS RUNNER SEAL FRT RH	SERVICEABLE	626.36	-
1	DOOR WAIST SEAL OUTER FRT RH	SERVICEABLE	291.27	-
1	DOOR WAIST SEAL INNER FRT RH	SERVICEABLE	122.15	-
1	CENTRE PILLAR OUTER RH	TO REPAIR SEE LABOUR	880.14	-
1	CENTER PILLAR REINFORCEMENT RH	TO REPAIR SEE LABOUR	1,176.15	-
1	CENTER PILLAR INNER RH	TO REPAIR SEE LABOUR	907.76	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	987.49	-
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR RH	SERVICEABLE	203.06	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR RH	DENTED	126.49	126.49
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-

Report Ref No. CS/EGI17022372/Kvbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
	LESS 10% DISCOUNT		-6,264.86	-1,489.03
			56,383.75	13,401.29
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET WHEELARCH CLIP FRT RH (SN)	NECESSARY	66.00	66.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER SUPPORT FRT CLIP RH (SN)	NOT NECESSARY	9.80	-
1	SET BUMPER RETAINER FRT CLIP RH (SN)	NOT NECESSARY	12.50	-
1	RIM RH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE RH FRT (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	DOOR STICKER "CLASSIC" (SN)	NECESSARY	30.00	15.00
1	DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
			1,059.30	267.00
	<b><u>LABOUR</u></b>			
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT, HEADLAMP PANEL FRT RH, WHEEL HOUSING PANEL FRT RH, STEERING PINION RACK, FRAME FULL SUPPORT BRACKET, BONNET, CHASSIS PANEL REINFORCEMENT FRT RH, DOOR HINGE PILLAR PANEL OUTER FRT RH, DOOR HINGE PILLAR PANEL INNER FRT RH, CENTRE PILLAR OUTER RH, CENTER PILLAR REINFORCEMENT RH, CENTER PILLAR INNER RH, ROCKER PANEL OUTER RH, }		4,200.00	1,100.00
	DOOR HINGE UPPER RH, DOOR HINGE LOWER AND FENDER PANEL REAR RH. }		-	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	1,320.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPGAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CS/EGI17022372/Kvbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
	TOWING FEES.		120.00	50.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			10,820.00	2,920.00
GRAND TOTAL			68,263.05	16,588.29

RECOMMENDED COST OF REPAIRS			16,588.29
-----------------------------	--	--	-----------

Report Ref No. CS/EGI17022372/Kvbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.