

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-247**

N O.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

C O/GST REG NO. 201019626G

SHD59R - ERGO

Vehicle No.:

SHD59R - JHOW

Chassis No.:

VF1ABL15AUC282639

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

21.11.2017

Third Party Insurer :

ERGO

		PART			LIST
1	1	BUMPER COVER FRT	\$		1,259.42
2	1	BUMPER ABSORBER FRT	\$		394.68
3	1	BUMPER BEAM FRT	\$		914.08
4	1	BUMPER SPOILER FRT	\$		181.75
5	1	BUMPER UNDERTRAY FRT	\$		472.83
6	1	BUMPER GRILLE LOWER FRT	\$		266.80
7	1	BUMPER FOG LAMP GRILLE RH	\$		207.22
8	1	BUMPER RETAINER FRT RH	\$		151.41
9	1	BUMPER BRACKET FRT RH	\$		181.75
10	1	HEADLAMP RH	\$		1,184.43
11	1	HEADLAMP PANEL FRT RH	\$		152.15
12	1	FENDER PANEL FRT RH	\$		783.83
13	1	FENDER INSULATOR RH	\$		130.84
14	1	FENDER BRACKET FRT RH	\$		34.14
15	1	WHEELARCH FRT RH	\$		278.84
16	1	WHEEL HOUSING PANEL FRT RH	\$		4,682.09
17	1	LOWER ARM FRT RH	\$		685.76
18	1	KUNCKLE ARM FRT RH	\$		846.98
19	1	KUNCKLE HUB+BEARING RH	\$		497.69
20	1	ABSORBER FRT RH	\$		360.54
21	1	STEERING PINION RACK	\$		4,413.11
22	1	WIPER RESERVOIR	\$		348.25
23	1	WIPER RESERVOIR NECK	\$		136.11
24	1	WIPER RESERVOIR MOTOR	\$		270.06
25	1	RADAITOR GRILLE	\$		1,707.78
26	1	RADAITOR GRILLE BADGE 'RENAULT'	\$		173.36
27	1	RADAITOR GRILLE FRAME	\$		1,353.75
28	1	FRAME FULL SUPPORT PANEL	\$		615.90
29	1	FRAME FULL SUPPORT BRACKET	\$		89.79
30	1	BONNET	\$		1,941.63
31	1	DOOR MIRROR RH	\$		1,483.40
32	1	DOOR MIRROR GLASS RH	\$		242.33
33	1	DOOR MIRROR BACK COVER RH	\$		218.46
34	1	DOOR MIRROR LAMP RH	\$		194.18

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-247**

NO. 2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

C/O GST REG NO. 201019626G

SHD59R - ERGO

35	1	CHASSIS PANEL REINFORCEMENT FRT RH	\$	1,095.24
36	1	DOOR HINGE PILLAR PANEL OUTER FRT RH	\$	2,896.14
37	1	DOOR HINGE PILLAR PANEL INNER FRT RH	\$	1,542.15
38	1	DOOR PANEL FRT RH	\$	2,844.66
39	1	DOOR FRAME PANEL FRT RH	\$	5,550.98
40	1	DOOR HINGE UPPER RH	\$	274.50
41	1	DOOR HINGE LOWER RH	\$	300.55
42	1	DOOR CHECK FRT RH	\$	194.77
43	1	DOOR LOCK FRT RH	\$	908.75
44	1	DOOR CATCH FRT RH	\$	131.23
45	1	DOOR GRAB HANDLE FRT RH	\$	210.96
46	1	DOOR HANDLE OUTER FRT RH	\$	477.76
47	1	DOOR HANDLE CAP FRT RH	\$	35.52
48	1	DOOR HANDLE SEAL FRT RH	\$	7.89
49	1	DOOR HANDLE COVER FRT RH	\$	13.22
50	1	DOOR HANDLE MODULE FRT RH	\$	133.60
51	1	DOOR REGULATOR FRT RH	\$	505.19
52	1	DOOR REGULATOR MOTOR FRT RH	\$	796.46
53	1	DOOR REGULATOR GUIDE FRT RH	\$	120.97
54	1	DOOR GLASS FRT RH	\$	625.96
55	1	DOOR CASING FRT RH	\$	1,509.06
56	1	DOOR WATER SHIELD FRT RH	\$	184.32
57	1	DOOR CASING LIGHT	\$	82.49
58	1	DOOR FINISHER FRT RH	\$	515.06
59	1	DOOR MOULDING FRT RH	\$	176.82
60	1	DOOR FINISHER INNER FRT RH	\$	323.44
61	1	DOOR FINISHER BRACKET INNER FRT RH	\$	46.97
62	1	DOOR WHETHERSTRIP FRT RH	\$	410.27
63	1	DOOR SEAL LOWER FRT RH	\$	91.17
64	1	DOOR SEAL FRT RH	\$	72.82
65	1	DOOR GLASS RUNNER SEAL FRT RH	\$	626.36
66	1	DOOR WAIST SEAL OUTER FRT RH	\$	291.27
67	1	DOOR WAIST SEAL INNER FRT RH	\$	122.15
68	1	CENTRE PILLAR OUTER RH	\$	880.14
69	1	CENTER PILLAR REINFORCEMENT RH	\$	1,176.15
70	1	CENTER PILLAR INNER RH	\$	907.76
71	1	ROCKER PANEL OUTER RH	\$	987.49
72	1	DOOR PANEL REAR RH	\$	2,844.66
73	1	DOOR GUIDE REAR RH	\$	176.82
74	1	DOOR HINGE UPPER RH	\$	274.50
75	1	DOOR HINGE LOWER	\$	300.55
76	1	DOOR CHECK REAR RH	\$	203.06

TRANS-CAB AUTO SERVICES PTE LTD
 NO. 2 ANG MO KIO ST 63 SINGAPORE 669111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
 SHD59R - ERGO

AAD1711-247

77	1	DOOR GRAB HANDLE REAR RH	\$	210.96
78	1	DOOR HANDLE OUTER REAR RH	\$	126.49
79	1	DOOR HANDLE CAP REAR RH	\$	35.52
80	1	DOOR HANDLE SEAL REAR RH	\$	7.89
81	1	DOOR HANDLE COVER REAR RH	\$	13.22
82	1	DOOR HANDLE MODULE REAR RH	\$	133.60
83	1	DOOR FINISHER REAR RH	\$	423.10
84	1	DOOR MOULDING REAR RH	\$	176.82
85	1	DOOR SEAL REAR RH	\$	162.02
86	1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69
87	1	FENDER PANEL REAR RH	\$	3,299.13

TOTAL	\$	62,648.61
10%	\$	6,264.86
	\$	56,383.75

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	66.00
2	1SET	FRONT BUMPER CLIP	\$	66.00
3	1SET	BUMPER SUPPORT FRT CLIP RH	\$	9.80
4	1SET	BUMPER RETAINER FRT CLIP RH	\$	12.50
5	1	RIM RH FRT	\$	385.00
6	1	TYRE RH FRT	\$	330.00
7	1	DOOR STICKER "Trans-cab"	\$	80.00
8	1	DOOR STICKER "Classic"	\$	30.00
9	1	DOOR STICKER "6555-3333"	\$	80.00

TOTAL	\$	1,059.30
TOTAL PARTS	\$	57,443.05

To Check Electrical Lighting Concerned. \$ 170.00

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 4,200.00

Putty and spray painting of the affected portion. \$ 4,500.00

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test. \$ 170.00

To transfer of tire, rim and on wheel balancing. \$ 170.00

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO/GST REG NO. 201019626G
SHD59R - ERGO

AAD1711-247

To check steering geometry and computer wheel alignment	\$	220.00
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00
Towing fees	\$	120.00
To rust-proofing of the affected areas.	\$	170.00
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00
TOTAL	\$	10,820.00
Over All Total	\$	68,263.05

(PARTS BY PARTS) Repair Days**15 Days**