



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 22.11.2017

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Attn: Motor Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Jiah 974 95749

WP

15 days

Lumpsum

Resurvey after repair

23/11/17 @ 1730

Surv @ lkkauto.com

* check repair limit.

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLR7418X TOYOTA AXIO HYBRID

To Supply

1)	1pc	rear bumper <i>de</i>	\$	700.00
2)	1pc	rear bumper right side retainer <i>nee</i>	\$	60.00
3)	1pc	rear bumper left side retainer <i>nee</i>	\$	60.00
4)	1set	rear bumper clip <i>nee</i>	\$	30.00
5)	1pc	rear bumper right bracket <i>nee</i>	\$	70.00
6)	1pc	rear bumper left bracket <i>nee</i>	\$	70.00
7)	1pc	rear bumper right reflector <i>cut</i>	\$	94.00
8)	1pc	rear bumper left reflector <i>cut</i>	\$	94.00
9)	1pc	rear bumper right ventilation duct <i>mis</i>	\$	33.50
10)	1pc	rear bumper left ventilation duct <i>de</i>	\$	33.50
11)	1pc	rear boot lid <i>bt</i>	\$	680.00
12)	1pc	rear boot lid right hinge <i>bt</i>	\$	185.20
13)	1pc	rear boot lid left hinge <i>bt</i>	\$	185.20
14)	1pc	rear boot lid lock <i>bt</i>	\$	90.00
15)	1pc	rear boot lid catch <i>bt</i>	\$	50.00
16)	1pc	rear boot lid "corolla" emblem <i>nee</i>	\$	59.60
17)	1pc	rear boot lid "Hybrid Synergy Drive" emblem <i>nee</i>	\$	61.70
18)	1pc	rear boot lid "Axio" emblem <i>nee</i>	\$	48.60
19)	1pc	rear boot lid weatherstrip <i>twi</i>	\$	120.00
20)	1pc	rear boot lid no plate lamp chrome garnish <i>de</i>	\$	295.26
21)	1set	rear boot lid no plate lamp ?	\$	62.80
22)	1pc	rear end panel <i>bt</i>	\$	380.00

23)	1pc	rear end panel top garnish <i>de</i>	\$	180.00
24)	1set	rear end panel top garnish clip <i>ne</i>	\$	20.00
25)	1pc	rear floor panel <i>buc</i>	\$	1,187.00
26)	1pc	right tail lamp <i>one</i>	\$	450.00
27)	1pc	left tail lamp <i>one</i>	\$	450.00
28)	1pc	right rear fender <i>buc</i>	\$	885.80
29)	1pc	right deck board trim 64730-13280 <i>de</i>	\$	518.10
30)	1pc	left rear fender <i>buc</i>	\$	885.80
31)	1pc	left deck trim panel assy 64740-13240 <i>de</i>	\$	24.00
32)	1pc	right rear fender mudflap <i>de</i>	\$	72.60
33)	1pc	left rear fender mudflap <i>de</i>	\$	72.60
34)	1pc	right rear luggage compartment cover 64712-12011 <i>de</i>	\$	316.00
35)	1pc	rear spare tyre top cover <i>de</i>	\$	386.90
36)	1pc	spare wheel cushion 64777-12150 ?	\$	264.10
37)	1pc	inner luggage compartment pad 64727-12051 ?	\$	136.60
38)	1pc	left deck floor box 64997-13051 ?	\$	518.10
39)	1pc	right deck floor box 64995-13050 ?	\$	240.10
40)	1pc	rear deck floor box 64993-13050 ?	\$	297.20
41)	1set	rear glass moulding <i>ne</i>	\$	386.90
42)	1pc	rear exhaust tail pipe with silencer 17430-21A30 <i>bt</i>	\$	623.70
43)	1pc	exhaust pipe support 17565-47010 <i>bt</i>	\$	26.90
44)	1pc	rear axle beam assy 42110-52332 ?	\$	2,092.68
45)	1pc	front bumper <i>de</i>	\$	1,370.00
46)	1pc	front bumper left side retainer <i>ne</i>	\$	97.00
47)	1pc	front bumper right side retainer <i>ne</i>	\$	97.00
48)	1set	front bumper clip <i>ne</i>	\$	20.00
49)	1pc	front bumper sponge <i>one</i>	\$	90.00
50)	1set	front bumper lower grille <i>ms</i>	\$	322.00
51)	1pc	front bumper reinforcement ?	\$	347.00
52)	1pc	left bumper fog lamp garnish ?	\$	55.40
53)	1pc	right bumper fog lamp garnish ?	\$	55.40
54)	1pc	front grille chrome <i>one</i>	\$	330.00
55)	1pc	front grille base <i>one</i>	\$	710.00
56)	1set	front grille clip <i>ne</i>	\$	10.00
57)	1pc	front grille emblem <i>ms</i>	\$	98.00
58)	1pc	front bonnet <i>bt</i>	\$	782.00
59)	1pc	front bonnet right hinge ?	\$	56.40
60)	1pc	front bonnet left hinge ?	\$	56.40
61)	1pc	front bonnet lock <i>bt</i>	\$	95.00
62)	1pc	left head lamp assy <i>one</i>	\$	825.00
63)	1pc	left head lamp moulding ?	\$	134.80
64)	1pc	left head lamp panel <i>one bt</i>	\$	97.00
65)	1pc	right head lamp assy <i>one</i>	\$	825.00

66)	1pc	right head lamp moulding ?	\$	134.80
67)	1pc	right head lamp panel <i>ht</i>	\$	97.00
68)	1pc	left front fender <i>Ry</i>	\$	680.00
69)	1pc	left front fender cowl	\$	161.60
70)	1set	left front fender cowl clip	\$	15.00
71)	1pc	left front fender "Hybrid" emblem <i>rel</i>	\$	90.00
72)	1pc	radiator support panel assy <i>ht</i>	\$	1,630.00
73)	1pc	support panel top cover <i>crd</i>	\$	310.00
74)	1pc	brace panel <i>ht</i>	\$	140.00
75)	1set	radiator	\$	1,570.00
76)	1set	a/con condensor <i>ht</i>	\$	1,545.00

Sub total parts	\$	26,345.24
Less: 25% discount	\$	(6,586.31)
	\$	19,758.93

To supply S.Nett Parts

1)	1pc	front No plate <i>mis</i>	\$	38.00
2)	1tube	rear glass sealant <i>rel</i>	\$	45.00
3)	1set	rear reverse sensor <i>dis</i>	\$	200.00
4)	1set	floor panel sealant <i>rel</i>	\$	150.00
5)	1tin	radiator coolant <i>rel</i>	\$	45.00

Sub total S.Nett Parts	\$	478.00
------------------------	----	--------

L/charges

1)	Towing charges (use king-trolley)	\$	80.00 ✓
2)	To tuff kote rear affected area	\$	180.00 <i>80</i>
3)	To remove & replace reverse sensor	\$	60.00 <i>30</i>
4)	To remove & refit rear glass	\$	120.00 ✓
5)	To transfer rear boot lid trim cover, handle, mechanism parts	\$	60.00 <i>40</i>
6)	To mount vehicle on chassis bench, align chassis	\$	250.00 ✓ <i>photo</i>
7)	To computerise wheel alignment	\$	80.00 ✓
8)	To remove rear boot lid, rear bumper right & left tail lamp. Cut right rear	\$	1,500.00 <i>1400</i>

- & left fender, end panel, floor panel & etc. straighten & align right & left rear chassis panel. Replace the above necessary part
- 9) To putty, respray painting rear boot lid inlet & outer, rear end panel, floor floor, right & left chassis panel, rear bumper & right & left rear fender. To polish 1500. \$ 1,800.00
- 10) To tuff kote front affection portion 60. \$ 80.00
- 11) To remove & fit a/con condensor, pipe, radiator. Replace a/con condensor, check wiring & refill a/con gas & vacuum. To remove & fit radiator, fan refill coolant 120. \$ 280.00
- 12) To focus right & left head lamp 30. \$ 60.00
- 13) To remove front bonnet, front bumper, right & left head lamp. Cut/ welding front support panel, left front fender. Straighten front right & left wheel house, replace front bumper, bonnet, left front fender, support panel & etc. 600 \$ 800.00
- 14) To putty, respray painting front support panel, right & left chassis panel, head lamp panel, front bonnet inlet & outer, front bumper, front left fender, 800 \$ 900.00

Sub total L/charges	\$	6,250.00
Estimated Total	\$	26,486.93