

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO : AXA INSURANCE SINGAPORE PTE LTD DATE : 20/11/2017
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SJU7717R
MODEL : TOYOTA VIOS 1.5E A
CHASSIS NO

ACCIDENT DETAILS DATE : 19-Nov-17
TIME : 06:30HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET <i>Pyis</i>	1	\$ 582.20	\$ 582.20
2	FRONT BUMPER <i>torn</i>	1	\$ 488.20	\$ 488.20
3	FRONT BUMPER SIDE RETAINER <i>LH New</i>	2	\$ 75.00	\$ 150.00
4	FRONT FENDER LH <i>Dented.</i>	1	\$ 680.00	\$ 680.00
5	FRONT FENDER EMBLEM 'WT-I' <i>New</i>	1	\$ 55.00	\$ 55.00
6	FRONT FENDER QUARTER GLASS COVER <i>LH</i>	1	\$ 52.60	\$ 52.60
7	FRONT FENDER INNER COWLING LH <i>New</i>	1	\$ 192.30	\$ 192.30
8	HEADLAMP LH <i>Cracked.</i>	1	\$ 450.30	\$ 450.30
9	FRONT SIDE MIRROR ASSY LH <i>Pyrid.</i>	1	\$ 613.00	\$ 613.00
10	FRONT SIDE MIRROR COVER LH <i>Pyrid.</i>	1	\$ 103.00	\$ 103.00
11	FRONT DOOR LH <i>Pyis</i>	1	\$ 1,266.90	\$ 1,266.90
12	FRONT DOOR PROTECTOR LH	1	\$ 130.00	\$ 130.00
13	FRONT DOOR OUTER MOULDING LH	1	\$ 103.00	\$ 103.00
14	FRONT DOOR OUTER HANDLE LH <i>New</i>	1	\$ 144.00	\$ 144.00
15	FRONT DOOR LOCK LH	1	\$ 433.80	\$ 433.80
16	FRONT DOOR WEATHERSTRIPE	1	\$ 189.00	\$ 189.00
17	REAR RH DOOR	1	\$ 1,233.50	\$ 1,233.50
18	REAR RH DOOR PROTECTOR <i>New</i>	1	\$ 130.00	\$ 130.00
19	REAR RH DOOR OUTER MOULDING <i>New</i>	1	\$ 103.00	\$ 103.00

20 Front RH Door Glass *CH4*

360.10

2684.3

2013.22

TOTAL PRICE \$ 7,099.80
 LESS 25% \$ 1,774.95
 SUB TOTAL PRICE \$ 5,324.85

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	FRONT FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00

20

TOTAL \$ 40.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	680	
3	TUFF COAT	\$ 180.00	x	
4	REFCOUS AND ADJUST HEADLAMPS ASSY	\$ 100.00	30	
5	TRANFER FRONT RH DOOR MECHANISM	\$ 150.00	x	
6	TRANFER FRONT LH DOOR MECHANISM	\$ 150.00	x.	
7	REMOVE AND REINSTALL RH SIDE DOOR PILLAR INNER TRIMS TO ASSIST REPAIR	\$ 350.00	x.	

TOTAL \$3,730.00

1110

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,364.85
 TOTAL LABOUR COST : \$ 3,730.00
 TOTAL REPAIR COST : \$ 9,094.85

total: 3143.22
 2/81 2.5/c
 04 days

APPROVED DETAILS

SURVEYOR :
 CONTACT NO :
 PART BY PART / LUMP SUM :

KK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 Parts prices are subject to confirmation
 Third party survey is on a "Without Prejudice" basis
 Illegal modification(s) is allowed
 • Complementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

knownedged by Repairer

Signature:

at: