

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9427B

DATE 21/11/2017 15:05

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X Repair</i>			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip <i>X</i>			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover <i>X</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X Repair</i>		\$ 38.00	\$ 76.00
	SUB TOTAL			\$ 1,482.90
	LESS 20%			\$ 296.58
	DISCOUNTED TOTAL			\$ 1,186.32
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70
	Rear Bumper Advertisement Logo <i>X /</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>/</i>		\$ 100.00	\$ 200.00
				\$ 385.70
	Labour Charge			
	Panel Beating			\$ 350.00 <i>100</i>
	Spray Painting Charge			\$ 200.00 <i>180</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 2,292.02
<p><i>Kalvi (C/C)</i> <i>22/11/17 1040hr</i> <i>2 Pags</i> <i>4/s</i> <i>After Repair photo</i></p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party suppliers on a "Without prejudice" basis • No illegal modifications allowed • Supplemental damages must be reserved and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				