

AIG TP



## Service Order Confirmation

SERVICE ORDER NO: 17IP3142  
 CUSTOMER NO.: CV031749  
 CUSTOMER NAME: TEO TECK CHUAN  
 TELEPHONE NO.:  
 ADDRESS: 111 JALAN PELATOK  
 Singapore

VEH No.: **SDL1168H**

Order Date: 11/22/17  
 Reg Date: 06/27/14 KM: 57.633  
 VIN NO.: WVVZZZ3CZEE536670 ENGINE NO:  
 MODEL: CC NF 2.0 TSI (DSG) R-line MODEL NO.: 3584P6

SA: Tan William

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
<b>Labor</b>						
1	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	280		280 ✓
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480 ✓
3	B&P MECH R&R REAR U/CARRIAGE	3	TU	840		2,520 2100 ✓
4	B&P MECH R&R REAR SUB FRAME	3	TU	840		2,520 2100? ✓
5	B&P MECH R&R RIM & BALANCE	4	TU	50		200 ✓
6	B&P MACP LABOUR LABOUR	10	UNIT	840		8,400 6720 ✓
7	B&P MACP PAINT SPRAY PAINT	10	UNIT	800		8,000 5600 ✓
8	B&P MACP LABOUR TRANSFER DOOR MECHANISM	1	UNIT	840		840 420 ✓
9	B&P MACP LABOUR R&R REAR W/SCREEN	1	UNIT	840		840 ✓
10	B&P MACP LABOUR R&R REAR LUGGAGE TRIM	1	UNIT	840		840 420 ✓
11	B&P MACP LABOUR R&R REAR SEAT	1	UNIT	840		840 420 ✓
12	EXT00040 Tyres PIRELLI PZERO NERO GT 235/40/18	2	PCS	680		1,360 20% cut ✓
<b>Item</b>						
13	3C8821022 RHS FRT FENDER	1	PCS	991.94		991.94 PH ✓
14	3C8807184C RHS BUMPER SIDE BRACKET	1	PCS	33.29		33.29 new ✓
15	3C8807183C LHS BUMPER SIDE BRACKET	1	PCS	33.29		33.29 new ✓
16	3C8831056H RHS FRT DOOR	1	PCS	2,428.92		2,428.92 PH ✓
17	3C8837701B 5AP DOOR SEAL	1	PCS	252.81		252.81 new ✓
18	D 378500A2 DOOR INSULATOR	1	PCS	53.34		53.34 new ✓
19	3C8853072B 2ZZ RHS FRT DOOR MOLDING CHROME	1	PCS	184.10		184.10 new ✓
20	3C8853074B 2ZZ RHS REAR DOOR MOLDING CHROME	1	PCS	184.09		184.09 new ✓
21	3C8853856C GRU SIDE SKIRT RH	1	PCS	1,286.87		1,286.87 PH ✓
22	3C0853934 RIVET	10	PCS	0.62		6.20 new ✓
23	3C0853586 GROMMET	17	PCS	2.33		39.61 new ✓
24	3C8809844 RHS REAR FENDER	1	PCS	1,512.03		1,512.03 PH ✓
25	D 506KD1A3 2K FOAM	1	PCS	182.27		182.27 new ✓
26	D 476KD1M2 SEALANT	1	PCS	89.30		89.30 new ✓
27	D 007600A1 INOXSPRAY	1	PCS	78.44		78.44 new ✓
28	D 180003M2 2KADHESIV	1	PCS	330.24		330.24 new ✓



## Service Order Confirmation

**SERVICE ORDER NO:** 17IP3142  
**CUSTOMER NO.:** CV031749  
**CUSTOMER NAME:** TEO TECK CHUAN  
**TELEPHONE NO.:**  
**ADDRESS:** 111 JALAN PELATOK  
 Singapore

**VEH No.:** **SDL1168H**

**Order Date:** 11/22/17  
**Reg Date:** 06/27/14 **KM:** 57,633  
**VIN NO.:** WVWZZZ3CZEE536670 **ENGINE NO:**  
**MODEL:** CC NF 2.0 TSI (DSG) R-line **MODEL NO.:** 3584P6

SA: Tan William

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	3C8810972B RHS REAR FENDER LINER	1	PCS	165.12		165.12 <i>DE</i>
30	3C8845051H NVB REAR W/SCREEN	1	PCS	1,284.18		<i>photo</i> 1,284.18 <i>rec</i>
31	D 004660M2 2K GLUE	1	PCS	183.87		183.87 <i>rec</i>
32	D 002000A2 CLEANER	1	PCS	147.86		147.86 <i>rec</i>
33	D 00920002 PRIMER	1	PCS	32.19		32.19 <i>rec</i>
34	D 00950025 APPLICATOR	2	PCS	11.19		22.38 <i>rec</i>
35	D 181802M1 ACTIVATOR	1	PCS	29.46		29.46 <i>rec</i>
36	3C0819465 RHS AIR DUCT	1	PCS	33.44		33.44 <i>?</i>
37	3C8945208AD RHS TAILLIGHT OUTER	1	PCS	601.43		601.43 <i>scr</i>
38	3C8945246 CLIP	1	PCS	9.14		9.14 <i>rec</i>
39	3C8807417ADGRU REAR BUMPER	1	PCS	2,192.97		2,192.97 <i>DE</i>
40	3C8807376B BUMPER SIDE BRACKET RH	1	PCS	50.40		50.40 <i>rec</i>
41	3C8807394D TAILLIGHT LOWER BRACKET RH	1	PCS	24.35		24.35 <i>?</i>
42	3C8807460B 2ZZ BUMPER SIDE MOLDING CHROME RH	1	PCS	163.53		163.53 <i>rec</i>
43	1S0919275C GRU SENSOR	1	PCS	202.04		202.04 <i>scr</i>
44	1K8601025R 88Z 18" "MALLORY" RIM ONLY	4	PCS	2,867.10		11,468.40 <i>scr</i>
45	311601361 RUBBER VALVE	4	PCS	1.73		6.92 <i>rec</i>
46	3C0505235AC REAR SUB FRAME	1	PCS	2,110.37		2,110.37 <i>?</i>
47	N 91114701 BOLT	1	PCS	13.44		13.44 <i>rec</i>
48	WHT000846 BOLT	3	PCS	24.11		72.33 <i>rec</i>
49	1K0511409CA STABILIZER	1	PCS	326.19		326.19 <i>?</i>
50	1K0505465AA CONN LINK	1	PCS	83.40		83.40 <i>?</i>
51	1K0501530C TIE ROD	1	PCS	232.74		232.74 <i>?</i>
52	3C0505224E TRAILING ARM	1	PCS	487.50		487.50 <i>?</i>
53	N 10628301 BOLT	1	PCS	12.84		12.84 <i>rec</i>
54	N 91201301 BOLT	1	PCS	19.22		19.22 <i>rec</i>
55	N 10769501 SCREW	2	PCS	17.94		35.88 <i>rec</i>
56	5Q0505323C UPPER CONTR ARM	1	PCS	420.11		420.11 <i>?</i>
57	1K0505311AB LOWER CONTR ARM	1	PCS	422.19		422.19 <i>?</i>
58	3C0505434K WHEEL BEARING HOUSING	1	PCS	1,107.54		1,107.54 <i>?</i>



## Service Order Confirmation

**SERVICE ORDER NO.:** 17IP3142  
**CUSTOMER NO.:** CV031749  
**CUSTOMER NAME:** TEO TECK CHUAN  
**TELEPHONE NO.:**  
**ADDRESS:** 111 JALAN PELATOK  
 Singapore  
**VEH No.:** **SDL1168H**  
**Order Date:** 11/22/17  
**Reg Date:** 06/27/14 **KM:** 57,633  
**VIN NO.:** WVVZZZ3CZEE536670 **ENGINE NO.:**  
**MODEL:** CC NF 2.0 TSI (DSG) R-line **MODEL NO.:** 3584P6

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to final approval
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) to be carried out
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

SA: Tan William

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
59	1T0598611B WHEEL BEARING	1	PCS	807.81		807.81 ?
60	N 91201301 BOLT	2	PCS	19.22		38.44 ✓
61	N 10640501 BOLT	2	PCS	11.49		22.98 ✓
62	WHT000228 SCREW	2	PCS	23.40		46.80 ✓
63	WHT000227 SCREW	1	PCS	23.40		23.40 ✓
64	3C0513046D SHOCK ABSORBER	1	PCS	936.48		936.48 ?
65	3C0513353E SHOCK ABSORBER TOP MTG	1	PCS	112.68		112.68 ?
66	3C0511359D STOP BUFFER	1	PCS	53.34		53.34 ?
67	3C0513425 SHOCK ABSORBER BELLOW	1	PCS	6.78		6.78 ✓
68	999999610 OWS BRAKE CLEANER	1	PCS	54.60		54.60 ✓

Rasul  
 Hp 90010068  
 21 days  
 24/11/17 @ 1020  
 Resurvey by part

Remarks : DIRECT SETTLEMENT (AIG)  
 DOA 21/11/2017  
 SURVEY BY  
 TP VEHICLE SDL1168H

**TOTAL** 58,871.48  
**GST AMOUNT** 4,121.00  
**TOTAL AMOUNT** 62,992.48



Certified Goods/Service received:

Customer