

ASS. REC. BY:

REF: C9/MSG17022407/R19/12

Special Instruction:

Surveyor: Murman ASSIGNMENT (Office)

From (Person): Catherine Thia of MSLH Date/Time: 23-11-2017 2:30pm

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 8926A Insured: SJS 7496M

at Workshop m/s Kah Motor Tel: 8288 6302

of 255 Leng Kee Road

Policy No: 7008429SMA Claim No: 5373 17.

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18112017
(Client's Record)

CA / REV / REP. / REV 24 HRS WP' 24.11.2017 @ Early morning H.O.D. Endorsement: _____

Date/Time: 23-11-2017 2:39pm Person Contacted: Patrick Vehicle: IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|--------------------------|---|
| | <u>SLP 8926A x</u> |
| | <u>SJS 7496M x</u> |
| <u>21/11/17 @ 4:33pm</u> | <u>revised to Catherine Thia via Messman.</u> |
| <u>21/11/18 @ 2:46pm</u> | <u>confirmed with Patrick Note final fig @ 2695.98, 5 days.</u> |
| | <u>(Paid @ 8285.40, 75%)</u> |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|---------------------------|---|
| MSIG INSURANCE (SINGAPORE) PTE LTD | | Ref : CS/MSG17022407/R1qb | |
| 16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581 | | Date : 24-11-2017 |  |
| Code : MSG | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SJS 7496M | Veh. Inspected | SLP 8926A |
| Policy No. | 29008429SMA | Coverage (\$) | 0.00 |
| Claim No. | 537317 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 23/11/2017 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 18/11/2017 | Inspection Date | 24/11/2017 |
| Survey held at | KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 20 Nov 2017 | | 23 Nov 2017 14:30 Assign | | | | New Assignment Cancel Case |

| | | | | |
|-------------|------------------|----------------------|------------------|-----------------|
| Main | Reference | Claim Details | Documents | Show All |
|-------------|------------------|----------------------|------------------|-----------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: Sundaram Bouvaneswaran, ID: S7064010D

Main Claimant: TAN SOON ENG, ID: S1747619Z

| | |
|---|--|
| Vehicle Reg. No.: SLP8926A | Date of Loss: 18/11/2017 00:00 - :59 |
| Claim Type: TP / 537317 | Policy/Cover Note No.: 29008429SMA Coverage: 07/10/2017 - 06/10/2018 |
| Vehicle Reg. No. (Insured): SJS7496M | Policy No. (Claimant): |
| Excess: | |

Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/11/2017]

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 21 March 2018 2:46 PM
To: Patrick Mok
Cc: SUR
Subject: FINALISE OF SLP 8926A (DOA: 18/11/2017)

Dear Patrick,

Confirm final fig \$2,695.98 before GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 27 Nov 2017

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SJS7496M | Accident Date | : 18/11/2017 |
| TP Vehicle No | : SLP8926A | Assignment Date | : 23/11/2017 |
| Make | : HONDA CIVIC | Est. Duration of Repair | : 5.00 |
| Date of Inspection | : 24/11/2017 | | |
| Inspection At | : KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 10,958.88 |
| Revised Amount | :S\$ | 9,709.15 |
| Check Items (Estimated) | :S\$ | 519.73 |
| Total | :S\$ | 10,228.88 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--|
| Date Of Report | 18/11/2017 14:39 |
| Date Of Accident | 18/11/2017 07:10 |
| Exact Location Of Accident | JUNCTION OF BT. BATOK WEST AVE 6 & AVE 8 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|--|--------------------------------------|
| Vehicle Registration Number | SLP8926A |
| Insured/Policyholder | |
| Name Of Registered Owner | TAN SOON ENG |
| NRIC No | S1747619Z |
| Email Address | 2006SET@GMAIL.COM |
| Mobile Phone No | (LOCAL) +65-97803245 |
| Alternative Phone No | OFFICE-97803245 |
| Vehicle Particulars | |
| Manufacturer | HONDA |
| Model | CIVIC-1.5 I-VTEC (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | TOKIO MARINE INSURANCE SINGAPORE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | MU007199 |
| Cover Note Number | |
| Driver | |
| Name of Driver | TAN ZI JIAN, BRENDAN |
| NRIC No | S9620117F |
| Date Of Birth | 12/06/1996 |
| Occupation | INDOOR |
| Date Of Driving Pass | 27/02/2016 |
| Driving Experience | 1 YEAR AND 8 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98283057 |
| Fax Number | |
| Contact Number | |
| EMail Address | 2006SET@GMAIL.COM |

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJS7496M
 Vehicle Make/Model/Colour CHEVROLET CRUZE WHITE
 Details Of Properties LEFT FRONT PORTION
 Name of Driver SUNDRAM BOUVANESWARAN
 NRIC/Passport Number S7064010D
 Contact Number 97428473
 Address BLK 192 BT.BATOK WEST AVE 6
 #14-61
 Postcode 650192
 Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Vehicle No SLP 8926A SKETCH PLAN

ANNEX D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurer's lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


[Handwritten signatures and initials]

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



SJS 7496A.

Please continue to Annex C

Vehicle No

SLP 8926A.

Annex E

Describe Circumstances of the Accident

On 18/11/2017, my son was driving the car with myself as passenger, along Bukit Katok West Ave 6.

At the junction of Bukit Katok West, Ave 6 and Ave 8, after the light had turned green, my son proceeded to drive forward on the left lane of Ave 6.

That lane was for turning left into Ave 8 or for going straight forward. However, the right lane was for strictly going forward.

The other car, SJS 7496W, which was on the right lane at the junction turned left, toward Ave 8.

The left side of SJS 7496W hit the right corner of my car. The right indicator area and right bumper area are damaged.

The damage to SJS 7496W was on its left front door, from what I can observe.


In a SMS message, the other driver wrote: "Mr Tan, can you please check car repair amount. I'll pay."


You had been advised by the workshop that in the event that you wish to claim against your own policy (OD-claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|--|---------------------|---------------------------|---------------------------|----------------|
| Customer | : MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581 | Document No. | : SQT17004727 | Page | 1 |
| Registration No | : SLP8926A | Date | : 18. Nov 2017 | Customer No. | : WZM003 |
| Chassis No | : MRHFC5650HT000045 | Svc Advisor | : PATRICK MOK LIP KAY | Engine No | : R16B22000062 |
| Model | : CIVIC 1.6 VTI YM2017 | Date Time | : 18. Nov 2017 2:41:55 PM | Surveyor Name | : |
| Owner's Name | : TAN SOON ENG | Survey Date | : | Authorisation Date | : |
| Ins Policy No. | : | | | | |
| Date of Accident | : | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | GST Amt | Amount incld GST |
|-----------------|---|-----|------------|--------|------------------|----------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN SOON ENG OWNER INSURER: TOKIO MARINE ACC DATE: 18/11/2017 SURVEYED BY: DATE: REF NO: TP INSURER: MSIG INSURANCE TP VEHICLE: SJS7496M | | | | | | |
| BOSUN | SUNDRIES | 1 | 100.00 | 50 | 100.00 | 7.00 | 107.00 |
| BKBU01A | REMOVE/REPLACE FRT BUMPER & RH FRONT FENDER | 1 | 1120.00 | 840 | 1120.00 | 78.40 | 1198.40 |
| BML01I | INSPECT FR LIGHTING MECHANISMS & FOCUS | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |
| BP02R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P) | 1 | 1300.00 | 900 | 1300.00 | 91.00 | 1391.00 |
| | | | | | Sum Labor | 2700.00 | 189.00 |
| | | | | | | | 2,889.00 |
| 60211-TBA-A00ZZ | PANELR.FENDER | 1 | 236.20 | 91 | 177.15 | 12.40 | 189.55 |
| 60213-TBA-A00ZZ | BRACKET AR.FR.FENDER | 1 | 27.90 | 25 | 20.92 | 1.46 | 22.38 |
| 74101-TEA-T00 | FENDERR.FR.INNER | 1 | 48.50 | 25 | 36.37 | 2.55 | 38.92 |
| 90853-SJA-A00 | RIVET4.8MM | 10 | 1.80 | 25 | 13.50 | 0.95 | 14.45 |
| 04715-TEC-Q00ZZ | FACE ASSYRR.BUMPER | 1 | 9999.99 | 25 | 7499.99 | 525.00 | 8024.99 |
| 71502-TEX-Y00 | GARNISHRR.BUMPER LOWER | 1 | 34.50 | 25 | 25.87 | 1.81 | 27.68 |
| 71503-TEA-T00 | GARNISHR.FR.BUMPER SIDE | 1 | 7.40 | 25 | 5.55 | 0.39 | 5.94 |
| 71504-TBA-A00 | COVERR.FINISHER | 1 | 15.70 | 25 | 11.77 | 0.82 | 12.59 |
| 71505-TBA-A00 | BRACKETR.RR.BUMPER SIDE | 1 | 2.20 | 25 | 1.65 | 0.12 | 1.77 |
| 71555-TBA-A00 | BRACKETL.RR.BUMPER SIDE | 1 | 2.20 | 25 | 1.65 | 0.12 | 1.77 |
| 71593-TEA-T01 | SPACERR.FR.BUMPER SIDE | 1 | 10.40 | 25 | 7.80 | 0.60 | 9.22 |
| 71598-TEA-T01 | SPACERL.FR.BUMPER SIDE | 1 | 10.40 | 25 | 7.80 | 0.60 | 9.22 |
| 91505-TM8-003 | CLIPBUMPER | 1 | 2.00 | 25 | 1.50 | 0.11 | 1.61 |
| 33100-TEC-Q01 | HEADLIGHT ASSYR. | 1 | 562.80 | 25 | 422.10 | 29.55 | 451.65 |



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MSIG INSURANCE (SINGAPORE) PTE
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581

Registration No : SLP8926A

Chassis No : MRHFC5650HT000045

Model : CIVIC 1.6 VTI YM2017

Owner's Name : TAN SOON ENG

Ins Policy No. :

Date of Accident :

Document No. : SQT17004727 **Page** 2

Date : 18. Nov 2017

Customer No. : WZM003

Svc Advisor : PATRICK MOK LIP KAY

Engine No : R16B22000062

Date | Time : 18. Nov 2017 2:41:55 PM

Surveyor Name :

Survey Date :

Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | GST Amt | Amount incld GST |
|-----------------|-----------------------|-----|------------|--------|----------------|---------------|------------------|
| 34300-TET-H01 | LIGHT ASSYR.SIDE TURN | 1 | 31.50 | 25 | 23.62 | 1.65 | 25.27 |
| Sum Item | | | | | 8258.88 | 578.13 | 8,837.01 |

Survey By Rasul - Hy 90010068

Date & Time 24/11/17 @ 0930

Excess _____ *5 days*

Status _____

Signature *[Signature]*

Total Amount 10,958.88 767.13 11,726.01

Total (Inclusive of GST) 11,726.01

1099210

Resurvey by paint

[Signature]
28/11/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1098130

Printed on 18/11/2017 3:59:21 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

| | | | |
|--------------------|--------------------------|-------------------------|---------------------|
| Customer: | S1747619Z / TAN SOON ENG | Document No: | SVO17073915 |
| Chassis No: | MRHFC5650HT000045 | Printed By: | PATRICKMOK |
| License No: | SLP8926A | Order Date: | 24. November 2017 |
| Mileage: | 8436 | Order Time: | 2:52:23 PM |
| Engine No: | R16B22000062 | Service Advisor: | PATRICK MOK LIP KAY |

| ITEM | DESCRIPTION | QTY | UNIT PRICE | DISC % | AMOUNT | GST Amt | Amount incld GST |
|-------------------|---|-----|------------|--------|-----------------|---------------|----------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN SOON ENG OWNER INSURER: TOKIO MARINE ACC DATE: 18/11/2017 SURVEYED BY: DATE: REF NO: TP INSURER: MSIG INSURANCE TP VEHICLE: SJS7496M | | | | | | |
| | | | | | | | 5 REPAIR DAYS |
| 60211-TBA-A00ZZ ✓ | PANELR.FENDER | 1 | 236.20 ✓ | 25 | 177.15 | 12.40 | 189.55 |
| 60213-TBA-A00ZZ | BRACKET AR.FR.FENDER | 1 | 27.90 ✓ | 25 | 20.92 | 1.46 | 22.38 |
| 90853-SJA-A00 | RIVET4.8MM | 10 | 1.80 ✓ | 25 | 13.50 | 0.95 | 14.45 |
| 91505-TM6-003 ✓ | CLIPBUMPER | 16 | 2.00 ✓ | 25 | 24.00 | 1.68 | 25.68 |
| 34300-TET-H01 | LIGHT ASSYR.SIDE TURN | 1 | 31.50 ✓ | 25 | 23.62 | 1.65 | 25.27 |
| 71101-TEA-T00ZZ ✓ | FACEFR.BUMPER | 1 | 579.90 ✓ | 25 | 434.92 ✓ | 30.44 | 465.36 |
| 71103-TEA-T00 | GARNISHR.FR.BUMPER SIDE | 1 | 17.10 ✓ | 25 | 12.82 | 0.90 | 13.72 |
| 71193-TEA-T01 ✓ | SPACERR.FR.BUMPER SIDE | 1 | 10.40 ✓ | 25 | 7.80 | 0.55 | 8.35 |
| 71198-TEA-T01 | SPACERL.FR.BUMPER SIDE | 1 | 10.40 ✓ | 25 | 7.80 | 0.55 | 8.35 |
| 90682-SEA-003 ✓ | CLIP ABUMPER (supplementary) <i>new</i> | 2 | 2.30 ✓ | 25 | 3.45 | 0.24 | 3.69 |
| | SUM PARTS: | | | | 725.98 | 50.82 | 776.80 |
| BOSUN | 0701 SUNDRIES | 1 | 50.00 ✓ | | 50.00 | 3.50 | 53.50 |
| BKBU01A | 1466 REMOVE/REPLACE FRT BUMPER & RH FRONT FENDER | 1 | 840.00 ✓ | | 840.00 | 58.80 | 898.80 |
| BML01I | 1466 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N) | 1 | 180.00 ✓ | | 180.00 | 12.60 | 192.60 |
| BP02R | 1624 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P) | 1 | 900.00 ✓ | | 900.00 | 63.00 | 963.00 |
| | SUM LABOUR: | | | | 1,970.00 | 137.90 | 2,107.90 |
| | TOTAL SGD | | | | 2,695.98 | 188.72 | 2,884.70 |
| | Total Payable (SGD) | | | | | | 2,884.70 |

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

| | | | | | |
|---------------------------|--|-----------------------|-------------------------|-----------------------------|--------------|
| Customer : | MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581 | Document No. : | SQT17004727 | Page : | 1 |
| Registration No : | SLP8926A | Date : | 18. Nov 2017 | Customer No. : | WZM003 |
| Chassis No : | MRHFC5650HT000045 | Svc Advisor : | PATRICK MOK LIP KAY | Engine No : | R16B22000062 |
| Model : | CIVIC 1.6 VTI YM2017 | Date Time : | 18. Nov 2017 2:41:55 PM | Surveyor Name : | |
| Owner's Name : | TAN SOON ENG | Survey Date : | | Authorisation Date : | |
| Ins Policy No. : | | | | | |
| Date of Accident : | | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | GST Amt | Amount incld GST | |
|-----------------|---|-----|------------|--------|------------------|----------------|------------------|--------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN SOON ENG OWNER INSURER: TOKIO MARINE ACC DATE: 18/11/2017 SURVEYED BY: DATE: REF NO: TP INSURER: MSIG INSURANCE TP VEHICLE: SJS7496M | | | | | | | |
| BOSUN | SUNDRIES | 1 | 100.00 | 50 | 100.00 | 7.00 | 107.00 | |
| BKBU01A | REMOVE/REPLACE FRT BUMPER & RH FRONT FENDER | 1 | 1120.00 | 840 | 1120.00 | 78.40 | 1198.40 | |
| BML01I | INSPECT FR LIGHTING MECHANISMS & FOCUS | 1 | 180.00 | | 180.00 | 12.60 | 192.60 | |
| BP02R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P) | 1 | 1300.00 | 900 | 1300.00 | 91.00 | 1391.00 | |
| | | | | | Sum Labor | 2700.00 | 189.00 | |
| | | | | | | | 2,889.00 | |
| 60211-TBA-A00ZZ | PANELR.FENDER | 1 | 236.20 | 94 | 25 | 177.15 | 12.40 | 189.55 |
| 60213-TBA-A00ZZ | BRACKET AR.FR.FENDER | 1 | 27.90 | 25 | 20.92 | 1.46 | 22.38 | |
| 74101-TEA-T00 | FENDERR.FR.INNER | 1 | 48.50 | 25 | 36.37 | 2.55 | 38.92 | |
| 90853-SJA-A00 | RIVET4.8MM | 10 | 1.80 | 25 | 13.50 | 0.95 | 14.45 | |
| 04715-TEC-Q00ZZ | FACE ASSYRR.BUMPER | 1 | 7499.99 | 25 | 7499.99 | 525.00 | 8024.99 | |
| 71502-TEX-Y00 | GARNISHRR.BUMPER LOWER | 1 | 34.50 | 25 | 25.87 | 1.81 | 27.68 | |
| 71503-TEA-T00 | GARNISHR.RR.BUMPER SIDE | 1 | 7.40 | 25 | 5.55 | 0.39 | 5.94 | |
| 71504-TBA-A00 | COVERR.FINISHER | 1 | 15.70 | 25 | 11.77 | 0.82 | 12.59 | |
| 71505-TBA-A00 | BRACKETR.RR.BUMPER SIDE | 1 | 2.20 | 25 | 1.65 | 0.12 | 1.77 | |
| 71555-TBA-A00 | BRACKETL.RR.BUMPER SIDE | 1 | 2.20 | 25 | 1.65 | 0.12 | 1.77 | |
| 71593-TEA-T01 | SPACERR.RR.BUMPER SIDE | 1 | 11.50 | 25 | 8.62 | 0.60 | 9.22 | |
| 71598-TEA-T01 | SPACERL.RR.BUMPER SIDE | 1 | 11.50 | 25 | 8.62 | 0.60 | 9.22 | |
| 91505-TM8-003 | CLIPBUMPER | 1 | 2.00 | 25 | 1.50 | 0.11 | 1.61 | |
| 33100-TEC-Q01 | HEADLIGHT ASSYR. | 1 | 562.80 | 25 | 422.10 | 29.55 | 451.65 | |



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|--|---------------------|---------------------------|---------------------------|----------------|
| Customer | : MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581 | Document No. | : SQT17004727 | Page | 2 |
| Registration No | : SLP8926A | Date | : 18. Nov 2017 | Customer No. | : WZM003 |
| Chassis No | : MRHFC5650HT000045 | Svc Advisor | : PATRICK MOK LIP KAY | Engine No | : R16B22000062 |
| Model | : CIVIC 1.6 VTI YM2017 | Date Time | : 18. Nov 2017 2:41:55 PM | Surveyor Name | : |
| Owner's Name | : TAN SOON ENG | Survey Date | : | Authorisation Date | : |
| Ins Policy No. | : | | | | |
| Date of Accident | : | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | GST Amt | Amount incld GST |
|-----------------|-----------------------|-----|------------|--------|----------------|---------------|------------------|
| 34300-TET-H01 | LIGHT ASSYR.SIDE TURN | 1 | 31.50 | 25 | 23.62 | 1.65 | 25.27 |
| Sum Item | | | | | 8258.88 | 578.13 | 8,837.01 |

| | | | | | |
|------------------------|---|---------------------------------|------------------|--------|-----------|
| Survey By | <u>Rasul - Hy 90010068</u> | Total Amount | 10,958.88 | 767.13 | 11,726.01 |
| Date & Time | <u>24/11/17 @ 0930</u> | Total (Inclusive of GST) | <u>11,726.01</u> | | |
| Excess | <u>5 days</u> | | | | |
| Status | | | | | |
| Signature | <u>Rasul</u> <u>Resurvey by part</u> | | | | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 20 Nov 2017 | | 23 Nov 2017 14:30 Edit Adj Rpt | S\$2,695.98 Edit Estimates | S\$2,695.98 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|---|------------------------|--|--------------------------|-----------------------------------|---------------------------------|--------------------------|-------------------|--------------|
| CLAIM SUBFOLDER DETAILS | | | | [Created by insurer] | | | | | |
| Insured: | Sundaram Bouvaneswaran , ID: S7064010D | | | | | | | | |
| Main Claimant: | TAN SOON ENG , ID: S1747619Z | | | | | | | | |
| Vehicle Reg. No.: | SLP8926A | Date of Loss: | 18/11/2017 00:00 - :59 | | | | | | |
| Claim Type: | TP / 537317 | Policy/Cover Note No.: | 29008429SMA Coverage: 07/10/2017 - 06/10/2018 | | | | | | |
| Vehicle Reg. No. (Insured): | SJS7496M | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/12/2017] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | | View All | Compose Case Mail | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS <input type="checkbox"/> | | | | View All | Search Tasks | Create New Task | Complete | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

***SLP8926A (537317)**
[SJS7496M]
TP
TAN SOON ENG
Nov 18 2017 12:00AM
[Sundaram Bouvaneswaran]
Kah Motor Co Sdn Bhd

| Upload Documents | | Upload Photos | Compose New Letter | View <input type="button" value="View in Browser"/> |
|----------------------------------|-----------------|---|------------------------------------|--|
| Assessment Reports | | | | 1 per page <input type="checkbox"/> |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 27/11/17 16:37 | Adjuster Immediate Advice | Load HTM | <input type="checkbox"/> |
| Photos/ Images | | | | 3 per page <input type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 22/03/18 09:50 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 22/03/18 09:50 | Chassis Number | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 22/03/18 09:50 | General View | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | | 1 per page <input type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 20/11/17 17:14 | PRI | Load PDF | <input type="checkbox"/> |
| 2 | 20/11/17 17:14 | Estimate and TP GIA REPORT | Load PDF | <input type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 26/03/18 11:32 | Supplementary | Load PDF | <input type="checkbox"/> |

Documents Checklist

| | |
|----------------------------|---|
| DOCUMENTS CHECKLIST | <input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/> |
|----------------------------|---|

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022407/R1QBE2

Date: 26/03/2018

REFERENCE

| | | |
|--|----------------------|--|
| Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 29008429SMA |
| Claimant Vehicle No : SLP8926A | Insured Vehicle No : | SJS7496M |
| Date of Loss: 18/11/2017 | Nature of Claim: | TP Claim No: 537317 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SLP8926A | Engine No: | R16B22000062 |
| Make & Model: | HONDA CIVIC, 1.6 VTI (A) | Chassis No: | MRHFC5650HT000045 |
| Reg. Date: | 21/06/2017 (Man. Year: 2017) | Odometer: | 8436 km |
| Colour: | Grey | | |
| Engine Capacity: | 1597 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 215/55 R16 | Rear Tyre Size: | 215/55 R16 |
| Front Left Side: | Hankook 6 mm | Rear Left Side: | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|-----------------|-----------------|--------------|
| Parts | 8,392.10 | 775.98 | 7,616.12 | 90.75 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,600.00 | 1,920.00 | 680.00 | 26.15 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 10,992.10 | 2,695.98 | 8,296.12 | 75.47 |
| + GST 7.00/7.00% (S\$) | 769.45 | 188.72 | 580.73 | 75.47 |
| Nett Amount (S\$) | 11,761.55 | 2,884.70 | 8,876.85 | 75.47 |

INSPECTION

| | | | |
|---------------------|------------|---------------|----------------------------|
| Date of Assignment: | 23/11/2017 | Inspected At: | Kah Motor Co Sdn Bhd (Ubi) |
| Date Inspected: | 24/11/2017 | | NO. 255 ALEXANDRA ROAD |
| | | | SINGAPORE 159937 |

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Mar 2018)
Parts: 143 HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP8926A)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------|---------------|-------------|------------|
| 1 | 1 | | *SUNDRIES | Necessary | 100.00 FS | *50.00 FS |
| 2 | 1 | | *PANELR.FENDER | Bent | 177.15 FS | *177.15 FS |
| 3 | 1 | | *BRACKET AR.FR.FENDER | Necessary | 20.92 FS | *20.92 FS |
| 4 | 1 | | *FENDERR.FR.LINER | Serviceable | 36.37 FS | *- FS |
| 5 | 10 | | *RIVET4.8MM | Necessary | 13.50 FS | *13.50 FS |
| 6 | 1 | | *FACE ASSYRR.BUMPER | Scratched | 7,499.99 FS | *434.92 FS |
| 7 | 1 | | *GARNISHRR.BUMPER LOWER | Serviceable | 25.87 FS | *- FS |
| 8 | 1 | | *GARNISHR.FR.BUMPER SIDE | Necessary | 12.82 FS | *12.82 FS |
| 9 | 1 | | *COVERR.FINISHER | Serviceable | 11.77 FS | *- FS |
| 10 | 1 | | *BRACKETR.RR.BUMPER SIDE | Not Necessary | 1.65 FS | *- FS |
| 11 | 1 | | *BRACKETL.RR.BUMPER SIDE | Not Necessary | 1.65 FS | *- FS |
| 12 | 1 | | *SPACERR.FR.BUMPER SIDE | Necessary | 8.62 FS | *7.80 FS |
| 13 | 1 | | *SPACERL.FR.BUMPER SIDE | Necessary | 8.62 FS | *7.80 FS |
| 14 | 16 | | *CLIPBUMPER | Necessary | 24.00 FS | *24.00 FS |
| 15 | 1 | | *HEADLIGHT ASSYR | Serviceable | 422.10 FS | *- FS |
| 16 | 1 | | *LIGHT ASSYR.SIDE TURN | Cracked | 23.62 FS | *23.62 FS |
| 17 | 1 | | *CLIP ABUMPER (2PCS) | Necessary | 3.45 FS | *3.45 FS |

F=Franchise part. S=SpcNett.

| | | |
|---------------------------|-----------------|---------------|
| Total Parts (\$\$) | 8,392.10 | 775.98 |
|---------------------------|-----------------|---------------|

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|--------------------------------|-----------------|
| Labour Items | | | | |
| 1 | REMOVE / REPLACE FRT BUMPER & RH FRONT FENDER | New | 1,120.00 | 840.00 |
| 2 | INSPECT FR LIGHTING MECHANISMS & FOCUS | New | 180.00 | 180.00 |
| 3 | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P) | New | 1,300.00 | 900.00 |
| | | | Gross Labour Cost (S\$) | 1,920.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >