



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: S1747619Z / TAN SOON ENG
Chassis No: MRHFC5650HT000045
License No: SLP8926A
Mileage: 8436
Engine No: R16B22000062

Document No: SVO17073915
Printed By: PATRICKMOK
Order Date: 24. November 2017
Order Time: 2:52:23 PM
Service Advisor: PATRICK MOK LIP KAY

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN SOON ENG OWNER INSURER: TOKIO MARINE ACC DATE: 18/11/2017 SURVEYED BY: DATE: REF NO: TP INSURER: MSIG INSURANCE TP VEHICLE: SJS7496M						
							5 REPAIR DAYS
60211-TBA-A00ZZ ✓	PANELR.FENDER	1	236.20 ✓	25	177.15	12.40	189.55
60213-TBA-A00ZZ	BRACKET AR.FR.FENDER	1	27.90 ✓	25	20.92	1.46	22.38
90853-SJA-A00	RIVET4.8MM	10	1.80 ✓	25	13.50	0.95	14.45
91505-TM8-003 ✓	CLIPBUMPER	16	2.00 ✓	25	24.00	1.68	25.68
34300-TET-H01	LIGHT ASSYR.SIDE TURN	1	31.50 ✓	25	23.62	1.65	25.27
71101-TEA-T00ZZ ✓	FACEFR.BUMPER	1	579.90 ✓	25	434.92 ✓	30.44	465.36
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE	1	17.10 ✓	25	12.82	0.90	13.72
71193-TEA-T01 ✓	SPACERR.FR.BUMPER SIDE	1	10.40 ✓	25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40 ✓	25	7.80	0.55	8.35
90682-SEA-003 ✓	CLIP ABUMPER (Supplementary) <i>new</i>	2	2.30 ✓	25	3.45	0.24	3.69
	SUM PARTS:				725.98	50.82	776.80
BOSUN	0701 SUNDRIES	1	50.00 ✓		50.00	3.50	53.50
BKBU01A	1466 REMOVE/REPLACE FRT BUMPER & RH FRONT FENDER	1	840.00 ✓		840.00	58.80	898.80
BML01I	1466 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	180.00 ✓		180.00	12.60	192.60
BP02R	1624 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)	1	900.00 ✓		900.00	63.00	963.00
	SUM LABOUR:				1,970.00	137.90	2,107.90
	TOTAL SGD				2,695.98	188.72	2,884.70
	Total Payable (SGD)						2,884.70

GST Amount is calculated from individual line(s)