

ASS. REC. BY:

REF:

C9/MSG17022412/Kibb

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From: (Person):

Justin Lim

of

MSU1

Date/Time:

23-11-2017 3:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 29555

Insured:

at Workshop m/s

Lim Tan

Tel:

6452 0893

of

176 Sin Ming Driv #03-09

Policy No:

B28636916MKC

Claim No:

537768

Sum Insured:

Excess:

\$ 750.00

Make of Veh:

(Client's Record)

D.O.A.

20-11-2017

CA / REV /

REP. / REV 24 HRS

24-11-2017

ITM . 55

H.O.D. Endorsement:

Date/Time:

23-11-2017 5:16pm

Person Contacted:

Richard

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 29555 x
28/13	\$11863.50 Confirmed by email P/P
	Red: \$2862.50, 191.

mslh

meimen

Date 24.11.2017

GBC 2955S 11 11

Estimated Cost

OD / TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect vehicle No GBC 2955S
at / work shop / ms LIM TOM
176 sin ming Drive #03-09

Insured

Policy No

Claims No

Sum Insured Excess \$ 750.00

Client's Record

Make of Ven

(Policy Condition)

Remark: The ven had commenced its repair at the time of inspection.

N.S	O.S

Bar or Market Value \$ 40k

DAC Accident Report Consistent? Yes or No

GIA PP Seen Consistent? Yes or No

Est. Repairs 09 days Res: Yes or No

Lim Sum 1.3.1 % 3 Val: Yes or No

OD REP 11/21
24 HRS

Date Person Contacted Vehicle IN/OUT

Type Motor / Cycle / Bus / Van / Truck / Trailer

Truck / Trailer of

Make MIT Canter 2977

Colour White

Se Posting 261782

Eng No

Ch No FB 70BBA 20428

Gen Cond Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Modif Nil / S Rim / STD A/Rim or

Tyre Size Goform 195 R15 X8
R: (D)

BS / DUN / EXNOVA / GY / FS UZA / MID / OHTSU / PIR / SUMI

TOYO / YOKO or Goform

Front	7	mm	Rear	7	mm
R.Bal	7	--	R.Bal	7	--
L.Bal	7	--	L.Bal	21	--
D.O.A	20/11/17		D.O.A	24/11/17	

Survey held at

Des of Damages Fr / Rear / O/S N/S U/C Roof top or

R/R N/S, R/R wheel cracked
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
27/11 File pass to Catherine

27/11/17 RBV in meimen.

28/11/17 mandate approved by Huey Ni.

28/11/17 @ 10.50am spoke & email to Richard, CA, Ex: 750

13/4.

RECEIVED 10 NOV 2018

Date / Time File Pass to

Prelim Report

Days Of Repair: 9

typist

Final Report

Resurvey No. of Trip 2

Date / Time File Return to

Survey Fee

Add Fee: Grease \$

Inspection

Repair Amount

OD

Grease \$

Grease \$

Grease \$

Grease \$

Grease \$

Sum Insured 11862.50

300
10
310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17022412/Kgb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 24-11-2017



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBC 2955S
Policy No.	B28636916MKC	Coverage (\$)	0.00
Claim No.	537768	Excess (\$)	750.00
Assign From	JOSLIN LIM (MERIMEN)	Assign Date	23/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/11/2017	Inspection Date	24/11/2017
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2017 Sendback Est	23 Nov 2017 10:34 S\$12,219.90	23 Nov 2017 15:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			
Insured:	P.I.L CONSORTIUM PTE LTD, Co. Reg. No.: 200312432W, Tel: +6588766759		
Vehicle Reg. No.:	GBC2955S	Date of Loss:	20/11/2017 04:00 - :59
Claim Type:	OD / 537768	Policy/Cover Note No.:	B28636916MKC (Comprehensive) Coverage: 21/11/2016 - 20/11/2017
		Excess:	S\$750.00
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/11/2017]		
Driver/Custodian:	LOW KHENG LEE (50 / Male / Others: -), NRIC: S1752956, Tel: +6593400312		
	Vehicle Source:	Drive/Walk-in	
Adj Asg. Remarks:	URGENT survey. Please revert		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
--------------------------	--------------------------	-----------------------------------

There are no mail for this case.

ALL ASSOCIATED TASKS										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	

No results.

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Tuesday, 28 November, 2017 10:52 AM
To: richard@ltm.sg
Cc: SUR
Subject: GBC 2955S MSIG-OD (DOA 20-11-2017)

Dear Richard,

Instructed by our client, please proceed to repair the insured vehicle **GBC 2955S (Excess \$750)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

Claim Audit

AUDIT TRAIL				By
No.	On	Audit	Remarks	
1	22 Nov 2017 20:21	Cim Veh Model Changed	(202205) MITSUBISHI FB70BB1SRDEA 3.0 D (M).	[R] Mandy Lim
2	22 Nov 2017 20:21	Cim Created	Reg No: GBC2955S. Policy No: B28636916MKC. Acct Date: 2017/11/20. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Lim Tan Motor Pte Ltd (HQ). Created from SAS:MLTM17154520	[R] Mandy Lim
3	23 Nov 2017 10:34	Cim Submitted	12219.90.	[R] Mandy Lim
4	23 Nov 2017 14:12	Cim Registration Modified	Excess: -> 750.00.	[I] Eng Huey Ni
5	23 Nov 2017 14:12	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):To authorise repair if damages is consistent, and if it is economical to repair the vehicle, subject to excess \$750	[I] Eng Huey Ni
6	23 Nov 2017 14:12	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/11/24	[I] Eng Huey Ni
7	23 Nov 2017 14:12	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eng Huey Ni
8	23 Nov 2017 14:31	Assignment 1st Accessed		[A] Pauline Soh Li Ping
9	23 Nov 2017 15:13	Adj Assignment Cancelled	I.H.S appointment full	[I] Joslin Lim
10	23 Nov 2017 15:13	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Joslin Lim
11	23 Nov 2017 15:15	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):URGENT survey. Please revert	[I] Joslin Lim
12	23 Nov 2017 15:15	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/11/24	[I] Joslin Lim
13	23 Nov 2017 15:15	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Joslin Lim
14	23 Nov 2017 15:18	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
15	24 Nov 2017 13:21	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] SHIAU CHAN
16	27 Nov 2017 15:03	Adj Rpt Initiated		[A] LOW AI PHING
17	27 Nov 2017 15:11	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/23	[A] LOW AI PHING
18	27 Nov 2017 15:11	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/23	[A] LOW AI PHING
19	27 Nov 2017 15:15	Adj Mandate Request	Cur Req:11273.90:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] LOW AI PHING
20	28 Nov 2017 09:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/23. Mandate Remarks: Approved mandate \$11273.90 (including check items \$4752) before excess \$750	[I] Eng Huey Ni
21	28 Nov 2017 09:29	Adj Mandate Set	Approved:11273.90:Approved mandate \$11273.90 (including check items \$4752) before excess \$750	[I] Eng Huey Ni

ACTIVITY

[23/11/2017 14:32] Pauline Soh Li Ping:
Car in, IHS unable to attend (ET-Paperwork, AL & DC-Apppt full)

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1647231	22/11/2017 20:21	Motor	Lim Tan Motor Pte Ltd (HQ)	Lim Tan Motor Pte Ltd (HQ)	GBC2955S		xx.xx
1650542	27/11/2017 15:03	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBC2955S		10.7J

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 27 Nov 2017

Preliminary Advice

Vehicle No	: GBC2955S	Accident Date	: 20/11/2017
Make	: MITSUBISHI FB70BB1SRDEA	Policy No.	: B28636916MKC
Assignment Date	: 23/11/2017	Excess	: S\$750.00
Date of Inspection	: 24/11/2017	Est. Duration of Repair	: 9.00
Inspection At	: LIM TAN MOTOR PTE LTD (HQ) BLK 176 SIN MING DRIVE #03-09/10, SIN MING AUTO CARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s and front windscreen cracked, parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,075.29
Revised Amount	:S\$	6,521.90
Check Items (Estimated)	:S\$	4,752.00
Total	:S\$	11,273.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	13,064.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,936.00

Remarks

(X) The vehicle is economical for repair.

We have not authorise repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 11 Apr 2018

Preliminary Advice

Vehicle No	: GBC2955S	Accident Date	: 20/11/2017
Make	: MITSUBISHI FB70BB1SRDEA	Policy No.	: B28636916MKC
Assignment Date	: 23/11/2017	Excess	: S\$750.00
Date of Inspection	: 24/11/2017	Est. Duration of Repair	: 9.00
Inspection At	: LIM TAN MOTOR PTE LTD (HQ) BLK 176 SIN MING DRIVE #03-09/10, SIN MING AUTO CARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,727.00	(include supplementary \$2,508.00)
Revised Amount	:S\$	11,863.50	(include check item + supplementary)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	11,863.50	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	13,064.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,936.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	2432W

Vehicle Details

Vehicle No.	GBC2955S
Vehicle to be Exported	No
Intended De-registration Date	27 Nov 2017
Vehicle Make	MITSUBISHI
Vehicle Model	FB70BB1SRDEA
Primary Colour	White
Manufacturing Year	2011
Engine No.	4M42A89379
Chassis No.	FB70BBA20428
Maximum Power Output	-
Open Market Value	\$31,638.00
Original Registration Date	21 Nov 2011
First Registration Date	21 Nov 2011
Transfer Count	1
Actual ARF Paid	\$1,582.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	20 Nov 2021
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$32,801.00
COE Rebate Amount	\$13,064.00
Total Rebate Amount	\$13,064.00

The information contained herein is correct as at 27 Nov 2017

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	2432W

Vehicle Details

Vehicle No.	GBC2955S
Vehicle to be Exported	Yes
Intended De-registration Date	20 Nov 2017
Vehicle Make	MITSUBISHI
Vehicle Model	FB70BB1SRDEA
Primary Colour	White
Manufacturing Year	2011
Engine No.	4M42A89379
Chassis No.	FB70BBA20428
Maximum Power Output	-
Open Market Value	\$31,638.00
Original Registration Date	21 Nov 2011
First Registration Date	21 Nov 2011
Transfer Count	1
Actual ARF Paid	\$1,582.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	20 Nov 2021
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$32,801.00
COE Rebate Amount	\$13,120.00
Total Rebate Amount	\$13,120.00

The information contained herein is correct as at 20 Nov 2017

OK



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co.Reg No. : 199307277D GST Reg No. : M2-0119086-0

Survey By : _____

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

Date / Time : 24 NOV 2017, 10.30am

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	B28636916MKC	Date of Loss:	20/11/2017
Vehicle Reg. No.:	GBC2955S	Driveable?	
Driver Age/Info:	50 / MALE / OTHERS: -	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	P.I.L CONSORTIUM PTE LTD	Contact No:	+6588766759
Driver:	LOW KHENG LEE		

Make/Model:	mitsubishi FB70BB1SRDEA, 3.0 D (M)	Vehicle Reg. Date:	21/11/2011
Vehicle Colour:	White	Chassis No:	FB70BBA20428
Engine No:	4M42A89379		
Odometer:	261782 KM		

Paint Type: _____
 Total Loss? **NO**
 Est. Duration of Repair (day) *48 days*

RM 11

Not Authorise
1.13.1
Resurvey By point Ex 87501
Fax: 62564315

Description of Accident/Loss: AS PER ATTACHED POLICE REPORT. (REPORT NO. T/20171120/2038)
 ON 19/11/2017 AT ABOUT 2315HRS, I PARKED MY COMPANY LORRY OF PLATE NUMBER GBC2955S AT BLOCK 163 ANG MO KIO AVENUE 4 AT LOT 86, EVERYTHING WAS INTACT AT THAT POINT OF TIME. ON 20/11/2017 AT ABOUT 0445HRS, WHILE I WAS GOING TO MY LORRY, I DISCOVERED THAT THE LEFT PORTION AREA INCLUDE THE WINDSCREEN WAS CRACKED AND DENTED. NO ONE LEFT ANY NOTE BEHIND AND I BELIEVED SOMEONE HAS HIT AND RUN. I DO NOT HAVE IN CAR CAMERA IN MY LORRY AND THE SAID CAR PARK ELECTRONIC PARKING HAS BEEN INSTALLED BUT HAS NOT BE ACTIVATED YET. I HAVE NO SUSPECT IN MIND. AT ABOUT 1115HRS, TP CAME AND TOOK PHOTOS OF THE SCENE. THE TP OFFICER THAN GAVE ME A CASE CARD TO LODGE A TRAFFIC REPORT UNDER TP SIO JEMY, 65476213. I AM LODGING THE IS TRAFFIC REPORT FOR ASSISTANCE. THAT'S ALL.

Present Location: **LIM TAN MOTOR PTE LTD (HQ)**

COST OF CLAIMS	Amount
Parts	9,499.90
Miscellaneous Items	0.00
Labour	1,720.00
Paintwork Labour	1,000.00
Towing	0.00
Calculated Gross Total (S\$)	12,219.90

- Excess (S\$)	750.00
(S\$)	11,469.90
+ GST 7.00% (S\$)	802.89
Nett Amount (S\$)	12,272.79

12,272.79

This claim is handled by: MANDY LIM

Generated using Merimen e-Claims Internet Estimation & Adjusting System

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/11/2017 13:58
Date Of Accident	20/11/2017 04:45
Exact Location Of Accident	BLK 163 ANG MO KIO AVE 4 OPEN SPACE CARPARK LOT 86
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC2955S
Insured/Policyholder	
Name Of Registered Owner	P.I.L CONSORTIUM PTE LTD
Co Reg No	200312432W
Email Address	JOVAN@PILCON.COM.SG
Mobile Phone No	(LOCAL) +65-88766759
Alternative Phone No	OFFICE-67434424
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FB70BB1SRDEA-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B28636916MKC
Cover Note Number	
Driver	
Name of Driver	LOW KHENG LEE
NRIC No	S1752956J
Date Of Birth	26/12/1966
Occupation	OUTDOOR
Date Of Driving Pass	12/06/1987
Driving Experience	30 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93400312
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the e-RA Records Management Centre established by the General Insurance Association of Singapore (GIAs) for archiving and the copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurer, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the insurers and/or (give to their third party service providers or agents (including their lawyers/law firms) which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be analysed and used to compile claims history for the purpose of fraud detection, investigation and management to prevent and defuse claims;
- (e) the information so collected under (d) above may be shared and disclosed:
- (i) to all insurer, and/or any other third parties that assist in or carrying out (including investigating, controlling or managing) to all regulators, law enforcement and government agencies, as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

22 NOV 2017

3:30pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

22 NOV 2017

3:30pm

Reporting Centre Personnel's Signature

Name:

NRN/IDN No.:

ANG WEI GUANG
S8410708E



**SINGAPORE
POLICE FORCE**



T/20171120/2038

1 of 3

Police Station Of Origin
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

Report No: T/20171120/2038

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 20/11/2017 12:18	Vide Report No F/20171120/0123	Station Diary No. 9
-------------------------------------------	-----------------------------------	------------------------

Informant / Witnesses			
Name of Informant LOW KHENG LEE		Address: APT BLK 170 ANG MO KIO AVENUE 4 #03-551 SINGAPORE 560170	
ID Type / ID No. NRIC NO / S1752956J		Contact No Home/Office	Mobile 93400312
Nationality: SINGAPORE CITIZEN		Email	
Sex Male	Age 50	Date of Birth: 26/12/1966	Type of Informant: Vehicle Owner
Race: Chinese		Language	Institution / School Name
Occupation: DELIVERY		Driving Licence Information Class	Date of Expiry

General Information of the Accident				
Type of Accident	Non-Injury Hit and Run	Drink Drive No	Date/Time of Accident 20/11/2017 04:45	Type of Location Car Park
Location: Along Road 1 ANG MO KIO AVENUE 4				
In the car park of block 163 Ang Mo Kio Ave 4, car park lot 86.				
Weather Clear		Road Surface Dry	Road Speed Limit	
Traffic Flow		Traffic Control	Traffic Volume	
Type of Collision: Left front portion of lorry been knocked by unknown			Anyone conveyed by ambulance No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC2955S	Lorry				Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved	No
No. of Pedestrians Injured	NIL
Use of Pedestrian Crossing	NA



**SINGAPORE
POLICE FORCE**



T/2017/120/2038

Police Station Of Origin
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No 1800-4589999

3 of 3

Report No: T/2017/120/2038

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report F / Sgt 1 TAN CHING LIN	Signature Of Informant
Signature Of Interpreter Not applicable	Date/Time 20/11/2017 12:18
Officer In Charge Of Case TP / HRT / SI ABDUL KAREEM BIN ABDUL HAGUE Contact No. 65476079	Classification Of Case

Authentication Stamp
NP168

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Nov 2017)
 Parts: N/A MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lim Tan Motor Pte Ltd/GBC2955S/23/11/2017 10:34
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1.	1		*FRONT BUMPER	Ry 0.00	0.00	*400.00 F	420
2	2		*FRONT BUMPER BRACKET	Ry 0.00	0.00	*110.00 F	120
3	1		*FRONT GRILLE	M3 CM 0.00	0.00	*320.00 F	2265
4	1		*FRONT PANEL	Ry 0.00	0.00	*480.00 F	60
5	1		*N/S FRONT CORNER PANEL	Ry 0.00	0.00	*260.00 F	25
6.	1		*FRONT WIPER GARNISH	CM M 0.00	0.00	*280.00 F	30
7	1		*FRONT WIPER GARNISH CANTER STICKER	N/A 0.00	0.00	*65.00 F	50
8	1		*FRONT WINDSCREEN GLASS	CM 0.00	0.00	*380.00 F	15
9	1		*FRONT WINDSCREEN RUBBER	N/A 0.00	0.00	*160.00 F	35
10	1		*N/S FRONT WING MIRROR BRACKET COVER	CM 0.00	0.00	*32.00 F	40
11	1		*N/S FRONT WING MIRROR ROUND	M3 0.00	0.00	*15.00 F	12
12	1		*N/S FRONT SIDE LAMP	Ry 0.00	0.00	*105.00 F	32
13	1		*N/S FRONT SIGNAL LAMP	Ry 0.00	0.00	*130.00 F	X
14	1		*N/S HEADLAMP	Ry 0.00	0.00	*350.00 F	X
15	1		*N/S HEADLAMP LOWER RUBBER	SM 0.00	0.00	*12.00 F	X
16	1		*N/S FRONT DOOR	BU 0.00	0.00	*900.00 F	X
17	1		*N/S FRONT DOOR INNER LOCK	R 0.00	0.00	*530.00 F	X
18	2		*N/S FRONT DOOR HINGES	R 0.00	0.00	*320.00 F	X
19	1		*N/S FRONT DOOR STEP GARNISH	CM 0.00	0.00	*250.00 F	210
20	1		*N/S FRONT DOOR ARCH GARNISH	SM 0.00	0.00	*40.00 F	X
21	1		*FRONT CABIN SUB-TUBE	SM 0.00	0.00	*150.00 F	X
22	1		*FRONT CABIN SUB-SHAFT	SM 0.00	0.00	*660.00 F	X
23	1		*AIR-CON BLOWER MOTOR	CM 0.00	0.00	*700.00 F	2680
24.	1		*AIR-CON COOLING COIL UNIT	CM 0.00	0.00	*1,500.00 F	X
25	1		*N/S FRONT DOOR CHECK	R 0.00	0.00	*40.00 F	X
26	1		*FRONT CABIN SUB-TAKE MOUNTING	SM 0.00	0.00	*420.00 F	X
27	1		*FRONT WINDSCREEN IU BRACKET	N/A 0	0.00	*15.00 FS	—
28	1		*N/S FRONT DOOR BODY LETTERING	N/A 0	0.00	*15.00 FS	—

F=Franchise part. S=SpcNett.

Sub Total (S\$) 8,639.00
 + Margin on L,N Items 10.00% (S\$) 860.90
Total Parts (S\$) 9,499.90

Lim Tan Motor Pte Ltd/GBC2955S/23/11/2017 10:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount	
<u>Paintwork Labour</u>				
1	TO PUTTY AND SPRAY PAINTING.	New	1,000.00	7200
<u>Labour Items</u>				
2	TO REPLACE FRONT WINDSCREEN GLASS.	New	100.00	600
3	TO REMOVE AND REFIX FRONT DASHBOARD ASSY. REPLACE AIR-CON BLOWER UNIT AND COOLING COIL UNIT.	New	380.00	3500
4	TO TRANSFER DOOR FITTINGS.	New	40.00	✓
5	LABOUR CHARGES.	New	1,200.00	10000
			Gross Labour Cost (\$)	2,720.00

Lim Tan Motor Pte Ltd/GBC2955S/23/11/2017 10:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co. Reg No. : 199307877D GST Reg No. : M2-0119086-0

(SUPPLEMENTARY)

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	B28636916MKC	Date of Loss:	20/11/2017
Vehicle Reg. No.:	GBC2955S	Driveable?	
Driver Age/Info:	50 / MALE / OTHERS: -	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	P.I.L CONSORTIUM PTE LTD	Contact No:	+6588766759
Driver:	LOW KHENG LEE		

Make/Model:	mitsubishi FB70BB1SRDEA, 3.0 D (M)	Vehicle Reg. Date:	21/11/2011
Vehicle Colour:	WHITE	Chassis No:	FB70BBA20428
Engine No:	4M42A89379		
Odometer:	261782 KM		

Paint Type:
Total Loss? NO
Est. Duration of Repair 45 (day)

Description of Accident/Loss AS PER ATTACHED POLICE REPORT. (REPORT NO. T/20171120/2038)

ON 19/11/2017 AT ABOUT 2315HRS, I PARKED MY COMPANY LORRY OF PLATE NUMBER GBC2955S AT BLOCK 163 ANG MO KIO AVENUE 4 AT LOT 86, EVERYTHING WAS INTACT AT THAT POINT OF TIME. ON 20/11/2017 AT ABOUT 0445HRS, WHILE I WAS GOING TO MY LORRY, I DISCOVERED THAT THE LEFT PORTION AREA INCLUDE THE WINDSCREEN WAS CRACKED AND DENTED. NO ONE LEFT ANY NOTE BEHIND AND I BELIEVED SOMEONE HAS HIT AND RUN. I DO NOT HAVE IN CAR CAMERA IN MY LORRY AND THE SAID CAR PARK ELECTRONIC PARKING HAS BEEN INSTALLED BUT HAS NOT BE ACTIVATED YET. I HAVE NO SUSPECT IN MIND. AT ABOUT 1115HRS, TP CAME AND TOOK PHOTOS OF THE SCENE. THE TP OFFICER THAN GAVE ME A CASE CARD TO LODGE A TRAFFIC REPORT UNDER TP SIO JEMY, 65476213. I AM LODGING THE IS TRAFFIC REPORT FOR ASSISTANCE. THAT'S ALL.

Present Location: LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS

Amount

Parts	2,508.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,508.00
+ GST 7.00% (S\$)	175.56
Nett Amount (S\$)	2,683.56
+ Previous Estimates (S\$)	12,272.79
Claim Total (S\$)	14,956.35

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Dec 2017)
 Parts: N/A MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lim Tan Motor Pte Ltd/GBC2955S/30/12/2017 13:39
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*N/S FRONT DOOR PILLAR	<i>B7</i> 0.00	0.00	*700.00 F
2	1		*N/S FRONT MIRROR BRACKET	<i>B7</i> 0.00	0.00	*200.00 F
3	1		*WASHER TANK	<i>110</i> 0.00	0.00	*100.00 F
4	1		*FRONT UPPER WINDSHIELD PANEL	<i>B7</i> 0.00	0.00	*850.00 F
5	1		*N/S FRONT STEP FENDER	<i>B7</i> 0.00	0.00	*210.00 F
6	1		*HEATER COOLING COIL	<i>110</i> 0.00	0.00	*180.00 F
7	1		*N/S FRONT MIRROR COVER	<i>M17</i> 0.00	0.00	*40.00 F
Sub Total (S\$)						2,280.00
+ Margin on L,N Items 10.00% (S\$)						228.00
Total Parts (S\$)						2,508.00

F=Franchise part.

Handwritten vertical marks on the right side of the table, possibly indicating a list or checkmark.

Lim Tan Motor Pte Ltd/GBC2955S/30/12/2017 13:39. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lim Tan Motor Pte Ltd/GBC2955S/30/12/2017 13:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

日美汽車私人有限公司 JAE AUTO PTE LTD


Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9939

Arrange By _____ Driver **MIC**



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

LIM TAN MOTOR PTE LTD
BLK 9 #01-38, SIN MING INDUSTRIAL ESTATE
S(575644)

TEL: 64532397 FAX: 64589127
ATTN: AHBEE

SEND TO>>>>#01-42

TAX INVOICE : AR201712-07032
DATE : 13/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : GBC2955S
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

STOCKID	DESCRIPTION
1. MK403447 ROC	COVER,RR VIEW LH (BIG)
2. MK353631R	HEADLAMP ASSY,LH (214-1178L-LD)

StkLoc	QTY	U/PRICE	AMOUNT
PA Supplement	1	40.00	40.00
PL2-N1-05B			
PA	1	320.00	320.00
PL2-P1-060			

SUB-TOTAL: 360.00
ADD GST 7.00% 25.20

E. & O.E TOTAL AMOUNT SGD: 385.20

[P] 13/12/2017 9:25:41AM

[E] 13/12/2017 9:22:21AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive: HUAT



This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGAI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9039



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 97

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

LIM TAN MOTOR PTE LTD
BLK 9 #01-38 SIM MING INDUSTRIAL ESTATE
s(575644)

176 SIM MING Auto Care
#03-09 38

TEL : 64532397 FAX : 64589127
ATTN : AH-BEE Thomas
SEND TO>>>#01-42

TAX INVOICE : AR201712-14877
DATE : 27/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : GBC2955S
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	MK997199	FR DOOR L.H	WT1	1	900.00	900.00 ✓
2	MK704170	PI.L.A.R,FR L.H	PI.3-I.1-060	1	700.00	700.00 ✓
3	MK404974	MIRROR STAY L.H	WT1 <u>Supplementary</u>	1	200.00	200.00 ✓
4	MK404971	FR VIEW MIRROR (ROUND)	2G6	1	35.00	35.00 ✓
5	ME402056	RADIATOR SPARE TANK	WH <u>Supplementary</u>	1	100.00	100.00 ✓

SUB-TOTAL : 1,935.00
ADD GST 7.00 % 135.45

TOTAL AMOUNT SGD : 2,070.45

[P] 27/12/2017 12:45:03PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 27/12/2017 12:41:55PM

JAE Auto Pte. Ltd.
Sales Executive : HUAT



* AR 201712 - 14877 *

Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司


JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 8745 9938



Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

LIM TAN MOTOR PTE LTD
Blk 9 #01-38 SIN MING INDUSTRIAL ESTATE
s(575644)

TEL : 64532397 FAX : 64589127
ATTN :

SEND TO>>>#01-42

GBC 2955

TAX INVOICE : AR201712-04616
DATE : 08/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : ~~688464~~
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. MK701615	PANTI, WINDSHIELD, UPR	MO Supplementary SUPPLIER		850.00	850.00
2. MK426790	HEATER COOLING COIL	MO Supplementary SUPPLIER	1	180.00	180.00

SUB-TOTAL : 1,030.00
ADD GST 7.00 % 72.10

E. & O.E


TOTAL AMOUNT SGD : 1,102.10

[E] 08/12/2017 11:41:47AM

[P] 08/12/2017 11:46:51AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : HUAT



Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD


Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Arrange By
Driver *KAWA*



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

LIM TAN MOTOR PTE LTD
BLK 9 #01-38 SIN MING INDUSTRIAL ESTATE
s(575644)

TEL: 64532397 FAX: 64589127
ATTN: AH BEE
SEND TO >>>> #01-42

GBC 2955S

TAX INVOICE : AR201712-04955
DATE : 08/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : ~~GPR 468K~~
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID
1 MK997120

(SS)

DESCRIPTION	StkLoo	QTY	U/PRICE	AMOUNT
FENDER,FR FLOOR SIDE LH	PA	1	210.00	210.00
	PL3-Q1-08B			

[Handwritten signature]

SUB-TOTAL : 210.00
ADD GST 7.00 % : 14.70
TOTAL AMOUNT SGD : 224.70

[P] 08/12/2017 4:31:10PM
Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on Overdue Account(s)

[E] 08/12/2017 4:28:30PM

JAE Auto Pte. Ltd.
Sales Executive : HUAT



Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9039

Arrange By _____ Driver _____

TOYOTA GENUINE PARTS LEXUS DAIHATSU
Dept Direct: 6305 9610 Dept Direct: 6305 9611 Dept Direct: 6417 9792

MAZDA FORD KIA HYUNDAI HONDA SUBARU NISSAN
Dept Direct: 6417 9794 Dept Direct: 6417 9795 Dept Direct: 6417 9796 Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

LIM TAN MOTOR PTE LTD
BLK 9 #01-38 SIN MING INDUSTRIAL ESTATE
s(575644)

TEL : 64532397 FAX : 64589127
ATTN : AH BEE
SEND TO >>> 01-42

TAX INVOICE : AR201712-05143
DATE : 09/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : GBC2955S
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
4 MK403539ROC	19 STEP,FR SIDE,LH(MK486093)	MO 2E12	1	210.00	210.00
4 MK403120ROC	3 FR GRILLE(MK488751)	MO 2C5	1	265.00	265.00
4 MK997155R	4 PANEL,CAB,FR(MB09-0301-00)	MO 2B16J	1	600.00	600.00
4 MK403828ROC	1 FR BUMPER (MB09-1401-00)	MO 2B15	1	420.00	420.00

SUB-TOTAL : 1,495.00
ADD GST 7.00 % 104.65

E. & O.E

TOTAL AMOUNT SGD : 1,599.65

[P] 09/12/2017 10:29:23AM

[E] 09/12/2017 10:20:07AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : HUAT



Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD


Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Arrange By _____ Driver ICW/KEP



Wiper blade: NWB (Nippon Wiper blade), Silpor (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

LIM TAN MOTOR PTE LTD
BLK 9 #01-38 SIN MING INDUSTRIAL ESTATE
s(575644)

TEL: 64532397 FAX: 64589127
ATTN: AH BEE

SEND TO >>> 01-42

TAX INVOICE : AR201712-07684
DATE : 13/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : GBC2955S
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SO STOCKID
MK402478

DESCRIPTION
STAY,FR BUMPER,LH

Stk Loc	QTY	U/PRICE	AMOUNT
PA PL3-N1-06E	1	120.00	120.00

SUB-TOTAL : 120.00
ADD GST 7.60 % 8.40

E & OE

TOTAL AMOUNT SGD: 128.40

[P] 13/12/2017 4:53:56PM

Goods Sold are not refundable for Cash.

[E] 13/12/2017 4:46:55PM

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte Ltd.

Sales Executive: IUAT

This is computer generated document.
No signature is required.



Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



天大汽车零件有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)


WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

6745



LIM TAN MOTOR PTE LTD
BLK 9 #01-38 SIN MING INDUSTRIAL ESTATE
s(575644)

TEL.: 64532397 FAX: 64589127
ATTN: AH BEE

SEND TO >>> #01-42

Wiper blade: NWB (Nippon Wiper blade), Slijper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201712-06367
DATE : 12/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : GBC2955S
TERMS : 30 days
PO NO. :
PAGE NO. : 367
Page 1 of 1
CURR : SGD

Handwritten: 9, 01-42

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	MK403437	GARNISH,FR PANEL	PA	1	300.00	300.00
2	MK997197R	PANEL,CAB FR CORNER,LH(MP09-0700-02)	PA	1	250.00	250.00
3	MK427117/9R	FR SIGNAL LAMP,LH(214-1648F.)	PL2-N1-09A	1	120.00	120.00
4	MK580853	LAMP ASSY,CORNERING,LH	PL2-P1-09A	1	110.00	110.00

Handwritten signature

SUB-TOTAL : 780.00
ADD GST 7.00% : 54.60
TOTAL AMOUNT SGD : 834.60

E & OE

PJ 12/12/2017 10:33:27AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 12/12/2017 10:23:16AM

JAE Auto Pte. Ltd.

Sales Executive: IUAT

This is computer generated document.
No signature is required.



AR201712-06367

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEL KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

LIM TAN MOTOR PTE LTD
176 SIN MING AUTO CARE
#03-09 SIN MING IND EST

SINGAPORE 575644
TEL : 64520893 FAX : 64589127
ATTN : BEE

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9702



Dept Direct: 6417 9794

Dept Direct: 6417 9765

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201712-08442
DATE : 14/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : GBU2955S
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. WMK403589/ML258257 FB71 FUSO 05"/FEA01	8 FRT W/S GLASS LH	MO 1C27	1	500.00	500.00
2. MLD.MIT FB71 05" CMC (OEM) FB71 FUSO 05"	9 MK548234/435625 W/S RUBBER	MO 1A83B	1	160.00	160.00

SUB-TOTAL : 660.00
ADD GST 7.00 % 46.20

E. & O.E TOTAL AMOUNT SGD : 706.20

P] 14/12/2017 4:31:58PM

[E] 14/12/2017 4:30:19PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : ANG



* AR 20 17 12 - 08442 *

Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD


BIK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Arrange By _____ Driver _____



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

LIM TAN MOTOR PTE LTD
BLK 9 #01-38 SIN MING INDUSTRIAL ESTATE
s(575644)

TEL : 64532397 FAX : 64589127
ATTN : AH BEE
SEND TO>>>#01-42

TAX INVOICE : AR201712-08417
DATE : 14/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : GBC2955S
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
MK403449 ROC	COVER,RR VIEW LH (TOP)	MO ILS19	1	15.00	15.00

SUB-TOTAL : 15.00
ADD GST 7.00 % 1.05

E. & O.D TOTAL AMOUNT SGD : 16.05

[P] 14/12/2017 4:07:35PM

[E] 14/12/2017 4:07:17PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.
Sales Executive : HUAT



This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL

日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
 GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

=====

LIM TAN MOTOR PTE LTD
 BLK 9 #01-38 SIN MING INDUSTRIAL ESTATE
 s(575644)

TEL : 64532397 FAX : 64589127
 ATTN : AH BEE

SEND TO>>>#01-42

WINDSCREEN GLASS
 Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Arrange By: *[Signature]* Driver: _____



TOYOTA LEXUS PARTS
 Dept Direct: 6305 9611 Dept Direct: 6417 9792



Dept Direct: 6417 9794



Dept Direct: 6417 9795



YONDA SUBARU
 Dept Direct: 6417 9796



NISSAN
 Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
 Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201712-05474
 DATE : 11/12/2017
 CUSTOMER ID : LIM002
 VEH REG. NO. : GBC2955S
 TERMS : 30 days
 PO NO. :
 PAGE NO. : Page 1 of 1
 CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1 MK583441	123 BLOWER ASSY, HEATER	MO SUPPLIER	1	680.00	680.00

SUB-TOTAL : 680.00
 ADD GST 7.00 % 47.60


TOTAL AMOUNT SGD : 727.60

P] 11/12/2017 9:46:15AM

[E] 11/12/2017 9:45:55AM

Goods Sold are not refundable for Cash.
 Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

AE Auto Pte. Ltd.
 Sales Executive : HUAT



Goods Received in Good Order

Signature / Co Stamp / Date

This is computer generated document.
 No signature is required.

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9930

Arrange By _____ Driver *MC*



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made In Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

LIM TAN MOTOR PTE LTD
BLK 9 #01-38 SIN MING INDUSTRIAL ESTATE
s(575644)

TEL: 64532397 FAX: 64589127
ATTN :

SEND TO >>> #01-42

TAX INVOICE : AR201712-05460
DATE : 11/12/2017
CUSTOMER ID : LIM002
VEH REG. NO. : GBC2955S
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

~~SQ STOCKID~~
MK447538J

24

DESCRIPTION
HEATER CASING

StkLoo	QTY	U/PRICE	AMOUNT
PA PL3-Q1-080	1	1500.00	1,500.00

SUB-TOTAL : 1,500.00
ADD GST 7.00 % 105.00

E & OE TOTAL AMOUNT SGD: 1,605.00

[P] 11/12/2017 9:46:17AM

[E] 11/12/2017 9:41:11AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive: IUUAT



This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2017 Sendback Est	23 Nov 2017 10:34 \$12,219.90	23 Nov 2017 15:15 Edit Adj Rpt	\$11,863.50 Edit Estimates	\$11,863.50 View Rpt		Pending for Survey Report Cancel Case
Supp #1	30 Dec 2017 13:29	30 Dec 2017 13:39 \$2,508.00	30 Dec 2017 13:39			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	P.I.L CONSORTIUM PTE LTD , Co. Reg. No.: 200312432W, Tel: +6588766759								
Vehicle Reg. No.:	GBC2955S	Date of Loss:	20/11/2017 04:00 - :59 [71 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 537768	Policy/Cover Note No.:	B28636916MKC (Comprehensive) Coverage: 21/11/2016 - 20/11/2017						
		Excess:	S\$750.00						
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/12/2017]								
Driver/Custodian:	LOW KHENG LEE (50 / Male / Others: -), NRIC: S1752956J, Tel: +6593400312								
		Vehicle Source:	Drive/Walk-in						
Adj Asg. Remarks:	URGENT survey. Please revert								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (12/04/2018): Alert - Adj Mandate Approved (\$11863.50) - GBC2955S - Claim Handler: Joslin Lim MSIG_SG (28/11/2017): Alert - Adj Mandate Approved (\$11273.90) - GBC2955S - Claim Handler: Joslin Lim 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBC2955S (537768)
OD
Nov 20 2017 4:00AM
[P.I.L CONSORTIUM PTE LTD]
Lim Tan Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>
Assessment Reports				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)		Thumbnail Print
1	23/11/17 10:34	Repairer Estimates		Load HTM
2	30/12/17 13:39	Repairer Estimates Suppl. #1		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/11/17 15:11	Adjuster Immediate Advice		Load HTM
2	11/04/18 17:29	Adjuster Immediate Advice		Load HTM
Photos/Images				3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
2	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
3	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
4	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
5	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
6	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
7	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
8	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
9	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
10	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
11	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
12	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
13	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
14	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
15	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
16	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
17	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
18	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
19	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
20	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
21	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
22	27/11/17 14:59	General View		Load JPG <input checked="" type="checkbox"/>
23	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
24	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
25	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
26	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
27	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
28	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
29	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
30	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
31	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
32	11/04/18 17:55	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
33	11/04/18 17:55	Dismantled Parts		<input checked="" type="checkbox"/>
34	11/04/18 17:55	Dismantled Parts		<input checked="" type="checkbox"/>
35	11/04/18 17:55	Dismantled Parts		<input checked="" type="checkbox"/>
36	11/04/18 17:55	Dismantled Parts		<input checked="" type="checkbox"/>
37	11/04/18 17:56	Reinspection Photo		<input checked="" type="checkbox"/>
38	11/04/18 17:56	Reinspection Photo		<input checked="" type="checkbox"/>
39	11/04/18 17:56	Reinspection Photo		<input checked="" type="checkbox"/>
40	11/04/18 17:56	Reinspection Photo		<input checked="" type="checkbox"/>
41	11/04/18 17:56	Reinspection Photo		<input checked="" type="checkbox"/>
42	11/04/18 17:56	Reinspection Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	23/11/17 14:13	Certificate of Insurance		<input type="checkbox"/>
2	23/11/17 14:13	Driver's IC & Driving Licence		<input type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/17 15:00	ESTIMATE		<input type="checkbox"/>
2	11/04/18 17:37	GBC 2955S SUPPLEMENTARY		<input type="checkbox"/>
3	17/04/18 11:27	Parts Invoice		<input type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	22/11/17 15:38	Accident Statement		<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
2	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
3	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
4	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
5	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
6	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
7	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
8	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
9	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
10	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
11	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
12	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
13	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
14	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
15	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
16	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
17	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>
18	22/11/17 14:10	Accident Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	22/11/17 14:06	Police Report Pg 1		<input checked="" type="checkbox"/>
2	22/11/17 14:06	Police Report Pg 2		<input checked="" type="checkbox"/>
3	22/11/17 14:06	Police Report Pg 3		<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
4	22/11/17 15:33	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
5	22/11/17 15:33	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17022412/KRBE2

Date: 17/04/2018

REFERENCE

Insured/Claimant:	P.I.L CONSORTIUM PTE LTD	Policy No:	B28636916MKC
Date of Loss:	20/11/2017	Nature of Claim:	OD
			Claim No: 537768

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC2955S	Engine No:	4M42A89379
Make & Model:	MITSUBISHI FB70BB1SRDEA, 3.0 D (M)	Chassis No:	FB70BBA20428
Reg. Date:	21/11/2011 (Man. Year: 2011)	Odometer:	261782 km
Colour:	White		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	S\$40,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8 (D)
Front Left Side:	Goform 7 mm	Rear Left Side:	Goform 2/1 mm
Front Right Side:	Goform 7 mm	Rear Right Side:	Goform 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,007.90	9,693.50	2,314.40	19.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	1,450.00	270.00	15.70
Paintwork Labour	1,000.00	720.00	280.00	28.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,727.90	11,863.50	2,864.40	19.45
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	13,977.90	11,113.50	2,864.40	20.49
+ GST 7.00/7.00% (S\$)	978.45	777.95	200.50	20.49
Nett Amount (S\$)	14,956.35	11,891.45	3,064.90	20.49

INSPECTION

Date of Assignment:	23/11/2017 Present Location:	Lim Tan Motor Pte Ltd (HQ)
Date Inspected:	24/11/2017 Inspected At:	Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care
		Singapore 575721
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 17 Apr 2018)
Parts:	N/A MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC2955S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	400.00 F	*420.00 F
2	2		*FRONT BUMPER BRACKET	Bent	110.00 F	*120.00 F
3	1		*FRONT GRILLE	MTG Cracked	320.00 F	*265.00 F
4	1		*FRONT PANEL	Bent	480.00 F	*600.00 F
5	1		*N/S FRONT CORNER PANEL	Bent	260.00 F	*250.00 F
6	1		*FRONT WIPER GARNISH	Cracked	280.00 F	*300.00 F
7	1		*FRONT WIPER GARNISH CANTER STICKER	Not Necessary	65.00 F	*- F
8	1		*FRONT WINDSCREEN GLASS	Cracked	380.00 F	*500.00 F
9	1		*FRONT WINDSCREEN RUBBER	Dented / Cut	160.00 F	*160.00 F
10	1		*N/S FRONT WING MIRROR BRACKET COVER	Cracked	32.00 F	*15.00 F
11	1		*N/S FRONT WING MIRROR ROUND	Missing	15.00 F	*35.00 F
12	1		*N/S FRONT SIDE LAMP	Broken	105.00 F	*110.00 F
13	1		*N/S FRONT SIGNAL LAMP	Broken	130.00 F	*120.00 F
14	1		*N/S HEADLAMP	Broken	350.00 F	*320.00 F
15	1		*N/S HEADLAMP LOWER RUBBER	Serviceable	12.00 F	*- F
16	1		*N/S FRONT DOOR	Buckled	900.00 F	*900.00 F
17	1		*N/S FRONT DOOR INNER LOCK	Repair	530.00 F	*- F
18	2		*N/S FRONT DOOR HINGES	Repair	320.00 F	*- F
19	1		*N/S FRONT DOOR STEP GARNISH	Cracked	250.00 F	*210.00 F
20	1		*N/S FRONT DOOR ARCH GARNISH	Serviceable	40.00 F	*- F
21	1		*FRONT CABIN SUB-TUBE	Serviceable	150.00 F	*- F
22	1		*FRONT CABIN SUB-SHAFT	Serviceable	660.00 F	*- F
23	1		*AIR-CON BLOWER MOTOR	Cracked	700.00 F	*680.00 F
24	1		*AIR-CON COOLING COIL UNIT	Housing Cracked	1,500.00 F	*1,500.00 F
25	1		*N/S FRONT DOOR CHECK	Repair	40.00 F	*- F
26	1		*FRONT CABIN SUB-TAKE MOUNTING	Serviceable	420.00 F	*- F
27	1		*FRONT WINDSCREEN IU BRACKET	Necessary	15.00 FS	*15.00 FS
28	1		*N/S FRONT DOOR BODY LETTERING	Necessary	15.00 FS	*15.00 FS
Supplementary #1						
29	1		*N/S FRONT DOOR PILLAR	Bent	700.00 F	*700.00 F
30	1		*N/S FRONT MIRROR BRACKET	Bent	200.00 F	*200.00 F
31	1		*WASHER TANK	Dented	100.00 F	*100.00 F
32	1		*FRONT UPPER WINDSHIELD PANEL	Bent	850.00 F	*850.00 F
33	1		*N/S FRONT STEP FENDER	Buckled	210.00 F	*210.00 F
34	1		*HEATER COOLING COIL	Cracked	180.00 F	*180.00 F
35	1		*N/S FRONT MIRROR COVER	Missing	40.00 F	*40.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	10,919.00	8,815.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,088.90	878.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (\$)	12,007.90	9,693.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO PUTTY AND SPRAY PAINTING.	New	1,000.00	720.00
<u>Labour Items</u>				
2	TO REPLACE FRONT WINDSCREEN GLASS.	New	100.00	60.00
3	TO REMOVE AND REFIX FRONT DASHBOARD ASSY. REPLACE AIR-CON BLOWER UNIT AND COOLING COIL UNIT.	New	380.00	350.00
4	TO TRANSFER DOOR FITTINGS.	New	40.00	40.00
5	LABOUR CHARGES.	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			2,720.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >