

ASS. REC. BY:

REF:

CS/mse/1707470/Gvb

n2

Special Instruction:

Surveyor:

m/mma

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

msch

Date/Time:

23/12/17 258pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 11327M

Insured:

SJL 5463H

at Workshop m/s

Trans Eurokars

Tel:

of

5 Ubi Close

Policy No:

28852122DM.A

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20-11-2017

CA / REV / REP. / REV 24 HRS (wpi)

24/12/17 @ 1030am

H.O.D. Endorsement:

Date/Time:

23-11-2017 428pm

Person Contacted:

Jess

Vehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|--|
| | SLE 4327M / SJL 5463H CBA/mse/17077234/Y DOA: 22/11/17 |
| | SLE 4327M CC3/mse/17009372/Gea392 DOA: 13/5/17 |
| 27/11/17 | Sent poli through menmen |
| | |
| | |

musmen

REF: MSTH

ASSIGNMENT

From: Date: 24.11.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLE 4327M
at Workshop No: Trans Eurokars
of: 5 Ubi close

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Ven:

10:30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS Wp

Vehicle IN / OUT

Date: Person Contacted:

Vehicle No: SLE4327M Vt Regn: 21 Jul 2016

Type: M/Cat / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Mazda 2 cc: 1496

Colour: Silver A/C Insured / Std / NI / NA

Sp Reading: 20094 T Radio: Insured / Std / NI / NA

Eng No:

C No: MM 6DL 2SAA G W196280

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 / 60 R 16

R: 11

BS: CUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or

Front:

Rear:

R.Bal: 7 mm R.Bal: 7 mm

L.Bal: 7 mm L.Bal: 7 mm

D.O.A: D.O.A: 24-11-17

Survey held at: W/S 10:30 AM

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision

Date: Time: Action / Instruction

18/7/18 Confirm \$3189.32 @ 3 days
Red: \$1695.98, 35%.

RECEIVED 1-8 JUL 2018

Date/Time File Pass to:



Preli. Report

Days Of Repair: 3

by: Typist



Final Report

Resurvey No. of Trip: 1

Date/Time File Return to:

Survey Fee

S:

Add Fee:



Site Visit \$



Inter. \$



Test \$



Test \$

Report Format:

TP

Lump Sum: 18103

3189.32

Transporter

18-11-17

Phone

Other

200
10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|--------------------------|------------|--|
| MSG INSURANCE (SINGAPORE) PTE LTD | | Ref : CS/MSG17022420/Grb | | |
| 16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581 | | Date : 24-11-2017 | | |
| | | Code : MSG | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SJL 5463H | Veh. Inspected | SLE 4327M | |
| Policy No. | 28852122DMA | Coverage (\$) | 0.00 | |
| Claim No. | | Excess (\$) | 0.00 | |
| Assign From | KATHERINE WONG (MERIMEN) | Assign Date | 23/11/2017 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 20/11/2017 | Inspection Date | 24/11/2017 | |
| Survey held at | TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 27 Nov 2017

Preliminary Advice

Insured Vehicle No : SJL5463H
TP Vehicle No : SLE4327M
Make : MAZDA 2
Date of Inspection : 24/11/2017
Inspection At : TRANS EUOKARS PTE LTD
NO. 5 UBI CLOSE, SINGAPORE
SINGAPORE 408605

Accident Date : 20/11/2017
Assignment Date : 23/11/2017
Est. Duration of Repair : 3.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,885.30 |
| Revised Amount | :S\$ | 3,189.32 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 3,189.32 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 23 Nov 2017 | | 23 Nov 2017 14:58 Assign | | | | New Assignment Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|---|------------------------|--|
| Insured: | Low Khuan Piew Tony, ID: S7920964C | | |
| Main Claimant: | GOH SAO-EE (WU ZHENYU), ID: S7604197J | | |
| Vehicle Reg. No.: | SLE4327M | Date of Loss: | 20/11/2017 08:00 - :59 |
| Claim Type: | TP | Policy/Cover Note No.: | 28852122DMA (Comprehensive) Coverage: 26/11/2016 - 25/11/2017 |
| Vehicle Reg. No. (Insured): | SJL5463H | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Trans Eurokars Pte Ltd () NO. 5 UBI CLOSE, SINGAPORE, 408605 Ubi - Tel: | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/11/2017] | | |
| Driver/Custodian (Insured): | Low Khuan Piew Tony (), NRIC: S7920964C | | |

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

24/11/2017 @ 10:30am

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|--|--|
| Date Of Report | 20/11/2017 16:57 |
| Date Of Accident | 20/11/2017 08:10 |
| Exact Location Of Accident | CLEMENTI AVE 6 AT AYE - CITY EXIT |
| Country/State of Loss | SINGAPORE |
| DETAILS OF OWN VEHICLE | |
| Vehicle Registration Number | SLE4327M |
| Insured/Policyholder | |
| Name Of Registered Owner | GOH SAO-EE (WU ZHENYU) |
| NRIC No | S7604197J |
| Email Address | SEDM0253@YAHOO.COM |
| Mobile Phone No | (LOCAL) +65-90238893 |
| Alternative Phone No | OFFICE-90238893 |
| Vehicle Particulars | |
| Manufacturer | MAZDA |
| Model | 2-1.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5092439707 |
| Cover Note Number | |
| Driver | |
| Name of Driver | GOH SAO-EE (WU ZHENYU) |
| NRIC No | S7604197J |
| Date Of Birth | 05/02/1976 |
| Occupation | INDOOR |
| Date Of Driving Pass | 05/08/1994 |
| Driving Experience | 23 YEARS AND 3 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-90238893 |
| Fax Number | |
| Contact Number | OFFICE-90238893 |
| Email Address | SEDM0253@YAHOO.COM |

| | |
|---|-----------------------------|
| Address | BLK 28 JALAN LEMPENG #11-02 |
| Postcode | 128807 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Was any body injured in the Accident? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---------------------|
| Vehicle Registration Number | SJL5463H |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Name of Driver | LOW KHUAN PIEW TONY |
| NRIC/Passport Number | S7920964C |
| Contact Number | 98509302 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Details of Witness

| | |
|---------------|--|
| Name | |
| Phone Number | |
| Email Address | |

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 20/11/2017
1125

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: SHARIZAT
NRIC/FIN No.: S9225985D

Sketch Plan #2

SKETCH PLAN



A: SLE 4327 M

B: S JL 5463 H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along the slip road from Clementi Ave 6 leading into AYE (towards city) this morning (~8am) 20 Nov. The slip road intersects with a ~~road~~ lane frequently used by buses. I stopped in front of the dashed white lines as there ~~are~~ ^{were} buses heading in my direction. After 2 seconds, a car (Honda, silver, S JL 5463 H) driven by Mr Tony Low Khuan Piew crashed into the rear of my car. My rear right bumper was crushed in and the sensor ^{reverse} popped out.

I have front- and rear-vehicle camera to record the traffic situation and to prove that the other driver was on a rolling stop. ~~He~~ He was looking at the ~~right~~ ^{left} direction of incoming ~~and~~ traffic on his right and not observing that my car was stopped.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 20 Nov 2017, 11:23am (If driver is not the policyholder)

Driver's Signature

Date & Time:

Reporting Centre Personnel's Signature

Name: SHARILIZAH

NRIC/FIN No.: S 2251851

Enquire Transfer Fee

| Vehicle Details | | |
|--|--------------------------------------|-------------------------|
| Vehicle No. | SLE4327M | |
| Vehicle Type | P10 - Passenger Motor Car | |
| Vehicle Attachment 1 | No Attachment | |
| Vehicle Scheme | Normal | |
| Vehicle Make | MAZDA | |
| Vehicle Model | MAZDA2 SEDAN 1.5L SP.6EAT (LED) | |
| Chassis No. | MM6DL2SAAGW196280 | |
| Propellant | Petrol | |
| Engine No. | P520348348 | |
| Engine Capacity | 1496 cc | |
| Maximum Power Output | 85.0 kW (113 bhp) | |
| Maximum Laden Weight | 1538 kg | |
| Unladen Weight | 1079 kg | |
| Year Of Manufacture | 2016 | |
| Original Registration Date | 21 Jul 2016 | |
| Lifespan Expiry Date | - | |
| COE Category | A - Car up to 1600cc & 97kW (130bhp) | |
| Quota Premium | \$53,000.00 | |
| COE Expiry Date | 20 Jul 2026 | |
| Road Tax Expiry Date | 20 Jul 2018 | |
| PARF Eligibility Expiry Date | 20 Jul 2026 | |
| Inspection Due Date | 20 Jul 2019 | |
| Intended Transfer Date | 27 Nov 2017 | |
| CO2 Emission | 121.00 (g/km) | |
| CEVS Rebate Utilised Amount | \$5,000.00 | |
| Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable. | | |
| Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred. | | |
| Amount Payable | | |
| | | |
| Amount Before GST (\$\$) | GST Amount (\$\$) | Amount After GST (\$\$) |



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

D04 20-11-2017
 545 546341
EUROKARS GROUP

| | | | | | |
|---|-------------------|--------------------------------------|-----------|-------------------------|-------------------|
| MSIG INSURANCE (SINGAPORE) PTE LTD | | NAME : Mr Goh Sao-Ee | | WIP : 46457 | |
| 4 SHENTON WAY | | ADDRESS : 42 Springside Place | | EXCESS : | |
| #21-01 SGX CENTRE 2 | | Singapore 786445 | | DATE: 22-Nov-17 | |
| SINGAPORE 068807 | | | | | |
| ATTN. : MOTOR CLAIMS | | TEL : 90238893 | | | |
| FAX : | | | | | |
| VEH NO : | SLE4327M | DATE IN : | | CONTACT PERSON : | JESS 6395 7874 |
| CHASSIS NO : | MM6DL2SAAGW196280 | MILEAGE : | 20094 | TYPE OF CLAIM : | THIRD PARTY CLAIM |
| MODEL : | MAZDA2 SEDAN | DATE REG.: | 21-Jul-16 | POLICY NO. : | |

NATURE OF WORKS

Parts Description

| NO | QTY | REVISED | PRICES |
|-------------------------|--|---------|---------------------------|
| 1 | REAR BUMPER / <i>RL</i> | 1 | MDB7A-50-221BBB \$ 909.00 |
| 2 | RETAINER(RHS), REAR BUMPER / <i>RL</i> | 1 | MDB7A-50-2H1 \$ 21.70 |
| 3 | STAY, REAR BUMPER X <i>NN</i> | 2 | MDB7A-50-271 \$ 24.60 |
| 4 | REFLECTOR RHS / <i>CRA</i> | 1 | MD350-51-5M0E \$ 50.40 |
| 5 | RHS REAR MUDGUARD X <i>NN</i> | 1 | MDB7A-50-340 \$ 50.00 |
| 6 | TAPE PROTECTOR, REAR BUMPER / | 3 | MGS1D-50-EM1A \$ 24.30 |
| 7 | FASTENER, REAR BUMPER / | 7 | MB45A-56-146A \$ 19.60 |
| 8 | CLIP, REAR BUMPER / | 1 | MGJ21-50-049 \$ 3.20 |
| 9 | GROMMET, REAR BUMPER / | 1 | M9991-00-501 \$ 2.80 |
| 10 | GROMMET, REAR BUMPER / | 4 | MBHN1-50-0Z1A \$ 10.00 |
| 11 | GASKET(LHS), TAILLAMP / | 1 | MDB7A-51-163 \$ 31.90 |
| 12 | GASKET(RHS), TAILLAMP / | 1 | MDB7A-51-153 \$ 31.90 |
| 13 | FASTENER, TAILLAMP X <i>NN</i> | 2 | MKD53-51-146B \$ 7.80 |
| 14 | GROMMET, TAILLAMP X <i>NN</i> | 2 | MGJ6A-51-14Y \$ 29.80 |
| TOTAL PARTS | | | \$ 1,217.00 |
| LESS 10% | | | \$ 121.70 |
| TOTAL PARTS COST | | | \$ 1,095.30 |

Labour Description

| 1 | MZ-BR-REAR01 | TO REPLACE REAR BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. | <i>630</i> \$ 1,260.00 |
|---|--------------|--|------------------------|
| 2 | MZ-SP-SREAR1 | TO RESPRAY REAR BUMPER. | <i>900</i> \$ 1,200.00 |
| 3 | MZ-BR-REVSEN | TO TRANSFER REVERSE SENSORS. | <i>315</i> \$ 630.00 |
| 4 | MZ-BR-ELECTR | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. | <i>150</i> \$ 250.00 |

| | | | | |
|---|--------------|---|------|-----------|
| 5 | MZ-BR-REPROG | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. | 180 | \$ 350.00 |
| 6 | MZ-BR-SUNDRI | SUNDRIES. | NETT | \$ 100.00 |

| | | |
|--------------------|------|-------------|
| TOTAL LABOUR | \$ - | \$ 3,790.00 |
| TOTAL PARTS | \$ - | \$ 1,095.30 |
| TOTAL | \$ - | \$ 4,885.30 |
| LESS EXCESS | \$ - | \$ - |
| TOTAL AFTER EXCESS | \$ - | |
| GST 7% | \$ - | \$ - |
| GRAND TOTAL | \$ - | \$ - |

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

3 Days.

before paint photos.

Guo Qiang - 82880822

Guo Qiang @ lkk auto. com

24/11/17

[Handwritten Signature]
28/11/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022420/GRBN2

Date: 18/07/2018

REFERENCE

| | | | |
|-----------------------|--------------------------------------|----------------------|-------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 28852122DMA |
| Claimant Vehicle No : | SLE4327M | Insured Vehicle No : | SJL5463H |
| Date of Loss: | 20/11/2017 | Nature of Claim: | TP |
| | | Claim No: | 537638 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|----------------------------------|-------------|-------------------|
| Reg No: | SLE4327M | Engine No: | P520348348 |
| Make & Model: | MAZDA 2, 1.5 SEDAN L SP.6EAT (A) | Chassis No: | MM6DL2SAAGW196280 |
| Reg. Date: | 21/07/2016 (Man. Year: 2016) | Odometer: | 20094 km |
| Colour: | Silver | | |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 185/60R16 | Rear Tyre Size: | 185/60R16 |
| Front Left Side: | Dunlop 7 mm | Rear Left Side: | Dunlop 7 mm |
| Front Right Side: | Dunlop 7 mm | Rear Right Side: | Dunlop 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 1,195.30 | 1,014.32 | 180.98 | 15.14 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,690.00 | 2,175.00 | 1,515.00 | 41.06 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 4,885.30 | 3,189.32 | 1,695.98 | 34.72 |
| + GST 7.00/7.00% (\$\$) | 341.97 | 223.25 | 118.72 | 34.72 |
| Nett Amount (\$\$) | 5,227.27 | 3,412.57 | 1,814.70 | 34.72 |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 23/11/2017 | |
| Date Inspected: | 24/11/2017 | Inspected At: Trans Eurokars Pte Ltd NO. 5 UBI CLOSE, SINGAPORE Singapore 408605 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|----------------------------|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 18 Jul 2018) |
| Parts: 143 | MAZDA 2 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLE4327M) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|----------|-----------------------------|---------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 909.00 FL | *909.00 FL |
| 2 | 1 | | *RETAINER (RHS),REAR BUMPER | Necessary | 21.70 FL | *21.70 FL |
| 3 | 2 | | *STAY,REAR BUMPER | Not Necessary | 24.60 FL | *- FL |
| 4 | 1 | | *REFLECTOR RHS | Cracked | 50.40 FL | *50.40 FL |
| 5 | 1 | | *RHS REAR MUDGUARD | Not Necessary | 50.00 FL | *- FL |
| 6 | 3 | | *TAPE PROTECTOR,REAR BUMPER | Necessary | 24.30 FL | *24.30 FL |
| 7 | 7 | | *FASTENER,REAR BUMPER | Necessary | 19.60 FL | *19.60 FL |
| 8 | 1 | | *CLIP,REAR BUMPER | Necessary | 3.20 FL | *3.20 FL |
| 9 | 1 | | *GROMMET,REAR BUMPER | Necessary | 2.80 FL | *2.80 FL |
| 10 | 4 | | *GROMMET,REAR BUMPER | Necessary | 10.00 FL | *10.00 FL |
| 11 | 1 | | *GASKET (LHS),TAILLAMP | Necessary | 31.90 FL | *31.90 FL |
| 12 | 1 | | *GASKET (RHS),TAILLAMP | Necessary | 31.90 FL | *31.90 FL |
| 13 | 2 | | *FASTENER,TAILLAMP | Not Necessary | 7.80 FL | *- FL |
| 14 | 2 | | *GROMMET,TAILLAMP | Not Necessary | 29.80 FL | *- FL |
| 15 | 1 | | *SUNDRIES | Necessary | 100.00 FS | *20.00 FS |
| F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | |
| Sub Total (\$\$) | | | | | 1,317.00 | 1,124.80 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | | | | | 121.70 | 110.48 |
| Total Parts (\$\$) | | | | | 1,195.30 | 1,014.32 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE REAR BUMPER.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT | New | 1,260.00 | 630.00 |
| 2 | TO RESPRAY REAR BUMPER | New | 1,200.00 | 900.00 |
| 3 | TO TRANSFER REVERSE SENSOR | New | 630.00 | 315.00 |
| 4 | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING | New | 250.00 | 150.00 |
| 5 | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS | New | 350.00 | 180.00 |
| Gross Labour Cost (\$\$) | | | 3,690.00 | 2,175.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >