

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Nov-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1072 U

1 pc	Front bumper X repair	\$	531.00
1 pc	Front bumper n/s protector X	\$	51.00
1 pc	Front bumper n/s fog lamp X	\$	66.00
2 pcs	Front bumper n/s side retainer @ \$16.00 X	\$	16.00
		\$	664.00
		Less 10%	\$ 66.40
		\$	597.60

S/NETT

1 set	Front n/s fender sticker X	\$	60.00
	Sundry	\$	50.00 X
	To check for wheel alignment	\$	80.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of same etc	\$	450.00 200
	To putty and spray painting on front bumper	\$	200.00 180
	To apply rustproofing on the repaired and replaced panels.	\$	200.00 X
		\$	<u>1,637.60</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Ka Loo KICKY
22/11/17 0950h
2 Pcs
PIP
After Repair