PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

22-Nov-17

ESTIMATE REPAIR BILL FOR HYUNDAI 130 WAGON REGN NO: SHD 1560 C

1 pc	Rear bumper —	\$ 778.64
1 pc	Rear bumper n/s bracket 🗡	\$ 52.20
1 pc	Rear n/s fender	\$ 1,575.23
1 pc	Rear n/s fender inner shield 🗡	\$ 120.00
1 pc	Rear n/s fender quarter glass moulding	\$ 65.00
1 pc	Rear n/s lower arm 📉	\$ 642.71
1 pc	Rear n/s shock absorber 🗡	\$ 568.59
1 pc	Rear n/s trailing arm	\$ 482.29
1 pc	Rear n/s assist arm 🗶	\$ 344.82
1 pc	Rear n/s upper arm 🗶	\$ 401.05
1 pc	Rear n/s bearing ×	\$ 349.60
1 pc	Rear n/s rim	\$ 246.00
	•	\$ 5,626.13
	Less 20%	\$ 1,125.23
		\$ 4,500.90
S/NETT	<u></u>	
1 set	Rear bumper clips	\$ 48.00
1 pc	Rear n/s fender sticker	\$ 100.00
1 pc	tyre ×	\$ 200.00
1 pc	Sealant	\$ 50.00

ESTIMATE REPAIR BILL FOR HYUNDAI 130 WAGON REGN NO: SHD 1560 C

Sundry		\$ 50.00 28
To Dismantle and refit reverse sensor and test system		\$ 50.00 20 80.00 20
To check alignment		\$ 160.00 ×
To dismantle and refit the rear n/s fender quarter glass to faciliate repair		\$ 129.00 50
To dismantle and replace rear n/s undercarriage		\$ 250.00 ×
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear n/s fender. Including to knock-out, straighten, repair, reshape of the same		\$ 1,000.00 600
To putty and spray painting on the rear bumper, rear n/s fender	Rin	\$ 50000 410
To apply rustproofing on the repaired and replaced panels		\$ 150.00 50
	Total	\$ 7,208.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalur 101(K)

M 23/11/17 0945hrs.

4 Reyears Pajat photo

P/P

LKK Aur the Rep • To residue. • To display democed particle ingressivey • Finits price, are schedute as imparion • To display democed particle ingressivey • Finits price, are schedute as imparion • To display democed the assistance in the schedute in the

120