

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 27 Nov 2017

Preliminary Advice

Vehicle No	: SLR2818H	Accident Date	: 23/11/2017
Make	: VOLKSWAGEN GOLF	Policy No.	: A28997161AVW
Assignment Date	: 24/11/2017	Excess	: S\$500.00
Date of Inspection	: 24/11/2017	Est. Duration of Repair	: 7.00
Inspection At	: VOLKSWAGEN CENTRE SINGAPORE - TUAS (HQ) 17 TUAS AVE 9 SINGAPORE 639197		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,515.00
Revised Amount	:S\$	6,581.90
Check Items (Estimated)	:S\$	1,508.10
Total	:S\$	8,090.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	48,717.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,283.00

Remarks

(X) The vehicle is economical for repair. Kindly let us have your approval please.

() The above survey was conducted on a 'without prejudice' basis.