

ASS. REC. BY:

REF:

CS/TP1702435/Kgbn2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

1-B1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 266J

Yr Regn:

11, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1895

Colour

m-white 1st

A/C:

Insured / Std / NI / NA

Sp. Reading

374876

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC - 282310

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Falken 215/80R16

Ling R: Long

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

20/11/17

D.O.I.

23/11/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/11

File pass to Carhous

SHD 266J to

Q 3025.47 (Red 6 20009.75, 872)

no resurvey photo.

RECEIVED 20 JUN 2018

20/6/2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 20/6/18

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

13x15=195

170+195

50

13

80

508

Report Format :

Lump Sum / I.B.I. (\$

3025.47




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP17022435/Kqb		
NO.2 ANG MO KIO STREET 63 SINGAPORE 569111		Date : 24-11-2017		
		Code : TP378		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected	SHD 266J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	23/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 20/11/2017		Inspection Date 23/11/2017		
Survey held at		TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3878K

Vehicle Details

Vehicle No.	SHD266J
Vehicle to be Exported	Yes
Intended De-registration Date	21 Nov 2017
Vehicle Make	RENAULT
Vehicle Model	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour	Red
Manufacturing Year	2015
Engine No.	M9R8839C002925
Chassis No.	VF1ABL15AUC282310
Maximum Power Output	127.0 kW (170 bhp)
Open Market Value	\$19,998.00
Original Registration Date	20 Nov 2015
First Registration Date	20 Nov 2015
Transfer Count	0
Actual ARF Paid	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	19 Nov 2023
PARF Rebate Amount	\$14,998.00

Intended COE Rebate Details

COE Expiry Date	19 Nov 2023
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$45,267.00
COE Rebate Amount	\$33,929.00
Total Rebate Amount	\$48,927.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Nov 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2017 16:02
Date Of Accident	20/11/2017 12:40
Exact Location Of Accident	SOMERSET ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD266J
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARDS

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	TAN CHIN SENG
NRIC No	S1172725E
Date Of Birth	23/08/1955
Occupation	OUTDOOR
Date Of Driving Pass	19/01/1982
Driving Experience	35 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98324278
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 86 LORONG 2 TOA PAYOH #09-335
Postcode	310086
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 20 NOVEMBER 2017 @ 1240HRS, I ALIGHTED A PASSENGER AT HOTEL JEN. WHEN I PROCEED TO EXIT FROM THE HOTEL JEN LOBBY AND ALREADY TURN OUT INTO THE MAIN ROAD. SUDDENLY A SALOON CAR, SLP 3556S FROM SECOND LANE JUST CUT INTO MY LANE WITHOUT ANY SIGNAL. THAT CAUSE SLP 3556S HIT ONTO MY FRONT LEFT PORTION OF MY TAXI. THERE IS 1 PASSENGER ON BOARD OF SLP 3556S.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP3556S
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20 NOV 2017

Reporting Centre Personnel's Signature
Name: JASMINE TAN SIEW KIM
NRIC/FIN No.: S74056361

Sketch Plan #2 Pg. 1

SKETCH PLAN

SKETCH PLAN

0 100

Hotel Green

A 540 363

B 510 355

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20 NOV 2017

Reporting Centre Personnel's Signature
Name: JASMINE TAN SIEW KIM
NRIC/FIN No.: S74056361

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20 NOV 2017

Reporting Centre Personnel's Signature
Name: JASMINE TAN SIEW KIM
NRIC/FIN No.: S74056361

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 266J -**AAD1711-224***Not Authenticated**Resing B4 paid**\$ 3075.47*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 266J - JASMINE

VF1ABL15AUC282310

RENAULT

LATITUDE

20.11.2017

GA

PART**LIST**

1	1	BUMPER COVER FRT	\$	<i>Per km</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
3	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.22
4	1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41
5	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 151.41
6	1	BUMPER SUPPORT FRT LH	\$	<i>SL</i> 123.88
7	1	BUMPER SUPPORT FRT RH	\$	<i>SL</i> 123.88
8	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
9	1	RADAITOR GRILLE	\$	<i>SL</i> 1,707.78
10	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
11	1	RADAITOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
12	1	AIR CLEANER LOWER	\$	<i>SL</i> 352.64
13	1	AIR CLEANER HOSE	\$	<i>SL</i> 76.14
14	1	BONNET	\$	<i>R</i> 1,941.63
15	1	BONNET HINGE LH	\$	<i>R</i> 348.31
16	1	BONNET STRUT LH	\$	<i>R</i> 88.61
17	1	HEADLAMP LH	\$	<i>SL</i> 1,184.43 ✓
18	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15
19	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83
20	1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84
21	1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84
22	1	DOOR MIRROR LH	\$	<i>SL</i> 1,483.40
23	1	DOOR MIRROR GLASS LH	\$	<i>SL</i> 148.20
24	1	DOOR MIRROR BACK COVER LH	\$	<i>SL</i> 218.46
25	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
26	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50
27	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55

TOTAL	\$	17,007.13
10%	\$	1,700.71
	\$	15,306.42

Specical Nett

1 ISET FRONT BUMPER CLIP

\$

R 66.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-224

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 266J -

2	1SET	WHEELARCH CLIP LH	\$	66.00	} X
3	1	TOW COVER FRT	\$	14.50	
4	1	CAP HUB LH FRT	\$	35.00	
5	1	RIM LH FRT	\$	385.00	
6	1	TYRE LH FRT	\$	330.00	
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	9.80	
8	1SET	BUMPR RETAINER FRT CLIP LH	\$	12.50	} X
9	1	DOOR STICKER "Trans-cab"	\$	80.00	
10	1	DOOR STICKER "Classic"	\$	30.00	

TOTAL	\$	1,028.80
TOTAL PARTS	\$	16,335.22

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 300

To Check Electrical Lighting Concerned.

\$ 170.00 20

Putty and spray painting of the affected portion.

\$ 3,000.00 440

To check steering geometry and computer wheel alignment

\$ 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ 170.00 X

TOTAL	\$	6,700.00
Over All Total	\$	23,035.22

(PARTS BY PARTS) Repair Days**10 Days**

2 days

- LKR Auto Consultants hereby notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CS/TP17022435/Kqbn2

NO.2 ANG MO KIO STREET 63 SINGAPORE 569111

Date : 22-06-2018



Code : TP378

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHD 266J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	23/11/2017

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC282310	Colour	METALLIC WHITE / RED
Odometer	374876	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	7 mm
L/H Front Tyre	215/60 R16	FALKEN	7 mm
R/H Rear Tyre	215/60 R16	LING LONG	7 mm
L/H Rear Tyre	215/60 R16	LING LONG	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/11/2017	Inspection Date	23/11/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 266J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	BUCKLED / CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.22	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT LH	SERVICEABLE	123.88	-
1	BUMPER SUPPORT FRT RH	SERVICEABLE	123.88	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	AIR CLEANER LOWER	SERVICEABLE	352.64	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET STRUT LH	TO REPAIR SEE LABOUR	88.61	-
1	HEADLAMP LH	CUT	1,184.43	1,184.43
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	DOOR MIRROR LH	SERVICEABLE	1,483.40	-
1	DOOR MIRROR GLASS LH	SERVICEABLE	148.20	-
1	DOOR MIRROR BACK COVER LH	SERVICEABLE	218.46	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-

Report Ref No. CS/TP17022435/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,700.71	-244.38
			15,306.42	2,199.47
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET WHEELARCH CLIP LH (SN)	NOT NECESSARY	66.00	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	SET BUMPER SUPPORT FRT CLIP LH (SN)	NOT NECESSARY	9.80	-
1	SET BUMPER RETAINER FRT CLIP LH (SN)	NOT NECESSARY	12.50	-
1	DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	30.00	-
			1,028.80	66.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,BONNET,BONNET HINGE LH,BONNET STRUT LH,HEADLAMP PANEL FRT LH,FENDER PANEL FRT LH,DOOR PANEL FRT LH,DOOR HINGE UPPER LH AND DOOR HINGE LOWER LH.		2,800.00	300.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	-		-	-
	-		-	-
	-		-	-
			6,700.00	760.00
	GRAND TOTAL		23,035.22	3,025.47
	RECOMMENDED COST OF REPAIRS			3,025.47

Report Ref No. CS/TP17022435/Kqbn2



Report Ref No. CS/TP17022435/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.