

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7546X

DATE 23/11/2017 14:48

Jumani

MAKE :

MODEL : HYUNDAI i40

MODEL	REPAIR	Qty	Parts Description/ Labour	Type	Unit Price	Amount	
			Front Bumper Cover ✓			\$ 562.30	
			Front Bumper Grille (RH) ✓			\$ 40.30	
			Front Bumper Bracket Top (RH) ?			\$ 22.40	
			Front Bumper Bracket (RH) ?			\$ 24.60	
			Front Bumper Retainer Mounting ?			\$ 9.20	
			Headlamp (RH) ✓			\$ 1,388.00	
			Front Fender (RH) ✓			\$ 619.00	
			Front Fender Shield (RH) X			\$ 169.80	
			Front Fender Retainer ?			\$ 9.20	
			Front Door (RH) X repair				
			SUB TOTAL			\$ 2,844.80	
			LESS 20%			\$ 568.96	
			DISCOUNTED TOTAL			\$ 2,275.84	
			(RH) Front Door Comfort Sticker -			\$ 75	
			Labour Charge				
			Panel Beating			\$ 560.00	
			Spray Painting Charge			\$ 400.00	
			Wiring Charge			\$ 50.00	
			Tuff Kote			\$ 50.00	
			TOTAL LABOUR			\$ 1,060.00	
			ESTIMATE TOTAL			\$ 3,335.84	
						3335.84	
			Kalvin LKK/ 23/11/17 1505hrs. 3 Days PIP Before Part photo				
			LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.							